




Kit Contents PRN015344

Ⓐ 6 x Rubber Bungs






Repeat  
Both Sides




Repeat  
Both Sides



Repeat  
Both Sides







Locate round holes amongst hexagons.


Push Rubber Spacer through from the back of the guard so Hexagonal shape sits on the front face












Repeat  
Both Sides






Repeat  
Both Sides




Do Not Fully  
Tighten



Repeat  
Both Sides

 Do Not Fully  
Tighten




Repeat  
Both Sides



Caution

Fully  
Tighten



Repeat  
Both Sides



Caution

Fully  
Tighten





## ESSENTIAL CHECKS

It is recommended that periodic inspections are made to ensure that dirt and debris have not become trapped between the guard and the radiator/oil cooler. Such dirt and debris would reduce the cooling efficiency of the radiator/oil cooler.

It is recommended that periodic inspections are made to ensure that all fixings are fully tightend.