


TOOL TRAY ASSEMBLY INSTRUCTIONS



READ THIS FIRST:

1. INSTALL EXTRUSION FASTENERS (as seen in DETAIL 1) INTO THE ENDS OF EXTRUSIONS C,D,E & F, THIS WILL HOLD EXTRUSIONS A&B TOGETHER.
2. INSTALL TOOL TRAY (H) USING DROP-IN NUTS AND SCREWS (as seen in DETAIL 2) THEN SLIDE THEM ONTO EXTRUSION A AND TIGHTEN.
3. PRE-INSTALL DROP IN NUTS AND SCREWS (as seen in DETAIL 3) ONTO TWO STANCHIONS. THEN SLIDE THEM INTO THE ENDS OF EXTRUSIONS A&B AND TIGHTEN. THIS HOLDS THE TOOL TRAY ASSEMBLY TO THE AIR PIPE.
4. ATTACH THE REMAINING TWO STANCHIONS TO EXTRUSIONS E&G ON THE MAIN WALKABOUT PLATFORM USING DROP IN NUTS AND SCREWS (as seen in DETAIL 3)



DETAIL 1
EXTRUSION FASTENERS



DETAIL 2
DROP-IN NUTS AND SCREWS



DETAIL 3
STANCHION


LIGHT POLE ASSEMBLY INSTRUCTIONS

READ THIS FIRST:

1. USE THE INCLUDED HARDWARE TO ATTACH THE LIGHT TO THE EXTRUSION (as seen in DETAIL 1).
2. INSTALL DROP-IN NUTS AND SCREWS TO THE OUTER UPPER AND LOWER EXTRUSIONS ON THE MAIN WALKABOUT PLATFORM IN LINE WITH EACH OTHER VERTICALLY. THE LIGHT FIXTURE WILL SLIDE OVER THE DROP-IN NUTS AND SCREWS (as seen in DETAIL 2) THIS ALLOWS YOU TO SLIDE THE LIGHT FIXTURE EXTRUSION ONTO THE PLATFORM WHERE YOU NEED IT AND TIGHTEN IN PLACE.
3. USE THE INCLUDED ZIP-TIES TO SECURE THE LIGHT ELECTRICAL CABLE TO THE LIGHT FIXTURE EXTRUSION.



DETAIL 1
LIGHT BRACKET ASSEMBLY



DETAIL 2
DROP-IN NUTS AND SCREWS

For ordering information, please contact
www.walkaboutplatform.com