



HOW TO REQUEST A CODE AND USE IT TO RE-CONFIGURE A HEX FLASH PROGRAMMING TOOL CABLE.


1. Download and execute “XDEVICE Toolkit” from VF-Engineering website download page.
2. Plug in your Hex-Flash programming cable into your USB (car is not needed).
3. Single click [Refresh List] and your cable ID should appear in the dialogue window.
4. Double-Click on your cable “VF FLASH USB” in the dialogue box to highlight it and a green progress bar will pop-up and complete. Then all the cable coding info will populate in the configuration tab as below.



5. Single-click on button at bottom “click HERE for XDEVICE Conf.....” and a new dialogue will pop-up as below.



- Single-click "Copy Reference Numbers" and this copies the cables reference data. You can then paste it [CTRL+V] into an email to VF-Engineering or upload it into your VF service ticket.



RESETTING CABLE:

ONCE YOU RECEIVE A RESET CODE BACK FROM VF-ENGINEERING TECHNICAL DEPT REPEAT STEPS 1 TO 5 ABOVE, TO GET TO THE CODING WINDOW (SEE BELOW) AND PASTE THE RESET CODE INTO THE BOX AND PRESS EXECUTE. A GREEN POP-UP PROGRESS BAR WILL APPEAR TO CONFIRM SUCCESS!

