



MAGNET SOURCE® CENTER

ROTATING DISPLAY SETUP INSTRUCTIONS


PARTS LIST




A Peg Board - 1 pc.



B Header - 1 pc.



C Base - 1 pc.



D Hook - 24 pcs.




E Allen Key - 1 pc.




F Bolt M6*12 - 3 pcs.

INSTRUCTIONS

STEP 1: Fix C to A with three bolts



STEP 2: Put B and D on fixture



FULLY ASSEMBLED



For more information call 888.293.9190



Your Best Source in the Magnetic Field

MASTER MAGNETICS, INC.
MAGNET
SOURCE™
magnetsource.com