

Assembly Instructions for the TTT 1600 Hand Crank Tumbler



PARTS LIST:

Frame Bottom (6 openings for legs)
Frame middle (6 openings for legs with bearing and coupler in place)
6 PVC legs (15")
2 aluminum pans with flanges
1 axle
1 Clear catch bag
1 net for trimming (1/2" mesh) (additional nets available to order)
Hand Crank

TOOLS NEEDED:

Rubber mallet (or PVC leg will work)
Wrench

ASSEMBLY:

Note: We have a dedicated page on our web site with assembly instructions and more.

<https://tomstumbletrimmer.com/pages/instructions>

SCAN ME



VISIT OUR WEB PAGE
FOR PRODUCT
ASSEMBLY INSTRUCTIONS



TTT 1600

FRAME ASSEMBLY:

1. Lay the bottom frame on the ground with open corners up.
2. Insert the six legs into the bottom frame.
3. Place middle frame (with bearing) on the legs and tap down with rubber mallet.

TUMBLER ASSEMBLY:

1. Thread the axle onto the pans with edges of the pans facing in.
2. Place axle and drums between the frame top. Hold axle with one hand. Then thread the drum end onto the coupler bushing. Hand tighten with wrench. Then put the Hand crank through the hole on the other side of the frame toward the inside of the frame, metal end first. Thread the other drum onto the threaded end of the metal. Hand tighten. Be sure the drums are tightened onto the coupler and hand crank. Drum should turn easily with the hand crank.
3. Roll the net onto the drums, velcro to velcro, and zip up to create a mesh barrel. Note that one zipper does not unzip completely to keep the netting together as one piece.

Retighten the drums on bushings as they may have loosened.





ATTACH BAG TO FRAME

Attach the clear bag to the frame using the velcro connectors. When you are done tumbling, remove the bag and empty into clean bin.



You are ready to Tumble!

USING THE TRIMMER

Make sure your product is completely dry on the outside. 5% to 10% moisture on the inside of the bud is good. See our website for suggestions on how to dry your product at TomsTumbleTrimmer.com. Take the large leaves and stems off. The more you prep your bud, the faster the trimming will occur.

TRIMMING

Put the (1/2" mesh net on the trimmer and put the **RIGHT AMOUNT** of product in the net- between 3/4 lb. and 1 pound. The ideal amount is to fill the barrel to about 2" under the axle. Over filling or under filling are not recommended. **Following these guidelines is critical to the effectiveness of the trimmer.** Once tumbling, the bud should have a nice rolling wave under the axle.

Do not over tumble. You may be done after 3 minutes. Stop tumbling every few minutes to check the progress. You should not need to tumble more than 5-7 minutes. If you do, your product is either not dry enough or too fluffy.

CLEANING

We recommend cleaning your funnel flow bag and dust cover after each use with a damp rag and Tom's Resin Remover organic cleaner. The mesh nets can be washed in a washing machine with cold water and detergent. Line dry only. Keep your zippers clean and lubricate as necessary, with Tom's Resin Remover.



OTHER PARTS AND ACCESSORIES AVAILABLE FOR OUR FULL LINE UP OF TOM'S TUMBLE TRIMMERS PLEASE INQUIRE TODAY! WE ARE HERE TO HELP!

Thank you again for your purchase!

Call us with any questions about assembly or use at 800-601-0797.

Tom Bruggemann
Inventor and CEO

ALL PARTS ARE COVERED BY OUR 1 YEAR WARRANTY.