

PowerSteamer/PowerLifter 1370, 1622, 1623, 25M1 Series  
ProHeat 25A3, 57G7 Series

## **Belt Keeps falling off**

**Replace the belt and try the unit again.** If belt continues to fall off, please contact one of our Authorized Service Centers to have a quality technician inspect your unit.