## FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL

| (END OF LISTING) | LED Taxi 01-0790589-00<br>Light  | Article Name Part Number                   | Whelen Engineering Company, Inc. 51 Winthrop Road Chester, CT. 06412-0684 |
|------------------|--|--|---|
|                  | Teleflex 4060622   | Approved Replacement for Part Number       |   |
|                  | Identicality per 14 CFR, § 21.303, licensing agreement between Whelen Engineering Company Inc. and Dassault Falcon Service, Assist Letter, dated September 20, 2012 DWG No: 90589 Rev: C Date: 8/29/12 or later FAA-approved revisions | Approval Basis and<br>Approved Design Data |   |
|                  | Dassault Falcon<br>Service   | Make<br>Eligibility                        | PMA NO. PQ0610NE SUPPLEMENT NO. 41 DATE September 28, 2012                |
|                  | MF900 / F900EX /<br>F900DX / F900EX<br>EASy / F900LX<br>MF50 / F50EX<br>F2000 / F200EX /<br>F2000EX EASy /<br>F2000LX  | Model<br>Eligibility                       | 0610NE<br>T NO. <u>41</u><br><u>ber 28, 2012</u>                          |

specifications are to be handled in the same manner as that for an original PMA. When these procedures are no longer applicable because of completion of the production contract, or termination of the licensing agreement or business relationship, all subsequent minor design changes to the PMA articles must be submitted in a manner as determined by the ACO. Major design changes (reference 14 CFR §§ 21.93 and 21.97) to drawings and incorporating the same minor changes on identical PMA replacement articles. The PMA holder must be able to show traceability relating to the TC, STC, or TSO authorization holder on all minor changes incorporated by this procedure. Note: The procedures that have been accepted by the type certificate or TSO authorization holder and their cognizant FAA Aircraft Certification Office, for minor changes to original articles used on type-certificated products, are also acceptable for

Richard Warren
Manager, Manufacturing Inspection District Office,
NE-MIDO-41