














ASSEMBLY INSTRUCTION

SWING CHAIR EGG

10950GS/10952GS/10954GS/10970GS/10942GS/10944GS/10946GS

NO.	PICTURE	QTY
A		1
B		1
C	 (M8X60)	1
D		1
E		1
F		1
G		1
H		1
I		1
J		1
K	 5#	1
L		5




ASSEMBLY INSTRUCTION


SWING CHAIR EGG

10950GS/10952GS/10954GS/10970GS/10942GS/10944GS/10946GS

STEP-1



STEP-2



STEP-3

