



SNAP SWITCHES

1021 2 Pole ON-OFF




1122B 3 Pole ON➔OFF<ON




1021A 2 Pole ON➔OFF


SPRING RETURN




1221 4 Pole ON-OFF



1121 3 Pole ON-OFF




1321 6 Pole ON-ON




1121A 3 Pole ON➔(ON)


SPRING RETURN




1322 6 Pole ON-OFF-ON




1122 3 Pole ON-OFF-ON




902 9 Pole ON-ON 3PDT




903 9 Pole ON-OFF-ON 3DPT



1122A 3 Pole ON-OFF<(ON) SPRING RETURN



1202 12 Pole ON-ON 3PDT



1203 12 Pole ON-OFF-ON 3DPT

