SC351 How To

Prepare for use

1



Unplug battery charger.

2



Wrap cord accordingly.

3



Inspect squeegee, brushes or pads then install.

4



Fill machine with appropriate solution (temperature should not exceed 130 °F).

5



Inspect ball float cage.

6



Lower recovery tank lid.

7



Get familiar with the control panel.

8



Enable push-button and lever to engage brush/pad holder then release.

9



Turn machine on.

10



Choose program for the type of work to be performed.

11



Press the solution flow control switch.

12



Begin scrubbing.



SC351 How To

Store the Machine



Empty recovery tank and solution tank.



2

5

8

Rinse and wash recovery tank with clean water.



Inspect and wash, vacuum grid and automatic shut-off float.



Take squeegee off and remove debris.



Inspect squeegee, rinse and replace if needed.



Remove, clean and inspect brush or pad. Rinse with warm water. Hang to dry. Replace if needed.





Charge batteries.



Wipe exterior of machine with a damp cloth.

9

6



Lift recover tank lid to allow inside of the tank to dry.

SC351 How To

Daily, Weekly and Occasional Maintenance

2

8



Clean brush daily.



Clean squeegee daily by removing debris.



Check each battery cell's water level (does not apply to gel batteries). Charge batteries daily.



Clean tank and vacuum grid daily.

5

Perform squeegee blade check and/or replacement weekly.

Every 6 Months

6

9

Screw and nut tightening check. Perform this task after the first 8 hours of operation.


7



Brush deck rubber pad check and/or replacement



Brush deck end-ofstroke cable check and/or replacement yearly.



Brush deck rubber flange check and/or replacement yearly.

