


Stria Pendant Installation Guide & Warranty



- Please use a registered electrician to install the ceiling canopy.
- Turn power off before installing the pendant.
- Use appropriate hardware to attach ceiling canopy to ceiling substrate.
- Install as per AS/NZS 3000
- 230 V a.c. 50 Hz only.
- Supply earth must be connected to the ceiling canopy earth.
- 75 Watts MAX / E27 Bulb.
- For INDOOR USE only.
- Total hung weight must not exceed 5 kg.

To attach ceiling canopy to ceiling substrate. Remove the bottom circular canopy plate (attached with magnets) to access screw mounts.



Ceiling canopy wiring diagram


230 V a.c. 50 Hz Supply




Set the height of the pendant shade by adjusting the length of the fabric cable and the suspension wire at the ceiling canopy.



Once the canopy is securely fixed to the ceiling substrate, thread the pendant balancer through the top of the pendant shade.



Ensure the arms of pendant balancer sit on either side of the four structural 'ribs' located inside the shade.



Level the pendant shade to sit horizontal on the pendant balancer. Use a small spirit level if required.

Stria Pendant Warranty

The Stria Pendant is warranted for two years from the date of purchase. Please note: Some pendant shades may exhibit minor cracks and shape fluctuations due to expansion and contraction of materials reacting to changes in humidity and temperature. Small cracks and shape variations are not covered by this warranty. However, if you do encounter a genuine issue, please let us know. To ensure the longevity of this pendant, please avoid prolonged exposure to direct sunlight.