

Wolff Industries Inc.

Carrying Case

Unpack the Carrying Case and Foam Inserts



Remove shoulder strap from carrying case.

Lay hold down straps to the outside of the case.

Insert High Density Foam (dark gray) flat in bottom of case and the Pluck Foam (light gray) on top of it.



Pluck foam squares to accommodate machine and accessories.



Machine should set in the center of case in order to be held by hold down straps when transporting.



Case with Foam # 24950

Foam only # 24955