

# INSTALL AS SHOWN

Change to clamp shown was implemented May 2005, the roll pin is no longer needed. The spring pushes the clamp towards the open position.

