
Half Rack







Read all safety warnings, instructions and illustrations provided for this piece of strength equipment. Failure to follow all instructions listed

below may result in serious injury or death. User assumes all potential risks of assembly or use of this product.

PERSONAL SAFETY

• Stay alert, watch what you are doing when assembling and operating the strength equipment. Do not use the strength equipment while you are tired or under the influence of drugs, alcohol or medication. A moment of inattention while operating or assembling the strength equipment may result in serious or fatal injury.


EQUIPMENT USE AND CARE

- Visually inspect all components in order to identify potential deformation or damage. If damages are observed, discontinue assembly and contact the manufacturer at shipping@texasstrengthsystems.com, wesz@texasstrengthsystems.com.
- Multiple components involved with assembly of this piece of strength equipment are above 50lbs and it is recommended that you have an additional person to assist in the positioning of these items.
- Ensure that all components are securely fastened before use.


Required Tools

- Crescent Wrench
- 9/16" Socket and Wrench


Parts




HFR-001 | (x2) | Part A



HFR-002 | (x1) | Part B




HFR-003 | (x1) | Part C



HFR-004 | (x2) | Part D




HFR-005 | (x2) | Part E



HFR-006* | (*x2*) | *Part F (If Purchased)




HFR-007 | (x10) | Part G



HFR-008 | (x2) | Part H



3/8" Lock Nut | (x20) | Part K



CR-200 | (x2) | Part L



 $^{3}\!/\!\!\!8$ " x 3.75" Bolt | (x20) | Part I



3/8" Flat Washer | (x8) | Part J

Assembly




Image 1

Parts A, B, and C are organized in the manner displayed in image 1.




Image 2

Repeat image above for all holes in part B




Image 3





Image 4

The top hole of parts A and C will require parts I and J as seen in image 4.



Part G will be placed and attached as seen in image 5.





Image 6

Part H will be attached with part G as seen in image 6 using the same hardware as image 5.



Place parts E and F in the desired location.





Image 7

Place part D in the desired location and attach using part L as seen in image 7.



You have now completed assembling your very own Half Rack! Thank you for choosing Texas Strength Systems for your fitness needs. If you have any questions, comments, or concerns please don't hesitate to contact our staff.

Contact Information

Email: wesz@texasstrengthsystems.com

Phone: (210) 233-6110, (210)-920-4877