





Before use, always check cables for signs of wear. Replace immediately, Never use machine if cable is damaged. Fallure to do so may result in serious injury.

Keep clear of the cables and all moving parts when the machine is in use. moving parts when the machine

THERE IS A RISK ASSUMED BY INDIVIDUALS WHO USE THIS TYPE OF EQUIPMENT. TO MINIMIZE RISK, YOU MUST FOLLOW THESE RULES:

1. Imspect equipment daily. Check that all nuts, boils and screws are fully tightened and replace worn parts immediately.

PAGE 2