OutdoorLiving.

We recommend that your spa has an annual service which includes our 30 Point Check. and pipe clean treatment, which we will post to you to be added 2 days before our visit.

- spa, clean acrylic surface and check shell for damage
- Cleaning of headrests
- Vacuum of remaining water
- Install new filter (if applicable), Check for leaks in filter unit and Check settings cycles for filtration
- Balance water PH and add sanitiser
- Check cabinet for damage
- Check operation / pressure of Jets and Check for leaks in jet backs
- Check Pumps for noise / water pressure and check seals in pumps

- Draining of spa, rinse

 Check Heater operation and seals on heater
 - Check suctions operation and Clean grates of suctions
 - Check for damage / leaks in lights and check operation of lights
 - Check for leaks / blockages in hose lines
 - Check operation of other associated extras
 - Clean / inspect cover and check cover lift operation and cover retaining clips
 - Check operation of topside
 - Check diverters / air controls

If there are found to be any defective / damaged parts these will be either replaced or repaired under warranty (if applicable) or after the Technician has consulted with yourself to confirm any additional costs.

Contact Your Dedicated Service Team: Monday to Friday

10am to 4pm

01482 212322

serviceteam@outdoorlivinghottubs.co.uk





www.outdoorlivinghottubs.co.uk

Hull Hot Tub Showroom 1 Goulton Street Hull East Yorkshire HU3 4DD T: 01482 212322

Leeds Hot Tub Showroom Low Road (A61) Leeds West Yorkshire **LS10 1RB** T: 01132 713469



OutdoorLiving.

Hot Tub Service Guide



Expert knowledge from our dedicated team





Award-winning customer service and after-sales support





£170

£349

Outdoor Sorvice

all Out Local	From £69
all Out Mid-Range	From £99
all Out Long-Range	From £12 9
ll Call Outs include diagnosis of i	issue, the repai
f a spa and/or give a full check o	ver and covers

up to 1 hour labour onsite. Any work after 1 our will occur extra charges at £50 per hour. Any parts required will be chargeable.

ClearRay™ Replacement £129

Includes the work to check ClearRay™ System and replacement of the ClearRay™ Bulb.

Ozone Replacement £189

Includes the work to check Ozone System and replace Ozonator.

Drain and Winterise Spa £129

Pumps and internal parts are wet vacuumed out to prevent freeze damage. Includes Spa Clean Puck.

Outdoor Se	ervice	£1/9
Includes a full a	annual service and a Spa (Clean Puck.
,	Add Filter(s)	£199
	Add O <u>Z</u>	£259
,	Add Filter(s) & OZ	£279
J200™ Ser	vice	£179
Includes a full a	annual service, a Spa Clea	n Puck.
	Add Filter	£199
	Add <u>CR</u>	£229
	Add Filter & <u>CR</u>	£249
J300™ Ser	vice	£199
Includes a full a	annual service, Spa Clean	Puck.
	Add Filters	£239
	Add <u>CR</u>	£249
	Add Filters & <u>CR</u>	£289
J400 & J50	0™ Service	£229
Includes a full a	annual service Spa Clean I	Puck.
	Add Filters	£299
	Add <u>CR</u>	£279

Note: OZ includes a replacement ozonator. CR includes a replacement ClearRay™ Bulb.

Add Filters & CR



Gold Service Packages £Request

If you lead a busy life and you don't have time to maintain your Hot Tub, our Gold Service Packages are for you. We will visit four times throughout the year to complete your 3-4 monthly drain and refills, as well as a full annual service at a discounted rate.

Swim Spa Service £399

Includes a full annual service which is conducted over two visits. A service on Day 1 and commissioning on Day 2. This also includes two Spa Clean Pucks and a new set of filters. For OZ or CR pricing, please ask upon booking.

Service Loyalty Card

Every service includes a VIP loyalty card which entitles you to 10% off store purchases (Hull and Leeds) or online at Jacuzzi Direct for 12 months. (www.outdoorlivinghottubs.co.uk)Terms & conditions apply.

Extended Warranty T&Cs apply

'Outdoor' branded hot tubs are entitled to one additional year parts and on-site labour only warranty when a service is taken within one year of the original installation date of the hot tub.