February 7, 1985

inor Change Received

Date

8 1985

and Acknowledged

FEB

FAA

Federal Aviation Administration 181 South Franklin Avenue Room 202 Valley Stream, NY 11581

Attn: Raymond Borowski ANE 173

Dear Sir,

A minor change has been made to Switlik Parachute Company's drawing S-11400-(), S-11450-() Rev. C.

Changed code numbers of Items 41 (Lanyard), 36 (Lanyard), 38 (Reflective Tape), 42 (Mirror), and changed the part number of Item 43 (Mirror Pouch). Added Item 47, (Tether Assy), 26 (Blast Patch), Note 10, and assemblies XX10, XX11. Changed illustration of mirror. Moved eyelet down 4". Added dash numbers to Battery Pull Tab. Removed knife pocket and cement.

The enclosed drawing is submitted to update the file held by your office. All of the other data submitted with the original application remains the same. The Federal Aviation Administration's approval of this (these) change(s) is requested. The required Quality Control data is currently on file with your Teterboro, New Jersey office.

Sincerely,

SWITLIK PARACHUTE CO., INC.

Gustavo Fanjul Chief Engineer

Gr:jn

Enclosure S-11400-(), S-11450-(), Rev.D

cc: Teterboro

Mysemy