ESTABLISHED 1920

FAA New York ACO Branch

TSO Minor Change

Data Received and

Acknowledged by FAA

1325 EAST STATE STREET • P.O. BOX 1328 • TRENTON, NEW JERSEY 08607-1328 • (609) 587-3300 • FAX (609) 586-6647

May 5, 2022

Federal Aviation Administration New York Aircraft Certification Office 1600 Stewart Avenue Suite 410 Westbury, NY 11590

Attn: Mr. Tim Hadsall, NYACO Manager

Subject:

S-9400-(), Model HV-35P Life Preserver, Minor Change Request

Dear Mr. Sciortino,

The life preserver drawing S-9400-() has had a minor change to it. Revision X, a compliance matrix and this letter are being submitted to bring our records up to date.

Revision X dated 4/22, added a new cover fabric option to the life preserver. This is shown in Note 8 on Sheet 1. The new fabric is the same fabric used on the covers of our FAA-approved S-7200-() X-Back and S-9450-() Aviator life preservers.

On Sheet 3, the word "INFANT" was removed from the cover assembly back strap and the donning instructions, inside the back strap cover, were updated.

Switlik has reviewed the design change, and all applicable data, and consider this a minor change per 14 CFR Part 21, Subpart O, §21.619 and as defined in our quality control manual. As no change was actually made to the FAA-approved life preserver, it does not require a substantially complete investigation to determine compliance with TSO-C13d, nor are the minimum performance standards of Appendix 1 affected.

We hereby certify that this life preserver meets or exceeds all the requirements of TSO C13d, complies with 14 CFR Part 21, Subpart O, and will be manufactured under the strict quality control procedures on file with your Saddle Brook, New Jersey office.

Should you have any questions regarding this change, please don't hesitate to contact us.

Best Regards,

David Gutierrez Engineering Manager

Enclosure:

Revision X to S-9400-(), TSO-C13d Compliance Matrix

DG

cc: FAA, Saddle Brook NJ