



## **Servicing Recommendation: Switlik Constant Wear Aviation Life Preservers**

To: Switlik Constant Wear Life Vest Operators

Switlik constant wear aviation life preservers should be inspected and tested as appropriate during their service life, taking into consideration such factors as operational history, route structure, frequency of handling, environmental and stowage conditions, etc. While the life preserver manufacturer can make a recommendation regarding its life preserver's service intervals, ultimately the Time Between Overhaul (TBO) intervals are to be determined between each operator and their local airworthiness authority.

Switlik Survival Products hereby recommends a standard 2 year service interval (TBO) on all Switlik TSO-C13d and TSO-C13f approved constant wear life preservers (S-9450, S-7200, S-9430, S-9400) as long as visual inspections are performed by the operator on no less than semi-annually basis. Any life preservers with visual damage or excessive wear must be pulled from operation and serviced by an approved maintenance facility holding a maintenance certificate issued by a recognized Airworthiness Authority.

Date of Issue:  
March 13, 2017