

HONDA SXS 700 Pioneer

Parts list for MCS 2630

<u>Item</u>	<u>Qty</u>	<u>Part Number</u>	<u>Description</u>
1	1	MCS 8000C	Computer
2	4 lengths		Foam tape (4 x 7cm pieces)
		<u>MCS 2632</u>	<u>Electric Throttle Servo assembly</u>
3	1	MCS 810	Electric throttle servo
4	1	MCS 2632A	Servo mounting bracket
	3		M6 x 16 bolts
	3		6mm flat washers
	3	MCS 2632B	Spacers
5	2	HoseClamp12	Hose Clamp 18~32mm
6	1	MCSAC 650 or 750	Throttle servo cable
7		<u>ATVSw MCS 211+SS</u>	<u>Control Switch assembly with OPTIONAL spray switch</u>
	1	MCS 822-90	Control Switch
	4		4 gauge x 1/2" pan head self-tap screws
	1	MCS 2634-835F	Switch bracket with spray switch
	1	MCS 823-90	Spray switch
		<u>OR</u>	
8		<u>ATVSw MCS 211</u>	<u>Control Switch assembly without spray switch</u>
	1	MCS 822-90	Control Switch
	4		4 gauge x 1/2" pan head self-tap screws
	1	MCS 2634-836F	Switch bracket without spray switch
9	2		M4 x 12 pan head screws
10	4		4mm flat washers
11	2		M4 Nyloc nuts
12	2		8g x 3/8 pan head self-tap screws
13	1	<u>MCS 2631</u>	<u>Wiring harness</u>
a			Computer plug (26 pin)
b			Cruise Control Power Fuse (3 amp fuse)
c			Speed sensor connectors (blue/black wires)
c1	HX6189-0940 + 6918-1979		Housing and retainer for above
d			Throttle servo connector (4 way)
e			Brake switch connectors (orange and grey wires)
f			Neutral sensor connectors (green wires)
f1	HX6189-0940 + 6918-1979		Housing and retainer for above
g			Ground connector (black wire)
h			Control switch plugs (6 way)
i			Spray switch plug (3 way plug for optional Spray switch)
j			Connectors for optional Spray power harness(pink & blue wires)
		<u>OPTIONAL</u>	
		<u>MCS 2630SPK</u>	<u>Spray Power Kit</u>
14	1	MCS 2631SPH	Spray Power Harness
	1	JD 046	Spray Power Plug
	3	H 3555	Terminals for above
	3		8g x 3/8 self-tapping screws (relay/power plug mount)
	1		M5 x 16 pan head screw (relay mount)
	1		5mm flat washer (relay mount)
	1		M5 Nyloc nut (relay mount)

15		<u>MCS 2635</u>	<u>Cable Interface Unit (CIU) assembly</u>
16	1	MCS 2635A	CIU housing
17	1	MCS 003M	Throttle servo spool
18	1	MCS 2636A	Throttle cable spool
19	1	MCS 2636	Carburettor (throttle body) cable spool
20	1	MCS 003H	Bush
21	1	MCS 003J	End Cap
22	1		M5 x 45 bolt - pivot bolt
23	2		5mm plated flat washer
24	1		Pivot nut M5 Nyloc nut
25	1		M4 x 6 pan head screw (throttle servo cable retainer)
26	1	MCS 851E	Mounting bracket
27	1	HoseClamp24	Hose Clamp 26-50mm
28	1	MCSCC 200	Carburettor cable (throttle body cable)
	1 bottle		Throttle cable oil
	10		1500mm cable ties
	10		200mm cable ties
	10		300mm cable ties

Information, Set up and Operation Manual
Operation and User Manual
Installation Manual
Trouble shooting guide

