

SUZUKI GSX-R1000

Parts list for MCS 6660 TBW kit

Item	Qty	Part Number	Description
1	1	MCS 8128TBW	Computer
2	2 lengths		Self-Adhesive Velcro 8cm long
<u>MCS 6664</u>			<u>MCS Control Switch Assembly.</u>
3	1	MCS 820-160	Control Switch
4	1	MCS 831T	Control switch bracket
	4		4 gauge x 1/2" pan head self-tap screw
5	1		M6 x 45 socket head cap screw
6	1		M6 x 35 socket head cap screw
7	1		6mm x 12mm flat washer
8	6		6mm x 19mm flat washers (spacers)
9	1	<u>MCS 6661</u>	<u>Cruise Control Wiring Harness</u>
a			Computer plug (26 pin)
b			Fuse holder (3 amp fuse)
c			TPS (Throttle Position Sensor) connectors
c1		6195-0009	TPS sensor connector and retainer
d			Speed (pink/white) & Tach (brown/black) sensor connectors
d1		6187-2311	Speed & Tach sensor connector
e			Rear brake switch connector (orange & grey wires)
f			Clutch sensor connector
g			Control switch plug (6 pin)
	10		100mm cable ties
	10		150mm cable ties
	6		200mm cable ties
1			Installation Manual
1			Information, Set up and Operation Manual
1			Operation and User Manual
1			Trouble shooting guide

