

KC005A PCIe Card

--- ① ---

Introduction


Product name: MAIWO KC005A desktop computer USB3.0 Converter

Item name:	USB3.0 PCIe Card
USB port	USB-A*4
Interface:	PCIE X1 is compatible with x4/x8/X16 card slots
Connector:	USB3.0-5gbps transmission bandwidth
Materials:	Aluminum full profile bracket
power supply:	PCIE interface +15Pin SATA dual power supply interface
Size:	115(L)*120(W)*18.6(H) MM
System:	windows2000/XP/7/8/10/Linux

Quick Installation Guide


Installation

- 1 . Insert express card to PClex1/4/8/16 slot on motherboard;
- 2 . Fix full profile bracket with tower panel of PC.



Quick Installation Guide

- 3 .When PCIE power supply is insufficient, the auxiliary power supply of 15PinSATA line can be connected




--- ③ ---

Note: Initialize the partitioned hard disk step when the USB interface is connected to the new removable hard disk

I 、 New hard disk format:


1. View "computer - Manage - disk management" to Find the new disk .



--- ④ ---

II 、 New hard disk format:


2. Right click the " External disk ", then click "New Simple Volume".



--- ⑤ ---

III 、 Hard disk partition:


- 3 . According to the instruction, choose the size of partition, then click "Next" to finish.



--- ⑥ ---

IV 、 Hard disk partition:

- 4 . Then you can find the new hard disk in the "Computer", it's ready to be use.



initialization, partition and format

1. View "computer - Manage - disk management" to Find the new disk .

Remark: There two types MBR and GPT. SSD capacity <=2T, please choose MBR, if more than 2T, choose GPT.

2. Right click the "Disk 1", then click "New Simple Volume".

--- ⑦ ---