


































WOOD PARTS TABLE

<p>1</p>  <p>Side top rail (2pcs)</p>	<p>2</p>  <p>End top rail (2pcs)</p>	<p>3</p>  <p>Side blind (2pcs)</p>	<p>4</p>  <p>End blind(2pcs)</p>	<p>5</p>  <p>Slate(3pcs)</p>	<p>6</p>  <p>Side panel(2pcs)</p>
<p>7</p>  <p>End panel(2pcs)</p>	<p>8</p>  <p>Side beam(2pcs)</p>	<p>9</p>  <p>Long beam(1pc)</p>	<p>10</p>  <p>Beam(2pcs)</p>	<p>11</p>  <p>Leg(2L+2R)</p>	<p>12</p>

HARDWARE PARTS TABLE


<p>A</p>  <p>Ø13/32"X1-3/16" Dowel(14pcs)</p>	<p>B</p>  <p>Ø5/16"X2-3/4" Hex bolt(12pcs)</p>	<p>C</p>  <p>Ø3/8" Dome washer(18pcs)</p>	<p>D</p>  <p>Ø5/16"XØ3/4" Washer(28pcs)</p>	<p>E</p>  <p>Ø5/16"X4-3/4" Hex bolt(4pcs)</p>	<p>F</p>  <p>Ø3/8"X3" Hex bolt(24pcs)</p>	<p>G</p>  <p>Ø1/4"X2-3/4" Hex screw(12pcs)</p>	<p>H</p>  <p>Ø1/4"XØ5/8" Washer(24pcs)</p>
<p>I</p>  <p>5-7/8"X1-1/2"X1-1/2" Iron(4pcs)</p>	<p>J</p>  <p>Ø1/4"X5/8" Bolt(24pcs)</p>	<p>K</p>  <p>5"X1"X1" Iron(14pcs)</p>	<p>L</p>  <p>Ø5/32"X1/2" Screw(96pcs)</p>	<p>M</p>  <p>Ø5/16"X2-1/2" Hex bolt(4pcs)</p>	<p>N</p>  <p>Ø5/16" Nut(4pcs)</p>	<p>O</p>  <p>Ø3/8"X2" Hex bolt(18pcs)</p>	<p>P</p>  <p>POCKET CENTER Pocket(2pcs)</p>
<p>Q</p>  <p>POCKET CORNER Pocket(4pcs)</p>	<p>R</p>  <p>Ø3/16"X1" Nail(24pcs)</p>	<p>S</p>  <p>Ø3/8"XØ1" Washer(24pcs)</p>	<p>T</p>  <p>SHIM(1PC)</p>	<p>U</p>  <p>Ø5/16"X2-1/4" hex bolt(4pcs)</p>	<p>V</p>	<p>W</p>	<p>X</p>

STEP 1:




STEP 2:


STEP 3:



STEP 4:



STEP 5:



FINISH:

