

NEEWER®



700W Photography Softbox Lighting Kit
Instruction Manual

Copyright

© 2021 Shenzhen NeeWER Technology Co., Ltd. All Rights Reserved.
This document is the sole property of Shenzhen NeeWER Technology Co., Ltd and shall not be, reproduced, transmitted, transcribed, stored in a retrieval system or translated in any form, by any means, without prior written permission from Shenzhen NeeWER Technology Co., Ltd. Shenzhen NeeWER Technology Co., Ltd reserves the right to change content in this instruction manual at any time and without prior notice.

Version Control

Date	Version number	Description	Issued by
12/15/2021	1.0	700W Photography Softbox Lighting Kit Manual	NEEWER®

Package Contents



Softbox ×2



Light bulb ×2



Tripod ×2



Carrying bag ×1

Assembly Steps

1. Installing the tripod






① Hold the center column of the tripod and pull the legs outwards.



② Ensure the legs are fully extended as shown.

01

If you have any questions about product,
we are glad to help.

 US +1 732-623-9777
 Send us an email
 www.neewer.com
 UK +44 (0) 3330113494 vip@neewer.com

Shenzhen NeeWER Technology Co., Ltd.
Room 1903, Block A, Lu Shan Building
No. 3023 Chunfeng Rd Luo Hu District,
Shenzhen Guangdong 518001, China

UK REP

Lingfeng Electronic (UK) Ltd
International House, 10 Churchill Way, Cardiff,
CF10 2HE, United Kingdom

EC REP

NW Formations GmbH (for authorities only)
Hoferstrasse 96, 71636 Ludwigsburg, Germany

Assembly Steps



③ Extend the telescopic bar to adjust to the required height.




④ Use the flip locks to secure each segment of the main bar.

2. Installing the softbox



① Unfold the softbox and mount it on the tripod.



② Insert the bulb into the softbox light socket.

02

Assembly Steps



③ Attach the diffusion panel to the front of the softbox.



④ The installation is complete.

Operating Instructions



Connect to a power source and turn on the switch to use.

03