

REMOVAL

CAUTION: DO NOT pry against the face of the radio, or passenger side/ignition switch bezel applique surfaces. Only pry on the OUTER perimeter of the bezel.

1. Before proceeding with the following repair procedure, review all warnings and cautions. (Refer to 23 - Body/ Instrument Panel - Warning)
2. Using a trim stick or equivalent, working around the **outside** perimeter of the bezel releasing the retaining clips and separate the bezel from the instrument panel.
3. Disconnect the electrical connectors and remove the bezel.