

Claymate... Technology that Counts

Claymate GMS Sporting 4 Trap Handset for WI Multitrap.

Ei claymate GMS

All led's off.

Press A Fires Trap A, B = B, C = C, D = D.

Sim Pair

Pair Button pressed (led Lit).

Press A or B or C or D. (Pair led light flashes).

Press a different Button – Both Traps Fire.

Pair led goes off.

Sim Pair with Solo Delay.

Pair Button pressed (led Lit).

Solo Button pressed (led Lit).

Press A or B or C or D. (Pair led light flashes).

Press a different button (Solo led light flashes + beep beep sound).

After a 3 Second Delay, both Traps fire.

Pair led goes off. Solo led stays on.

Single Trap with Solo Delay.

Solo Button pressed (led Lit).

Press A or B or C or D. (Solo led light flashes + beep beep sound).

Selected Trap fires after a 3 Second Delay.

Following Pair with Solo Delay.

Solo Button pressed (led Lit).

Press A or B or C or D. (Solo led light flashes + beep beep sound).

Before 1st trap fires Press A or B or C or D.

(Solo led light flashes + beep beep sound).

1st Trap fires after a 3 second delay, 2nd Trap fires after a short delay.

8 Bird Following Flush.

Solo Button pressed (led Lit).

Press the A or B or C or D Buttons one after the other, in any order, a maximum of 8 times to create an 8 Bird Following Flush, which then starts after a 3 second delay. To repeat, the Flush has to be re-entered into the Handset every time.

TP Oct 2023.