



MS50 PARTS LIST 2

ITEM NO.	PART NO.	DESCRIPTION	QTY
62	T5782-1986-M6X18	BOLT M6X18	8
63	T93-1987-6	SPRING WASHER 6	8
64	T95-1985-6	WASHER 6	8
65	Z500100022	BEARING COVER	1
66	Z500100023	O-RING	2
67	T276-6208	BEARING 6208	2
68	Z500100024	ECCENTRIC ROTATOR	1
69	T1096-1979-C8X15	KEY	1
72	Z500100026	BEARING COVER	1
73	Z500100027	PULLEY	1
74	T5287-1985-8	WASHER 8	1
75	T93-1987-8	SPRING WASHER 8	1
76	T5782-1986-M8X25	BOLT M8X25	1