PARTS AND HARDWARE.

PARTS LIST

NO.	DESCRIPTION	IMAGE	Q'TY
P1	Тор		1
P2	Metal Plate		1
P3	Metal Plate	$\langle \cdot \rangle$	1
P4	Metal Plate		1
P5	Base		1
P6	Base		1
P7	Base		1

HARDWARES LIST


NO.	DESCRIPTION	IMAGE	QTY
H1	Allen BOLT		6
H2	Allen BOLT		12
H 3	Allen Key		1

NOTES.


Thank you for purchasing this quality product! Be sure to check all packing material carefully for small part that may have come loose inside the carton during shipping.

CAUTION: The item is heavy, assembly should be performed by two people.


STEP 1.



STEP 2,



STEP 3.



STEP 4.

