

RSCBUSB

RS232 - USB CONVERTER CABLE



RS232 - USB converter cable, essential for the configuration and the maintenance of Dini Argeo weight indicators. The connection is fast and easy, thanks to the RJ11 quick connector on the scale side.

MAIN FEATURES

- Length: about 1,5m
- Connectors:
 - RJ11 for the quick connection to the RS232 serial port, standard fitted on the female connector available on all Dini Argeo indicators;
 - USB on the PC side.
- PC minimum requirements:
 - Windows 7 or greater;
 - 2.0 USB port or greater;
 - communication drivers integrated in the Dinitools software.



GRAVITATION LTD.

UNIT 2B SECTION 5 DUNSHAUGHLIN - - CO. MEATH - IRELAND

Tel. 00353469078900 Fax. 00353469078911 E-mail info@gravitation.ie Web www.gravitation.ie

