



www.cyeleeoptics.com

Support:

cs@cyeleeoptics.com

We strive to supply optical solutions at affordable prices. For any questions or warranty support please reach out to us at our website or thru our support email.



Included Items

1. *T10 Absolute Co-Witness* Reflex Sight
2. Hex Key
3. Microfiber Cloth
4. Lens Cap
5. Low Profile Mount
6. CR2032 Battery

* Battery Installation *

Remove the battery cap by rotating the cap in the counter-clockwise (CCW) direction. Insert the CR2032 coin cell battery negative (-) facing inward and directly in contact with the circuit. The positive (+) contact should be facing outward. Reattach the battery cap by



rotating the cap in the clockwise (CW) direction until tight.

✓Note: Failure to properly tighten the battery cap could lead to intermittent LED illumination or allow moisture into the battery compartment.

***Power On & Off / Brightness Control**

➊ Press and hold either the (+) or (-) button longer than 1 second to turn the sight on. To turn the sight off press and hold either the (+) or (-) button longer than 1 second and the LED dot should turn off.

➋ Increase the brightness by pressing and (+) button. Decrease the brightness by pressing the (-) button.



3 The sight features MOTAC and will automatically enter standby mode after 5 minutes of non-use. As soon as the sight senses motion it will automatically become active again. (✔Note: **Shake Awake will not work while the optic is off**)

4 The sight has 10 illumination settings; 8 daytime and 2 night vision.

Mounting

The T10 was designed for use on most types of firearms that utilize the MILSTD 1913 Picatinny Rail or Weaver style rails.

✔Note: **Make sure the screws are tight**



whenever mounting or adjusting!

Windage and Elevation Adjustment

The T10 features adjustable elevation and windage dials with 1/2 MOA marks.

Adjust dials up or down or left or right as indicated by arrows.

(One dial mark yields 1/2 MOA of adjustment.

One MOA = 1.05 inches @100 yards)

Troubleshooting

If you have:

Intermittent LED Dot Illumination during live fire:

- Re-tighten the battery cap



If you see a blurred or enlarged dot, use a phone camera with a clean lens to check. If it looks clear and crisp thru your phone you may have astigmatism.

Warranty

Within Two Year of Purchase: Contact Cyelee for repair or replacement.

This warranty does not cover normal wear and tear, modifications, misuse, accidents.



CYELEE



Cyelee Optics

www.cyeleeoptics.com