

1200 New Jersey Ave., SE Washington, D.C. 20590

In Reply Refer To: HSST-1/WZ-395

Mr. Eric Willetts MDI Worldwide 38271 W. Twelve Mile Road Farmington Hills, MI 48331

Dear Mr. Willetts:

This letter is in response to your December 2, 2019 request for the Federal Highway Administration (FHWA) to review a roadside safety device, hardware, or system for eligibility for reimbursement under the Federal-aid highway program. This FHWA letter of eligibility is assigned FHWA control number WZ-395 and is valid until a subsequent letter is issued by FHWA that expressly references this device.

Decision

The following device is eligible within the length-of-need, with details provided in the form which is attached as an integral part of this letter:

• MDI Worldwide 4814M-SL Sign Stand TL-3

Scope of this Letter

To be found eligible for Federal-aid funding, new roadside safety devices should meet the crash test and evaluation criteria contained in the American Association of State Highway and Transportation Officials' (AASHTO) Manual for Assessing Safety Hardware (MASH). However, the FHWA, the Department of Transportation, and the United States Government do not regulate the manufacture of roadside safety devices. Eligibility for reimbursement under the Federal-aid highway program does not establish approval, certification or endorsement of the device for any particular purpose or use.

This letter is not a determination by the FHWA, the Department of Transportation, or the United States Government that a vehicle crash involving the device will result in any particular outcome, nor is it a guarantee of the in-service performance of this device. Proper manufacturing, installation, and maintenance are required in order for this device to function as tested.

This finding of eligibility is limited to the crashworthiness of the system and does not cover other structural features, nor conformity with the Manual on Uniform Traffic Control Devices.

Eligibility for Reimbursement

Based solely on a review of crash test results and certifications submitted by the manufacturer, and the crash test laboratory, FHWA agrees that the device described herein meets the crash test and evaluation criteria of the AASHTO's MASH. Therefore, the device is eligible for reimbursement under the Federal-aid highway program if installed under the range of tested conditions.

Name of system: MDI Worldwide 4814M-SL Sign Stand

Type of system: Work Zone

Test Level: MASH Test Level 3 (TL3)

Testing conducted by: Applus IDIADA KARCO Engineering, LLC.

Date of request: December 2, 2019

FHWA concurs with the recommendation of the accredited crash testing laboratory on the attached form.

Full Description of the Eligible Device

The device and supporting documentation, including reports of the crash tests or other testing done, videos of any crash testing, and/or drawings of the device, are described in the attached form.

Notice

This eligibility letter is issued for the subject device as tested. Modifications made to the device are not covered by this letter. Any modifications to this device should be submitted to the user (i.e., state DOT) as per their requirements.

You are expected to supply potential users with sufficient information on design, installation and maintenance requirements to ensure proper performance.

You are expected to certify to potential users that the hardware furnished has the same chemistry, mechanical properties, and geometry as that submitted for review, and that it will meet the test and evaluation criteria of AASHTO's MASH.

Issuance of this letter does not convey property rights of any sort or any exclusive privilege. This letter is based on the premise that information and reports submitted by you are accurate and correct. We reserve the right to modify or revoke this letter if: (1) there are any inaccuracies in the information submitted in support of your request for this letter, (2) the qualification testing was flawed, (3) in-service performance or other information reveals safety problems, (4) the system is significantly different from the version that was crash tested, or (5) any other information indicates that the letter was issued in error or otherwise does not reflect full and complete information about the crashworthiness of the system.

Standard Provisions

- To prevent misunderstanding by others, this letter of eligibility designated as FHWA control number WZ-395 shall not be reproduced except in full. This letter and the test documentation upon which it is based are public information. All such letters and documentation may be reviewed upon request.
- This letter shall not be construed as authorization or consent by the FHWA to use, manufacture, or self any patented system for which the applicant is not the patent holder.
- This FHWA eligibility letter is not an expression of any Agency view, position, or determination of validity, scope, or ownership of any intellectual property rights to a specific device or design. Further, this letter does not impute any distribution or licensing rights to the requester. This FHWA eligibility letter determination is made based solely on the crash-testing information submitted by the requester. The FHWA reserves the right to review and revoke an earlier eligibility determination after receipt of subsequent information related to crash testing.

Sincerely,

Michael S. Griffith

Director, Office of Safety Technologies

Modael S. Fuffitl

Office of Safety

Enclosures

Request for Federal Aid Reimbursement Eligibility of Highway Safety Hardware

	Date of Request:	December 2, 2019	New	Resubmission	
		EricWilletts			
itter	Company:	MDIWorldwide			
bmit	Address:	38271 W.Twelve Mile Road, Farmington	on Hills, MI 48331		
United States					
	To:	Michael S. Griffith, Director FHWA, Office of Safety Technologies			

I request the following devices be considered eligible for reimbursement under the Federal-aid highway program.

Device & Testing Criterion - Enter from right to left starting with Test Level					!-!-!	
SystemType	SubmissionType	Device Name / Va	riant	TestingCriterion	Test Level	
'WZ':CrashWorthyWorkZon	Physical Crash TestingEngineering Analysis	4814M-SL		AASHTOMASH	TL3	

By submitting this request for review and evaluation by the Federal Highway Administration, I certify that the product(s) was (were) tested in conformity with the AASHTO Manual for Assessing Safety Hardware and that the evaluation results meet the appropriate evaluation criteria in the MASH.

Individual or Organization responsible for the product:

Contact Name:	EricWilletts	SameasSubmitter 🖂
CompanyName:	MDIWorldwide	SameasSubmitter 🖂
Address:	38271 W.Twelve Mile Road, Farmington Hills, MI 48331	SameasSubmitter 🖂
Country:	United States	SameasSubmitter 🖂

Enter below all disclosures of financial interests as required by the FHWA `Federal-Aid Reimbursement Eligibility Process for Safety Hardware Devices' document.

Marketing Displays, Inc., doing business as MDI Worldwide ("MDI"), whose principal place of business is 38271 West Twelve Mile Road, Farmington Hills, Michigan 48331-3041, and Applus IDIADA KARCOEngineering, LLC., whose principal place of business is 9270 Holly Road, Adelanto, CA 92301 share no (\$0.00) financial interests between the two organizations. This includes no (\$0.00) financial interest but not limited to:

- i.Compensation, including wages, salaries, commissions, professional fees, or fees for business referrals (dollar valuesare not needed);
- ii. Consulting relationships;
- iii. Research funding or other forms of research support;
- iv. Patents, copyrights, and other intellectual property interests;
- v. Licenses or contractual relationships; or
- vi. Business ownership and investment interest.

PRODUCT DESCRIPTION

Help						
New Hardware or Modification to						
Significant Me		Existing Hardware				
Product Descrip		_				
(Reference Draw		and ica work zone troffic contr	ral davias usad ta display	traffia agntral aigna		
	The 4814M-SL temporary sign stand is a work-zone traffic control device used to display traffic control signs. Further Description:					
		support isa portable/fold-up s	ign stand manufactured	with two vertically		
		oil springs. The sign stand cons				
		he two piece telescoping legsa ched to the upright with the us				
14".	on up sign isattat	shed to the upright with the us	e of ascrew-lock bracket	atanxed height of		
	nt of the stand is	29" [736.6mm]. The total weig	ht of the stand isapproxi	mately 25 lbs (no sign).		
		CRASH TEST	IING			
	By signature below, the Engineer affiliated with the testing laboratory, agrees in support of this submission that					
		ash tests for this device listed				
theMASH criteria		nined that no other crash test	sare necessary to deteri	mine the device meets		
Engineer Name	:	NickV.Injev				
EngineerSignature: NickInjev Digitally signedbyNick Injev DN: cn=Nick Injev, o=ApplusIDIADAKARCO, ou, email-nick.injev@idiada.com, c=US Date: 2019.12.3114.08:43-0800'			olusIDIADAKARCO,ou, .com,c=US			
Address:		9270 Holly Road, Adelanto, CA 92301		SameasSubmitter		
Country:		USA		SameasSubmitter		
A brief description of each crash test and its result: Help						
RequiredTest		Narrative Ev		uation		
Number Description		Results				
	_	aluate the ability of asmall				
		ate any breakaway, fracture,				
		chanism. Is considered ork-zone traffic control				
3-70 (1100C)		ng less than 220 lbs (100 kg).	Non-Relevant Test, not of	conducted		
	_	evice weighed 30.5 lbs (13.8				

kg) and therefore Test 70 was not

performed.

		1 ago o or 1
RequiredTest Number	Narrative Description	Evaluation Results
3-71 (1100C)	An 1100C test vehicle approached the test article at a nominal speed of 62 mph. The first 4814M-SL sign stand impacted was oriented at 0° and the second test article at 90°. Upon impact the sign face on both devices flexed over the front of the hood causing it to release from the base. The top corner of the 0° sign face made contact with the windshield. The impact did not tear the plastic liner or cause excessive deformation. The occupant compartment was not penetrated and the deformation limits were not exceeded. The devices did not induce any vehicle instability. The 4814M-SL met all the requirements for MASHTest 3-71.	PASS
3-72 (2270P)	A 2270P test vehicle approached the test article at a nominal speed of 62 mph. The first 4814M-SL sign stand impacted was oriented at 0° and the second at 90°. Upon impact the sign face on both devices flexed over the front of the vehicle causing it to release from the base. There was no penetration into the test vehicles occupant compartment nor were the deformation limits exceeded. The devices did not induce any vehicle instability. The 4814M-SL met all the requirements for MASHTest 3-72.	PASS

Full Scale Crash Testing was done in compliance with MASH by the following accredited crash test laboratory (cite the laboratory's accreditation status as noted in the crash test reports.):

Laboratory Name:	Applus IDIADA KARCOEngineering, LLC.		
LaboratorySignature:	DN: cn=Nick Injew; o=Applus IDIADA KARCO,ou, Date: 2019.12.3114:09:04-08'00'		
Address:	9270 Holly Road, Adelanto, CA 92301	SameasSubmitter	
Country:	USA	SameasSubmitter	
Accreditation Certificate Number and Dates of current Accreditation period:	TL-371:July 1,2019 - July 1,2022	,	

SubmitterSignature*: EricWilletts DigitallysignedbyEricWilletts Date: 2019.07.1608:33:37 -04'00'

Submit Form


Attach to this form:

- 1) Additional disclosures of related financial interest as indicated above.
- 2) A copy of the full test report, video, and a Test Data Summary Sheet for each test conducted in support of this request.
- 3) A drawing or drawings of the device(s) that conform to the Task Force-13 Drawing Specifications [Hardware Guide Drawing Standards]. For proprietary products, a single isometric line drawing is usually acceptable to illustrate the product, with detailed specifications, intended use, and contact information provided on the reverse. Additional drawings (not in TF-13 format) showing details that are relevant to understanding the dimensions and performance of the device should also be submitted to facilitate our review.

FHWA Official Business Only:

Eligi	bility Letter	
Number Date		Key Words

MASH 2016 Test 3-71 Summary



GENERAL INFORMATION				
Test Agency	Applus IDIADA KARCO			
Test No	P39091-01			
Test Designation	. 3-71			
Test Date	3/29/19			
TEST ARTICLE				
Name / Model	. 4814M-SL with Vinyl-Roll Up Sign			
Туре	Work-Zone Device			
Device Height				
Key Elements	Vinyl Roll-Up Sign, Steel Coil Springs			
Road Surface	Concrete			
TEST VEHICLE				
Type / Designation	. 1100C			
Year, Make, and Model	2009, KIA, Rio			
Curb Mass	. 2,335.8 lbs (1,059.5 kg)			
Test Inertial Mass	. 2,399.7 lbs (1,088.5 kg)			
Gross Static Mass				
Figure 2 Summary of Toot 2 74				

Figure	2	Summary	of	Test 3-71
---------------	---	----------------	----	------------------

Impact Conditions Impact Velocity Device 1 61.60 mph (99.14 km/h) Impact Velocity Device 2 60.05 mph (96.64 km/h) Device 1 Angle 90.0° Device 2 Angle 90.0° Device 1 Kinetic Energy 304.4 kip-ft (412.8 kJ) Device 2 Kinetic Energy 289.3 kip-ft (392.2 kJ) Exit Conditions Device 1 Exit Velocity 60.9 mph (98.1 km/h) Device 2 Exit Velocity 58.2 mph (93.7 km/h) Vehicle Resting Position 319.0 ft (97.2 m) Downstream 2.0 ft (0.6 m) Left Vehicle Stability Satisfactory Maximum Roll Angle N/A* Maximum Pitch Angle N/A*	
Impact Velocity Device 2	Impact Conditions
Device 1 Angle	Impact Velocity Device 1 61.60 mph (99.14 km/h)
Device 2 Angle	Impact Velocity Device 2 60.05 mph (96.64 km/h)
Device 1 Kinetic Energy	Device 1 Angle 0.0°
Device 2 Kinetic Energy 289.3 kip-ft (392.2 kJ) Exit Conditions Device 1 Exit Velocity 60.9 mph (98.1 km/h)	Device 2 Angle 90.0°
Exit Conditions Device 1 Exit Velocity	Device 1 Kinetic Energy 304.4 kip-ft (412.8 kJ)
Device 1 Exit Velocity	Device 2 Kinetic Energy 289.3 kip-ft (392.2 kJ)
Device 1 Exit Velocity	
Device 2 Exit Velocity 58.2 mph (93.7 km/h) Vehicle Resting Position 319.0 ft. (97.2 m) Downstream 2.0 ft. (0.6 m) Left Vehicle Stability Satisfactory Maximum Roll Angle N/A* Maximum Pitch Angle N/A*	Exit Conditions
Vehicle Resting Position 319.0 ft. (97.2 m) Downstream 2.0 ft. (0.6 m) Left Vehicle Stability Satisfactory Maximum Roll Angle N/A* Maximum Pitch Angle N/A*	Device 1 Exit Velocity 60.9 mph (98.1 km/h)
Vehicle Resting Position 319.0 ft. (97.2 m) Downstream 2.0 ft. (0.6 m) Left Vehicle Stability Satisfactory Maximum Roll Angle N/A* Maximum Pitch Angle N/A*	Device 2 Exit Velocity 58.2 mph (93.7 km/h)
Vehicle Stability Satisfactory Maximum Roll Angle N/A* Maximum Pitch Angle N/A*	Vehicle Resting Position 319.0 ft. (97.2 m) Downstream
Maximum Roll Angle N/A* Maximum Pitch AngleN/A*	2.0 ft. (0.6 m) Left
Maximum Pitch AngleN/A*	Vehicle Stability Satisfactory
	Maximum Roll Angle N/A*
	Maximum Pitch AngleN/A*
Maximum Yaw AngleN/A*	Maximum Yaw AngleN/A*
* Not Applicable, device weighs less than 220 lbs (100 kg)	


Occupant Riok	
Longitudinal OIV	N/A*
Lateral OIV	N/A*
Longitudinal RA	N/A*
Lateral RA	
THIV	. N/A*
PHD	. N/A*
ASI	
Test Article Deflections (From initial point of contact) Debris Field (longitudinal) Debris Field (lateral)	,
	, ,
Vehicle Damage	, ,
<u>Vehicle Damage</u> Vehicle Damage Scale	. 12-FC-1

12 TR-P39091-01-A

Occupant Risk

MASH 2016 Test 3-72 Summary

0° CIA 90° CIA





CENERAL INFORMATION	Import Conditions

GENE	:KAL	INFO	KIVIA	IIUN

Test Agency	Applus IDIADA KARCO
Test No	P39091-02
Test Designation	3-72
Test Date	3/29/19

TEST ARTICLE

Name / Model	4814M-SL
Туре	Work-Zone Device
Device Height	6.8 ft. (2.1 m)
Key Elements	Vinyl Roll-Up Sign, Steel Coil Springs
Pood Surface	Concrete

TEST VEHICLE

Type / Designation	2270P
Year, Make, and Model	2013, Ram, 1500
Curb Mass	4,994.5 lbs (2,265.5 kg)
Test Inertial Mass	5,012.1 lbs (2,273.5 kg)
Gross Static Mass	5,012.1 lbs (2,273.5 kg)

Figure 2 Summary of Test 3-72

Impact Conditions

inipact Conditions	
Impact Velocity Device 1	. 62.53 mph (100.64 km/h)
Impact Velocity Device 2	. 61.00 mph (98.17 km/h)
Device 1 Angle	0.0°
Device 2 Angle	90.0°
Device 1 Kinetic Energy	655.2 kip-ft (888.4 kJ)
Device 2 Kinetic Energy	. 623.5 kip-ft (845.3 kJ)

xit Conditions
Device 1 Exit Velocity 61.3 mph (98.6 km/h)
Device 2 Exit Velocity 59.6 mph (95.9 km/h)
Vehicle Resting Position 306.0 ft. (93.3 m) Downstream
1.4 ft. (0.4 m) Left
Vehicle Stability Satisfactory
Maximum Roll Angle N/A*
Maximum Pitch AngleN/A*
Maximum Yaw AngleN/A*

^{*} Not Applicable, device weighs less than 220 lbs (100 kg)

12

Occupant Risk

Longitudinal OIV	N/A*
Lateral OIV	
Longitudinal RA	N/A*
Lateral RA	N/A*
THIV	N/A*
PHD	N/A*
ASI	N/A*

Test Article Deflections

(From initial point of contact)

Debris	Field	(longitudinal)	96.0	ft.	(29.3)	m)
Debris	Field	(lateral)	40.0	ft.	(12.2)	m)

Vehicle Damage

Vehicle Damage Sca	ale 12-FC-1
CDC	12FDAW1
Maximum Intrusion	N/A

TR-P39091-02-A




Figure 1: 4814M-SL Sign Stand