







# Decor™ LED Overhead Light Installation Instructions

(Base Part #'s: 69926B, 69927B & 69928B)

PARTS/TOOLS NEEDED:			
			
Decor Overhead Light	Mounting Screws (Qty: 2)	Butt Splice Connectors (Not Provided)	Power Drill & 2.25" Hole Saw

## IMPORTANT SAFETY INSTRUCTIONS. READ CAREFULLY FOR YOUR PROTECTION AND SAVE ALL INSTRUCTIONS.


- \*Disconnect power before installing, adding or changing any component.
- \*To avoid a hazard to children, account for all parts and destroy all packing materials.
- \*It is recommended that fuse protection be added to the positive(+) input.

**1. 69926** | Determine the installation location and drill a 2.5" hole using a hole saw. **69927 & 69928** | Determine the installation location and use the bezel to mark and drill screw holes and wiring hole.

69926




69927 & 69928



**3. 69926** | Push clips on both sides of light up and slide housing and clips through hole. Clips will snap down and hold the light in place. **69927 & 69928** | Screw down the bezel using the provided screws. Feed the wires back through the hole and push the light into the bezel.

69926




69927 & 69928



**2A. 69927 & 69928** | Pull the units wiring through. Screw down the bezel using the provided screws.



**2B.** Using the wiring diagrams below, wire the light to the incoming 12V DC power. Test the light.



For warranty info visit [www.itc-us.com/warranty](http://www.itc-us.com/warranty)

3030 Corporate Grove Dr • Hudsonville • MI • 49426

Phone: 616-396-1355 • Fax: 616-396-1152 • [www.itc-us.com](http://www.itc-us.com) • [sales@itc-us.com](mailto:sales@itc-us.com) • Rev A: 05.30.19