



Chevrolet Impala (2006-2010)
Chevrolet Monte Carlo (2006-2007)



PART NUMBER: MV-50-03-L

PLEASE READ COMPLETE INSTRUCTIONS BEFORE INSTALLING THIS Pro.Fit Legend.

All instructions assume a drivers seat vantage point. Caution is advised when removing and reassembling wood or plastic parts of a dash. Applying unnecessary force or pressure may cause a piece to crack or break.

TOOLS REQUIRED: #2 Phillips screwdriver, drill and 5/64" bit, Dash trim removal tool (DM-40-22), 10mm nut driver, marking pen

PARTS INCLUDED: Pro.Fit Legend, instructions, two (2) # 8 x 1/2" screws.

LOCATION: Right of radio

STEP 1. Insert dash trim tool behind the lower-right corner of the trim bezel that surrounds the radio and climate control. Press tool down to release retainer clip. Work tool around bezel to release six (6) clips. Set bezel aside.

STEP 2. Remove a Phillips screw from each side of the climate control. Slide climate control out of its cavity, wrap in protective cloth and let hang down. Remove two (2) screws from each side of the radio. Slide radio out of its cavity, wrap in protective cloth and let hang down. Do not disconnect either the radio or climate control. **Photo 1.**



STEP 3. Place the Legend VSM against the dash pad, right of the radio. Align the Legend's screw hole with the upper-right clip hole. **Photo 2.** Using the holes in the Legend as a guide, mark pilot holes with marking pen. Set the mount aside. **Carefully** drill pilot holes with 5/64" drill bit and drill. Align the Legend over pilot holes and insert provided screws. Tighten with # 2 Phillips screwdriver.



STEP 4. Assemble dash in reverse order securing all clips. This completes the installation of your Pro.Fit Legend.



Pro.Fit International, Inc.® may not be held liable for any damage to a vehicle before, during or after the installation or removal of this Pro.Fit Legend®. Pro.Fit may not be held liable for any personal injury resulting from accident or improper installation. Pro.Fit International, Inc.® 1335 Eagandale Court, Eagan, MN 55121, Ph: 651-688-3588 or 800-388-0073 Fx: 651-688-9876

