

With our touch up kit, you can fix or patch any join that was caused by cutting or installing your ledges. This oxide kit is the base of how we color these products and when applied, will blend with your background and ledges.

The kit comes with:

Color oxides

A paintbrush



Tray

Steps:

- 1- Apply silicon to the affected area
- 2-Wet brush lightly
- 3- Dip brush in the oxide, starting with the darkest color
- 4- Dab brush into wet silicon (do not paint it on, dab it on creating textures)
- 5- Let dry and rinse and reapply if necessary until your joins blend perfectly



