

CERTIFICATE OF ANALYSIS

PRODUCT NAME: Melt & Pour No Sweat (NS) - White Base

Bomar Batch: Q0812 (LOT NUMBER: LOT0014925)

PRODUCT CODE: K0813

MANUFACTURING DATE: 04/04/2022

BEST BEFORE DATE: 04/04/2024

Analytics	DETAILS	RESULTS	
	Transparent solid at 25°C	-	
Appearance	FREE FROM CONTAMINATION AND AIR		
	ENTRAINMENT.		
Water Content (Dean & Stark)	30% - 35%	33.69	
FFA	0.8% - 1.2%	0.58	
COLOUR (NEAT) 5¼" LOVIBOND CELL	0.3 Red/3.0 Yellow maximum	-	

Ingredient	Range %	CAS	EINECS
Aqua	25-50	7732-18-5	231-791-2
Sodium Stearate	10-25	822-16-2	212-490-5
PROPYLENE GLYCOL	5-10	57-55-6	200-338-0
Sorbitol	10-25	50-70-4	200-061-5
Sucrose	5-10	57-50-1	200-334-9
SODIUM LAURATE	1-5	629-25-4	211-082-4
SODIUM CHLORIDE	1-5	7647-14-5	231-598-3
SODIUM LAURETH SULFATE	1-5	68891-38-3	500-234-8
STEARIC ACID	0.1-0.5	57-11-4	200-313-4
LAURIC ACID	0.1-0.5	143-07-7	205-582-1
PENTASODIUM PENTETATE	<0.1	140-01-2	205-391-3
Tetrasodium Etidronate	<0.1	3794-83-0	223-267-7
GLYCERIN	1-5	56-81-5	200-289-5
Sodium Myristate	1-5	822-12-8	212-487-9
SODIUM LAURYL SULFATE	1-5	151-21-3	205-788-1

The attached information is considered to be correct at the time the client received this information. Please be aware that detail can change and we encourage clients to update their records with Bomar regularly. The information is not and should not be considered a guarantee or warranty, or a part of our contractual or other legal obligations. The information is not to be disclosed to others, reproduced or transmitted in whole or in part without permission from Bomar.



TITANIUM DIOXIDE	0.1-0.5	13463-67-7	215-280-1

The attached information is considered to be correct at the time the client received this information. Please be aware that detail can change and we encourage clients to update their records with O&3 regularly. The information is not and should not be considered a guarantee or warranty, or a part of our contractual or other legal obligations. The information is not to be disclosed to others, reproduced or transmitted in whole or in part without permission from O&3.