

# LUXOR

INNOVATIVE WORKSPACE PRODUCT SOLUTIONS

## Parts List


\* # of bins and depth of bins vary by unit ordered




A x8 pcs



B x2 pcs



C x2 pcs




D x4 pcs




E x4 pcs

07/22/16



\*F




\*G




H x1 pcs





J x4 pcs



K x2 pcs




L x1 pcs



\* Do not fully tighten screws until the last step

# LUXOR

INNOVATIVE WORKSPACE PRODUCT SOLUTIONS



**\* Do not fully tighten screws until the last step**