

This LED lamp attachment works with any of the existing Wiz family machines, allowing you to light your work surface. The attachment allows for color temperature control as well as brightness control. There is no bulb change required and the LED has a life span of 10,000 hours.

Setup & usage

- 1. Insert the included screws from the bottom of the holes on the back of your machine.
- 2. Place the lamp bar over the screws using the provided holes. Secure with the brass nuts.
- 3. The lamp can be clamped anywhere on the lamp bar. The Inland Craft FaceShield and MagnaShield can be inserted into the lamp bar as well using the smaller secondary holes.
- 4. Connect the AC adapter to the light and to an electrical outlet.
- **5.** Optionally, the power switch can be attached to the side of the machine housing using the adhesive backing. The switch can also adjust the brightness of the lamp as well as power it off. Setting O is Off, Setting I is high brightness, and Setting II is normal brightness.
- Click the circular switch to change the color temperature. There are three different color settings; Cool White Light - 6500K, Warm White Light - 3000K, and Daylight Light - 4500K.

NOTE: This lamp is NOT waterproof. It is water resistant, but always use clean hands when adjusting the position of the lamp.



inlandcraft.com