



KBD67 Lite Acceptable Quality Standards

1. Marks left during injection molding



2. There will be the sprue marks inside the case after the injection, but once the keyboard is assembled, the marks are not visible



3. The slight unevenness may be present on the front side of the case



4. There will be some colour difference in the joint of the stiffener inside the case

