

17.08.2021, Lier

Important information for those who have purchased Rottefella roller ski bindings in 2020 or 2021

We have had some incidents where the extra security lock of the roller ski binding has not worked properly, and we strongly regret that. Rottefella has now developed a new security lock that will mechanically lock the open/close mechanism whilst continuing to being easy to use. We encourage all who have bought Rottefella roller ski bindings in 2020 or 2021 to change their existing handles to the new handles with the new security lock. The new security lock will be available soon. In the meantime, we encourage you to check whether the binding «clicks» in place when you lock it. The “click” should be considerable when it locks, and you should feel considerable resistance when you open. If you do not hear/feel a click when you lock the binding, we recommend that you as an extra precaution use cable ties or tape around the handle in the locked position.


See contact information below. You will get the new security lock in the post and you can follow the instructional video to assist you in changing to the new handles which will soon be available here: <https://www.dropbox.com/sh/f7r7hpok2gjuvvy/AADUSnAVYegyCMZdsV-upuPa?dl=0>

Contact info:

The US: Elan USA Corporation; info@elansports.com

Canada: Elan Sports Inc; cs@elansports.ca

Europe: Rottefella AS; support@rottefella.no



The new security lock works in the following way:

