



Wire position




Plug the wires into the six-port socket



Link the battery box to the six-port socket like the picture



stick the light and to the right side.





Stick the light strip to the spot like the picture

