D8 Bluetooth and CarPlay Troubleshooting for D8-MST2015L/H

If Bluetooth is not connecting or disconnects frequently, make sure you have the included "BT WiFi Antenna Extension Cable" threaded into the "WIFI BT" connection on the back of the Dynavin and the other end of it threaded into the "BT WiFi Antenna". For optimal reception, run the extension under the center console (near the parking brake) in between the seats. DO NOT place it behind the Dynavin.


Lastly, make sure your firmware is up to date.



BT WiFi Antenna



BT WiFi Antenna Extension Cable



If you're still having trouble after completing the above instructions or you need the antenna extension, please contact us at support@DynavinNorthAmerica.com