


PalaDrive

W - S e r i e s

Worm gear units & gear motor.



W-Series





Products in the range

Serving a great quality and high efficiency of gear drives, transmission components, electric motors, variable speed drives, starting and stopping assisting devices, linear motion system and motion control system. Palawatr make your demand better beyond expectation.



PalaDrive Series M
Helical Gearmotors



PalaDrive Series C
Helical Worm
Gearmotors



PalaDrive Series F
Parallel Helical Shaft
Mounted




PalaDrive Series K
Right Angle Helical Bevel
Gearmotors



PalaDrive Series A
Worm Gearmotors



PalaDrive
Custom Gear



PalaDrive
Custom Gear




PIV Gearunits and
Replacement Chains



PalaDrive
ST Variator



PalaDrive NMRV
Worm Gear



PalaDrive Parallel Shaft
Mount Reducer



PalaDrive
Planetary
Gearbox



PalaDrive Shaft Mounted Reducers



PalaFlex
KR Coupling



PalaFlex
Gear Sleeve Coupling



PalaFlex
Chain Coupling



PalaFlex
Pin & Bush Coupling



PalaFlex
Taper Grid Coupling




PalaFlex
Gear Coupling



PalaFlex
Disc Coupling



Kop-Flex
Elastomeric Coupling



Kop-Flex Series H
Gear Coupling



Kop-Flex
Fasts Gear Coupling



Kop-Flex
Waldron Flexalign Gear
Coupling



Kop-Flex
KD Disc Coupling



Rotofluid
Fluid Coupling



SurfaLoc
Shaft Locking Device



PalaFlex
QD Bush




PalaFlex
Split Taper Bush



Taper Tite
Bushing




Taper Tite
Pulleys



Taper Tite
Timing Pulley




PalaFlex
Chain Drives



Power Twist Plus
V section Link Belt



Super T Link
Wedge section Link Belt




Products in the range

Serving a great quality and high efficiency of gear drives, transmission components, electric motors, variable speed drives, starting and stopping assisting devices, linear motion system and motion control system. Palawatr make your demand better beyond expectation.



Safeguard
Torque Limiter



Siemens Energy-saving motors eff1,
Improved Efficiency eff2, EPACT, Pole-change Motors
For converter-fed operation



Siemens
COMBIMASTER
Motor with converter



Siemens Increased
Safety EEx e II motors



Siemens Explosion-proof
Enclosure EEx de IIC
Motors



Siemens Modular
Concept Motors



Siemens
Solution Motors,
Smoke extraction motors,
Marine motors




Siemens
Micromaster 440
Inverters



Siemens
Micromaster 420
Inverters



Siemens Sinamics G110
Inverters



Siemens Profibus module
DeviceNet module
Encoder module



Vibrating Motor



KENDRION Binder
Fail-safe Brake



Galvi Drum and Disk
Brakes



Emerson Servo motors,
Drives and Controllers



Bayside Precision
Gearheads




Micro Slides Precision
Linear Stage



SBC Cam Clutch and
Back Stop




Hepco DLS
Linear Transmission &
Positioning System



Hepco PDU2
Aluminium Profile Driven
Unit




Hepco HDS
Heavy Duty Slide System



Hepco RTS
Ring Slides & Track
System



Hepco DTS
Driven Track System



Hepco HDLS
Heavy Duty Driven Linear
System



Hepco GV3
Linear Guidance and
Transmission System




Hepco SL2
Stainless Steel Based
Slide System




Hepco MCS
Aluminium Frame and
Machine Construction
System




Hepco Dual-Vee
Single Edge Slide
System




Worm gear reducers

01 ... 07**W - 1**


with worm gear pair

08 ... 14**W - 2**



with 1 cylindrical gear pair plus worm





Worm gearmotors

01 ... 07**MW-1**


with worm gear pair

08 ... 14**MW-2**






with 1 cylindrical gear pair plus worm


**02 ... 07****MW-3**

with 2 cylindrical gear pairs plus worm

08 ... 10


Combined gear reducer and gearmotors units

**W 1 + W 1****W 1 + W 2****MW1 + R 2, R 3****MW 2 + R 2, R 3****W 1 + M W 1****W 1 + M W 2****MW 1 + R 2, R 3****MW 2 + R 2, R 3**




Gear reducers and garmotors (worm wheel)

01 ... 03




04 ... 11



12





13, 14



01* ... 12

Gear reducers (worm)






13, 14



01* ... 12

Gearmotors (worm)

13, 14



* Size **01**: double row angular contact ball bearing plus ball bearing.

** For MW 011, 021 with motor size 63 and 71, MW 031 with motor size 71 and 80, MW 041..071 with motor 80 and 90 motor flange is usually integral with casing.



1. Symbols and units of measure

Symbols used in the catalogue and formulae, in alphabetical order, with relevant units of measure.

Symbol	Definition	Units of measure			Notes
		In the catalogue	In the formulae		
			Technical System	SI ¹⁾ System	
	dimensions	mm	-		
<i>a</i>	acceleration	-	m/s ²		
<i>d</i>	diameter	-	m		
<i>f</i>	frequency	Hz	Hz		
<i>fs</i>	service factor				
<i>ft</i>	thermal factor				
<i>F</i>	force	-	kgf	N ²⁾	1 kgf ≈ 9,81 N ≈ 0,981 daN
<i>F_r</i>	radial load	daN	-		
<i>F_a</i>	axial load	daN	-		
<i>g</i>	acceleration of gravity	-	m/s ²		normal value 9,81 m/s ²
<i>G</i>	weight (weight force)	-	kgf	N	
<i>Gd</i> ²	dynamic momen	-	kgf m ²	-	
<i>i</i>	transmission ratio				$i = \frac{n_1}{n_2}$
<i>I</i>	electric current	-	A		
<i>J</i>	moment of inertia	kg m ²	-	kg m ²	
<i>L_h</i>	bearing life	h	-		
<i>m</i>	mass	kg	kgf s ² /m	kg ³⁾	
<i>M</i>	torque	daN m	kgf m	N m	1 kgf m ≈ 9,81 N m ≈ 0,981 daN m
<i>n</i>	speed	min ⁻¹	giri/min rev/min	-	1 min ⁻¹ ≈ 0,105 rad/s
<i>P</i>	power	kW	CV	W	1 CV ≈ 736 W ≈ 0,736 kW
<i>Pt</i>	thermal power	kW	-		
<i>r</i>	radius	-	m		
<i>R</i>	variation ratio				$R = \frac{n_{2 \text{ max}}}{n_{2 \text{ min}}}$
<i>s</i>	distance	-	m		
<i>t</i>	Celsius temperature	°C	-		
<i>t</i>	time	s min h d	s		1 min = 60 s 1 h = 60 min = 3 600 s 1 d = 24 h = 86 400 s
<i>U</i>	voltage	V	V		
<i>v</i>	velocity	-	m/s		
<i>W</i>	work, energy	MJ	kgf m	J ⁴⁾	
<i>z</i>	frequency of starting	avv./h starts/h	-		
α	angular acceleration	-	rad/s ²		
η	efficiency				
η_s	static efficiency				
μ	friction coefficient				
φ	plane angle	°	rad		1 giro = 2 π rad 1 rev = 2 π rad $1^\circ = \frac{\pi}{180}$ rad
ω	angular velocity	-	-	rad/s	1 rad/s ≈ 9,55 min ⁻¹

Additional indexes and other signs

Ind	Definition
max	maximum
min	minimum
N	nominal
1	relating to high speed shaft (input)
2	relating to low speed shaft (output)
÷	from ... to
≈	approximately equal to
≥	greater than or equal to
≤	less than or equal to

1) SI are the initials of the International Unit System, defined and approved by the General Conference on Weights and Measures as the only system of units of measure.
Ref. CNR UNI 10 003-84 (DIN 1 301-93 NF X 02.004, BS 5 555-93, ISO 1 000-92).

UNI: Ente Nazionale Italiano di Unificazione.

DIN: Deutscher Normenausschuss (DNA).

AFNOR: Association Fran^çaise de Normalisation (AFNOR).

BSI: British Standards Institution (BSI).

ISO: International Organization for Standardization.

2) Newton [N] is the force imparting an acceleration of 1 m/s² to a mass of 1 kg.

3) Kilogramme [kg] is the mass of the prototype kept at S_{vres} (i.e. 1 dm³ of distilled water at 4°C).

4) Joule [J] is the work done when the point of application of a force of 1 N is displaced through a distance of 1 m.



2. Specifications


Universal mounting having **feet integral with casing** on 3 faces (sizes 01 ..07) or on 2 faces (sizes 08 ...14) and **B14 flange** on 2 faces. Design and strength of the casing per **interesting shaft mounting solutions**

Thickened size and performance gradation (some sequential sizes are obtained with the same casing and many components in common)

High, reliable and tested performances (Ni bronze); optimization of worm gear pair performances (ZI involute profile and adequately conjugate worm wheel profile)

Compactness, standardized dimensions and compliance with standards

IEC standardized motor



01 ... 07

Rigid and precise cast iron monolithic casing

Generous internal space between train of gears and casing allowing:

- high oil capacity;
- lower oil pollution;
- greater duration of worm wheel and worm bearings;
- lower running temperature.


Possibility of fitting particularly powerful motors and transmitting high nominal and maximum torques

Improved and up-graded modular construction both for component parts and assembled product which ensures manufacturing and product management flexibility

High manufacturing quality standard

Possibility of obtaining multiple drives and at synchronous speed


Wide design and accessory availability: shaft-mounting arrangements, mixed keying systems with key and locking elements (rings for sizes 01 ...03, bush for sizes 04 ...14), **square flanges for servo-motors** and hub clamp, **reduced backlash**, etc.



08 ... 14

Reduced maintenance

A combination of modern concepts, analytical calculations carried out on **each single part**, use of the very latest machine tools, plus systematic checks on materials, assembling and workmanship, gives this series of gear reducers **high efficiency**, running **precision**, regular motion and **noiselessness**, constant performances, **life and reliability**, strength and overload withstanding and suitability for **heaviest applications**, wide size and ratio range, excellent service the **advantages typically associated with high quality worm gear reducers produced in large series**.





a - Gear reducer

Structural features

Main specifications are:

universal mounting having **feet integral with casing** (lower, upper feet and vertical on the face opposite to motor for sizes 01... 07; lower and upper feet for sizes 08 ... 14) and **B14 flange** (integral with casing for sizes 01 ... 03) on 2 faces of hollow low speed shaft output. **B5 flange** with spigot recess which can be mounted onto B14 flanges (see chap. 17). Design and strength of the casing permit **interesting shaft mounting solutions**;



01	02	03	04	05	06	07	08	09	10	11	12	13	14	
71 48	82 56	100 67	125 80	150 100	180 125	225 150			280 180	335 225		410 280	H H ₀	
19 24	28	32	38	40	48	60			70	75	90		110	D
4 7.5	7.1 14	12.8 25	21.9 47.5	26.1 80	42.2 90	50 160	83 300	133 158	245 500	291 560	462 1000		802 1900	M _{N2} * M _{2 Grand.}
180 250	250 355	355 530	800	1250	1800 (2000)				2650	3000	4500		6300 (7100)	F _{r2} Size

* concerning $n_1 = 1400 \text{ min}^{-1}$ and transmission ratio stated in the scheme.

1) H, H₀ shaft height; D Ø low speed shaft end [mm]; M_{N2}, M_{2 Size} torque [daN m]; F_{r2} radial load [daN].

- tickened size (10 sizes with 4 size pairs with final centre distance 01 ... 14) and performance gradation; the size pairs are obtained with the same casing and with many components in common;
- gear reducer structure sized so as to accept particularly powerful motors – both MW 1 and MW 2 – and to permit the transmission of high nominal and maximum torques at low output speeds, this being the particular advantage of worm gear pairs;
- gearmotors sizes 02... 10 with **2** cylindrical coaxial gear pair **first stage** in order to obtain high – **reversible** and irreversible – transmission ratios with standardized motor (63 ... 112) in a compact and economy way;
- normally, gearmotors MW 1 sizes 01, 02 (with motor sizes 63 and 71) 03 (with motor sizes 71 and 80) and 04 ... 07 (with motor sizes 80 and 90) have motor flange **integral** with the casing;
- hollow low speed shaft with keyway, and (sizes 04 ... 14) with circlip groove for removal purposes: in spheroidal cast iron (grey cast iron for sizes 01 and 02) integral with wormwheel (sizes 01 ... 12) or steel (sizes 13 and 14); standard (left or right extension) or double extension low speed shaft (see ch. 17).
- gear reducers: input face with machined surface W1 or flange W2 and with fixing holes: wormshaft end with key, and reduced wormshaft end with circlip groove (the same as for W 2 , MW 2 , MW3, MW 111... 141 with coupling);
- gearmotors: **IEC standardized motor directly** keyed into the worm (MW1), for motor sizes 200 ... 250 **patented** keying system to obtain easier installing and removing and avoid fretting corrosion; standardized motor with pinion directly mounted onto the shaft end (MW2 , MW3);


- **fan cooling** (sizes 08 ...14); use of **double extension worm-shaft** simply obtained by removing the fan cowl centre disc; for MW071 with motor 100 and 112, fan incorporated in motor mounting flange;
- bearings on worm: double row angular contact ball bearing plus ball bearing (size 01); face-to-face taper roller bearings (sizes 02 ... 12); paired back-to-back taper roller bearings plus one ball bearing (sizes 13 and 14);
- bearings on wormwheel: ball bearings (sizes 01 ... 11); taper roller bearings (sizes 12 ... 14);
- 200 UNI ISO 185 **cast iron monolithic casing** with transverse stiffening ribs, and high oil capacity;
- oil bath lubrication with **synthetic oil** (ch. 16) for «long-life» lubrication: units provided with one plug (sizes 01 ... 05) or two plugs (sizes 06 and 07) supplied **filled with oil**; with filler plug with **valve**, drain plug and level plug (sizes 08 ... 14) supplied **without oil**; sealed;
- paint: external coating in epoxy powder paint (sizes 01 ... 07) or in synthetic paint (sizes 08... 14) appropriate for resistance to normal industrial environments and suitable for the application of further coats of synthetic paint; colour blue RAL 5010 DIN 1843; internal protection in epoxy powder paint (sizes 01 ... 07) or in epoxy resin paint (sizes 08 ... 14) appropriate for resistance to synthetic oils;
- possibility of obtaining combined gear reducer and gearmotor units providing high transmission ratios with different train of gears depending on overall dimension, efficiency, and final output speed requirements.



Lines of contact and area of action determined by computer to check on each individual gear pair design.



Fan cowl centre disc removed so as to utilize double extension wormshaft.



Gear reducer design UO2B:
reduced wormshaft end (also suitable for W2, MW2, MW3, MW11...141 with coupling). Double extension low speed shaft.

Train of gears:

- worm gear pair; 1 cylindrical gear pair plus worm; with 2 cylindrical gear pairs plus worm gear pair (garmotor only);
- worm gear pairs, with **whole-number** transmission ratios ($i = 10 \dots 63$) **identical** for the different sizes; $i = 7$ for MR V 32 ... 81;
- 10 sizes having 4 sizes pairs (standard and strengthened) with final reduction centre distance to R 10 series (01... 14) for a total of **14 sizes**;
- nominal transmission ratios to R 10 series (01... 14; up to 16 000 for combined units);
- casehardened and hardened cylindrical worm in 16 CrNi4 or 20 MnCr5 UNI 7846-78 steel (depending on size) with ground and **superfinished involute** profile (ZI);
- wormwheel with profile especially conjugate to the worm through hob optimization, with hub in spheroidal or grey cast iron (depending on size) and **Ni bronze** CuSn12Ni2-B (EN1982-98) gear rim with high pureness and controlled phosphor contents;
- casehardened and hardened cylindrical gear pair in 16CrNi4 UNI 7846-78 steel with ground profile and helical toothing;
- train of gear load capacity calculated for breakage and wear; thermal capacity verified.

Specific standards:

- nominal transmission ratios and principal dimensions according to UNI 2016 standard numbers (DIN 323-74, NF X 01.001, BS 2045-65, ISO 3-73);
- basic rack to BS 721-83; involute profile (ZI) to UNI 4760/4-77 (DIN 3975-76), ISO/R 1122/2-69);
- shaft heights to UNI 2946-68 (DIN 747-67, NF E 01.051, BS 5186-75, ISO 496-73);
- fixing flanges B14 and B5 (the latter with spigot «recess») taken from UNIL 13501-69 (DIN 42948-65, IEC 72.2);
- medium series fixing holes to UNI 1728-83 (DIN 69-71, NF E 27.040, BS 4186-67, ISO/R 273);
- cylindrical shaft ends (long or short) to UNI ISO 775-88 (DIN 748, NF E 22.051, BS 4506-70, ISO/R775/88) with tapped butt-end hole to UNI 9321 (DIN 332 Bl. 2-70, NF E 22.056) excluding d-D diameter ratio;
- parallel keys to UNI 6604-69 (DIN 6885 Bl. 1-68, NF E 27.656 and 22.175, BS 4235.1-72, ISO/R 773-69) except for specific cases of motor-to-gear reducer coupling where key height is reduced;
- mounting positions taken from UNEL 05513-67 (DIN 42950-64, IEC 34;7);
- worm gear pair load capacity and efficiency to **BS 721-83** integrated with ISO/CD 14521.

b - Electric motor

Standard design:

- **IEC standardized** motor;
- asynchronous three-phase, totally-enclosed, externally ventilated, with cage rotor;
- single polarity, frequency 50 Hz, voltage Δ 230 V Y 400 V $\pm 10\%$ ¹⁾ up to size 132, Δ 400 V $\pm 10\%$ from size 160 upwards;
- IP 55 protection, insulation class F, temperature rise class B¹⁾;

1) Max and min limits of motor supply; temperature rise class F for some motors with power or power-to-size correspondence not according to standard and motors 200 LR 6, 200 L 6.

- rated power delivered on continuous duty (S1) and at standard voltage and frequency; maximum ambient temperature 40 °C, altitude 1 000 m: consult us if higher;
- capacity to withstand one or more overloads up to 1,6 times the nominal load for a maximum total period of 2 min per single hour;
- starting torque with direct on-line start at least 1,6 times the nominal (usually is higher);
- mounting position B5 and derivates as shown in the following table.
- **suitable for the running with inverter** (generous electromagnetic sizing, low-loss electrical stamping, phase separators, etc.)
- design available for every application need: flywheel, independent cooling fan, independent cooling fan and encoder, etc.

For other specifications and details see **specific literature**.

Motor size	Main coupling dimensions	
	UNEL 13117-71 (DIN 42677 Bl 1.A-65, IEC 72.2)	Flange Ø P B5
132, 160 B5R	38 × 80	300
160	42 × 110	350
180, 200 B5R	48 × 110	350
200	55 × 110	400
225, 250 B5R	60 × 140	450

1) Motor length Y and overall dimension Y₁ (ch. 10 and 12) increase of 14 mm for sizes 71, 18 mm for size 80, 22 mm for sizes 100 and 112, 29 mm for sizes 132.

Brake motor

- **IEC standardized** motor having the same specifications as normal motor;
- particularly strong construction to withstand braking stresses; **maximum noiselessness**;
- spring-loaded **d.c.** electromagnetic brake feeding from the terminal box; brake can also be fed independently direct from the line;
- braking torque **proportionate** to motor torque (normally $M_B \approx 2 M_N$) adjustable by adding or removing couples of springs;
- high frequency of starting enabled;
- rapid, precise stopping;
- hand lever for manual release with automatic return; removable lever rod.

For other specifications and details see **specific literature**.



Short time duty (S2) and intermittent periodic duty (S3); duty cycles S4 ... S10

In case of a duty-requirement type S2 ... S10 the motor power can be increased as per the following table; starting torque keeps unchanged.

Short time duty (S2). - Running at constant load for a given period of time less than that necessary to reach normal running temperature, followed by a rest period long enough for motoris return to ambient temperature.

Intermittent periodic duty (S3). - Succession of identical work cycles consisting of a period of running at constant load and a rest period. Current peaks on starting are not to be of an order that will influence motor heat to any significant extent.

$$\text{Cyclic duration factor} = \frac{N}{N+R} \cdot 100\%$$

where: N being running time at constant load,

R the rest period and $N + R \leq 10$ min (if longer consult us).

Motor size ¹⁾		
63 ... 90	100 ... 132	160 ... 280
1	1	1,06
1	1,06	1,12
1,12	1,18	1,25
1,25	1,25	1,32
1,06*		
1,12*		
1,25		
1,32		
consult us		

1) For motor sizes 90LC 4, 112MC 4, 132MC 4, consult us.

* These values become **1,12, 1,18** for brake motors.

Frequency of starting z

As a general rule, the maximum permissible frequency of starting z for direct on-line start (maximum starting time $0,5 \div 1$ s) is 63 starts/h up to size 90, 32 starts/h for sizes 100 ... 132 and 16 starts/h for sizes 160 ... 250 (star-delta starting is advisable for sizes 160 ... 250).

Brake motors can withstand a starting frequency double that of normal motors as described previously.

A greater frequency of starting z is often required for brake motors. In this case it is necessary to verify that:

$$z \leq z_0 \cdot \frac{J_0}{J_0 + J} \cdot \left[1 - \left(\frac{P}{P_1} \right)^2 \cdot 0,6 \right]$$

where:


z_0 , J_0 , P_1 are shown in the following table;

J is the external moment of inertia (of mass) in kg m^2 , (gear reducers, see ch 15 couplings, driven machine) referred to the motor shaft;

P is the power in kW absorbed by the machine referred to the motor shaft (therefore taking into account efficiency).

If during starting the motor has to overcome a resisting torque, verify the frequency of starting by means of the following formula:

$$z \leq 0,63 \cdot z_0 \cdot \frac{J_0}{J_0 + J} \cdot \left[1 - \left(\frac{P}{P_1} \right)^2 \cdot 0,6 \right]$$


**Principal specifications of normal and brake
motors (50 Hz)**

Motor size	Mf _{max} ≈ daN m 2) 4)	2 - poles - 2 800 min ⁻¹)				4 - poles - 1 400 min ⁻¹)				6 - poles - 900 min ⁻¹)			
		P ₁	J ₀	z ₀	M - start.	P ₁	J ₀	z ₀	M - start.	P ₁	J ₀	z ₀	M - start.
		kW	≈ kg m ² 2)	3)	3)	kW	≈ kg m ² 2)	3)	3)	kW	≈ kg m ² 2)	3)	3)
63 A	0,35	0,18	0,0002	4 750	2,5	0,12	0,0002	12 500	2,9	0,09	0,0004	12 500	2,7
63 B	0,35	0,25	0,0003	4 750	2,7	0,18	0,0003	12 500	2,8	0,12	0,0004	12 500	2,7
63 C	0,35	0,37*	0,0003	4 000	3	0,25*	0,0003	10 000	2,6	-	-	-	-
71 A	0,75	0,37	0,0004	4 000	3	0,25	0,0005	10 000	2,6	0,18	0,0012	11 200	2,4
71 B	0,75	0,55	0,0005	4 000	3	0,37	0,0007	10 000	2,5	0,25	0,0012	11 200	2,1
71 C	0,75	0,75*	0,0006	3 000	2,8	0,55*	0,0008	8 000	2,4	0,37*	0,0013	10 000	2,1
80 A	1,6	0,75	0,0008	3 000	2,5	0,55	0,0015	8 000	2,6	0,37	0,0019	9 500	2,1
80 B	1,6	1,1	0,0011	3 000	2,2	0,75	0,0019	7 100	2,9	0,55	0,0024	9 000	2,1
80 C	1,6	1,5 *	0,0013	2 500	2,9	1,1 *	0,0025	5 000	3	0,75*	0,0033	7 100	2,1
90 S	1,6	1,5	0,0013	2 500	2,9	1,1	0,0025	5 000	3	0,75	0,0033	7 100	2,1
90 SB	1,6	1,85*	0,0014	2 500	2,8	-	-	-	-	-	-	-	-
90 L	1,6	-	-	-	-	1,5	0,0041	4 000	2,7	1,1	0,005	5 300	2,3
90 LA	4	2,2	0,0017	2 500	2,9	-	-	-	-	-	-	-	-
90 LB	4	3	0,0019	1 800	2,8	1,85*	0,0044	4 000	2,7	-	-	-	-
90 LC	4	-	-	-	-	2,2 *	0,0048	3 150	2,8	1,5 *	0,0055	5 000	2,5
100 LA	4	3	0,0035	1 800	2,7	2,2	0,0051	3 150	2,6	1,5	0,0104	3 550	2,6
100 LB	4	4 *	0,0046	1 500	3,9	3	0,0069	3 150	2,9	1,85*	0,0118	3 150	2,5
112 M	7,5 ⁵⁾	4	0,0046	1 500	3,9	4	0,0097	2 500	3,1	2,2	0,0142	2 800	2,9
112 MB	4	5,5 *	0,0054	1 400	3,9	-	-	-	-	-	-	-	-
112 MC	7,5	7,5 *	0,0076	1 060	3,9	5,5 *	0,0115	1 800	3,1	3 * *	0,0169	2 500	2,9
132 S	7,5	-	-	-	-	5,5	0,0216	1 800	3	3	0,0216	2 360	2,3
132 SA	7,5	5,5	0,0099	1 250	2,4	-	-	-	-	-	-	-	-
132 SB	7,5	7,5	0,0118	1 120	3	-	-	-	-	-	-	-	-
132 SC	7,5	9,2 *	0,0137	1 060	3,7	-	-	-	-	-	-	-	-
132 M	15	11 *	0,0178	850	3,7	7,5	0,0323	1 180	3,2	4	0,0323	1 420	2,9
132 MB	15	15 *	0,0226	710	3,8	9,2 *	0,0391	1 070	3	5,5	0,0391	1 260	2,6
132 MC	15	-	-	-	-	11 *	0,0424	900	3,4	7,5 *	0,0532	1 000	2,4
160 MR	25	11	0,039	450	2,1	-	-	-	-	-	-	-	-
160 M	25	15	0,044	425	2,4	11	0,072	900	2	7,5	0,096	1 120	2
160 L	25	18,5	0,049	400	2,6	15	0,084	800	2,3	11	0,119	950	2,3
180 M	25	22	0,057	355	2,5	18,5	0,099	630	2,3	-	-	-	-
180 L	40	-	-	-	-	22	0,13	500	2,4	15	0,15	630	2,3
200 LR	40	30	0,185	160	2,4	-	-	-	-	18,5	0,19	500	2,1
200 L	40	37	0,2	160	2,5	30	0,2	400	2,4	22	0,24	400	2,4
200 LG	-	-	-	-	-	37	0,34	-	2,3	-	-	-	-
225 S	-	-	-	-	-	37	0,32	-	2,3	-	-	-	-
225 M	-	-	-	-	-	45	0,41	-	2,4	30	0,47	-	2,4
250 M	-	-	-	-	-	55	0,52	-	2,3	37	0,57	-	2,6

- 1) Motor speed on the basis of which the gearmotor speeds n₂ have been calculated.
 2) Moment of inertia values J₀, braking torque values Mf are valid for brake motor (size ≤ 200L), only.
 3) For size ≤ 132, M_{start} / M_N values and no load starting frequency z₀ [start/h] values are valid for brake motor, only.
 4) Motor is usually supplied with lower braking torque setting (see **specific literature**).
 5) For 2 pole 4 daN m.
 * Power or motor power-to-size correspondence not according to standard.



3. Designation

	TYPE	W MW	Gear reducer Gear motor
	SIZE	01..14	
	NO OF STAGE	1 2 3	1-worm 1-helical plus 1-worm 2-helical plus 1-worm
	DESIGN	A B C D	Standard Reduced wormshaft end Double extension wormshaft with reduced end Double extension wormshaft
	REDUCTION RATIO		[For gear reducer or garmotor w/o motor]
	MOTOR FRAME		[For garmotor only]
	NUMBER OF POLES	2...6	[For garmotor only]
	OUTPUT SPEED		[For garmotor only]
	MOUNTING POSITION		
W 14 1 D -1:25			
MW 06 1 A -1:25 -90B5			
MW 06 1 A -90L 4 /56			

4. Thermal power P_t [kW]

Nominal thermal power P_{tN} , indicated in gray in ch. 7 and 9 is that which can be applied at the gear reducer input when operating on continuous duty at a maximum ambient temperature of 40 °C and air velocity $\geq 1,25$ m/s, without exceeding 95 °C approximately oil temperature.

Thermal power P_t can be higher than the nominal P_{tN} , described above, as per the following formula: $P_t = P_{tN} \cdot f_t$ where f_t is the thermal factor depending on ambient temperature and type of duty as indicated in the table.

Wherever nominal thermal power P_{tN} , is indicated in the catalogue it should be verified that the applied power P_1 is less than or equal to the P_t value ($P_1 \leq P_t = P_{tN} \cdot f_t$). If $P_1 > P_t$, consider the use of special lubricant: consult us.

For B6 or B7 mounting position gear reducers and garmotors with train of gears **V** multiply P_{tN} by **0,9**.

Thermal power needs not be taken into account when maximum duration of continuous running time is 1 ÷ 3 h (from small to large gear reducer sizes) followed by rest periods long enough to restore the gear reducer to near ambient temperature (likewise 1 ÷ 3 h).

In case of maximum ambient temperature above 40 °C or below 0 °C consult us.

Maximum ambient temperature °C	continuous S1	Duty on intermittent load S3 ... S6			
		Cyclic duration factor [%] for 60 min running ¹⁾	60	40	25
40	1	1,18	1,18	1,32	1,5
30	1,18	1,4	1,6	1,8	2
20	1,32	1,6	1,8	2	2,24
10	1,5	1,8	2	2,24	2,5

1) Duration of running on load [min] 100
60



5. Service factor f_s

Service factor f_s takes into account the different running conditions (nature of load, running time, frequency of starting, other considerations) which must be referred to when performing calculations of gear reducer selection and verification.

The powers and torques shown in the catalogue are nominal (i.e. valid for $f_s = 1$) for gear reducers, corresponding to the f_s indicated for gearmotors.

Service factor based: on the nature of load and running time (this value is to be multiplied by the values shown in the tables alongside).

Nature of load of the driven machine		Running time [h]				
Ref.	Description	3 150 2 h/d	6 300 2 ÷ 4 h/d	12 500 4 ÷ 8 h/d	25 000 8 ÷ 16 h/d	50 000 16 ÷ 24 h/d
a	Uniform	0,67	0,85	1	1,25	1,6
b	Moderate overloads (1,6 normal)	0,85	1,06	1,25	1,6	2
c	Heavy overloads (2,5 normal)	1	1,25	1,5	1,9	2,36

Service factor based on frequency of starting referred to the nature of load.

Load ref.	Frequency of starting z [starts/h]							
	4	8	16	32	63	125	250	500
a	1	1,06	1,12	1,18	1,25	1,32	1,4	1,5
b	1	1	1,06	1,12	1,18	1,25	1,32	1,4
c	1	1	1	1,06	1,12	1,18	1,25	1,32

Details of service factor and considerations.

Given f_s values are valid for:

- electric motor with cage rotor, direct on-line starting up to 9,2 kW, star-delta starting for higher power ratings; for direct on-line starting above 9,2 kW or for brake motors, select f_s according to a frequency of starting double the actual frequency; for internal combustion engines multiply f_s by 1,25 (multicylinder) or 1,5 (single-cylinder);
- maximum time on overload 15 s; on starting 3 s; if over and/or subject to heavy shock effect, consult us;
- a whole number of overload cycles (or start) **imprecisely** completed in 1, 2, 3 or 4 revolutions of low speed shaft; if **precisely** a continuous overloads should be assumed;
- **standard** level of reliability; if a **higher** degree of reliability is required (particularly difficult maintenance conditions, key importance of gear reducer to production, personnel safety, etc.) multiply f_s by **1,25 ÷ 1,4**.

Motors having a starting torque not exceeding nominal values (star-delta starting, particular types of motor operating on direct current, and single-phase motors), and particular types of coupling between gear reducer and motor, and gear reducer and driven machine (flexible, centrifugal, fluid and safety couplings, clutches and belt drives) affect service factor favourably, allowing its reduction in certain heavy-duty applications; consult us if need be.



6. Selection

a - Gear reducer

Determining the gear reducer size

- Make available all necessary data: required output power P_2 of gear reducer, speeds n_2 and n_1 , running conditions (nature of load, running time, frequency of starting z , other considerations) with reference to ch. 5.
- Determine service factor f_s on the basis of running conditions (ch. 5).
- Select the gear reducer size (also, the train of gears and transmission ratio i at the same time) on the basis of n_2 , n_1 and of a power P_{N2} greater than or equal to $P_2 \cdot f_s$ (ch. 7).
- Calculate power P_1 required at input side of gear reducer using the formula $\frac{P_2}{\eta}$, where $\eta = \frac{P_{N2}}{P_{N1}}$ is the efficiency of the gear reducer (ch. 7).

When for reasons of motor standardization, power P_1 applied at input side of gear reducer turns out to be higher than the power required (considering motor/gear reducer efficiency), it must be certain that this excess power applied will never be required, and frequency of starting z is so low as not to affect service factor (ch. 5).

Otherwise, make the selection by multiplying P_{N2} by $\frac{P_1 \text{ applied}}{P_1 \text{ required}}$. Calculations can also be made on the basis of torque instead of power; this method is even preferable for low n_2 values.

b - Gearmotor

Determining the gearmotor size

- Make available all necessary data: required output power P_2 of gearmotor, speed n_2 , running conditions (nature of load, running time, frequency of starting z , other considerations) with reference to ch. 5.
- Determine service factor f_s on the basis of running conditions (ch. 5).
- Select the gearmotor size on the basis of n_2 , f_s , P_2 (ch. 9).

When for reasons of motor standardization, power P_2 available in catalogue is much greater than that required, the gearmotor can be selected on the basis of a lower service factor ($f_s \cdot \frac{P_2 \text{ required}}{P_2 \text{ available}}$) provided it is certain that this excess power available will never be required and frequency of starting z is low enough not to affect service factor (ch. 5).

Calculations can also be made on the basis of torque instead of power; this method is even preferable for low n_2 values.

Verifications

- Verify possible radial load F_{r2} and axial load F_{a2} referring to directions and values given in ch. 14.
- For the motor, verify frequency of starting z when higher than that normally permissible, referring to directions and values given in ch. 2b; this will normally be required for brake motors only.
- When a load chart is available, and/or there are overloads – due to starting on full load (especially with high inertias and low transmission ratios), braking, shocks, irreversible or with low reversibility gear reducers in which the wormwheel becomes driving member due to the driven machine inertia, other static or dynamic causes – verify that the maximum torque peak (ch. 15) is always less than $M_{2\max}$ (ch. 7); if it is higher or cannot be evaluated, in the above instances, install suitable safety devices so that $M_{2\max}$ will never be exceeded. $M_{2\max}$ value can be read off in ch. 7 against the corresponding speed n_2 and transmission ratio i of the worm gear pair.
- When nominal thermal power P_{tN} is indicated in red in ch. 9, verify that $P_1 \leq P_t$ (ch. 4).

Verifications

- Verify possible radial loads F_{r1} , F_{r2} and axial load F_{a2} by referring to instructions and values given in ch. 13 and 14.
- When the load chart is available, and/or there are overloads – due to starting on full load (mainly for high inertias and low transmission ratios), braking, shocks, irreversible or with low reversibility gear reducers in which the wormwheel becomes driving member due to the driven machine inertia, applied power higher than that required, other static or dynamic causes – verify that the maximum torque peak (ch. 15) is always less than $M_{2\max}$ (ch. 7); if it is higher or cannot be evaluated, in the above cases, install a safety device so that $M_{2\max}$ will never be exceeded.
- When nominal thermal power P_{tN} is indicated in red in ch. 7, verify that $P_1 \leq P_t$ (ch. 4).

Designation for ordering

When ordering give the complete designation of the gear reducer as shown in ch. 3. The following information is to be given: design and mounting position (only when different from B3, B3 or B8 for size ≤ 64) (ch. 8); input speed n_1 for sizes 200 and 250 mounting position B7, – for the remainder, only if greater than $1\ 400 \text{ min}^{-1}$ or less than 355 min^{-1} , accessories and non-standard designs, if any (ch. 17).

E.g.: W061A-1:25 mounting position V5

W141A-1:50 = 560 min^{-1} , mounting position B7.

Designation for ordering


When ordering give the complete designation of the gearmotor as shown in ch. 3. The following information is to be given: design and mounting position of gearmotor (only if different from B3, B3 or B8 for size ≤ 05) (ch. 10), voltage and mounting position of motor; accessories and non-standard designs, if any (ch. 17).

E.g.: MW061A-90L4/56 mounting position V5; with flexible

When motor is supplied by the Buyer,

E.g.: MW131A-180 B5

The motor supplied by the Buyer must be to **UNEL standards** with mating surfaces machined under accuracy rating (UNEL 13501-69) and is to be sent **carriage and expenses paid to our factory** for fitting to the gear reducer.



c - Combined gear reducer and gearmotor units

Combined units are obtained by coupling together **normal single** gear reducers and/or gearmotors.

Determining the final gear reducer size

- Make available all necessary data relating to the output of the final gear reducer: required torque M_2 , speed n_2 , running conditions (nature of load, running time, frequency of starting z , other considerations) with reference to ch. 5.
- Determine service factor f_s on the basis of running conditions (ch. 5) and of n_2 (see *, ** ch. 11).
- Select the final gear reducer size and the corresponding efficiency η (ch. 11, table A), on the basis of n_2 and a torque value M_{N2} greater than or equal to $M_2 \cdot f_s$ (the η value shown can be taken as valid even if the final gear reducer's train of gears is type IV).
For $f_s < 1$ verify that $M_2 \leq M_2 \text{ size}$.

Determining the type of combined unit

- Select the final gear reducer basic reference, and the type and size of initial gear reducer or gearmotor (ch. 11 table B), on the basis of the final gear reducer size, and of the type of combined unit selected.

When selecting the type of unit, refer to the drawings in table B bearing in mind the following considerations:

gear reducer: gives greater operational flexibility; stress deriving from starting and heavy duty can be diminished thanks to the possibility of locating couplings (flexible, centrifugal, fluid, safety or friction type), belt drives, etc. between gear reducer and motor;

gearmotor: provides a more compact and economical solution compared to the equivalent gear reducer combined unit;


combined units **W 1 + W 1** or **MW1 W 1 + W 2** or **MW2** input and output shafts can be either parallel or orthogonal, overall dimensions are kept to a minimum, especially within the plane perpendicular to the low speed shafts; these units are normally irreversible; the latter two types give higher transmission ratios than the former two types as well as higher efficiency, with the same transmission ratio;

combined units **MW 1 + R 2, R 3** or **MR 2, MR 3** input and output shafts are orthogonal, overall dimensions kept at minimum along the direction of the low speed shaft; high efficiency;

combined units **MR 2 + R 2, R 3** or **MR 2, MR 3** the same as above but with the possibility of higher transmission ratios, and with overall dimensions of the initial gear reducer or gearmotor contained within those planes defined by the mounting feet.



E.g: W 081 A/25
coupled with
W 031 A/32



W 081 A/25 mounting position V5
coupled with
V 031 A-71 A/28 pos. 3

Selection of initial gear reducer or gearmotor

- Calculate the speed n_2 and the required power P_2 at the initial gear reducer or gearmotor output, using the following formulae:

$$n_2 \text{ initial} = n_2 \text{ final} \cdot i \text{ final}$$

$$P_2 \text{ initial} = \frac{M_2 \text{ final} \cdot n_2 \text{ final}}{955 \cdot \eta \text{ final}} [\text{kW}]$$


– In the case of gear reducer, establish input speed n_1 at the input of the initial gear reducer.

- Make the selection of initial gear reducer or gearmotors as shown in ch. 6, paragraph a) or b) of this catalogue (in the case of worm gear reducers and gearmotors), or of catalogue E (in the case of coaxial gear reducers and gearmotors), bearing in mind that sizes are pre-established (and cannot be changed on account of couplings being standard) and that it is not necessary to verify the service factor.


Designation for ordering

When ordering combined units, the single gear reducers or gearmotors must be designed **separately**, as indicated in ch. 6 paragraph a) or b), of this catalogue (for the final gear reducer and initial worm gear reducer or gearmotor) or of catalogue E (for initial coaxial gear reducer or gearmotor), bearing in mind the following:

- for all combined units, insert the words **coupled with** between the final gear reducer designation and that of the initial gear reducer or gearmotor;
- in the case of **W 1 + W 1** or **MW 1** and **W 1 + W 2** or **MW 2**, select the initial gear reducer or gearmotor stating the coupling **position** where applicable (ch. 12);
- when ordering **MW 1 + R 2, R 3** or **MR 2, MR 3** and **MW 2 + R 2, R 3** or **MR 2, MR 3** always add the words **without motor** to the final gear reducer designation and select for the initial gear reducer or gearmotor **oversized B5 flange** design (for size 63 also add – **Ø 28**); in case of initial gear reducer or gearmotor size 32 or 40 select **FC1A** flange design;
- in order to make easier the individualization of mounting position of initial gear reducer or gearmotor see ch. 12.



MW 131 A-180 L 4/43,8 without motor
coupled with
R 2I 100 UC2A/29,3 oversized B5 flange



MW 132 A-1:17.1-132 B 5 without motor, mounting position B6, double extension low speed shaft
coupled with
MR 3I 80 UC2A - 80A 4 230.400 B5/18,5 mounting position V5 oversized B5 flange



Considerations on selection

Motor power

Taking into account the efficiency of the gear reducer, and other drives — if any — motor power is to be as near as possible to the power rating required by the driven machine: accurate calculation is therefore recommended.

The power required by the machine can be calculated, seeing that it is related directly to several requirements of the work to be carried out, to friction (starting, sliding or rolling friction) and inertia (particularly when mass and/or acceleration or deceleration are considerable). It can also be determined experimentally on the basis of tests, comparison with existing applications, or readings taken with amperometers or wattmeters.

An oversized motor would involve: a greater starting current and consequently larger fuses and heavier cable; a higher running cost as power factor ($\cos \varphi$) and efficiency would suffer; greater stress on the drive, causing danger of mechanical failure, drive being normally proportionate to the power rating required by the machine, not to motor power.

Only high values of ambient temperature, altitude, frequency of starting or other particular conditions require an increase in motor power.

Driving machines with high kinetic energy

When driving machines with high inertias and/or speeds, **avoid** the use of **irreversible** gear reducers or gearmotors, rather select a train of gears with higher efficiency (e.g. IV, 2IV in place of V), keeping the same transmission ratio, as stopping and braking can cause very high overloads (cap. 15).

Drives with low input speed ($n_1 < 355 \text{ min}^{-1}$)

Wherever possible select the following transmission $i = 20$ for sizes 32 ... 50, $i = 25$ for sizes 63 ... 100, $i = 32$ for sizes 125 ... 200, $i = 40$ for size 250, these being the ratios capable of transmitting highest torque (for performance figures see table A ch. 11; for sizes 32 and 40, consult us).

n_1 min^{-1}	P_{N2}	M_{N2}
2 800	1,4	0,71
2 240	1,25	0,8
1 800	1,12	0,9
1 400	1	1

Input speed

For n_1 higher than $1\,400 \text{ min}^{-1}$, **power** and **torque** ratings relating to a given transmission ratio vary as shown in the table alongside. In this case no loads should be imposed on the high speed shaft end.


For variable n_1 , the selection should be carried out on the basis of $n_{1\max}$; but it should also be verified on the basis of $n_{1\min}$.

When there is a belt drive between motor and gear reducer, different input speeds n_1 , should be examined in order to select the most suitable unit from engineering and economy standpoints alike (our catalogue favours this method of selection as it shows a number of input speed values n_1 relating to a determined output speed n_{N2} in the same section).

Input speed should not be higher than $1\,400 \text{ min}^{-1}$, unless conditions make it necessary; better to take advantage of the transmission, and use an input speed lower than 900 min^{-1} .



7. Nominal powers and torques (gear reducers)



n _{N2} min ⁻¹	n ₁ min ⁻¹	Train of gears i 1)	P [kW] M [daNm]	Gear reducer size														
				01	02	03	04	05	06	07	08	09	10	11	12	13	14	
140	1 400	V 10	P _{N1}	0,57	1,01	1,79	1,4	3,02	2,3	3,59	2,3	5,5	3,6	6,6	3,6	10,6	16,7	19,8
			P _{N2}	0,48	0,87	1,55	—	2,68	—	3,19	—	4,96	5,9	5,9	6,6	9,5	15,1	18
			M _{N2}	3,29	5,9	10,6	—	18,3	—	21,7	—	33,9	40,3	65	103	123	186	222
			M _{2max}	5,9	10,5	19,4	—	33,2	—	36,1	—	63	68	120	188	204	342	394
125	1 250	V 10	P _{N1}	0,53	0,94	1,66	1,3	2,82	2,2	3,36	2,2	5,2	3,4	6,2	3,4	9,9	15,7	18,7
			P _{N2}	0,44	0,8	1,44	—	2,5	—	2,97	—	4,65	5,5	5,5	6,2	8,9	14,2	16,9
			M _{N2}	3,4	6,1	11	—	19,1	—	22,7	—	35,6	42,3	68	109	129	196	233
			M _{2max}	6,2	11,2	19,9	—	35,1	—	38,1	—	65	70	124	195	212	357	410
112	1 400	V 13	P _{N1}	0,47	0,82	1,49	—	2,44	2	2,9	2	4,55	3	5,4	3	9	14,4	17,2
			P _{N2}	0,39	0,69	1,27	—	2,12	—	2,52	—	3,99	4,75	71	13	115	15,4	24
			M _{N2}	3,47	6,1	11,3	—	18,8	—	22,3	—	35,4	42,1	71	128	203	213	254
			M _{2max}	6,2	11,3	20,6	—	35,1	—	38,1	—	66	71	128	203	209	380	413
100	1 250	V 13	P _{N1}	0,49	0,88	1,55	1,3	2,64	2,1	3,14	2,1	4,91	3,3	5,8	3,3	9,3	14,9	17,7
			P _{N2}	0,41	0,75	1,34	—	2,33	—	2,77	—	4,37	5,2	71	8,4	115	13,4	24
			M _{N2}	3,51	6,4	11,4	—	19,9	—	23,6	—	37,3	44,3	71	128	203	209	244
			M _{2max}	6,4	11,5	20,5	—	37	—	40,2	—	67	73	128	203	209	371	427
90	1 400	V 16	P _{N1}	0,43	0,76	1,39	—	2,28	1,9	2,72	1,9	4,25	2,9	5,1	2,9	8,5	13,6	16,1
			P _{N2}	0,36	0,64	1,18	—	1,97	—	2,35	—	3,71	4,41	74	7,5	12,1	14,4	22,6
			M _{N2}	3,58	6,4	11,8	—	19,6	—	23,3	—	36,8	43,8	74	121	191	213	225
			M _{2max}	6,4	11,6	21,1	—	36,9	—	40,1	—	69	75	135	219	238	412	448
90	1 250	V 10	P _{N1}	0,45	0,82	1,44	1,2	2,46	2	2,92	2	4,57	3,1	5,4	3,1	8,7	14	16,7
			P _{N2}	0,38	0,69	1,23	—	2,16	—	2,57	—	4,05	4,82	74	7,8	12,6	15	22,4
			M _{N2}	3,62	6,6	11,8	—	20,6	—	24,5	—	38,7	46,1	74	120	191	214	255
			M _{2max}	6,6	11,8	21	—	38,2	—	41,5	—	70	77	134	214	233	393	452
90	1 120	V 13	P _{N1}	0,41	0,73	1,3	—	2,14	1,8	2,55	1,8	4,03	2,8	4,79	2,8	7,5	12	14,3
			P _{N2}	0,34	0,61	1,1	—	1,83	—	2,18	—	3,49	4,15	72	6,6	10,6	12,6	20,1
			M _{N2}	3,67	6,6	12	—	20	—	23,8	—	38,1	45,3	72	116	138	224	219
			M _{2max}	6,1	11,1	20,2	—	35,9	—	39	—	68	73	127	206	209	403	437
80	900	V 10	P _{N1}	0,42	0,77	1,35	—	2,3	1,9	2,74	1,9	4,28	3	5,1	3	8,2	13,2	15,8
			P _{N2}	0,35	0,65	1,15	—	2,01	—	2,39	—	3,78	4,5	73	7,3	11,9	14,2	21
			M _{N2}	3,73	6,9	12,2	—	21,3	—	25,4	—	40,1	47,7	78	126	150	223	265
			M _{2max}	6,7	12,1	21,5	—	39,4	—	42,7	—	74	80	140	225	245	407	468
80	1 250	V 16	P _{N1}	0,38	0,68	1,22	—	2	—	2,38	1,7	3,78	2,7	4,5	2,7	7,1	11,3	13,4
			P _{N2}	0,31	0,56	1,02	—	1,7	—	2,03	—	3,26	3,88	75	6,2	9,9	11,8	18,8
			M _{N2}	3,81	6,9	12,5	—	20,8	—	24,8	—	39,8	47,4	75	121	144	230	274
			M _{2max}	6,4	11,5	20,7	—	37	—	40,2	—	70	76	136	213	232	418	454
80	1 000	V 13	P _{N1}	0,37	0,66	1,21	—	2	1,7	2,38	1,7	3,71	2,6	4,42	2,6	7,4	12	14,3
			P _{N2}	0,31	0,55	1,02	—	1,71	—	2,03	—	3,21	3,82	81	6,5	10,7	12,7	19,9
			M _{N2}	3,82	6,8	12,6	—	21,2	—	25,2	—	39,9	47,4	81	133	158	247	294
			M _{2max}	6,8	12,3	22,2	—	39,6	—	43	—	74	80	145	234	254	442	481
71	710	V 10	P _{N1}	0,39	0,71	1,25	—	2,12	—	2,52	1,8	3,96	2,8	4,71	2,8	7,6	12,4	14,7
			P _{N2}	0,32	0,59	1,06	—	1,85	—	2,2	—	4,14	4,94	81	6,8	11,1	13,2	19,5
			M _{N2}	3,85	7,1	12,6	—	22	—	26,2	—	41,5	49,4	81	132	157	233	278
			M _{2max}	7,1	12,7	22,8	—	40,4	—	43,9	—	76	83	143	233	253	429	493
71	1 400	V 20	P _{N1}	0,38	0,67	1,18	0,9	1,7	—	2,03	1,7	3,14	2,6	3,73	2,6	6,2	10,1	12,1
			P _{N2}	0,29	0,52	0,94	—	1,44	—	1,71	—	2,68	3,19	73	5,3	8,9	10,6	16,4
			M _{N2}	4,01	7,1	12,8	—	19,6	—	23,3	—	36,6	43,5	73	121	144	224	266
			M _{2max}	6,8	12,2	22,3	—	34,6	—	37,5	—	65	71	126	209	227	401	436
71	1 120	V 16	P _{N1}	0,36	0,64	1,15	—	1,87	—	2,23	1,6	3,55	2,5	4,23	2,5	6,6	10,6	12,6
			P _{N2}	0,29	0,52	0,96	—	1,59	—	1,89	—	3,05	3,63	79	5,8	9,3	11,1	17,7
			M _{N2}	3,95	7,1	13,1	—	21,6	—	25,7	—	41,6	49,5	79	127	151	242	288
			M _{2max}	6,6	12	21,2	—	38,1	—	41,4	—	72	78	139	220	239	432	476
71	900	V 13	P _{N1}	0,35	0,62	1,13	—	1,87	—	2,23	1,6	3,49	2,5	4,15	2,5	7	11,4	13,5
			P _{N2}	0,29	0,51	0,94	—	1,59	—	1,89	—	3	3,57	84	6,1	10,1	12	18,7
			M _{N2}	3,93	7	13	—	22	—	26,1	—	41,4	49,3	84	139	165	242	263
			M _{2max}	6,9	12,5	22,7	—	39,7	—	43,2	—	75	81	149	242	263	457	497
71	710	V 10	P _{N1}	0,36	0,65	1,16	—	1,95	—	2,33	1,8	3,65	2,7	4,35	2,7	7,1	11,5	13,7
			P _{N2}	0,3	0,54	0,97	—	1,69	—	2,01	—	3,2	3,81	84	6,3	10,3	12,2	18,2
			M _{N2}	3,98	7,3	13,1	—	22,8	—	27,1	—	43	51	84	138	165	244	291
			M _{2max}	7,2	13	23,3	—	41,3	—	44,9	—	78	85	147	240	260	442	509

Values in red state nominal thermal power P_{T0} (ambient temperature 40 °C, continuous duty see ch. 4).

For n₁ higher than 1 400 min⁻¹ or lower than 355 min⁻¹ see ch. 6 and page 28.

1) Values given for train of 2-stage gears are nominal; see page 28 for effective transmission ratios.



2) M_{2max} represents maximum torque peak the gear reducer will withstand.

**PalaDrive**

Worm Gear Reducers and Gear Motors

SERIES W

7. Nominal powers and torques (gear reducers)




n_{N2} min ⁻¹	n_1 min ⁻¹	Train of gears i 1) 2)	P [kW]	M [dan m]	Gear reducer size																					
					01	02	03	04	05	06	07	08	09	10	11	12	13	14								
63	1 250	V 20	P_{N1}	0,35	0,63	1,1	0,9	1,59	1,89	1,6	2,93	2,4	3,49	2,4	5,8	9,6	11,4	17,4	20,8	16	34,2	25	59	38		
			P_{N2}	0,27	0,49	0,87		1,33	1,58	2,49	2,96	4,98	8,3		9,9	15,3	18,2	30,3	52							
			M_{N2}	4,15	7,4	13,4		20,3	24,2	38	45,3	76	127		151	234	279	463	798							
	1 000	V 16	M_{2max}	6,9	12,7	22,8		36,7	39,9	69	75	129	224		243	415	451	790	1366							
			P_{N1}	0,33	0,59	1,07		1,75	2,08	1,6	3,31	2,4	6,2		10	11,8	9,6	18,7	15	22,3	15	34,5	25	61	39	
			P_{N2}	0,27	0,48	0,89		1,47	1,75	2,82	3,36	5,4	8,7		10,3	16,5	19,7	30,9	56							
	800	V 13	M_{N2}	4,08	7,3	13,6		22,4	26,7	43,2	51	82	133		158	253	301	473	849							
			M_{2max}	6,8	12,2	22,3		39,2	42,6	74	80	145	228		247	463	503	843	1441							
			P_{N1}	0,32	0,57	1,04		1,74	2,07	1,5	3,24	2,4	3,86	2,4	6,5	10,6	12,6	9,4	19,5	15	23,2	15	36,1	23		
	630	V 10	P_{N2}	0,26	0,47	0,86		1,47	1,75	2,78	3,3	5,6	9,3	11,1		17,4	172	270	321	503						
			M_{N2}	4,07	7,3	13,4		22,8	27,1	43,1	51	87	145		257	280	477	518	907							
			M_{2max}	7,2	12,9	23,9		42	45,6	46,6	79	86	152													
56	1 400	V 25	P_{N1}	0,3	0,55	0,99		1,61	1,3	1,92	1,3	3,04	2,1	3,61	2,1	5,9	8,4	9,9	15,3	18,2	28,4	51	39			
			P_{N2}	0,23	0,42	0,77		1,29	1,53	2,47	2,94	4,89	7,2	8,6		13,3	15,9	25	45,7							
			M_{N2}	3,89	7,2	13,2		21,9	26,1	42,2	50	83	123		146	227	270	426	779							
	1 120	V 20	M_{2max}	6,6	12,3	22,4		38,5	41,9	73	80	148	217	235		397	432	745	1341							
			P_{N1}	0,33	0,59	1,04	0,8	1,48	1,76	2,74	3,26	2,3	5,4	9	10,7	16,4	19,5	15	32,4	23	55	36				
			P_{N2}	0,25	0,45	0,81		1,23	1,47	2,32	2,76	4,65	7,8	9,3		14,3	17,1	28,6	49,2	488	838					
	900	V 16	M_{N2}	4,28	7,7	13,9		21	25	39,5	47	79	133	158		245	291	486	836	1424						
			M_{2max}	7,1	13,2	23,3		37,8	41	71	77	132	231	251		429										
			P_{N1}	0,31	0,55	1		1,64	1,95	1,5	3,1	2,3	3,68	2,3	5,8	9,4	11,2	8,9	17,6	14	21	14	32,6	23		
	710	V 13	P_{N2}	0,25	0,45	0,83		1,37	1,63	2,63	3,13	5	85	139		165	263	313	495	889						
			M_{N2}	4,21	7,6	14		23,2	27,6	44,6	53	85	146	235		255	477	518	855	1498						
			M_{2max}	7,3	12,8	22,8		40,3	43,8	76	83	146														
50	1 250	V 25	P_{N1}	0,3	0,53	0,95		1,61	1,92	1,5	3,01	2,3	3,58	2,3	6	9,8	11,7	8,7	18,2	14	21,7	14	33,7	21		
			P_{N2}	0,24	0,43	0,79		1,36	1,61	2,56	3,05	5,2	8,6	10,3		16,2	19,3	30,2	50,2	884						
			M_{N2}	4,22	7,5	13,8		23,7	28,2	44,8	53	91	151		180	283	337	528	929							
	800	V 16	M_{2max}	7,3	13,3	24,3		42,9	46,6	82	89	156														
			P_{N1}	0,3	0,55	0,98		1,66	1,97	1,6	3,11	2,5	3,7	2,5	6	9,9	11,8	8,3	17,5	13	20,8	13				
			P_{N2}	0,25	0,45	0,82		1,43	1,7	2,7	3,21	5,3	8,8	10,4		15,6	18,6									
	630	V 13	M_{N2}	4,21	7,7	13,9		24,3	29	46	55	90	149		178	266	316									
			M_{2max}	7,7	13,9	24,9		44,3	48,2	82	89	153														
			P_{N1}	0,27	0,49	0,87		1,49	1,78	1,4	2,78	2,2	3,31	2,2	5,6	9,1	10,8	8	17	13	20,2	13	31,5	20		
45	1 400	V 32	P_{N2}	0,22	0,39	0,72		1,25	1,48	2,36	2,81	4,79	8	9,5		157	187	296	352	555						
			M_{N2}	4,34	7,8	14,2		24,6	29,2	46,5	55	94	161		272	295	513	575	951							
			M_{2max}	7,6	13,9	25,2		45	48,9	85	92	161														
	500	V 10	P_{N1}	0,28	0,5	0,9		1,53	1,82	1,5	2,86	2,3	3,41	2,3	5,6	9,1	10,9	7,7	16,3	12	19,4	12				
			P_{N2}	0,23	0,41	0,75		1,31	1,56	2,48	2,95	4,88	8,1	9,6		14,5	17,2									
			M_{N2}	4,31	7,9	14,3		25	29,7	47,3	56	93	154		183	276	329									
	1 120	V 25	M_{2max}	7,9	14,5	25,7		46,4	50	85	92	161														
			P_{N1}	0,24	0,44	0,75		1,26	1,5	1,2	2,35	1,8	2,79	1,8	4,63	7,4	8,8		13,4	16	13	25	19	37,8		
			P_{N2}	0,17	0,33	0,57		0,98	1,16	1,86	2,22	3,74	82	133		158	245	291	462	724						
			M_{N2}	3,81	7,1	12,4		21,3	25,4	40,7	48,4	82														
			M_{2max}	6,4	12	21,3		37,2	40,4	70	77	140														
			P_{N1}	0,26	0,48	0,86		1,41	1,2	1,68	1,2	2,68	1,8	3,19	1,8	5,2	7,3	8,6		13,4	15,9	25,6	22	45,8		
			P_{N2}	0,2	0,36	0,66		1,11	1,32	2,15	2,56	4,24	54	90		132	157	247	294	478						
			M_{N2}	4,17	7,7	14,1		23,7	28,2	45,7	54	90	156		230	250	423	460	819	1449						



Values in red state nominal thermal power P_{t_w} (ambient temperature 40 °C, continuous duty see ch. 4).For n₁ higher than 1 400 min⁻¹ or lower than 355 min⁻¹ see ch. 6 and page 28.

1) Values given for train of 2-stage gears are nominal; see page 28 for effective transmission ratios.

2) M_{2max} represents maximum torque peak the gear reducer will withstand.



n_{N2} min ⁻¹	Train of gears i 1)	P [kW] M [daNm m] 2)	Gear reducer size																					
			01	02	03	04	05	06	07	08	09	10	11	12	13	14								
45	900	V 20	P_{N1} 0,29	0,51	0,91	0,8	1,29	1,53	2,39	2,85	2,1	4,78	7,9	9,4	14,4	17,2	13	28,8	20	49,4	31			
			P_{N2} 0,22	0,38	0,7	1,06	1,26	2	2,38	4,06	6,8	8,1	12,5	14,9	265	316	536	25,3	43,7	928	1595			
			M_{N2} 4,58	8,2	14,9	22,5	26,7	42,4	50	86	144	172	265	316	513	900	1595							
			M_{2max} 7,8	14,1	25	39,6	43	75	82	143	245	266	472	513	900	1595								
	710	V 16	P_{N1} 0,26	0,47	0,86	1,4	1,66	1,3	2,65	2,1	3,15	2,1	5,1	8,2	9,7	7,5	15,3	12	18,2	12	28,2	20		
			P_{N2} 0,21	0,37	0,7	1,15	1,37	2,22	2,64	4,32	7	8,4	13,3	15,9	180	287	342	25,1	45,4	539	977			
			M_{N2} 4,5	8,1	15	24,8	29,6	47,8	57	93	151	180	278	505	549	897	1619							
			M_{2max} 7,5	13,6	24,3	43,1	46,9	83	90	157	256	278	505	549	897	1619								
	560	V 13	P_{N1} 0,25	0,45	0,8	1,38	1,64	1,3	2,58	2,1	3,07	2,1	5,2	8,4	10	7,4	15,8	12	18,8	12	29,5	18		
			P_{N2} 0,2	0,36	0,66	1,15	1,36	2,17	2,59	4,42	7,3	8,7	14	16,6	194	309	368	583	973	—				
			M_{N2} 4,46	8	14,6	25,4	30,3	48,2	57	98	163	194	279	303	530	576	973							
			M_{2max} 7,8	14,2	25,9	46,8	51	88	95	167	275	299	510	587	973									
	450	V 10	P_{N1} 0,26	0,47	0,84	1,42	1,68	2,65	3,16	2,3	5,2	8,5	7,2	10,1	7,2	15,3	11	18,2	11	—	—	—		
			P_{N2} 0,21	0,38	0,69	1,21	1,44	2,29	2,72	4,54	7,5	8,9	13,5	16,1	188	287	342	510	587	—	—	—		
			M_{N2} 4,42	8,1	14,7	25,7	30,5	48,5	58	96	158	188	299	510	587	973								
			M_{2max} 8,1	14,7	26,5	47,2	51	87	95	164	275	299	510	587	973									
40	1 250	V 32	P_{N1} 0,23	0,41	0,71	1,17	1,39	1,1	2,19	1,7	2,61	1,7	4,33	7	8,3	12,6	15	11	23,6	18	35,7	31,2		
			P_{N2} 0,16	0,3	0,53	0,9	1,07	1,73	2,06	3,48	5,7	6,8	10,5	12,4	165	256	304	487	850	763	1335			
			M_{N2} 3,93	7,3	13	22	26,2	42,2	50	85	139	165	264	450	489	850	1335							
			M_{2max} 6,6	12,4	22	39,4	42,8	74	80	143	243	243	264	450	489	850	1335							
	1 000	V 25	P_{N1} 0,25	0,45	0,81	1,32	1,1	1,57	1,1	2,5	1,7	2,98	1,7	4,82	6,7	8	12,5	14,8	24,1	20	43	31		
			P_{N2} 0,18	0,33	0,61	1,03	1,22	1,99	2,37	3,92	5,7	6,8	10,7	12,8	163	256	305	501	904	—	37,9	1530		
			M_{N2} 4,31	7,9	14,6	24,5	29,2	47,6	57	94	137	163	240	436	473	863	1530							
			M_{2max} 7,4	13,4	24,2	43,9	47,6	81	88	162	240	277	485	527	927	1653								
	800	V 20	P_{N1} 0,27	0,47	0,84	1,19	1,41	2,21	2,63	2	4,45	7,4	8,8	13,4	16	12	26,8	18	46,1	29	—	—		
			P_{N2} 0,2	0,35	0,65	0,97	1,15	1,83	2,18	3,75	6,3	7,5	11,6	13,8	150	178	277	330	559	23,4	40,7	972		
			M_{N2} 4,7	8,4	15,4	23,1	27,5	43,8	52	90	150	178	277	485	527	927	1653							
			M_{2max} 7,9	14,3	25,9	41,4	45	78	85	146	255	277	485	527	927	1653								
	630	V 16	P_{N1} 0,24	0,43	0,79	1,28	1,53	1,3	2,44	2	2,9	2	4,69	7,6	9	7	14,2	11	16,9	11	26,2	18	46,9	29
			P_{N2} 0,19	0,34	0,64	1,05	1,26	2,03	2,42	3,96	6,5	7,7	12,3	14,7	187	299	355	562	931	23,2	42	1018		
			M_{N2} 4,61	8,3	15,4	25,6	30,4	49,3	59	96	157	187	299	355	562	931	1683							
			M_{2max} 7,5	13,7	25,1	45,1	49	85	93	160	266	290	315	552	600	1023								
	500	V 13	P_{N1} 0,23	0,41	0,74	1,28	1,52	1,3	2,39	2	2,84	2	4,79	7,8	9,3	6,9	14,7	11	17,5	11	27,5	17		
			P_{N2} 0,18	0,33	0,6	1,05	1,25	2,06	2,38	4,07	6,7	8	12,9	15,4	168	199	321	382	606	24,4	—	—		
			M_{N2} 4,57	8,2	15	26,2	31,2	49,7	59	101	168	199	315	552	600	1023								
			M_{2max} 8,1	14,6	26,7	47,8	52	89	97	172	290	315	552	600	1023									
	400	V 10	P_{N1} 0,24	0,43	0,77	1,32	1,54	2,44	2,89	2,2	4,8	7,8	9,3	6,7	14,2	10	16,9	10	—	—	—	—		
			P_{N2} 0,19	0,35	0,63	1,12	1,31	2,09	2,48	4,16	6,8	8,1	12,5	14,9	163	194	299	356	602	—	—	—		
			M_{N2} 4,55	8,3	15,1	26,7	31,2	50	59	99	163	194	309	523	602	1043								
			M_{2max} 8,3	14,9	26,9	48,6	53	90	98	171	284	300	523	602	1043									
35,5	1 400	V 40	P_{N1} 0,19	0,34	0,6	1	1,19	1,86	2,21	1,7	3,64	5,7	6,8	10,9	12,9	19,8	35	27	—	—	—	—		
			P_{N2} 0,13	0,24	0,44	0,76	0,9	1,44	1,71	2,88	4,58	5,4	8,9	10,6	16,5	249	289	449	802	449	802	1445		
			M_{N2} 3,6	6,6	11,9	20,7	24,6	39,2	46,7	79	125	149	243	289	449	802								
			M_{2max} 6,1	11,1	20,3	36,3	39,4	69	75	133	227	247	432	469	817	1445								
	1 120	V 32	P_{N1} 0,21	0,38	0,67	1,1	1,3	1,1	2,06	1,6	2,45	1,6	4,07	6,6	7,8	11,8	14,1	11	22,4	17	33,8	29,4		
			P_{N2} 0,15	0,28	0,49	0,83	0,99	1,61	1,91	3,24	5,3	6,3	9,8	11,6	18,8	212	318	512	802	512	802	1385		
			M_{N2} 4,05	7,5	13,5	22,8	27,1	43,8	52	88	145	173	267	318	504	881	1385							
			M_{2max} 6,9	12,8	22,8	40,4	43,9	77	83	146	254	276	464	504	881	1385								
	900	V 25	P_{N1} 0,23	0,42	0,76	1,24	1,48	1,1	2,35	1,7	2,8	1,7	4,51	6,3	7,5	11,7	13,9	22,8	18	40,4	30	—	—	
			P_{N2} 0,17	0,31	0,57	0,96	1,14	1,86	2,21	3,64	5,3	6,3	10	11,9	19,7	272	315	524	943	874	1612	—		
			M_{N2} 4,44	8,1	15,1	25,4	30,2	49,3	59	97	141	168	265	315	487	874	1612							
			M_{2max} 7,5	13,6	25	45,6	49,5	84	92	168	250	272	448	487	874	1612								
	710	V 20	P_{N1} 0,24	0,44	0,78	1,09	1,29	2,04	2,43	1,9	4,14	6,8	8,1	12,5	14,9	11	24,9	17	43,1	26	—	—		
			P_{N2} 0,18	0,32	0,59	0,88	1,05	1,68	2	3,47	5,8	6,9	10,7	12,8	21,7	37,8	534	583	1018	583				




n_{N2} min ⁻¹	n_1	Train of gears i 1)	P [kW] M [daNm]	Gear reducer size															
				01	02	03	04	05	06	07	08	09	10	11	12	13	14		
35,5	355	V 10	P _{N1} P _{N2} M _{N2} M _{2max}	0,22 0,17 4,69 8,4	0,39 0,31 8,4 15,1	0,71 0,58 15,6 27,3	1,22 1,03 27,7 49,9	1,4 1,19 51 54	2,24 1,91 61 93	2,65 2,1 2,26 102 101	4,41 3,81 168 293	7,2 6,2 7,4 200	8,5 11,5 13,7 311	6,2 11,5 13,7 370	13,1 9,6 15,6 9,6 — 623	— —	— —		
31,5	1 250	V 40	P _{N1} P _{N2} M _{N2} M _{2max}	0,18 0,12 3,71 6,4	0,32 0,22 6,8 11,6	0,56 0,4 12,3 21	0,94 0,7 21,4 38,3	1,11 0,83 25,5 41,6	1,74 1,33 40,7 71	2,07 1,6 1,59 48,5 77	3,39 2,67 82 136	5,4 4,26 130 234	6,4 5,1 253 254	10,2 8,3 253 445	12,1 9,9 302 484	18,7 15,4 471 846	32,8 25 27,5 840		
	1 000	V 32	P _{N1} P _{N2} M _{N2} M _{2max}	0,2 0,14 4,19 7,1	0,35 0,25 7,7 12,9	0,62 0,45 13,9 23,2	1,02 0,77 23,6 42	1,22 1 0,92 45,3 79	1,91 1,6 1,48 54 85	2,28 1,6 1,76 91 152	3,79 2,99 151 261	6,1 4,95 180 283	7,3 5,9 277 493	11,1 9,1 21 15 536	13,2 9,8 10,8 330 536	21 15 17,6 31,6 929	31,6 27,4 838 1458		
	800	V 25	P _{N1} P _{N2} M _{N2} M _{2max}	0,21 0,15 4,58 7,8	0,38 0,28 8,3 14,2	0,7 0,52 15,4 25,8	1,15 0,88 26,2 46,6	1,37 1 1,04 31,2 51	2,17 1,6 1,7 51 86	2,59 1,6 2,02 60 94	4,17 3,34 100 169	5,8 4,88 146 257	6,9 5,8 173 279	10,7 9,2 273 467	12,8 10,9 325 508	21,2 17 18,3 546 908	37,9 27 33,1 988 1668		
	630	V 20	P _{N1} P _{N2} M _{N2} M _{2max}	0,22 0,16 4,96 8,3	0,4 0,3 9 15	0,72 0,54 16,5 27,5	0,99 0,8 24,3 43,9	1,18 0,95 28,9 47,7	1,87 1,53 46,5 83	2,23 1,8 1,83 55 90	3,83 3,19 161 156	6,3 5,3 192 272	7,5 6,3 300 295	11,6 9,9 357 519	13,8 10 11,8 606 564	23,1 16 20 1069 983	40,3 24 35,3 1778		
	500	V 16	P _{N1} P _{N2} M _{N2} M _{2max}	0,2 0,16 4,84 7,9	0,36 0,28 8,7 14,3	0,66 0,53 16,2 26,5	1,09 0,88 26,9 47,2	1,29 1,05 32,1 51	2,07 1,71 52 91	2,46 1,8 2,03 102 171	4,01 3,35 169 284	6,5 5,5 201 308	7,8 6,6 102 308	12,3 9,4 10,5 322 561	14,6 9,4 12,5 383 610	22,4 16 19,7 601 984	40,3 25 35,7 1092 1754		
	400	V 13	P _{N1} P _{N2} M _{N2} M _{2max}	0,2 0,15 4,78 8,4	0,35 0,28 8,6 15	0,63 0,51 15,7 27,8	1,09 0,89 27,8 49,9	1,3 1,06 33 54	2,05 1,7 53 95	2,44 1,8 2,03 63 103	4,12 3,47 108 181	6,6 5,7 177 309	7,9 6,8 211 335	12,8 9,5 11,1 346 588	15,2 9,5 13,3 411 638	23,9 15 21 653 1063	—		
28	1 400	IV 50	P _{N1} P _{N2} M _{N2} M _{2max}	0,2 0,14 5,1 8,5	0,34 0,26 8,9 14,5	0,63 0,49 16,6 27,2	1 0,79 27,6 48,4	1,2 0,94 32,8 53	1,91 1,54 53 93	2,28 1,7 1,83 3,03 101	3,72 3,03 174 173	6,2 5,1 174 289	7,4 5,6 208 314	11,5 8,7 9,6 334 575	13,7 8,7 11,5 397 624	20,8 15 17,8 618 1002	37,4 23 32,5 1125 1788		
	1 400	V 50	P _{N1} P _{N2} M _{N2} M _{2max}	0,14 0,1 3,24 5,2	0,26 0,18 6 10	0,47 0,32 11,1 19,6	0,77 0,56 19,2 34,7	0,92 1,44 22,9 37,7	1,44 1,72 36,9 65	2,69 4,49 43,9 71	4,49 5,3 120 123	5,3 8,3 143 212	8,3 9,9 227 231	9,9 9,9 270 409	16 13 445 445	28,1 23,3 795 1408			
	1 120	V 40	P _{N1} P _{N2} M _{N2} M _{2max}	0,16 0,11 3,81 6,5	0,3 0,2 7 11,8	0,52 0,37 12,7 21,7	0,88 0,65 22,1 39,2	1,04 0,77 26,3 42,6	1,63 1,24 42,2 72	1,94 1,5 1,47 50 79	3,18 2,48 85 139	5,1 4,74 136 241	6 7,7 162 261	9,6 9,2 264 458	11,4 9,7 7,7 315	17,6 15 14,5 494 498	30,9 24 25,8 879 1557		
	900	V 32	P _{N1} P _{N2} M _{N2} M _{2max}	0,18 0,13 4,32 7,3	0,33 0,23 7,9 13,6	0,58 0,42 14,3 23,6	0,96 0,72 24,3 43,6	1,14 1 0,85 29 47,3	1,79 1,5 1,64 46,7 81	2,13 1,5 2,78 56 88	3,55 4,63 94 157	5,8 5,5 157 268	6,9 5,5 187 291	5,8 8,5 287 507	10,4 10,1 342 551	12,4 9,1 10,1 560 977	19,8 14 16,5 874 1530		
	710	V 25	P _{N1} P _{N2} M _{N2} M _{2max}	0,2 0,14 4,73 8	0,35 0,25 8,5 14,4	0,64 0,47 15,8 26,5	1,06 0,8 27 47,4	1,27 1 0,96 32,2 51	2,01 1,5 1,85 52 88	2,39 1,5 3,06 103 175	3,85 4,48 151 263	5,4 5,3 179 286	6,4 8,4 282 486	9,9 8,4 335 528	11,7 10 569 941	19,7 16 16,9 1036 1704	35,4 25 30,8 1036 1704		
	560	V 20	P _{N1} P _{N2} M _{N2} M _{2max}	0,21 0,15 5,1 8,5	0,37 0,27 9,3 15,6	0,67 0,5 17,1 28,2	0,91 0,73 24,8 44,6	1,08 0,87 29,6 48,5	1,72 1,4 47,8 86	2,05 1,67 57 93	3,54 2,93 100 158	5,8 4,89 167 279	6,9 5,8 199 303	5,8 5,8 312 539	10,7 9,1 371 586	12,8 9,2 10,9 629	21,4 15 18,5 1121	37,7 23 32,9 1121 1842	
	450	V 16	P _{N1} P _{N2} M _{N2} M _{2max}	0,19 0,15 4,96 8	0,34 0,26 8,9 14,5	0,62 0,49 16,6 27,2	1,01 0,81 27,6 48,4	1,2 0,97 32,8 53	1,92 1,57 53 93	2,28 1,7 1,87 64 101	3,73 3,1 105 173	6,1 5,1 174 289	7,3 6,1 208 314	5,6 9,8 334 575	11,5 8,7 11,7 397	13,7 8,7 11,7 677	20,8 15 18,2 618	37,4 23 33,1 1125 1788	
	355	V 13	P _{N1} P _{N2} M _{N2} M _{2max}	0,18 0,14 4,89 8,5	0,32 0,25 8,8 15,7	0,58 0,46 16,1 28,2	1,01 0,82 28,6 51	1,2 0,97 34 56	1,89 1,56 55 96	2,25 1,7 1,86 65 104	3,79 3,17 111 183	6,1 5,2 182 317	7,2 6,2 217 345	5,6 6,2 358 597	11,8 8,8 10,2 345	14 8,8 12,2 426 649	22,1 14 19,4 677	—	34,6 22 29,9 1161 1872
25	1 250	IV 50	P _{N1} P _{N2} M _{N2} M _{2max}	0,19 0,13 5,2 8,7	0,31 0,24 9,1 14,9	0,58 0,44 16,9 27,6	0,92 0,72 32,1 49,1	1,09 0,86 33,4 53	1,75 1,4 55 95	2,09 1,7 1,67 65 103	3,42 2,77 108 178	5,7 4,68 178 298	6,8 5,6 178 323	5,2 5,6 212 588	10,7 8,1 10,6 345	12,7 8,1 10,6 410	19,1 14 16,3 634	34,6 22 29,9 1161 1872	

Values in red state nominal thermal power P_{t_k} (ambient temperature 40 °C, continuous duty see ch. 4).

For n_1 higher than 1 400 min⁻¹ or lower than 355 min⁻¹ see ch. 6 and page 28.

1) Values given for train of 2-stage gears are nominal; see page 28 for effective transmission ratios.

2) M_{2max} represents maximum torque peak the gear reducer will withstand.





n_{N2} min ⁻¹	n_1 min ⁻¹	Train of gears i 1)	P [kW] M [daNm] 2)	Gear reducer size																	
				01	02	03	04	05	06	07	08	09	10	11	12	13	14				
25	1 250	V 50	P _{N1}	0,13	0,24	0,43	0,72	0,85	1,34	1,6	2,5	4,17	4,96	7,8	9,3	15,2	26,6				
			P _{N2}	0,09	0,16	0,3	0,52	0,61	1	1,18	1,91	3,25	3,86	6,2	7,4	12,3	22				
	1 000	V 40	M _{N2}	3,29	6,1	11,4	19,7	23,5	38	45,3	73	124	148	237	282	469	840				
			M _{2max}	5,2	10,1	19,8	35,5	38,6	67	73	127	225	244	428	465	840	1484				
	800	V 32	P _{N1}	0,15	0,27	0,48	0,81	0,97	1,52	1,8	1,4	2,96	4,71	5,6	9	10,7	8,9	16,4			
			P _{N2}	0,1	0,19	0,34	0,59	0,71	1,14	1,36	2,28	3,68	4,38	7,2	8,6	13,4	24,1				
	630	V 25	M _{N2}	3,88	7,1	13	22,7	27	43,5	52	87	141	167	275	327	513	920				
			M _{2max}	6,7	12,2	22,1	40,7	44,2	76	83	146	251	272	478	519	921	1610				
	500	V 20	P _{N1}	0,17	0,3	0,54	0,89	1,05	1,66	1,98	1,4	3,3	5,4	6,4	5,3	9,7	11,5	8,4	18,6		
			P _{N2}	0,12	0,21	0,39	0,65	0,78	1,26	1,5	2,56	4,27	5,1	7,8	9,3	15,3	23,6				
	400	V 16	M _{N2}	4,46	8,1	14,7	25	29,7	48,2	57	98	163	194	299	356	584	901				
			M _{2max}	7,5	13,6	24,6	44,3	48,1	85	92	162	279	303	520	565	1010	1562				
22,4	1 400	IV 63	P _{N1}	0,18	0,32	0,59	0,98	1,17	0,9	1,85	1,4	2,2	3,56	4,93	5,9	9,1	10,8	18,1	14	32,7	23
			P _{N2}	0,13	0,23	0,43	0,73	0,87	1,42	1,69	2,8	4,09	4,87	7,7	9,1	15,5	28,4				
	1 400	V 63	M _{N2}	4,84	8,8	16,3	27,8	33,1	54	64	106	155	185	291	346	588	1076				
			M _{2max}	8,1	14,8	27,3	49,4	54	91	99	180	277	301	505	549	960	1739				
	1 120	IV 50	P _{N1}	0,19	0,34	0,62	0,83	0,99	1,58	1,88	3,26	5,4	6,4	5,4	10	11,9	8,5	19,8	13	35,2	21
			P _{N2}	0,14	0,25	0,46	0,66	0,79	1,28	1,52	2,69	4,47	5,3	8,4	10	17	30,5				
	1 120	V 50	M _{N2}	5,2	9,5	17,5	25,3	30,1	48,8	58	103	171	203	322	383	650	1165				
			M _{2max}	8,7	15,7	28,6	45,8	49,7	88	96	165	289	314	552	600	1051	1878				
	900	V 40	P _{N1}	0,17	0,31	0,56	0,91	1,09	1,75	2,08	1,7	3,41	5,6	6,6	5,2	10,6	8,1	19	14	34,522	
			P _{N2}	0,13	0,24	0,44	0,73	0,87	1,43	1,7	2,82	4,67	5,6	9	10,7	16,6	30,4				
	710	V 32	M _{N2}	5,1	9,1	16,9	28,1	33,4	55	65	108	178	212	345	410	634	1161				
			M _{2max}	8	14,9	27,6	49,1	53	95	103	178	298	323	588	638	1047	1872				
18	1 400	IV 80	P _{N1}	0,16	0,33	0,59	0,76	0,91	1,45	1,73	3,02	5,1	6	5,1	9,3	11,1	8	18,5	13	33,1	20
			P _{N2}	0,11	0,23	0,42	0,59	0,7	1,15	1,36	2,42	4,11	4,89	7,7	9,1	15,5	28				
	1 400	V 63	M _{N2}	4,96	9,7	18	25,7	30,6	49,8	59	105	175	208	333	396	671	1211				
			M _{2max}	8,2	15,8	29	46,8	51	90	98	168	297	323	565	614	1083	1913				
	1 120	IV 50	P _{N1}	0,18	0,34	0,58	0,69	1,1	1,31	2,11	3,44	4,1	6,2	7,4	11,9	11,9	21,2				
			P _{N2}	—	0,12	0,23	0,4	0,48	0,79	0,94	1,57	2,61	3,11	4,84	5,8	9,5	17,2				
	1 120	V 50	M _{N2}	4,96	9,7	17,2	20,5	33,9	40,3	67	112	134	208	248	406	739					
			M _{2max}	7,5	14,9	29	32,5	59	67	117	201	219	386	419	739	1339					
	560	V 25	P _{N1}	0,17	0,29	0,53	0,84	1	1,62	1,93	1,6	3,15	5,3	6,3	4,8	9,9	7,5	17,7	13	32,2	20
			P _{N2}	0,12	0,22	0,41	0,66	0,78	1,29	1,53	2,54	4,29	5,1	8,2	9,8	15	27,7				
	450	V 20	M _{N2}	5,3	9,2	17,3	28,6	34	56	66	110	183	217	356	424	651	1198				
			M _{2max}	8,9	15,1	27,9	49,7	54	96	104	183	306	332	597	649	1064	1903				
	355	V 16	P _{N1}	0,12	0,22	0,41	0,67	0,79	1,25	1,49	2,33	3,89	4,63	7,4	8,8	14,4	25,3				
			P _{N2}	0,08	0,15	0,28	0,47	0,56	0,92	1,09	1,76	3	3,57	5,8	6,9	11,6	20,8				
	710	V 32	M _{N2}	3,34	6,3	11,7	20,2	24,1	39,2	46,6	75	128	152	247	294	494	887				
			M _{2max}	5,2	10,1	19,9	36,4	39,5	69	75	132	231	251	446	484	869	1560				
	900	V 40	P _{N1}	0,14	0,25	0,45	0,76	0,9	1,42	1,69	1,4	2,76	4,41	5,3	8,4	10	8,3	15,5	13	27,4	20
			P _{N2}	0,09	0,17	0,31	0,55	0,65	1,05	1,26	2,12	3,42	4,07	6,7	8	12,5	22,6				
	560	V 25	M _{N2}	3,95	7,3	13,2	23,3	27,7	44,8	53	90	145	173	284	339	532	960				
			M _{2max}	6,8	12,5	22,4	41,9	45,5	78	85	148	253	275	498	540	966	1666				
	450	V 20	P _{N1}	0,16	0,28	0,5	0,82	0,97	1,54	1,83	1,4	3,06	5	6	4,9	9	10,7	7,7	17,3	12	25,3
			P _{N2}	0,11	0,19	0,35	0,6	0,71	1,15	1,37	2,35	3,93	4,68	7,2	8,6	14,2	21,6				
	355	V 16	M _{N2}	4,6	8,3	15,2	25,6	30,5	49,7	59	101	169	201	312	371	610	929				
			M _{2max}	7,7	13,9	25	45	48,9	87	94	167	289	314	534	579	1031	1593				
	560	V 25	P _{N1}	0,17	0,3	0,54	0,9	1,07	0,9	1,71	1,4	2,03	3,29	4,54	5,4	8,4	10	16,7	13	30,3	21
			P _{N2}	0,12	0,21	0,39	0,67	0,8	1,3	1,55	2,57	3,74	4,46	7	8,4	14,2	26,2				
	450	V 20	M _{N2}	9	16,7	28,6	34	55	66	109	160	190	300	357	607	1117					
			M _{2max}	8,9	15,8	29	46,8	51	90	98	168	283	307	524	569	978	1773				
	355	V 16	P _{N1}	0,18	0,32	0,58	0,76	0,91	1,46	1,73	3,03	4,98	5,9	9,3	11,1	8	18,5	13	33,120		
			P _{N2}	0,13	0,23	0,42	0,61	0,72	1,17	1,4	2,48	4,12	4,9	7,8	9,3	15,8	28,5				
	355	V 16	M _{N2}	5,3	9,7	18	25,7	30,6	49,8	59	105	175	208	333	396	671	1211				
			M _{2max}	8,1	15,1	27,9	49,7	54	96	104	183	306	332	597	649	1064	1903				
	18	1 400	P _{N1}	0,13	0,26	0,47	0,76	0,91	1,46	1,73	1,2	2,84	3,95	4,7	7,2	8,5	14,2	12	26	19	
			P _{N2}	0,09	0,17	0,33	0,55	0,65	1,07	1,27	2,13	3,15	3,75	5,8	6,9	11,7	21,8				
			M _{N2}	4,89	9,3	17,4	29,7	35,3	57	99	108	116	168	299	324	547	1039	1179	1888		

Values in red state nominal thermal power P_{th} (ambient temperature 40 °C, continuous duty see ch. 4).

For n , higher than 1 400 min⁻¹ or lower than 355 min⁻¹ see ch. 6 and page 28.

1) Values given for train of 2-stage gears are nominal; see page 28 for effective transmission ratios.

2) M_{2max} represents maximum torque peak the gear reducer will withstand.



n_{N2} min ⁻¹	n_1	Train of gears i	P [kW] M [daNm m] 1) 2)	Gear reducer size															
				01	02	03	04	05	06	07	08	09	10	11	12	13	14		
18	1 120	IV 63	P _{N1}	0,14	0,28	0,5	0,66	0,76	1,22	1,45	2,56	4,3	5,1	8	9,5	6,9	15,9	11	28,7 17
			P _{N2}	0,09	0,19	0,35	0,5	0,58	0,95	1,13	2,03	3,45	4,1	6,5	7,7	13,2	24	24	
			M _{N2}	5,2	10,2	18,9	27,3	31,6	52	61	110	183	218	352	419	713	1301		
			M _{2max}	8,6	16,5	30,5	47,1	53	93	101	176	306	332	599	651	1118	2032		
	1 120	V 63	P _{N1}	—	0,15	0,29	0,5	0,58	0,95	1,13	1,83	2,97	3,54	5,4	6,4	10,5	18,8		
			P _{N2}	—	0,09	0,18	0,34	0,39	0,66	0,79	1,32	2,21	2,63	4,12	4,9	8,2	15	15	
	900	IV 50	P _{N1}	0,15	0,24	0,44	0,71	0,84	1,37	1,63	2,69	4,45	5,3	4,3	8,5	6,7	15	11	27,3 18
			P _{N2}	0,1	0,18	0,34	0,55	0,65	1,07	1,28	2,14	3,6	4,28	7	8,3	12,7	23,3		
	900	V 50	M _{N2}	5,5	9,5	17,8	29,5	34,9	58	69	116	190	227	377	448	682	1256		
			M _{2max}	9	15,9	29,6	53	58	103	111	196	328	357	643	699	1144	2054		
	710	V 40	P _{N1}	0,1	0,19	0,35	0,57	0,68	1,09	1,3	2,02	3,38	4,03	6,4	7,7	12,9	22,8 19		
			P _{N2}	0,06	0,12	0,23	0,4	0,47	0,78	0,93	1,49	2,56	3,05	5	5,9	10,2	18,5		
			M _{N2}	3,41	6,6	12,3	21,1	25,1	41,4	49,3	79	136	162	265	315	543	980		
			M _{2max}	5,2	10,2	20	38,6	42	74	80	136	242	263	469	509	915	1665		
			P _{N1}	0,12	0,21	0,38	0,64	0,76	1,21	1,44	2,36	3,83	4,56	7,3	8,7	13,4 11	23,8 17		
			P _{N2}	0,08	0,14	0,26	0,45	0,54	0,88	1,05	1,77	2,91	3,46	5,7	6,8	10,7	19,3		
			M _{N2}	4,13	7,5	13,8	24,4	29,1	47,5	57	95	157	186	308	366	578	1040		
			M _{2max}	6,8	13,1	23,7	43,2	46,9	83	90	158	273	296	522	567	1004	1830		
			P _{N1}	0,13	0,23	0,42	0,68	0,81	1,31	1,56	1,2	2,62	4,29	5,1	4,2	7,8	6,6	14,8 10	21,3
			P _{N2}	0,09	0,16	0,29	0,49	0,58	0,96	1,15	1,97	3,31	3,94	6,1	7,3	12	18		
	450	V 25	P _{N1}	0,14	0,25	0,46	0,77	0,91	1,46	1,74	1,2	2,84	3,89	4,62	7,2	8,5	14,2 12	26 19	
			P _{N2}	0,1	0,17	0,33	0,56	0,67	1,09	1,3	2,18	3,16	3,76	5,9	7,1	12	22,2		
			M _{N2}	5,2	9,3	17,4	29,7	35,3	58	69	116	168	200	315	375	634	1179		
			M _{2max}	8,6	15,9	28,7	53	57	99	108	196	299	324	547	594	1039	1888		
			P _{N1}	0,15	0,27	0,49	0,65	0,75	1,2	1,43	2,53	4,17	4,96	7,9	9,4	6,9	15,7 11	28,317	
			P _{N2}	0,1	0,19	0,35	0,51	0,59	0,96	1,14	2,05	3,41	4,05	6,5	7,8	13,3	24,2		
	355	V 20	M _{N2}	5,5	10,2	18,9	27,3	31,6	52	61	110	183	218	352	419	713	1301		
			M _{2max}	9	16,5	30,5	47,1	53	93	101	176	306	332	599	651	1118	2032		
14	1 400	IV 100	P _{N1}	0,1	0,2	0,36	0,58	0,69	1,11	1,32	2,26	3,77	4,48	3,6	6,7	5,7	12,8 9	18,2	
			P _{N2}	0,06	0,13	0,24	0,4	0,48	0,79	0,94	1,64	2,8	3,33	5,1	6,1	10	14,9		
			M _{N2}	4,25	9,1	16,6	27,8	33	55	65	114	190	227	353	420	690	1030		
			M _{2max}	6,9	15	27,6	49,8	54	94	102	182	322	350	600	652	1138	1686		
	1 120	IV 80	P _{N1}	0,11	0,21	0,4	0,64	0,76	1,24	1,47	1,1	2,44	3,37	4,01	6,1	7,2	12 10	22,1 16	
			P _{N2}	0,07	0,14	0,27	0,45	0,54	0,89	1,06	1,81	2,66	3,17	4,85	5,8	9,8	18,3		
	900	IV 63	P _{N1}	0,12	0,23	0,42	0,56	0,64	1,04	1,23	2,16	3,63	4,32	6,8	8,1	6,1	13,5 9,5	24,5 15	
			P _{N2}	0,08	0,16	0,29	0,42	0,49	0,8	0,94	1,69	2,88	3,42	5,5	6,5	11,1	20,3		
	900	V 63	M _{N2}	5,4	10,5	19,5	28,4	32,8	54	64	114	190	227	370	440	745	1368		
			M _{2max}	8,8	17,4	31,7	48,3	54	97	105	188	328	356	643	699	1202	2136		
	900	V 40	P _{N1}	—	0,13	0,24	0,43	0,49	0,82	0,97	1,57	2,56	3,04	4,68	5,6	9,2	16,5		
			P _{N2}	—	0,08	0,15	0,28	0,32	0,55	0,66	1,11	1,86	2,21	3,5	4,16	7,1	13		
	710	IV 50	M _{N2}	5,1	9,9	19	21,6	37,1	44,1	74	124	148	234	278	474	870			
			M _{2max}	7,6	15	29,3	32,8	60	67	119	228	247	438	476	848	1568			
	710	V 50	P _{N1}	0,12	0,2	0,37	0,6	0,68	1,12	1,33	2,22	3,68	4,38	7,1	5,9	8,5	5,9	12,4 10	22,7 16
			P _{N2}	0,08	0,15	0,27	0,46	0,52	0,87	1,04	1,75	2,94	3,5	5,8	6,9	10,3	19,2		
	710	V 40	M _{N2}	5,7	9,8	18,4	31,2	35,6	60	71	120	198	235	395	470	707	1309		
			M _{2max}	9,5	16,5	30,5	56	60	107	116	205	351	381	689	748	1171	2154		
	560	V 40	P _{N1}	0,09	0,16	0,3	0,48	0,57	0,92	1,09	1,72	2,87	3,41	5,6	6,6	11,1	19,9 16		
			P _{N2}	0,05	0,1	0,19	0,33	0,39	0,64	0,76	1,24	2,13	2,53	4,22	5	8,6	15,9		
	450	V 32	M _{N2}	3,53	6,9	12,9	22	26,1	43	51	83	143	170	284	338	581	1068		
			M _{2max}	5,3	10,2	20,1	39,3	44	76	83	144	260	282	504	547	975	1789		
	450	V 20	P _{N1}	0,11	0,2	0,36	0,58	0,69	1,12	1,33	1,1	2,26	3,7	4,41	3,6	6,7	5,7	12,8 9	18,2
			P _{N2}	0,07	0,13	0,24	0,41	0,49	0,81	0,96	1,67	2,8	3,34	5,2	6,2	10,2	15,2		
			M _{N2}	5,1	9,1	16,6	27,8	33	55	65	114	190	227	353	420	690	1030		
			M _{2max}	8,1	15	27,6	49,8	54	94	102	182	322	350	600	652	1138	1686		

Values in red state nominal thermal power P_{tq} (ambient temperature 40 °C, continuous duty see ch. 4).

For n_1 higher than 1 400 min⁻¹ or lower than 355 min⁻¹ see ch. 6 and page 28.

1) Values given for train of 2-stage gears are nominal; see page 28 for effective transmission ratios.

2) M_{2max} represents maximum torque peak the gear reducer will withstand.




PalaDrive



Worm Gear Reducers and Gear Motors

SERIES W

7. Nominal powers and torques (gear reducers)



n_{N2} min ⁻¹	n ₁ min ⁻¹	Train of gears i 1)	P [kW] M [daNm] 2)	Gear reducer size																
				01	02	03	04	05	06	07	08	09	10	11	12	13	14			
14	355	V 25	P _{N1}	0,12	0,21	0,39	0,63	0,75	1,22	1,46	1,1	2,42	3,27	3,89	6	7,1	11,9	10		
			P _{N2}	0,08	0,14	0,27	0,45	0,54	0,9	1,07	1,82	2,63	3,13	4,88	5,8	9,9	18,4	16		
			M _{N2}	5,4	9,5	18,1	30,6	36,4	61	72	123	177	211	328	390	663	1236	1997		
			M _{2max}	8,8	16,2	29,7	55	59	102	111	202	302	333	577	626	1084				
11,2	1 400	IV 125	P _{N1}	0,07	0,15	0,27	0,46	0,54	0,85	1,02	1,69	2,87	3,42	5,6	6,6	5,1	10,1	8		
			P _{N2}	0,04	0,09	0,17	0,31	0,36	0,58	0,7	1,19	2,05	2,44	4,11	4,89	7,7	13,7	13		
			M _{N2}	3,62	8	14,7	26,5	31,6	51	60	103	174	208	356	423	663	1190			
			M _{2max}	5,3	13,4	25,9	47,5	52	90	97	171	301	327	583	634	1100	2013			
11,2	1 120	IV 100	P _{N1}	0,08	0,17	0,31	0,49	0,59	0,94	1,12	1,92	3,24	3,85	3,1	5,8	4,8	6,9	4,8	11	
			P _{N2}	0,05	0,11	0,2	0,33	0,39	0,66	0,78	1,37	2,36	2,8	4,29	5,1	8,4	12,6	15,6		
			M _{N2}	4,34	9,3	17,1	28,9	34,3	57	68	119	200	239	372	442	730	1092			
			M _{2max}	6,9	15,5	28,2	52	56	99	107	191	339	368	636	691	1201	1792			
900	900	IV 80	P _{N1}	0,1	0,18	0,34	0,55	0,64	1,05	1,25	1,1	2,09	2,86	3,41	5,2	6,1	10,2	18,7	14	
			P _{N2}	0,06	0,12	0,23	0,38	0,44	0,74	0,89	1,52	2,23	2,65	4,08	4,86	8,2	15,3	1288		
			M _{N2}	5,3	9,8	18,8	32	37,4	63	75	129	184	219	344	409	693		2094		
			M _{2max}	8,4	17	31,1	58	63	109	118	215	309	347	617	670	1149				
710	710	IV 63	P _{N1}	0,1	0,19	0,35	0,47	0,52	0,88	1,01	1,79	2,98	3,55	5,7	6,7	5,4	11,2	8,5	20,4	
			P _{N2}	0,06	0,13	0,24	0,35	0,39	0,67	0,77	1,38	2,34	2,78	4,5	5,4	9,1	16,7	13		
			M _{N2}	5,6	10,8	20,1	30	33,5	57	66	118	196	233	384	458	775	1423			
			M _{2max}	9,3	18,3	33,4	49,4	55	101	111	196	349	379	687	746	1286		2992		
710	710	V 63	P _{N1}	—	0,1	0,2	0,36	0,41	0,69	0,81	1,34	2,16	2,57	3,99	4,74	7,9	14,1			
			P _{N2}	—	0,06	0,12	0,23	0,26	0,46	0,54	0,92	1,53	1,83	2,92	3,47	6	11			
			M _{N2}	5,1	10,1	19,7	22,1	38,8	45,5	78	130	155	247	294	505	929		1625		
			M _{2max}	7,7	15,1	29,5	33	60	68	119	233	261	458	497	877					
560	560	IV 50	P _{N1}	0,1	0,16	0,3	0,5	0,55	0,94	1,1	1,82	3,02	3,6	5,9	7	5,4	10,2	18,6	14	
			P _{N2}	0,07	0,12	0,22	0,38	0,42	0,72	0,85	1,42	2,39	2,84	4,74	5,6	8,5	15,6			
			M _{N2}	5,8	10	18,8	32,9	36,2	63	73	124	203	242	410	488	732	1350			
			M _{2max}	9,9	16,9	32	59	62	113	122	217	366	397	735	798	1197		2204		
560	560	V 50	P _{N1}	0,07	0,13	0,25	0,4	0,48	0,76	0,91	1,46	2,44	2,9	4,73	5,6	9,5	16,9	14		
			P _{N2}	0,04	0,08	0,16	0,27	0,32	0,52	0,62	1,03	1,77	2,1	3,52	4,19	7,3	13,3			
			M _{N2}	3,62	7	13,5	22,8	27,1	44,4	53	88	151	179	300	357	621	1135			
			M _{2max}	5,3	10,3	20,2	39,5	44,2	80	87	149	277	300	526	571	1007	1850			
450	450	V 40	P _{N1}	0,08	0,15	0,27	0,46	0,55	0,85	1,02	1,69	2,82	3,36	5,6	6,6	5,1	10,1	8	17,8	13
			P _{N2}	0,05	0,09	0,17	0,31	0,37	0,6	0,71	1,22	2,05	2,44	4,19	4,99	7,8	14			
			M _{N2}	4,34	8	14,7	26,5	31,6	51	60	103	174	208	356	423	663	1190		2013	
			M _{2max}	6,9	13,4	25,9	47,5	52	90	97	171	301	327	583	634	1100				
355	355	V 32	P _{N1}	0,1	0,17	0,3	0,49	0,58	0,93	1,11	1,9	3,14	3,73	3,1	5,7	6,8	4,8	10,9	7,7	15,4
			P _{N2}	0,06	0,11	0,2	0,34	0,4	0,66	0,79	1,38	2,33	2,77	4,32	5,1	8,5	12,7	1092		
			M _{N2}	5,3	9,3	17,1	28,9	34,3	57	68	119	200	239	372	442	730			1792	
			M _{2max}	8,4	15,5	28,2	52	56	99	107	191	339	368	636	691	1201				
9	1 400	IV 160	P _{N1}	—	0,11	0,22	0,35	0,41	0,64	0,77	1,24	2,13	2,54	4,03	4,8	8,2	14,5	12		
			P _{N2}	—	0,07	0,13	0,22	0,26	0,42	0,5	0,84	1,48	1,76	2,88	3,43	6	11			
			M _{N2}	7,2	13,9	23,8	28,1	45,8	54	91	157	187	312	371	653	1189				
			M _{2max}	10,3	20,2	39,6	44,3	81	91	156	284	308	558	606	1062					
1 120	1 120	IV 125	P _{N1}	0,06	0,12	0,23	0,38	0,45	0,72	0,85	1,43	2,45	2,91	4,79	5,7	4,4	8,8	6,9	15,4	11
			P _{N2}	0,03	0,08	0,14	0,25	0,3	0,48	0,57	0,99	1,71	2,04	3,46	4,12	6,5	11,7			
			M _{N2}	3,69	8	15,2	27	32,1	52	62	107	182	217	374	446	703	1270			
			M _{2max}	5,3	13,4	26,3	48,5	53	94	102	178	316	343	614	667	1157	2072			
900	900	IV 100	P _{N1}	0,07	0,14	0,26	0,42	0,49	0,81	0,96	1,64	2,74	3,27	4,95	5,9	4,3	9,5	6,8	13,3	
			P _{N2}	0,04	0,09	0,17	0,28	0,33	0,55	0,65	1,15	1,96	2,34	3,63	4,32	7,1	10,6			
			M _{N2}	4,37	9,6	17,8	30,1	35,3	59	71	124	208	248	391	466	767	1141			
			M _{2max}	6,9	16,3	29,7	54	59	105	114	204	361	392	680	739	1258	1830			
710	710	IV 80	P _{N1}	0,08	0,15	0,28	0,47	0,52	0,87	1,03	1,74	2,4	2,82	4,38	5,1	8,4	15,4	12		
			P _{N2}	0,05	0,1	0,18	0,32	0,36	0,6	0,72	1,24	1,85	2,27	3,42	3,99	6,7	12,4			
			M _{N2}	5,5	10,2	19,4	33,8	38	65	77	133	194	227	365	426	713	1326			
			M _{2max}	8,8	17,8	32,7	61	65	113	123	229	316	354	634	710	1227	2240			
560	560	IV 63	P _{N1}	0,08	0,16	0,29	0,39	0,43	0,74	0,84	1,45	2,46	2,9	4,67	5,6	9,3	7,6	16,6	12	
			P _{N2}	0,05	0,1	0,19	0,29	0,32	0,55	0,63	1,11	1,9	2,24	3,68	4,37	7,4	13,5			
			M _{N2}	5,7	11,1	20,5	31,5	34,3	60	68	120	202	239	398	473	803	1457			
			M _{2max}	9,5	19,1	35	50	56	104	116	203	364	395	716	778	1370	2448			
560	560	V 63	P _{N1}	0,09	0,16															



n_{N2} min ⁻¹	n_1 min ⁻¹	Train of gears i 1)	P [kW] M [daNm]	- Gear reducer size															
				01	02	03	04	05	06	07	08	09	10	11	12	13	14		
9	450	IV 50	P _{N1}	0,08	0,13	0,25	0,42	0,46	0,81	0,91	1,54	2,6	2,99	4,97	5,9	4,6	8,6	15,5 12	
			P _{N2}	0,05	0,1	0,18	0,31	0,34	0,61	0,69	1,19	2,03	2,34	3,95	4,67	7,1	12,9		
			M _{N2}	6	10,2	19,2	34	36,8	66	75	128	215	248	425	503	762	1392		
	450	V 50	M _{2max}	10,4	17,3	33,5	61	62	119	127	224	388	418	766	832	1226	2281		
			P _{N1}	0,06	0,11	0,21	0,35	0,41	0,65	0,77	1,24	2,09	2,49	4,03	4,8	8,2	14,5 12		
			P _{N2}	0,03	0,07	0,13	0,22	0,26	0,43	0,51	0,86	1,48	1,76	2,94	3,49	6,2	11,2		
	355	V 40	M _{N2}	3,69	7,2	13,9	23,8	28,1	45,8	54	91	157	187	312	371	653	1189		
			M _{2max}	5,3	10,3	20,2	39,6	44,3	81	91	156	284	308	558	606	1062	1907		
			P _{N1}	0,07	0,12	0,22	0,38	0,45	0,71	0,84	1,41	2,37	2,82	4,72	5,6	4,4	8,6 6,9	15,2 11	
			P _{N2}	0,04	0,07	0,14	0,25	0,3	0,49	0,58	1	1,69	2,02	3,48	4,14	6,5	11,8		
			M _{N2}	4,37	8	15,2	27	32,1	52	62	107	182	217	374	446	703	1270		
			M _{2max}	6,9	13,4	26,3	48,5	53	94	102	178	316	343	614	667	1157	2072		
7,1	1 400	IV 200	P _{N1}	—	0,07	0,14	0,25	0,28	0,5	0,56	1,34	2,18	2,59	4,04	4,8	3,9	7,8 6	10,8	
			P _{N2}	—	0,04	0,08	0,15	0,17	0,31	0,35	0,92	1,53	1,82	2,91	3,47	5,8	8,5		
			M _{N2}	5,4	10,6	20,6	23	42,2	47,3	128	213	253	406	483	802	1181			
	1 120	IV 160	M _{2max}	7,7	15,2	29,6	33,1	61	68	212	376	409	725	787	1344	1865			
			P _{N1}	—	0,1	0,18	0,29	0,34	0,55	0,65	1,05	1,82	2,16	3,42	4,07	7	12,3 10		
			P _{N2}	—	0,06	0,11	0,18	0,21	0,35	0,42	0,7	1,24	1,47	2,39	2,84	5	9,1		
	900	IV 125	M _{N2}	7,3	14,3	24,7	28,9	47,6	57	95	165	195	323	385	677	1236			
			M _{2max}	10,3	20,3	39,6	44,4	81	91	160	297	322	572	621	1089	2007			
			P _{N1}	0,05	0,11	0,19	0,33	0,38	0,61	0,72	1,2	2,07	2,46	4,06	4,83	3,9	7,6 6,1	13,4 9,6	
	710	IV 100	P _{N2}	0,03	0,06	0,12	0,21	0,24	0,4	0,47	0,82	1,42	1,69	2,88	3,43	5,5	9,9		
			M _{N2}	3,77	8,3	15,4	28,5	32,4	54	64	110	188	223	388	462	748	1340		
			M _{2max}	5,3	13,7	26,9	51	55	97	106	186	337	366	655	712	1210	2220		
	560	IV 80	P _{N1}	0,05	0,12	0,22	0,36	0,41	0,66	0,79	1,36	2,25	2,68	4,12	4,9	3,9	7,9 6	11	
			P _{N2}	0,03	0,07	0,14	0,23	0,26	0,44	0,53	0,93	1,58	1,88	2,97	3,54	5,9	8,6		
			M _{N2}	4,49	9,8	18,4	31,7	36,1	61	73	128	213	253	406	483	802	1181		
	450	IV 63	M _{2max}	7,1	16,7	30,6	57	61	109	119	212	376	409	725	787	1344	1865		
			P _{N1}	0,07	0,13	0,24	0,33	0,35	0,63	0,71	1,22	2,11	2,41	3,95	4,66	7,8	13,8 10		
			P _{N2}	0,04	0,09	0,16	0,24	0,26	0,47	0,53	0,92	1,61	1,84	3,07	3,62	6,1	11,1		
	450	V 63	M _{N2}	5,8	11,5	21	32,5	34,6	63	71	124	214	244	414	488	826	1491		
			M _{2max}	9,8	19,6	36,6	52	58	106	119	208	385	413	746	810	1425	2605		
			P _{N1}	—	0,07	0,14	0,25	0,28	0,5	0,56	0,95	1,59	1,89	2,95	3,48	5,8	10,3		
	450	V 63	P _{N2}	—	0,04	0,08	0,15	0,17	0,32	0,35	0,62	1,07	1,28	2,05	2,42	4,15	7,7		
			M _{N2}	5,4	10,6	20,6	23	42,2	47,3	83	144	171	275	323	555	1030			
			M _{2max}	7,7	15,2	29,6	33,1	61	68	120	234	262	491	548	952	1769			
	355	IV 50	P _{N1}	0,07	0,11	0,2	0,35	0,37	0,66	0,75	1,25	2,14	2,45	4,1	4,79	7,1	12,9		
			P _{N2}	0,04	0,08	0,15	0,26	0,27	0,5	0,56	0,96	1,66	1,89	3,22	3,77	5,8	10,6		
			M _{N2}	6,1	10,4	19,6	35,6	37,4	68	77	131	222	254	440	515	786	1448		
	355	V 50	M _{2max}	10,6	17,7	34,3	64	64	123	130	235	400	423	809	875	1250	2329		
			P _{N1}	0,05	0,09	0,18	0,29	0,34	0,54	0,64	1,04	1,77	2,09	3,37	4,02	6,9	12,2 10		
			P _{N2}	0,03	0,05	0,11	0,18	0,21	0,42	0,64	1,07	1,23	1,45	2,4	2,86	5	9,2		
			M _{N2}	3,77	7,3	14,3	24,7	28,9	47,6	57	95	165	195	323	385	677	1236		
			M _{2max}	5,3	10,3	20,3	39,6	44,4	81	91	160	297	322	572	621	1089	2007		
5,6	1 400	IV 250	P _{N1}	—	—	—	—	—	—	—	0,98	1,67	1,98	3,28	3,91	6,2	11 8,5		
			P _{N2}	—	—	—	—	—	—	—	0,65	1,12	1,33	2,29	2,72	4,45	8		
			M _{N2}	—	—	—	—	—	—	—	114	195	230	398	474	775	1400		
	1 120	IV 200	M _{2max}	—	0,06	0,12	0,21	0,24	0,42	0,47	1,12	1,85	2,17	3,41	4,06	6,5 5,4	9,1		
			P _{N1}	—	0,03	0,06	0,12	0,14	0,25	0,28	0,76	1,27	1,49	2,42	2,88	4,74	7,1		
			P _{N2}	—	0,05	0,09	0,15	0,17	0,29	0,34	0,58	1,06	1,22	2,01	2,35	4,19	7,6		
	900	IV 160	M _{N2}	—	0,08	0,15	0,25	0,29	0,47	0,55	0,89	1,59	1,82	2,94	3,44	5,9	10,5 8,9		
			M _{2max}	—	0,05	0,09	0,15	0,17	0,29	0,34	0,58	1,06	1,22	2,01	2,35	4,19	7,6		
			P _{N1}	—	0,05	0,09	0,16	0,27	0,31	0,52	0,59	1	1,73	2,04	3,35	3,99	6,4	11,2 8,5	
	710	IV 125	P _{N2}	—	0,02	0,05	0,09	0,17	0,19	0,33	0,38	0,66	1,16	1,37	2,33	2,78	4,54	8,2	
			M _{N2}	—	0,08	0,15	0,25	0,29	0,45	0,53	0,89	1,59	1,95	230	398	474	775	1400	
			M _{2max}	—	0,04	0,09	0,16	0,27	0,31	0,52	0,59	1	1,73	2,04	3,35	3,99	6,4	11,2 8,5	

Values in red state nominal thermal power P_{tq} (ambient temperature 40 °C, continuous duty see ch. 4).

For n_1 higher than 1 400 min⁻¹ or lower than 355 min⁻¹ see ch. 6 and page 28.

1) Values given for train of 2-stage gears are nominal; see page 28 for effective transmission ratios.

2) M_{2max} represents maximum torque peak the gear reducer will withstand.





PalaDrive

Worm Gear Reducers and Gear Motors

SERIES W

7. Nominal powers and torques (gear reducers)



n_{N2} min ⁻¹	n_1	Train of gears i	P [kW] M [daNm]	Gear reducer size														
				01	02	03	04	05	06	07	08	09	10	11	12	13	14	
5,6	560	IV 100	P_{N1}	0,05	0,1	0,18	0,3	0,33	0,56	0,65	1,13	1,88	2,21	3,43	4,08	6,6	5,4	9,1
			P_{N2}	0,03	0,06	0,11	0,19	0,21	0,37	0,43	0,76	1,29	1,52	2,43	2,89	4,77	7,1	7,1
			M_{N2}	4,6	10	18,7	32,6	36,6	64	74	132	220	259	421	501	826	1228	1228
			M_{2max}	7,2	17,1	31,9	59	61	115	123	220	391	425	754	819	1430	1948	1948
	450	IV 80	P_{N1}	0,05	0,1	0,19	0,33	0,36	0,62	0,7	1,21	1,71	1,92	3,07	3,54	5,9	10,5	10,5
			P_{N2}	0,03	0,07	0,12	0,22	0,23	0,41	0,47	0,84	1,28	1,44	2,34	2,7	4,56	8,3	8,3
	355	IV 63	M_{N2}	5,6	10,8	20,2	36,7	39,4	70	80	141	212	238	395	454	768	1402	1402
			M_{2max}	9,2	18,7	35,1	66	67	123	134	250	329	369	661	740	1290	2484	2484
	355	V 63	P_{N1}	0,05	0,11	0,19	0,27	0,28	0,52	0,57	0,98	1,74	1,97	3,33	3,8	6,4	11,3	9,1
			P_{N2}	0,03	0,07	0,13	0,2	0,2	0,38	0,42	0,74	1,31	1,49	2,56	2,92	4,97	9	9
			M_{N2}	6	11,6	21,3	33,4	34,7	65	73	126	220	249	437	499	849	1531	1531
			M_{2max}	10,2	20,1	37,5	53	59	108	121	212	397	417	786	848	1481	2709	2709



Values in red state nominal thermal power P_{t0} (ambient temperature 40 °C, continuous duty see ch. 4).For n , higher than 1 400 min⁻¹ or lower than 355 min⁻¹ see ch. 6 and page 28.

1) Values given for train of 2-stage gears are nominal; see page 28 for effective transmission ratios.

2) M_{2max} represents maximum torque peak the gear reducer will withstand.



7. Nominal powers and torques (gear reducers)



		Train of gears i 1)	P [kW] M [daNm m] 2)	Gear reducer size													
n _{N2} min ⁻¹	n ₁ min ⁻¹			01	02	03	04	05	06	07	08	09	10	11	12	13	14
3,55	355	IV 100	P _{N1} P _{N2} M _{N2} M _{2max}	0,03 0,02 4,98 7,4	0,07 0,04 10,4 18,2	0,12 0,07 19,3 34	0,2 0,13 34,6 62	0,22 0,14 37,4 62	0,39 0,25 68 122	0,44 0,28 77 129	0,77 0,5 136 236	1,33 0,88 237 426	1,52 1,01 270 450	2,46 1,68 459 826	2,83 1,93 528 893	4,58 3,21 876 1544	6,4 4,82 1318 2015
2,8	900	IV 315	P _{N1} P _{N2} M _{N2} M _{2max}	—	—	—	—	—	—	—	0,51 0,31 105 172	0,94 0,59 198 337	1,05 0,66 222 377	1,77 1,14 386 696	2,03 1,31 443 754	3,37 2,23 755 1331	6 4,14 1402 2463
	710	IV 250	P _{N1} P _{N2} M _{N2} M _{2max}	—	—	—	—	—	—	—	0,57 0,36 122 218	1,01 0,64 219 395	1,14 0,72 246 412	1,94 1,28 438 778	2,22 1,46 501 850	3,62 2,44 838 1473	6,5 4,48 1540 2713
	560	IV 200	P _{N1} P _{N2} M _{N2} M _{2max}	—	0,03 0,02 5,7 8,1	0,07 0,03 11,3 16	0,12 0,06 22,1 31,1	0,13 0,07 24,7 34,8	0,24 0,13 45,3 64	0,27 0,15 51 72	0,62 0,4 0,71 242	1,09 0,78 248 446	1,19 1,36 271 460	2,02 1,54 472 840	2,29 1,54 536 911	3,71 2,56 891 1622	5,2 3,85 1343 2044
	450	IV 160	P _{N1} P _{N2} M _{N2} M _{2max}	—	0,04 0,02 7,9 11,1	0,09 0,05 15,5 21,8	0,15 0,09 29 42,6	0,16 0,09 30,7 47,7	0,28 0,17 56 87	0,32 0,19 63 98	0,52 0,31 105 172	0,96 0,6 198 337	1,07 0,67 222 377	1,78 1,15 386 696	2,04 1,32 443 754	3,39 2,24 755 1331	6,1 4,16 1402 2463
	355	IV 125	P _{N1} P _{N2} M _{N2} M _{2max}	0,02 0,01 4,05 5,7	0,05 0,03 0,05 14,7	0,09 0,05 0,1 28,9	0,16 0,1 32,6 56	0,16 0,1 33,8 57	0,3 0,19 64 114	0,34 0,21 122 119	0,57 0,36 219 218	1,03 0,65 246 395	1,16 0,73 438 412	1,95 1,28 438 778	2,23 1,47 501 850	3,64 2,45 838 1473	6,5 4,51 1540 2713
2,24	710	IV 315	P _{N1} P _{N2} M _{N2} M _{2max}	—	—	—	—	—	—	—	0,43 0,26 110 174	0,78 0,48 203 342	0,85 0,52 223 378	1,5 1,07 405 718	1,7 1,07 460 774	2,77 1,8 772 1397	5 3,36 1444 2554
	560	IV 250	P _{N1} P _{N2} M _{N2} M _{2max}	—	—	—	—	—	—	—	0,46 0,28 124 223	0,85 0,53 229 413	0,92 0,57 248 422	1,61 1,03 451 790	1,82 1,03 510 850	2,96 1,96 853 1536	5,3 3,59 1562 2812
	450	IV 200	P _{N1} P _{N2} M _{N2} M _{2max}	—	0,03 0,01 5,8 8,2	0,05 0,03 11,5 16,2	0,1 0,05 22,4 31,6	0,11 0,06 25,1 35,4	0,2 0,11 46,1 65	0,22 0,12 52 73	0,5 0,32 138 249	0,91 0,59 0,63 458	0,98 0,63 272 463	1,72 1,14 494 850	1,94 1,28 556 921	3,15 2,13 923 1662	4,27 3,15 1364 2073
	355	IV 160	P _{N1} P _{N2} M _{N2} M _{2max}	—	0,04 0,02 8 11,3	0,07 0,04 15,7 22,1	0,12 0,07 29,5 43,2	0,13 0,07 31,1 48,4	0,23 0,13 58 89	0,26 0,15 110 99	0,43 0,26 203 174	0,79 0,48 0,87 342	0,87 0,53 223 378	1,51 1,08 405 718	1,71 1,28 460 774	2,78 1,81 772 1397	5 3,38 1444 2554
1,8	560	IV 315	P _{N1} P _{N2} M _{N2} M _{2max}	—	—	—	—	—	—	—	0,35 0,21 112 177	0,64 0,39 209 347	0,68 0,41 224 381	1,24 0,76 416 728	1,39 0,86 469 774	2,29 1,46 795 1426	4,13 2,73 1484 2671
	450	IV 250	P _{N1} P _{N2} M _{N2} M _{2max}	—	—	—	—	—	—	—	0,38 0,24 128 226	0,71 0,44 236 424	0,75 0,46 249 424	1,35 0,86 465 800	1,52 0,96 522 850	2,49 1,61 874 1573	4,5 3 1628 2931
	355	IV 200	P _{N1} P _{N2} M _{N2} M _{2max}	—	0,02 0,01 5,9 8,4	0,04 0,02 11,7 16,5	0,08 0,04 22,8 32,1	0,09 0,05 25,5 35,9	0,16 0,09 46,7 66	0,18 0,1 52 74	0,42 0,26 144 252	0,75 0,48 263 468	0,79 0,5 275 467	1,39 1,02 500 850	1,56 1,02 560 921	2,62 1,75 961 1730	3,44 2,52 1384 2102
1,4	450	IV 315	P _{N1} P _{N2} M _{N2} M _{2max}	—	—	—	—	—	—	—	0,29 0,17 116 179	0,54 0,32 216 352	0,56 0,34 226 384	1,03 0,63 428 738	1,15 0,7 477 774	1,95 1,22 827 1446	3,5 2,26 1532 2757
	355	IV 250	P _{N1} P _{N2} M _{N2} M _{2max}	—	—	—	—	—	—	—	0,32 0,19 131 226	0,58 0,36 243 428	0,6 0,37 251 427	1,11 0,7 481 810	1,24 0,78 534 850	2,03 1,3 894 1597	3,71 2,43 1666 2995
1,12	355	IV 315	P _{N1} P _{N2} M _{N2} M _{2max}	—	—	—	—	—	—	—	0,24 0,14 120 181	0,45 0,26 225 356	0,45 0,27 229 385	0,85 0,51 442 748	0,94 0,57 489 774	1,59 1,26 845 1465	2,88 2,26 1579 2769

Values in red state nominal thermal power P_{tq} (ambient temperature 40 °C, continuous duty see ch. 4).For n_1 higher than 1 400 min⁻¹ or lower than 355 min⁻¹ see ch. 6 and page 28.

1) Values given for train of 2-stage gears are nominal; see page 28 for effective transmission ratios.

2) M_{2max} represents maximum torque peak the gear reducer will withstand.



**Summary of transmission ratios i and torques valid
for $n_1 \leq 90 \text{ min}^{-1}$**

M_{N2} e $M_{2\max}$ sono rispettivamente il momento torcente nominale e di picco validi per $n_1 \leq 90 \text{ min}^{-1}$.

W 1

i	M [daN m]	Gear reducer size													
		01	02	03	04	05	06	07	08	09	10	11	12	13	14
10	M_{N2} $M_{2\max}$	6,1 11 11	11,1 20 20	20,4 36,7 37,3	37,5 68 67	38,7 68 67	72 129 131	80 136 137	132 238 250	229 411 410	252 428 451	434 781 842	493 888 902	— — 1 537	— — —
13	M_{N2} $M_{2\max}$	6,1 11	11,2 20,1	20,7 37,3	37,3 67	38,5 67	73 131	81 137	139 243	243 410	265 451	468 842	530 902	886 1 537	— —
16	M_{N2} $M_{2\max}$	5,9 9,2	10,7 18	19,9 35,4	36,6 66	37,5 66	70 126	78 132	134 241	233 420	255 434	464 835	526 894	824 1 274	1 495 2 374
20	M_{N2} $M_{2\max}$	6,4 ¹⁾ 11,5	11,6 ¹⁾ 20,9	21,3 ¹⁾ 38,4	34,9 53	35,4 60	67 110	74 123	127 216	231 416	252 428	450 810	510 866	863 1 554	1 563 2 813
25	M_{N2} $M_{2\max}$	6,2 10,9	11,3 20,1	20,8 37,4	39,4 ¹⁾ 71	40,6 ¹⁾ 71	74 ¹⁾ 132	82 ¹⁾ 140	146 ¹⁾ 263	225 341	242 381	427 683	482 766	817 1 335	1 508 2 605
32	M_{N2} $M_{2\max}$	5,9 9,9	10,6 18,6	19,6 34,9	36,1 65	37,8 65	70 125	78 131	139 242	248 ¹⁾ 446	271 ¹⁾ 460	472 ¹⁾ 840	536 ¹⁾ 911	891 ¹⁾ 1 622	1 343 2 044
40	M_{N2} $M_{2\max}$	5,4 7,7	9,8 14,9	17,9 29,3	33,5 57	34,4 58	65 117	72 119	124 223	229 413	248 422	451 790	510 850	853 1 536	1 562 ¹⁾ 2 812
50	M_{N2} $M_{2\max}$	4,17 5,9	8,1 11,4	15,9 22,4	30 43,8	31,2 49	60 90	66 100	112 177	209 347	224 381	416 728	469 774	795 1 426	1 484 2 671
63	M_{N2} $M_{2\max}$	— —	6 8,5	11,8 16,7	23 32,5	25,6 36,4	47,3 67	53 75	93 131	182 257	201 288	379 540	426 604	707 1 054	1 353 2 056

W 2

i _N	Gear reducer size					Gear reducer size												
	01	02, 03, 09, 10	04, 05, 06, 07, 08	11, 12, 13, 14	M													
		i ₂₎	i ₂₎	i ₂₎	[daN m]	01	02	03	04,05	06	07	08	09,10	11	12	13	14	
50	51,8 2,59	49,9 3,12 ³⁾	50,9 3,18	50,8 3,17	M_{N2} $M_{2\max}$	7,3 11,5	13 19,5	24,1 37,7	44,3 70	78 133	84 138	144 250	272 455	487 880	540 953	824 1383	1 495 2 406	
63	64,8	62,4	63,6	63,5	M_{N2} $M_{2\max}$	7,1 10,9	13,7 21,4	25 40,2	41 65	76 119	86 128	151 233	277 453	487 880	540 910	975 1 697	1 718 2 863	
80	82,9	78	79,5	79,3	M_{N2} $M_{2\max}$	6,7 10	13,3 20,2	24,4 38	47,5 73	80 133	90 141	160 268	260 384	487 735	540 824	925 1 597	1 743 2 802	
100	104	99,8	102	102	M_{N2} $M_{2\max}$	5,7 8,1	12,6 18,6	23,2 34,9	43,3 66	78 128	88 131	155 252	295 ¹⁾ 468	500 850	560 921	1 000 1 736	1 438 2 227	
125	130	125	127	127	M_{N2} $M_{2\max}$	4,38 6,2	11,3 15,9	21,2 31,2	40,6 60	75 119	85 124	146 226	273 428	487 820	540 850	975 1 597	1 800 ¹⁾ 3 034	
160	—	156	159	159	M_{N2} $M_{2\max}$	— —	8,6 12,1	16,9 23,8	33 49	68 95	76 107	133 188	252 385	487 774	540 774	925 1 470	1 748 2 769	
200	—	197	200	—	M_{N2} $M_{2\max}$	— —	6,3 8,9	12,5 17,7	26,4 38,5	50 71	56 79	— —	— —	— —	— —	— —	— —	
200	—	203 6,36	204 6,38	204 6,38	M_{N2} $M_{2\max}$	— —	— —	— —	— —	— —	— —	156 150	300 289	500 487	560 540	1 000 975	1 483 1 900	
250	—	254	255	255	M_{N2} $M_{2\max}$	— —	— —	— —	— —	— —	— —	137 193	268 385	487 774	540 774	975 1 470	1 850 2 769	
315	—	318	319	319	M_{N2} $M_{2\max}$	— —	— —	— —	— —	— —	— —	137 193	268 385	487 774	540 774	975 1 470	1 850 2 769	


1) For these transmission ratios (which will transmit higher torques at lower speeds) torque increases further as n_1 decreases, as stated in table A ch. 11; for sizes 32 and 40 consult us.

2) Gear ratio of input cylindrical gear pair.

3) For sizes 09 and 10 it is equal to 3,13.



9. Manufacturing programme (gearmotors)



P₁ kW	n₂ min ⁻¹	P₂ kW	M₂ daN m	fs	Gear reducer - Motor		i
					2)		
0,09	2,06	0,05	23,3	0,8	MW 033 - 63 A 6	10,9 x40	
	2,58	0,05	19,7	1	MW 033 - 63 A 6	10,9 x32	
	3,3	0,06	15,9	0,71	MW 023 - 63 A 6	10,9 x25	
	3,3	0,06	16,2	1,32	MW 033 - 63 A 6	10,9 x25	
	4,12	0,06	13,3	0,9	MW 023 - 63 A 6	10,9 x20	
	4,12	0,06	13,5	1,6	MW 033 - 63 A 6	10,9 x20	
	4,08	0,05	11,3	1	MW 032 - 63 A 6	3,5 x63	
	5,07	0,06	10,6	1	MW 023 - 63 A 6	7,11 x25	
	5,14	0,05	9,4	0,8	MW 022 - 63 A 6	3,5 x50	
	5,07	0,06	10,8	1,9	MW 033 - 63 A 6	7,11 x25	
	5,14	0,05	9,6	1,5	MW 032 - 63 A 6	3,5 x50	
	6,33	0,06	8,8	1,32	MW 023 - 63 A 6	7,11 x20	
	6,43	0,05	8	1,06	MW 022 - 63 A 6	3,5 x40	
	6,43	0,06	8,2	1,9	MW 032 - 63 A 6	3,5 x40	
	7,92	0,07	7,9	1,32	MW 023 - 63 A 6	7,11 x16	
	8,04	0,06	6,8	1,4	MW 022 - 63 A 6	3,5 x32	
	8,04	0,06	6,9	2,65	MW 032 - 63 A 6	3,5 x32	
	8,68	0,05	6	0,71	MW 012 - 63 A 6	2,59 x40	
	10,3	0,06	5,5	1,8	MW 022 - 63 A 6	3,5 x25	
	10,9	0,06	5,1	1,06	MW 012 - 63 A 6	2,59 x32	
	12,9	0,06	4,59	2,36	MW 022 - 63 A 6	3,5 x20	
	13,9	0,06	4,16	1,32	MW 012 - 63 A 6	2,59 x25	
	14,3	0,05	3,62	1,4	MW 021 - 63 A 6	63	
	17,4	0,06	3,45	1,6	MW 012 - 63 A 6	2,59 x20	
	18	0,06	3	1,12	MW 011 - 63 A 6	50	
	18	0,06	3,08	2,12	MW 021 - 63 A 6	50	
	21,7	0,07	3,02	1,7	MW 012 - 63 A 6	2,59 x16	
	22,5	0,06	2,53	1,6	MW 011 - 63 A 6	40	
	28,1	0,06	2,12	2	MW 011 - 63 A 6	32	
	36	0,07	1,73	2,5	MW 011 - 63 A 6	25	
0,12	2,58	0,07	26,3	0,75	MW 033 - 63 B 6	10,9 x32	
	3,21	0,07	20,6	0,8	MW 033 - 63 A 4	10,9 x40	
	3,3	0,07	21,6	1	MW 033 - 63 B 6	10,9 x25	
	4,01	0,07	17,4	1,12	MW 033 - 63 A 4	10,9 x32	
	4,12	0,08	18	1,25	MW 033 - 63 B 6	10,9 x20	
	4,08	0,06	15	0,75	MW 032 - 63 B 6	3,5 x63	
	5,13	0,08	14	0,8	MW 023 - 63 A 4	10,9 x25	
	5,13	0,08	14,3	1,4	MW 033 - 63 A 4	10,9 x25	
	5,14	0,07	12,8	1,18	MW 032 - 63 B 6	3,5 x50	
	6,41	0,08	11,7	1	MW 023 - 63 A 4	10,9 x20	
	6,43	0,07	10,7	0,8	MW 022 - 63 B 6	3,5 x40	
	6,41	0,08	11,8	1,8	MW 033 - 63 A 4	10,9 x20	
	6,35	0,07	10,2	1,06	MW 032 - 63 A 4	3,5 x63	
	6,43	0,07	10,9	1,4	MW 032 - 63 B 6	3,5 x40	
	7,88	0,08	9,3	1,12	MW 023 - 63 A 4	7,11 x25	
	8	0,07	8,4	0,85	MW 022 - 63 A 4	3,5 x50	
	8,04	0,08	9	1,06	MW 022 - 63 B 6	3,5 x32	
	7,88	0,08	9,5	2,12	MW 033 - 63 A 4	7,11 x25	
	8	0,07	8,7	1,6	MW 032 - 63 A 4	3,5 x50	
	8,04	0,08	9,2	2	MW 032 - 63 B 6	3,5 x32	
	9,85	0,08	7,7	1,4	MW 023 - 63 A 4	7,11 x20	
	10	0,07	7,1	1,12	MW 022 - 63 A 4	3,5 x40	
	10,3	0,08	7,4	1,32	MW 022 - 63 B 6	3,5 x25	
	10	0,08	7,3	2	MW 032 - 63 A 4	3,5 x40	
	10,9	0,08	6,7	0,8	MW 012 - 63 B 6	2,59 x32	
	12,3	0,09	6,9	1,4	MW 023 - 63 A 4	7,11 x16	
	12,5	0,08	6	1,5	MW 022 - 63 A 4	3,5 x32	
	12,9	0,08	6,1	1,7	MW 022 - 63 B 6	3,5 x20	
	13,5	0,08	5,4	0,8	MW 012 - 63 A 4	2,59 x40	
	13,9	0,08	5,5	0,95	MW 012 - 63 B 6	2,59 x25	
	14,3	0,07	4,83	1,06	MW 021 - 63 B 6	63	
	14,3	0,07	4,99	2	MW 031 - 63 B 6	63	
	16,9	0,08	4,51	1,06	MW 012 - 63 A 4	2,59 x32	
	16	0,08	4,94	1,9	MW 022 - 63 A 4	3,5 x25	
	17,4	0,08	4,6	1,18	MW 012 - 63 B 6	2,59 x20	


P₁ kW	n₂ min ⁻¹	P₂ kW	M₂ daN m	fs	Gear reducer - Motor		i
					2)		
0,12	18	0,08	4	0,85	MW 011- 63 B 6	50	
	18	0,08	4,1	1,6	MW 021- 63 B 6	50	
	20	0,09	4,08	2,5	MW 022- 63 A 4	3,5 x20	
	21,6	0,08	3,7	1,32	MW 012- 63 A 4	2,59 x25	
	22,5	0,08	3,37	1,18	MW 011- 63 B 6	40	
	22,2	0,08	3,29	1,5	MW 021- 63 A 4	63	
	22,5	0,08	3,44	2,12	MW 021- 63 B 6	40	
	27	0,09	3,06	1,7	MW 012 - 63 A 4	2,59 x20	
	28	0,08	2,7	1,18	MW 011 - 63 A 4	50	
	28,1	0,08	2,83	1,5	MW 011 - 63 B 6	32	
	28	0,08	2,77	2,12	MW 021 - 63 A 4	50	
	33,8	0,09	2,65	1,8	MW 012 - 63 A 4	2,59 x16	
	35	0,08	2,27	1,6	MW 011 - 63 A 4	40	
	36	0,09	2,31	1,9	MW 011 - 63 B 6	25	
	35	0,08	2,32	2,8	MW 021 - 63 A 4	40	
	43,8	0,09	1,89	2	MW 011 - 63 A 4	32	
	45	0,09	1,91	2,36	MW 011 - 63 B 6	20	
	56	0,09	1,54	2,5	MW 011 - 63 A 4	25	
	70	0,09	1,27	3,15	MW 011 - 63 A 4	20	
	87,5	0,1	1,08	3,35	MW 011 - 63 A 4	16	
	108	0,1	0,89	4	MW 011 - 63 A 4	13	
	140	0,1	0,7	4,75	MW 011 - 63 A 4	10	
0,18	1,49	0,1	65	0,95	MW 063 - 71 A 6	12,1 x50	
	1,49	0,1	65	1,06	MW 073 - 71 A 6	12,1 x50	
	1,86	0,11	55	1,25	MW 063 - 71 A 6	12,1 x40	
	1,86	0,11	55	1,32	MW 073 - 71 A 6	12,1 x40	
	2,33	0,11	44,7	0,85	MW 043 - 71 A 6	12,1 x32	
	2,33	0,11	45,8	1,6	MW 063 - 71 A 6	12,1 x32	
	2,33	0,11	45,8	1,7	MW 073 - 71 A 6	12,1 x32	
	2,98	0,11	36,6	1,12	MW 043 - 71 A 6	12,1 x25	
	2,98	0,12	37,6	2	MW 063 - 71 A 6	12,1 x25	
	2,98	0,12	37,6	2,24	MW 073 - 71 A 6	12,1 x25	
	3,56	0,12	31,1	1,25	MW 043 - 71 A 6	10,1 x25	
	3,56	0,12	31,7	2,36	MW 063 - 71 A 6	10,1 x25	
	3,56	0,12	31,7	2,65	MW 073 - 71 A 6	10,1 x25	
	4,01	0,11	26	0,75	MW 033 - 63 B 4	10,9 x32	
	3,76	0,1	25,8	0,85	MW 042 - 71 A 6	3,8 x63	
	3,76	0,1	25,8	0,95	MW 052 - 71 A 6	3,8 x63	
	3,76	0,11	26,7	1,7	MW 062 - 71 A 6	3,8 x63	
	4,55	0,11	24	0,85	MW 033 - 71 A 6	7,91 x25	
	4,42	0,11	24,5	1,4	MW 043 - 71 A 6	6,36 x32	
	4,74	0,11	21,9	1,25	MW 042 - 71 A 6	3,8 x50	
	4,74	0,11	21,9	1,32	MW 052 - 71 A 6	3,8 x50	
	4,74	0,11	22,6	2,36	MW 062 - 71 A 6	3,8 x50	
	5,13	0,11	21,4	0,95	MW 033 - 63 B 4	10,9 x25	
	5,69	0,12	19,9	1,06	MW 033 - 71 A 6	7,91 x20	
	5,66	0,12	20	1,8	MW 043 - 71 A 6	6,36 x25	
	5,92	0,11	18,5	1,6	MW 042 - 71 A 6	3,8 x40	
	5,92	0,11	18,5	1,8	MW 052 - 71 A 6	3,8 x40	
	6,41	0,12	17,7	1,18	MW 033 - 63 B 4	10,9 x20	
	6,35	0,1	15,3	0,71	MW 032 - 63 B 4	3,5 x63	
	6,99	0,12	15,9	1,25	MW 033 - 71 A 6	5,15 x25	
	7,1	0,11	14,5	1	MW 032 - 71 A 6	2,54 x50	
	7,4	0,12	15,4	2	MW 042 - 71 A 6	3,8 x32	
	7,88	0,12	14	0,75	MW 023 - 63 B 4	7,11 x25	
	7,88	0,12	14,2	1,4	MW 033 - 63 B 4	7,11 x25	
	8	0,11	13	1,06	MW 032 - 63 B 4	3,5 x50	
	8,87	0,11	12	0,67	MW 022 - 71 A 6	2,54 x40	
	8,74	0,12	13,2	1,6	MW 033 - 71 A 6	5,15 x20	
	8,87	0,11	12,3	1,25	MW 032 - 71 A 6	2,54 x40	
	8,84	0,12	13,2	2,24	MW 042 - 71 A 6	3,18 x32	
	9,85	0,12	11,6	0,95	MW 023 - 63 B 4	7,11 x20	
	10	0,11	10,7	0,75	MW 022 - 63 B 4	3,5 x40	
	9,85	0,12	11,8	1,7	MW 033 - 63 B 4	7,11 x20	

1) Power valid for continuous duty S1; **increase** possible for S2 ... S10 (see ch. 2b) in which case P₂, M₂ increase and fs decreases proportionately

2) For complete designation when ordering see ch. 3.



9. Manufacturing programme (gearmotors)



P₁ kW	n₂ min ⁻¹	P ₂ kW	M ₂ daN m	fs	Gear reducer - Motor				i
1)					2)				
0,18	10	0,12	11	1,32	MW	032 - 63 B	4	3,5 x40	
	11,1	0,12	10,1	0,9	MW	022 - 71 A	6	2,54x32	
	11,1	0,12	10,3	1,7	MW	032 - 71 A	6	2,54x32	
	12,3	0,13	10,3	0,95	MW	023 - 63 B	4	7,11x16	
	12,5	0,12	9,1	1	MW	022 - 63 B	4	3,5 x32	
	12,5	0,12	9,2	1,8	MW	032 - 63 B	4	3,5 x32	
	14,2	0,12	8,3	1,18	MW	022 - 71 A	6	2,54x25	
	14,3	0,11	7,2	0,71	MW	021 - 71 A	6	63	
	14,2	0,13	8,4	2,12	MW	032 - 71 A	6	2,54x25	
	14,3	0,11	7,5	1,32	MW	031 - 71 A	6	63	
	16,9	0,12	6,8	0,71	MW	012 - 63 B	4	2,59x32	
	16	0,12	7,4	1,25	MW	022 - 63 B	4	3,5 x25	
	16	0,13	7,6	2,36	MW	032 - 63 B	4	3,5 x25	
	17,7	0,13	6,8	1,5	MW	022 - 71 A	6	2,54x20	
	18	0,12	6,2	1,06	MW	021 - 71 A	6	50	
	17,7	0,13	7	2,65	MW	032 - 71 A	6	2,54x20	
	18	0,12	6,3	2	MW	031 - 71 A	6	50	
	20	0,13	6,1	1,6	MW	022 - 63 B	4	3,5 x20	
	21,6	0,13	5,5	0,9	MW	012 - 63 B	4	2,59x25	
	22,2	0,14	6	1,5	MW	022 - 71 A	6	2,54x16	
	22,2	0,11	4,93	1	MW	021 - 63 B	4	63	
	22,5	0,12	5,2	1,4	MW	021 - 71 A	6	40	
	22,2	0,12	5,1	1,9	MW	031 - 63 B	4	63	
	25	0,14	5,3	1,7	MW	022 - 63 B	4	3,5 x16	
	27	0,13	4,59	1,12	MW	012 - 63 B	4	2,59x20	
	28	0,12	4,05	0,8	MW	011 - 63 B	4	50	
	28,1	0,12	4,24	1	MW	011 - 71 A	6	32	
	28	0,12	4,16	1,4	MW	021 - 63 B	4	50	
	28,1	0,13	4,33	1,8	MW	021 - 71 A	6	32	
	28	0,13	4,28	2,65	MW	031 - 63 B	4	50	
	33,8	0,14	3,98	1,18	MW	012 - 63 B	4	2,59x16	
	35	0,12	3,4	1,06	MW	011 - 63 B	4	40	
	36	0,13	3,47	1,32	MW	011 - 71 A	6	25	
	35	0,13	3,48	1,9	MW	021 - 63 B	4	40	
	36	0,13	3,51	2,36	MW	021 - 71 A	6	25	
	43,8	0,13	2,84	1,32	MW	011 - 63 B	4	32	
	45	0,13	2,86	1,6	MW	011 - 71 A	6	20	
	43,8	0,13	2,9	2,5	MW	021 - 63 B	4	32	
	56	0,14	2,31	1,7	MW	011 - 63 B	4	25	
	56	0,14	2,34	3,15	MW	021 - 63 B	4	25	
	70	0,14	1,9	2,12	MW	011 - 63 B	4	20	
	87,5	0,15	1,61	2,24	MW	011 - 63 B	4	16	
	108	0,15	1,34	2,65	MW	011 - 63 B	4	13	
	140	0,15	1,05	3,15	MW	011 - 63 B	4	10	
	175	0,15	0,84	3,35	MW	011 - 63 A	2	16	
	200	0,16	0,76	3,75	MW	011 - 63 B	4	7	
	215	0,16	0,69	4	MW	011 - 63 A	2	13	
	280	0,16	0,54	4,75	MW	011 - 63 A	2	10	



P₁ kW	n₂ min ⁻¹	P ₂ kW	M ₂ daN m	fs	Gear reducer - Motor				i
1)					2)				
0,25	1,49	0,14	90	0,67	MW	063 - 71 B	6	12,1 x50	
	1,49	0,14	90	0,75	MW	073 - 71 B	6	12,1 x50	
	1,86	0,15	77	0,9	MW	063 - 71 B	6	12,1 x40	
	1,86	0,15	77	0,95	MW	073 - 71 B	6	12,1 x40	
	2,32	0,15	60	0,95	MW	063 - 71 A	4	12,1 x50	
	2,32	0,15	60	1,06	MW	073 - 71 A	4	12,1 x50	
	2,33	0,16	64	1,12	MW	063 - 71 B	6	12,1 x32	
	2,33	0,16	64	1,25	MW	073 - 71 B	6	12,1 x32	
	2,98	0,16	51	0,8	MW	043 - 71 B	6	12,1 x25	
	2,89	0,15	51	1,25	MW	063 - 71 A	4	12,1 x40	
	2,89	0,15	51	1,4	MW	073 - 71 A	4	12,1 x40	
	2,98	0,16	52	1,5	MW	063 - 71 B	6	12,1 x25	
	2,98	0,16	52	1,6	MW	073 - 71 B	6	12,1 x25	
	3,62	0,16	41	0,85	MW	043 - 71 A	4	12,1 x32	
	3,62	0,16	41	0,9	MW	053 - 71 A	4	12,1 x32	
	3,56	0,16	43,2	0,9	MW	043 - 71 B	6	10,1 x25	
	3,62	0,16	41,9	1,6	MW	063 - 71 A	4	12,1 x32	
	0,25	1,49	0,14	90	MW	063 - 71 B	6	12,1 x50	
	1,49	0,14	90	0,75	MW	073 - 71 B	6	12,1 x50	
	1,86	0,15	77	0,9	MW	063 - 71 B	6	12,1 x40	
	1,86	0,15	77	0,95	MW	073 - 71 B	6	12,1 x40	
	2,32	0,15	60	0,95	MW	063 - 71 A	4	12,1 x50	
	2,32	0,15	60	1,06	MW	073 - 71 A	4	12,1 x50	
	2,33	0,16	64	1,12	MW	063 - 71 B	6	12,1 x32	
	2,33	0,16	64	1,25	MW	073 - 71 B	6	12,1 x32	
	2,98	0,16	51	0,8	MW	043 - 71 B	6	12,1 x25	
	2,89	0,15	51	1,25	MW	063 - 71 A	4	12,1 x40	
	2,89	0,15	51	1,4	MW	073 - 71 A	4	12,1 x40	
	2,98	0,16	52	1,5	MW	063 - 71 B	6	12,1 x25	
	2,98	0,16	52	1,6	MW	073 - 71 B	6	12,1 x25	
	3,62	0,16	41	0,85	MW	043 - 71 A	4	12,1 x32	
	3,62	0,16	41	0,9	MW	053 - 71 A	4	12,1 x32	
	3,56	0,16	43,2	0,9	MW	043 - 71 B	6	10,1 x25	
	3,62	0,16	41,9	1,6	MW	063 - 71 A	4	12,1 x32	

1) Powers valid for continuous duty S1; **increase** possible for S2 ... S10 (see ch. 2b) in which case P₂, M₂ increase and fs decreases proportionately

2) For complete designation when ordering see ch. 3.



9. Manufacturing programme (garmotors)




P₁ kW	n₂ min ⁻¹	P₂ kW	M₂ daN m	fs	Gear reducer - Motor				i
1)					2)				
0,25	22,1	0,18	7,7	1,18	MW	022 - 71 A	4	2,54x25	
	22,2	0,16	6,9	0,71	MW	021 - 63 C	4	63	
	22,2	0,16	6,9	0,71	MW	021 - 71 A	4	63	
	22,5	0,17	7,2	1	MW	021 - 71 B	6	40	
	22,1	0,18	7,8	2,12	MW	032 - 71 A	4	2,54x25	
	22,2	0,16	7,1	1,4	MW	031 - 71 A	4	63	
	22,5	0,17	7,4	1,8	MW	031 - 71 B	6	40	
	22,2	0,17	7,5	2,36	MW	041 - 71 A	4	63	
	25	0,19	7,4	1,25	MW	022 - 63 C	4	3,5 x16	
	27	0,18	6,4	0,8	MW	012 - 63 C	4	2,59x20	
	28,1	0,17	5,9	0,75	MW	011 - 71 B	6	32	
	27,6	0,18	6,3	1,5	MW	022 - 71 A	4	2,54x20	
	28	0,17	5,8	1,06	MW	021 - 63 C	4	50	
	28	0,17	5,8	1,06	MW	021 - 71 A	4	50	
	28,1	0,18	6	1,32	MW	021 - 71 B	6	32	
	27,6	0,19	6,4	2,65	MW	032 - 71 A	4	2,54x20	
	28	0,17	5,9	1,9	MW	031 - 71 A	4	50	
	28,1	0,18	6,1	2,36	MW	031 - 71 B	6	32	
	33,8	0,2	5,5	0,85	MW	012 - 63 C	4	2,59x16	
	35	0,17	4,73	0,75	MW	011 - 63 C	4	40	
	36	0,18	4,81	0,9	MW	011 - 71 B	6	25	
	34,5	0,2	5,5	1,6	MW	022 - 71 A	4	2,54x16	
	35	0,18	4,83	1,32	MW	021 - 63 C	4	40	
	35	0,18	4,83	1,32	MW	021 - 71 A	4	40	
	36	0,18	4,88	1,7	MW	021 - 71 B	6	25	
	35	0,18	4,97	2,36	MW	031 - 71 A	4	40	
	43,8	0,18	3,94	0,95	MW	011 - 63 C	4	32	
	43,8	0,18	3,94	0,95	MW	011 - 71 A	4	32	
	45	0,19	3,97	1,18	MW	011 - 71 B	6	20	
	43,8	0,18	4,03	1,8	MW	021 - 63 C	4	32	
	43,8	0,18	4,03	1,8	MW	021 - 71 A	4	32	
	45	0,19	4,01	2	MW	021 - 71 B	6	20	
	56	0,19	3,21	1,18	MW	011 - 63 C	4	25	
	56	0,19	3,21	1,18	MW	011 - 71 A	4	25	
	56	0,19	3,26	2,24	MW	021 - 63 C	4	25	
	56	0,19	3,26	2,24	MW	021 - 71 A	4	25	
	70	0,19	2,64	1,5	MW	011 - 63 C	4	20	
	70	0,19	2,64	1,5	MW	011 - 71 A	4	20	
	70	0,2	2,67	2,65	MW	021 - 71 A	4	20	
	87,5	0,21	2,24	1,6	MW	011 - 63 C	4	16	
	87,5	0,21	2,24	1,6	MW	011 - 71 A	4	16	
	87,5	0,21	2,27	2,8	MW	021 - 71 A	4	16	
	108	0,21	1,86	1,9	MW	011 - 63 C	4	13	
	108	0,21	1,86	1,9	MW	011 - 71 A	4	13	
	140	0,21	1,45	2,24	MW	011 - 63 C	4	10	
	140	0,21	1,45	2,24	MW	011 - 71 A	4	10	
	175	0,21	1,16	2,5	MW	011 - 63 B	2	16	
	200	0,22	1,05	2,65	MW	011 - 63 C	4	7	
	200	0,22	1,05	2,65	MW	011 - 71 A	4	7	
	215	0,22	0,96	2,8	MW	011 - 63 B	2	13	
	280	0,22	0,75	3,55	MW	011 - 63 B	2	10	
	400	0,22	0,54	4,25	MW	011 - 63 B	2	7	
0,37	1,49	0,22	138	0,85	MW	083 - 80 A	6	12,1 x50	
	1,86	0,23	116	1,12	MW	083 - 80 A	6	12,1 x40	
	2,32	0,22	89	0,67	MW	063 - 71 B	4	12,1 x50	
	2,32	0,22	89	0,71	MW	073 - 71 B	4	12,1 x50	
	2,33	0,23	94	0,75	MW	063 - 71 C	6	12,1 x32	
	2,33	0,23	94	0,85	MW	073 - 71 C	6	12,1 x32	
	2,33	0,23	96	1,4	MW	083 - 80 A	6	12,1 x32	
	2,89	0,23	75	0,85	MW	063 - 71 B	4	12,1 x40	
	2,89	0,23	75	0,95	MW	073 - 71 B	4	12,1 x40	
	2,98	0,24	77	1	MW	063 - 71 C	6	12,1 x25	
	2,98	0,24	77	1,06	MW	073 - 71 C	6	12,1 x25	
	2,98	0,25	79	1,9	MW	083 - 80 A	6	12,1 x25	
	3,62	0,24	62	1,06	MW	063 - 71 B	4	12,1 x32	
	3,62	0,24	62	1,25	MW	073 - 71 B	4	12,1 x32	
	3,56	0,25	67	2,24	MW	083 - 80 A	6	10,1 x25	

P₁ kW	n₂ min ⁻¹	P₂ kW	M₂ daN m	fs	Gear reducer - Motor				i
1)					2)				
0,37	3,76	0,22	55	0,8	MW	062 - 71 C	6	3,8 x63	
	3,76	0,22	55	0,9	MW	072 - 71 C	6	3,8 x63	
	3,76	0,23	57	1,5	MW	082 - 80 A	6	3,8 x63	
	4,63	0,24	49,7	0,75	MW	043 - 71 B	4	12,1 x25	
	4,63	0,24	49,7	0,8	MW	053 - 71 B	4	12,1 x25	
	4,74	0,22	45	0,67	MW	052 - 71 C	6	3,8 x50	
	4,63	0,25	51	1,4	MW	063 - 71 B	4	12,1 x25	
	4,63	0,25	51	1,6	MW	073 - 71 B	4	12,1 x25	
	4,74	0,23	46,5	1,12	MW	062 - 71 C	6	3,8 x50	
	4,74	0,23	46,5	1,25	MW	072 - 71 C	6	3,8 x50	
	4,74	0,24	48,1	2,12	MW	082 - 80 A	6	3,8 x50	
	5,53	0,24	42	0,85	MW	043 - 71 B	4	10,1 x25	
	5,53	0,24	42	0,95	MW	053 - 71 B	4	10,1 x25	
	5,85	0,22	35,9	0,67	MW	052 - 71 B	4	3,8 x63	
	5,92	0,24	38	0,75	MW	042 - 71 C	6	3,8 x40	
	5,92	0,24	38	0,85	MW	052 - 71 C	6	3,8 x40	
	5,92	0,24	39,2	1,7	MW	072 - 71 C	6	3,8 x40	
	6,88	0,24	33,4	0,95	MW	042 - 71 B	4	6,36x32	
	6,88	0,24	33,4	1,06	MW	053 - 71 B	4	6,36x32	
	7,09	0,25	33,2	1,06	MW	043 - 80 A	6	5,08x25	
	7,09	0,25	33,2	1,18	MW	053 - 80 A	6	5,08x25	
	7,37	0,23	30,3	0,8	MW	042 - 71 B	4	3,8 x50	
	7,37	0,23	30,3	0,95	MW	052 - 71 B	4	3,8 x50	
	7,4	0,25	31,6	1	MW	042 - 71 C	6	3,8 x32	
	7,4	0,25	31,6	1,12	MW	052 - 71 C	6	3,8 x32	
	6,88	0,25	34,4	1,8	MW	063 - 71 B	4	6,36x32	
	6,88	0,25	34,4	2,12	MW	073 - 71 B	4	6,36x32	
	7,37	0,24	31,3	1,5	MW	062 - 71 B	4	3,8 x50	
	7,37	0,24	31,3	1,8	MW	072 - 71 B	4	3,8 x50	
	8,85	0,25	26,8	0,75	MW	033 - 71 B	4	7,91x20	
	8,8	0,25	27,2	1,25	MW	043 - 71 B	4	6,36x25	
	8,8	0,25	27,2	1,4	MW	053 - 71 B	4	6,36x25	
	9,21	0,25	25,5	1,06	MW	042 - 71 B	4	3,8 x40	
	9,21	0,25	25,5	1,25	MW	052 - 71 B	4	3,8 x40	
	9,21	0,25	25,5	1,4	MW	042 - 71 C	6	3,18x32	
	9,21	0,25	26,3	1,4	MW	052 - 71 C	6	3,18x32	
	10,9 </								



9. Manufacturing programme (gearmotors)






P₁ kW	n₂ min ⁻¹	P₂ kW	M₂ daN m	fs	Gear reducer - Motor		i
1)					2)		
0,37	22,1	0,26	11,4	0,8	MW	022 - 71 B 4	2,54x25
	22,5	0,25	10,6	0,67	MW	021 - 71 C 6	40
	22,1	0,27	11,6	1,4	MW	032 - 71 B 4	2,54x25
	22,2	0,29	12,5	1,4	MW	032 - 71 C 6	2,54x16
	22,2	0,24	10,5	0,95	MW	031 - 71 B 4	63
	22,5	0,26	10,9	1,18	MW	031 - 71 C 6	40
	22	0,29	12,7	2	MW	042 - 71 B 4	3,18x20
	22,2	0,26	11	1,6	MW	041 - 71 B 4	63
	22,2	0,26	11	1,9	MW	051 - 71 B 4	63
	22,5	0,27	11,4	2	MW	041 - 71 C 6	40
	22,5	0,27	11,4	2	MW	041 - 80 A 6	40
	27,6	0,27	9,4	1	MW	022 - 71 B 4	2,54x20
	28	0,25	8,6	0,71	MW	021 - 71 B 4	50
	28,1	0,26	8,9	0,9	MW	021 - 71 C 6	32
	27,6	0,28	9,5	1,8	MW	032 - 71 B 4	2,54x20
	27,7	0,29	10,1	1,6	MW	032 - 80 A 6	2,03x16
	28	0,26	8,8	1,25	MW	031 - 71 B 4	50
	28,1	0,27	9,1	1,6	MW	031 - 71 C 6	32
	28	0,27	9,2	2,12	MW	041 - 71 B 4	50
	34,5	0,29	8,1	1,06	MW	022 - 71 B 4	2,54x16
	35	0,26	7,1	0,9	MW	021 - 71 B 4	40
	36	0,27	7,2	1,12	MW	021 - 71 C 6	25
	34,5	0,3	8,2	1,9	MW	032 - 71 B 4	2,54x16
	35	0,27	7,4	1,6	MW	031 - 71 B 4	40
	36	0,28	7,4	2	MW	031 - 71 C 6	25
	35	0,28	7,6	2,65	MW	041 - 71 B 4	40
	43,8	0,27	5,8	0,67	MW	011 - 71 B 4	32
	45	0,28	5,9	0,8	MW	011 - 71 C 6	20
	43,8	0,27	6	1,18	MW	021 - 71 B 4	32
	45	0,28	5,9	1,4	MW	021 - 71 C 6	20
	43,8	0,28	6,1	2	MW	031 - 71 B 4	32
	45	0,29	6,1	2,5	MW	031 - 71 C 6	20
	56	0,28	4,75	0,8	MW	011 - 71 B 4	25
	56	0,28	4,82	1,5	MW	021 - 71 B 4	25
	56	0,29	4,93	2,65	MW	031 - 71 B 4	25
	70	0,29	3,91	1	MW	011 - 71 B 4	20
	70	0,29	3,96	1,8	MW	021 - 71 B 4	20
	87,5	0,3	3,31	1,12	MW	011 - 71 B 4	16
	87,5	0,31	3,36	1,9	MW	021 - 71 B 4	16
	108	0,31	2,75	1,25	MW	011 - 71 B 4	13
	108	0,31	2,78	2,24	MW	021 - 71 B 4	13
	140	0,32	2,15	1,5	MW	011 - 71 B 4	10
	140	0,32	2,17	2,8	MW	021 - 71 B 4	10
	175	0,32	1,72	1,7	MW	011 - 63 C 2	16
	175	0,32	1,72	1,7	MW	011 - 71 A 2	16
	175	0,32	1,74	2,8	MW	021 - 71 A 2	16
	200	0,33	1,55	1,8	MW	011 - 71 B 4	7
	200	0,33	1,57	3,35	MW	021 - 71 B 4	7
	215	0,32	1,42	1,9	MW	011 - 63 C 2	13
	215	0,32	1,42	1,9	MW	011 - 71 A 2	13
	280	0,32	1,11	2,36	MW	011 - 63 C 2	10
	280	0,32	1,11	2,36	MW	011 - 71 A 2	10
	400	0,33	0,79	2,8	MW	011 - 63 C 2	7
	400	0,33	0,79	2,8	MW	011 - 71 A 2	7

P₁ kW	n₂ min ⁻¹	P₂ kW	M₂ daN m	fs	Gear reducer - Motor		i
1)					2)		
0,55	1,86	0,34	173	0,75	MW	083 - 80 B 6	12,1 x40
	2,32	0,33	135	0,8	MW	083 - 80 A 4	12,1 x50
	2,33	0,35	143	0,95	MW	083 - 80 B 6	12,1 x32
	2,89	0,35	114	1,06	MW	083 - 80 A 4	12,1 x40
	2,98	0,37	117	1,25	MW	083 - 80 B 6	12,1 x25
	3,62	0,35	92	0,75	MW	063 - 71 C 4	12,1 x32
	3,62	0,35	92	0,85	MW	073 - 71 C 4	12,1 x32
	3,62	0,36	94	1,4	MW	083 - 80 A 4	12,1 x32
	3,56	0,37	99	1,5	MW	083 - 80 B 6	10,1 x25
	3,76	0,34	85	1,06	MW	082 - 80 B 6	3,8 x63
	4,63	0,36	75	0,95	MW	063 - 71 C 4	12,1 x25
	4,63	0,36	75	1,06	MW	073 - 71 C 4	12,1 x25
	11	0,38	32,8	0,95	MW	043 - 80 A 4	5,08x25
	11	0,38	32,8	1,12	MW	053 - 80 A 4	5,08x25
	11,5	0,38	31,4	0,9	MW	042 - 71 C 4	3,8 x32
	11,5	0,38	31,4	1,12	MW	052 - 71 C 4	3,8 x32
	11	0,36	31,5	0,71	MW	042 - 80 A 4	2,54x50
	11	0,36	31,5	0,85	MW	052 - 80 A 4	2,54x50
	11,1	0,38	32,6	0,9	MW	042 - 80 B 6	2,54x40
	11,1	0,38	32,6	1,06	MW	052 - 80 B 6	2,54x40
	11	0,39	33,7	1,9	MW	063 - 80 A 4	5,08x32
	11	0,39	33,7	2,24	MW	073 - 80 A 4	5,08x25
	11,5	0,39	32,3	1,8	MW	062 - 71 C 4	3,8 x32
	11,5	0,39	32,3	2,12	MW	072 - 71 C 4	3,8 x32
	11	0,38	32,5	1,4	MW	062 - 80 A 4	2,54x50
	11	0,38	32,5	1,6	MW	072 - 80 A 4	2,54x50
	11,1	0,39	33,6	1,7	MW	062 - 80 B 6	2,54x32
	11,1	0,39	33,6	2	MW	072 - 80 B 6	2,54x32
	13,8	0,39	26,8	1,06	MW	042 - 71 C 4	3,18x32
	13,8	0,39	26,8	1,25	MW	052 - 71 C 4	3,18x32
	13,8	0,38	26,5	0,95	MW	042 - 80 A 4	2,54x40
	13,8	0,38	26,5	1,12	MW	052 - 80 A 4	2,54x40
	14,2	0,39	26,5	1,18	MW	042 - 80 B 6	2,54x25
	14,2	0,39	26,5	1,4	MW	052 - 80 B 6	2,54x25
	14,3	0,36	24,1	0,8	MW	041 - 80 B 6	63
	14,3	0,36	24,1	0,9	MW	051 - 80 B 6	63
	13,8	0,4	27,6	2	MW	062 - 71 C 4	3,18x32
	13,8	0,4	27,6	2,36	MW	072 - 71 C 4	3,18x32
	13,8	0,39	27,1	1,8	MW	062 - 80 A 4	2,54x40
	13,8	0,39	27,1	2,12	MW	072 - 80 A 4	2,54x40
	14,3	0,37	25	1,5	MW	061 - 80 B 6	63
	14,3	0,37	25	1,8	MW	071 - 80 B 6	63
	17,3	0,38	21,2	0,75	MW	032 - 71 C 4	2,54x32

1) Powers valid for continuous duty S1; increase possible for S2 ... S10 (see ch. 2b) in which case P₂, M₂ increase and fs decreases proportionately.

2) For complete designation when ordering see ch. 3.




P_1 kW	n_2 min ⁻¹	P_2 kW	M_2 daN m	fs	Gear reducer - Motor				i
1)	2)								
0,55									
17,7	0,39	21,1	0,8	MW	032 - 80 B	6	2,03x25		
17,6	0,4	21,8	1,4	MW	042 - 71 C	4	3,18x25		
17,6	0,4	21,8	1,6	MW	052 - 71 C	4	3,18x25		
17,2	0,39	21,8	1,18	MW	042 - 80 A	4	2,54x32		
17,2	0,39	21,8	1,5	MW	052 - 80 A	4	2,54x32		
18	0,38	20,2	1,06	MW	041 - 80 B	6	50		
18	0,38	20,2	1,25	MW	051 - 80 B	6	50		
17,6	0,41	22,3	2,65	MW	062 - 71 C	4	3,18x25		
17,6	0,41	22,3	3,15	MW	072 - 71 C	4	3,18x25		
17,2	0,4	22,4	2,36	MW	062 - 80 A	4	2,54x32		
17,2	0,4	22,4	2,8	MW	072 - 80 A	4	2,54x32		
18	0,39	20,9	2	MW	061 - 80 B	6	50		
18	0,39	20,9	2,36	MW	071 - 80 B	6	50		
22,1	0,4	17,2	0,95	MW	032 - 71 C	4	2,54x25		
21,5	0,39	17,3	0,9	MW	032 - 80 A	4	2,03x32		
22,2	0,4	17,4	1,06	MW	032 - 80 B	6	2,03x20		
22,5	0,38	16,2	0,8	MW	031 - 80 B	6	40		
22	0,44	18,9	1,32	MW	042 - 71 C	4	3,18x20		
22	0,44	18,9	1,6	MW	052 - 71 C	4	3,18x20		
22,1	0,41	17,7	1,6	MW	042 - 80 A	4	2,54x25		
22,1	0,41	17,7	1,9	MW	052 - 80 A	4	2,54x25		
22,2	0,38	16,4	1,06	MW	041 - 71 C	4	63		
22,2	0,38	16,4	1,25	MW	051 - 71 C	4	63		
22,2	0,38	16,4	1,06	MW	041 - 80 A	4	63		
22,2	0,38	16,4	1,25	MW	051 - 80 A	4	63		
22,5	0,4	16,9	1,4	MW	041 - 80 B	6	40		
22,5	0,4	16,9	1,6	MW	051 - 80 B	6	40		
22,2	0,39	16,9	2	MW	061 - 80 A	4	63		
22,2	0,39	16,9	2,36	MW	071 - 80 A	4	63		
0,41									
27,6	0,4	13,9	0,67	MW	022 - 71 C	4	2,54x20		
27,6	0,41	14,2	1,18	MW	032 - 71 C	4	2,54x20		
27,6	0,41	14	1,12	MW	032 - 80 A	4	2,03x25		
28	0,38	13,1	0,85	MW	031 - 71 C	4	50		
28	0,38	13,1	0,85	MW	031 - 80 A	4	50		
28,1	0,4	13,5	1,06	MW	031 - 80 B	6	32		
27,5	0,44	15,4	1,8	MW	042 - 71 C	4	3,18x16		
27,5	0,44	15,4	2,12	MW	052 - 71 C	4	3,18x16		
27,6	0,44	15,3	1,6	MW	042 - 80 A	4	2,54x20		
27,6	0,44	15,3	1,9	MW	052 - 80 A	4	2,54x20		
28	0,4	13,7	1,4	MW	041 - 71 C	4	50		
28	0,4	13,7	1,7	MW	051 - 71 C	4	50		
28	0,4	13,7	1,4	MW	041 - 80 A	4	50		
28	0,4	13,7	1,7	MW	051 - 80 A	4	50		
28,1	0,41	13,9	1,7	MW	041 - 80 B	6	32		
28,1	0,41	13,9	2,12	MW	051 - 80 B	6	32		
0,46									
34,5	0,43	12	0,71	MW	022 - 71 C	4	2,54x16		
36	0,4	10,7	0,75	MW	021 - 80 B	6	25		
34,5	0,44	12,2	1,32	MW	032 - 71 C	4	2,54x16		
34,5	0,42	11,5	1,4	MW	032 - 80 A	4	2,03x20		
35	0,4	10,9	1,06	MW	031 - 71 C	4	40		
35	0,4	10,9	1,06	MW	031 - 80 A	4	40		
36	0,41	11	1,4	MW	031 - 80 B	6	25		
34,5	0,45	12,4	2,12	MW	042 - 80 A	4	2,54x16		
35	0,42	11,4	1,8	MW	041 - 71 C	4	40		
35	0,42	11,4	1,8	MW	041 - 80 A	4	40		
43,8	0,41	8,9	0,8	MW	021 - 71 C	4	32		
45	0,42	8,8	0,9	MW	021 - 80 B	6	20		
43,1	0,45	9,9	1,5	MW	032 - 80 A	4	2,03x16		
43,8	0,42	9,1	1,4	MW	031 - 71 C	4	32		
43,8	0,42	9,1	1,4	MW	031 - 80 A	4	32		
45	0,42	9	1,7	MW	031 - 80 B	6	20		
43,8	0,43	9,3	2,24	MW	041 - 80 A	4	32		
56	0,42	7,2	1	MW	021 - 71 C	4	25		
56	0,42	7,2	1	MW	021 - 80 A	4	25		
56	0,43	7,3	1,8	MW	031 - 71 C	4	25		
56	0,43	7,3	1,8	MW	031 - 80 A	4	25		
0,44									
70	0,43	5,8	0,71	MW	011 - 71 C	4	20		
70	0,43	5,9	1,18	MW	021 - 71 C	4	20		
70	0,43	5,9	1,18	MW	021 - 80 A	4	20		
70	0,44	6	2,12	MW	031 - 71 C	4	20		
70	0,44	6	2,12	MW	031 - 80 A	4	20		
87,5	0,45	4,93	0,75	MW	011 - 71 C	4	16		

P_1 kW	n_2 min ⁻¹	P_2 kW	M_2 daN m	fs	Gear reducer - Motor				i
1)	2)								
0,55									
87,5	0,46	4,99	1,32	MW	021 - 71 C	4	16		
87,5	0,46	4,99	1,32	MW	021 - 80 A	4	16		
87,5	0,46	5,1	2,36	MW	031 - 71 C	4	16		
87,5	0,46	5,1	2,36	MW	031 - 80 A	4	16		
108	0,46	4,09	0,85	MW	011 - 71 C	4	13		
108	0,47	4,13	1,5	MW	021 - 71 C	4	13		
108	0,47	4,13	1,5	MW	021 - 80 A	4	13		
108	0,47	4,18	2,65	MW	031 - 71 C	4	13		
140	0,47	3,19	1	MW	011 - 71 C	4	10		
140	0,47	3,23	1,8	MW	021 - 71 C	4	10		
140	0,47	3,23	1,8	MW	021 - 80 A	4	10		
175	0,47	2,56	1,12	MW	011 - 71 B	2	16		
175	0,47	2,58	2	MW	021 - 71 B	2	16		
200	0,48	2,31	1,25	MW	011 - 71 C	4	7		
200	0,49	2,33	2,24	MW	021 - 71 C	4	7		
200	0,49	2,33	2,24	MW	021 - 80 A	4	7		
215	0,48	2,11	1,32	MW	011 - 71 B	2	13		
215	0,48	2,13	2,24	MW	021 - 71 B	2	13		
280	0,48	1,64	1,6	MW	011 - 71 B	2	10		
280	0,49	1,66	2,8	MW	021 - 71 B	2	10		
400	0,49	1,18	1,9	MW	011 - 71 B	2	7		
400	0,5	1,19	3,35	MW	021 - 71 B	2	7		
0,75									
1,5	0,45	286	0,75	MW	093 - 90 S	6	12	x50	
1,87	0,46	236	1	MW	093 - 90 S	6	12	x40	
2,33	0,48	195	0,71	MW	083 - 80 C	6	12,1	x32	
2,34	0,48	198	1,32	MW	093 - 90 S	6	12	x32	
2,89	0,47	155	0,8	MW	083 - 80 B	4	12,1	x40	
2,98	0,5	160	0,95	MW	083 - 80 C	6	12,1	x25	
2,88	0,49	162	1,5	MW	093 - 90 S	6	9,75	x32	
2,88	0,49	162	1,7	MW	103 - 90 S	6	9,75	x32	
3,62	0,49	128	1,06	MW	083 - 80 B	4	12,1	x32	
3,55	0,48	130	1,6	MW	093 - 90 S	6	6,34	x40	
3,55	0,48	130	1,9	MW	103 - 90 S	6	6,34	x40	
3,7	0,47	121	1,32	MW	092 - 90 S	6	3,86	x63	
3,7	0,47	121	1,6	MW	102 - 90 S	6	3,86	x50	
3,76	0,46	116	0,75	MW	082 - 80 C	6	3,8	x63	
4,46	0,5	107	0,75	MW	073 - 80 C	6	8,08	x25	
4,63	0,51	105	1,4	MW	083 - 80 B	4	12,1	x25	
4,74	0,48	98	1	MW	082 - 80 C	6	3,8	x50	
4,67	0,5	102	1,8	MW	092 - 90 S	6	3,86	x50	
5,42	0,49	87	0,75	MW	063 - 80 B	4	8,08	x32	
5,42	0,49	87	0,85	MW	073 - 80 B	4	8,08	x32	
5,53	0,52	89	1,6	MW	083 - 80 B	4	10,1	x25	
5,85	0,48	78	1,06	MW	082 - 80 B	4	3,8	x63	
5,92	0,51	82	1,4	MW	082 - 80 C	6	3,8	x40	
5,83	0,51	84	2,36	MW	092 - 90 S	6	3,86	x40	
6,93	0,51	71	0,95	MW	063 - 80 B	4	8,08	x25	
6,93	0,51	71	1,12	MW	073 - 80 B	4	8,08	x25	
7,09	0,49	66	0,71	MW	062 - 80 C	6	2,54	x50	
7,09	0,49	66	0,85	MW	072 - 80 C	6	2,54	x50	
6,88	0,51	71	1						



9. Manufacturing programme (gearmotors)




P_1 kW	n_2 min ⁻¹	P_2 kW	M_2 daN m	fs	Gear reducer - Motor				i
1)					2)				
0,75	11	0,53	45,9	1,6	MW	073 - 80 B	4	5,08x25	
	11	0,51	44,4	1	MW	062 - 80 B	4	2,54x50	
	11	0,51	44,4	1,18	MW	072 - 80 B	4	2,54x50	
	11,1	0,53	45,8	1,25	MW	062 - 80 C	6	2,54x32	
	11,1	0,53	45,8	1,5	MW	072 - 80 C	6	2,54x32	
	11,5	0,54	45,2	2,65	MW	082 - 80 B	4	3,8 x32	
	13,8	0,52	36,1	0,71	MW	042 - 80 B	4	2,54x40	
	13,8	0,52	36,1	0,85	MW	052 - 80 B	4	2,54x40	
	14,2	0,54	36,2	0,85	MW	042 - 80 C	6	2,54x25	
	14,2	0,54	36,2	1	MW	052 - 80 C	6	2,54x25	
	14,1	0,53	35,8	0,8	MW	042 - 90 S	6	2 x32	
	14,3	0,49	32,9	0,67	MW	051 - 80 C	6	63	
	14,3	0,49	32,9	0,67	MW	051 - 90 S	6	63	
	13,8	0,53	37	1,32	MW	062 - 80 B	4	2,54x40	
	13,8	0,53	37	1,6	MW	072 - 80 B	4	2,54x40	
	14,2	0,55	37,1	1,6	MW	062 - 80 C	6	2,54x25	
	14,2	0,55	37,1	1,9	MW	072 - 80 C	6	2,54x25	
	14,3	0,51	34,1	1,06	MW	061 - 90 S	6	63	
	14,3	0,51	34,1	1,32	MW	071 - 90 S	6	63	
	14,3	0,53	35,4	2,12	MW	081 - 90 S	6	63	
	17,2	0,54	29,8	0,9	MW	042 - 80 B	4	2,54x32	
	17,2	0,54	29,8	1,06	MW	052 - 80 B	4	2,54x32	
	18	0,55	29,1	1	MW	042 - 90 S	6	2 x25	
	18	0,55	29,1	1,18	MW	052 - 90 S	6	2 x25	
	18	0,52	27,6	0,75	MW	041 - 80 C	6	50	
	18	0,52	27,6	0,9	MW	051 - 80 C	6	50	
	18	0,52	27,6	0,75	MW	041 - 90 S	6	50	
	18	0,52	27,6	0,9	MW	051 - 90 S	6	50	
	17,2	0,55	30,6	1,7	MW	062 - 80 B	4	2,54x32	
	17,2	0,55	30,6	2	MW	072 - 80 B	4	2,54x32	
	18	0,56	29,8	1,9	MW	062 - 90 S	6	2 x25	
	18	0,54	28,5	1,5	MW	061 - 90 S	6	50	
	18	0,54	28,5	1,7	MW	071 - 90 S	6	50	
	18	0,55	29,4	2,65	MW	081 - 90 S	6	50	
	0,58	22,2	0,55	23,7	0,75	MW	032 - 80 C	6	2,03x20
		22,1	0,56	24,1	1,18	MW	042 - 80 B	4	2,54x25
		22,1	0,56	24,1	1,4	MW	052 - 80 B	4	2,54x25
		22,2	0,52	22,4	0,75	MW	041 - 80 B	4	63
		22,2	0,52	22,4	0,9	MW	051 - 80 B	4	63
		22,5	0,54	23	1	MW	041 - 80 C	6	40
		22,5	0,54	23	1,18	MW	051 - 80 C	6	40
		22,5	0,54	23	1	MW	041 - 90 S	6	40
		22,5	0,54	23	1,18	MW	051 - 90 S	6	40
		22,5	0,54	23	1	MW	041 - 80 A	2	40
		22,5	0,54	23	1	MW	051 - 90 A	2	40
		22,5	0,54	23	1,18	MW	051 - 90 S	6	40
		22,1	0,57	24,7	2,24	MW	062 - 80 B	4	2,54x25
		22,1	0,57	24,7	2,65	MW	072 - 80 B	4	2,54x25
		22,2	0,54	23,1	1,5	MW	061 - 80 B	4	63
		22,2	0,54	23,1	1,7	MW	071 - 80 B	4	63
		22,5	0,56	23,7	1,9	MW	061 - 90 S	6	40
		22,5	0,56	23,7	2,24	MW	071 - 90 S	6	40
	0,63	27,6	0,55	19,2	0,85	MW	032 - 80 B	4	2,03x25
	0,63	28,1	0,54	18,4	0,8	MW	031 - 80 C	6	32
		27,6	0,6	20,8	1,18	MW	042 - 80 B	4	2,54x20
		27,6	0,6	20,8	1,4	MW	052 - 80 B	4	2,54x20
		28,1	0,6	20,5	1,32	MW	042 - 90 S	6	2 x16
		28,1	0,6	20,5	1,6	MW	052 - 90 S	6	2 x16
		28	0,55	18,6	1,06	MW	041 - 80 B	4	50
		28	0,55	18,6	1,25	MW	051 - 80 B	4	50
		28,1	0,56	19	1,32	MW	041 - 80 C	6	32
		28,1	0,56	19	1,5	MW	051 - 80 C	6	32
		28,1	0,56	19	1,32	MW	041 - 90 S	6	32
		28,1	0,56	19	1,5	MW	051 - 90 S	6	32
		27,6	0,61	21,2	2,24	MW	062 - 80 B	4	2,54x20
		27,6	0,61	21,2	2,65	MW	072 - 80 B	4	2,54x20
		28	0,56	19,2	1,9	MW	061 - 80 B	4	50
		28	0,56	19,2	2,24	MW	071 - 80 B	4	50
		28,1	0,57	19,5	2,36	MW	061 - 90 S	6	32
		34,5	0,57	15,7	1	MW	032 - 80 B	4	2,03x20
		35	0,55	14,9	0,8	MW	031 - 80 B	4	40
		36	0,56	14,9	1	MW	031 - 80 C	6	25
		34,5	0,61	17	1,6	MW	042 - 80 B	4	2,54x16
		34,5	0,61	17	1,8	MW	052 - 80 B	4	2,54x16
		35	0,57	15,5	1,32	MW	041 - 80 B	4	40

P_1 kW	n_2 min ⁻¹	P_2 kW	M_2 daN m	fs	Gear reducer - Motor				i	
1)					2)					
0,75	35	0,57	15,5	1,6	MW	051 - 80 B	4	40		
	36	0,58	15,3	1,7	MW	041 - 80 C	6	25		
	36	0,58	15,3	2	MW	051 - 80 C	6	25		
	36	0,58	15,3	1,7	MW	041 - 90 S	6	25		
	36	0,58	15,3	2	MW	051 - 90 S	6	25		
	35	0,58	15,8	2,5	MW	061 - 80 B	4	40		
	0,5	45	0,57	12	0,67	MW	021 - 80 C	6	20	
		43,1	0,61	13,5	1,12	MW	032 - 80 B	4	2,03 x16	
		43,8	0,57	12,4	1	MW	031 - 80 B	4	32	
		45	0,58	12,3	1,18	MW	031 - 80 C	6	20	
		43,8	0,58	12,7	1,7	MW	041 - 80 B	4	32	
		43,8	0,58	12,7	2	MW	051 - 80 B	4	32	
	0,55	56	0,57	9,8	0,75	MW	021 - 80 B	4	25	
		56	0,59	10	1,32	MW	031 - 80 B	4	25	
		56	0,6	10,2	2,12	MW	041 - 80 B	4	25	
		0,6	70	0,59	8	0,9	MW	021 - 80 B	4	20
		70	0,6	8,2	1,6	MW	031 - 80 B	4	20	
		70	0,63	8,6	2,24	MW	041 - 80 B	4	20	
		87,5	0,62	6,8	0,95	MW	021 - 80 B	4	16	
		87,5	0,63	6,9	1,7	MW	031 - 80 B	4	16	
		87,5	0,64	7	2,8	MW	041 - 80 B	4	16	
		108	0,63	5,6	1,12	MW	021 - 80 B	4	13	
		108	0,64	5,7	2	MW	031 - 80 B	4	13	
		140	0,61	4,16	0,75	MW	011 - 71 C	2	20	
		140	0,65	4,4	1,32	MW	021 - 80 B	4	10	
		140	0,65	4,4	2,36	MW	031 - 80 B	4	10	
		175	0,64	3,49	0,8	MW	011 - 71 C	2	16	
		175	0,64	3,52	1,4	MW	021 - 71 C	2	16	
		175	0,64	3,52	1,4	MW	021 - 80 A	2	16	
		175	0,65	3,56	2,5	MW	031 - 71 C	2	16	
		175	0,65	3,56	2,5	MW	031 - 80 A	2	16	
		200	0,66	3,18	1,6	MW	021 - 80 B	4	7	
		200	0,67	3,2	3	MW	031 - 80 B	4	7	
		1,1	1,87	0,68	346	0,71	MW	103 - 90 L	6	12 x40
			2,33	0,67	277	0,75	MW	093 - 90 S	4	12 x50



9. Manufacturing programme (gearmotors)




P_1 kW	n_2 min^{-1}	P_2 kW	M_2 daN m	fs	Gear reducer - Motor				i
1)					2)				
1,1	5,76	0,73	120	1,25	MW	092 - 90 S	4	3,86x63	
	5,76	0,73	120	1,5	MW	102 - 90 S	4	3,86x63	
	5,83	0,75	123	1,6	MW	092 - 90 L	6	3,86x40	
	5,83	0,75	123	1,9	MW	102 - 90 L	6	3,86x40	
0,92	6,93	0,75	104	0,75	MW	073 - 80 C	4	8,08x25	
	6,93	0,77	106	1,32	MW	083 - 90 S	4	8,08x25	
	7,37	0,74	96	1	MW	082 - 80 C	4	3,8 x50	
	7,09	0,74	100	0,95	MW	082 - 90 L	6	2,54x50	
	6,9	0,77	107	2	MW	093 - 90 S	4	6,34x32	
	7,26	0,76	100	1,6	MW	092 - 90 S	4	3,86x50	
	7,26	0,76	100	1,9	MW	102 - 90 S	4	3,86x50	
	7,2	0,77	102	1,8	MW	092 - 90 L	6	3,13x40	
	8,62	0,75	83	0,71	MW	063 - 80 C	4	5,08x32	
	8,62	0,75	83	0,85	MW	073 - 80 C	4	5,08x32	
	9	0,73	78	0,71	MW	072 - 90 L	6	2 x50	
	8,8	0,79	85	1,6	MW	083 - 80 C	4	6,36x25	
	8,62	0,77	85	1,5	MW	083 - 90 S	4	5,08x32	
	9,21	0,78	81	1,32	MW	082 - 80 C	4	3,8 x40	
	8,75	0,74	80	1	MW	082 - 90 S	4	2,54x63	
	8,86	0,78	84	1,25	MW	082 - 90 L	6	2,54x40	
	9,07	0,79	83	2,24	MW	092 - 90 S	4	3,86x40	
11	0,78	67	0,95	MW	063 - 80 C	4	5,08x25		
11	0,78	67	1,12	MW	073 - 80 C	4	5,08x25		
11	0,75	65	0,71	MW	062 - 80 C	4	2,54x50		
11	0,75	65	0,8	MW	072 - 80 C	4	2,54x50		
11,1	0,73	63	0,71	MW	072 - 90 S	4	2 x63		
11,3	0,77	65	0,8	MW	062 - 90 L	6	2 x40		
11,3	0,77	65	0,9	MW	072 - 90 L	6	2 x40		
11	0,8	69	1,9	MW	083 - 90 S	4	5,08x25		
11,5	0,8	66	1,8	MW	082 - 80 C	4	3,8 x32		
11	0,78	67	1,32	MW	082 - 90 S	4	2,54x50		
11,1	0,8	69	1,7	MW	082 - 90 L	6	2,54x32		
13,8	0,84	58	0,9	MW	062 - 80 C	4	5,08x20		
13,8	0,84	58	1,06	MW	073 - 80 C	4	5,08x20		
13,8	0,78	54	0,9	MW	062 - 80 C	4	2,54x40		
13,8	0,78	54	1,06	MW	072 - 80 C	4	2,54x40		
14	0,77	52	0,8	MW	062 - 90 S	4	2 x50		
14	0,77	52	1	MW	072 - 90 S	4	2 x50		
14,1	0,8	54	1	MW	062 - 90 L	6	2 x32		
14,1	0,8	54	1,18	MW	072 - 90 L	6	2 x32		
14,3	0,75	50	0,75	MW	061 - 90 L	6	63		
14,3	0,75	50	0,9	MW	071 - 90 L	6	63		
13,8	0,86	60	1,9	MW	083 - 90 S	4	5,08x20		
13,8	0,81	56	2	MW	082 - 80 C	4	3,18x32		
13,8	0,81	56	1,8	MW	082 - 90 S	4	2,54x40		
14,2	0,83	56	2,24	MW	082 - 90 L	6	2,54x25		
14,3	0,78	52	1,4	MW	081 - 90 L	6	63		
0,8	17,2	0,79	43,7	0,71	MW	052 - 80 C	4	2,54x32	
0,82	18	0,8	42,6	0,71	MW	042 - 90 L	6	2 x25	
0,82	18	0,8	42,6	0,85	MW	052 - 90 L	6	2 x25	
17,2	0,81	44,8	1,18	MW	062 - 80 C	4	2,54x32		
17,2	0,81	44,8	1,4	MW	072 - 80 C	4	2,54x32		
17,5	0,8	43,6	1,06	MW	062 - 90 S	4	2 x40		
17,5	0,8	43,6	1,32	MW	072 - 90 S	4	2 x40		
18	0,82	43,7	1,32	MW	062 - 90 L	6	2 x25		
18	0,82	43,7	1,6	MW	072 - 90 L	6	2 x25		
18	0,79	41,7	1	MW	061 - 90 L	6	50		
18	0,79	41,7	1,18	MW	071 - 90 L	6	50		
17,2	0,83	45,9	2,36	MW	082 - 90 S	4	2,54x32		
18	0,81	43,2	1,8	MW	081 - 90 L	6	50		
0,88	22,1	0,82	35,4	0,8	MW	042 - 80 C	4	2,54x25	
0,88	22,1	0,82	35,4	0,95	MW	052 - 80 C	4	2,54x25	
0,87	21,9	0,8	35,1	0,75	MW	042 - 90 S	4	2 x32	
0,87	21,9	0,8	35,1	0,85	MW	052 - 90 S	4	2 x32	
0,88	22,5	0,8	33,8	0,8	MW	051 - 90 L	6	40	
	22,1	0,84	36,2	1,5	MW	062 - 80 C	4	2,54x25	
	22,1	0,84	36,2	1,8	MW	072 - 80 C	4	2,54x25	
21,9	0,83	36,1	1,4	MW	062 - 90 S	4	2 x32		
21,9	0,83	36,1	1,6	MW	072 - 90 S	4	2 x32		
22,2	0,79	33,8	1	MW	061 - 80 C	4	63		
22,2	0,79	33,8	1,18	MW	071 - 80 C	4	63		
22,2	0,79	33,8	1	MW	061 - 90 S	4	63		

P_1 kW	n_2 min^{-1}	P_2 kW	M_2 daN m	fs	Gear reducer - Motor				i
1)					2)				
1,1	22,2	0,79	33,8	1,18	MW	071 - 90 S	4	63	
	22,5	0,82	34,7	1,32	MW	061 - 90 L	6	40	
	22,5	0,82	34,7	1,5	MW	071 - 90 L	6	40	
	22,1	0,86	37,2	3	MW	082 - 90 S	4	2,54x25	
	22,2	0,82	35	1,9	MW	081 - 90 S	4	63	
	27,6	0,88	30,6	0,8	MW	042 - 80 C	4	2,54x20	
	27,6	0,88	30,6	0,95	MW	052 - 80 C	4	2,54x20	
	28	0,83	28,4	1,12	MW	052 - 90 S	4	2 x25	
	28	0,83	30,1	0,9	MW	042 - 90 L	6	2 x16	
	28	0,8	27,3	0,71	MW	041 - 80 C	4	50	
	28	0,8	27,3	0,85	MW	051 - 80 C	4	50	
	28	0,8	27,3	0,71	MW	041 - 90 S	4	50	
	28	0,8	27,3	0,85	MW	051 - 90 S	4	50	
	28	0,82	28,1	1,32	MW	061 - 80 C	4	50	
	28	0,82	28,1	1,6	MW	071 - 80 C	4	50	
	28	0,82	28,1	1,6	MW	071 - 90 S	4	50	
0,69	34,5	0,83	23,1	0,71	MW	032 - 80 C	4	2,03x20	
0,69	36	0,83	21,9	0,67	MW	031 - 90 L	6	25	
	34,5	0,9	24,9	1,06	MW	042 - 80 C	4	2,54x16	
	34,5	0,9	24,9	1,25	MW	052 - 80 C	4	2,54x16	
	35	0,89	24,4	1	MW	042 - 90 S	4	2 x20	
	35	0,89	24,4	1,18	MW	052 - 90 S	4	2 x20	
	35	0,83	22,7	0,9	MW	041 - 80 C	4	40	
	35	0,83	22,7	1,06	MW	051 - 80 C	4	40	
	35	0,83	22,7	1,25	MW	052 - 90 S	4	2 x20	
	35	0,83	22,7	1,5	MW	072 - 80 C	4	2,54x16	
	35	0,85	23,2	1,7	MW	061 - 80 C	4	40	
	35	0,85	23,2	2	MW	071 - 80 C	4	40	
	35	0,85	23,2	1,7	MW	061 - 90 S	4	40	
	35	0,85	23,2	2	MW	071 - 90 S	4	40	
	36	0,87	23	2,12	MW	061 - 90 L	6	25	
0,88	43,1	0,89	19,8	0,75	MW	032 - 80 C	4	2,03x16	
0,76	43,8	0,83	18,2	0,67	MW	031 - 80 C	4	32	
0,75	45	0,85	18	0,85	MW	031 - 90 L	6	20	
	43,8	0,91	19,8	1,25	MW	042 - 90 S	4	2 x16	
	43,8	0,91	19,8	1,5	MW	052 - 90 S	4	2 x16	
	43,8	0,85	18,6	1,12	MW	041 - 80 C	4	32	
	43,8	0,85	18,6	1,32	MW	051 - 80 C	4	32	
	43,8	0,85	18,6	1,12	MW	041 - 90 S	4	32	
	43,8	0,85	18,6	1,32	MW	051 - 90 S	4	32	
	45	0,9	19,2	1,4	MW	051 - 90 L	6	20	
	43,8	0,92	20,1	2,36	MW	062 - 90 S	4	2 x16	
	43,8	0,92	20,1	2,8	MW	072 - 90 S	4	2 x16	
	43,8	0,87	19,1	2,12	MW	061 - 80 C	4	32	
	43,8	0,87	19,1	2,5	MW	071 - 80 C	4	32	
	43,8	0,87	19,1	2,12	MW	061 - 90 S	4	32	
0,84	56	0,86	14,7	0,9	MW	031 - 80 C	4	25	
0,84	56	0,86	14,7	0,9	MW	031 - 90 S	4	25	
	56	0,88	15	1,5	MW	041 - 80 C	4	25	
	56	0,88	15	1,7	MW	051 - 80 C	4	25	
	56	0,88	15	1,5	MW	041 - 90 S	4	25	
	56	0,88	15	1,7	MW	051 - 90 S	4	25	
	56	0,9	15,3	2,8	MW	061 - 90 S	4	25	
	56	0,9	15,3	3,35	MW	071 - 90 S	4	25	
0,92	70	0,88	12	1,06	MW	031 - 80 C	4	20	

Values in red state nominal thermal power P_{th} (ambient temperature 40 °C, continuous duty, see ch. 4).



9. Manufacturing programme (gearmotors)



P_1 kW	n_2 min ⁻¹	P_2 kW	M_2 daN m	fs	Gear reducer - Motor		i
1)					2)		
1,1	0,92	70	0,88	12	1,06	MW 031 - 90 S 4	20
		70	0,93	12,7	1,5	MW 041 - 80 C 4	20
		70	0,93	12,7	1,8	MW 051 - 80 C 4	20
		70	0,93	12,7	1,5	MW 041 - 90 S 4	20
		70	0,93	12,7	1,8	MW 051 - 90 S 4	20
		69,2	0,93	12,9	1,7	MW 041 - 90 L 6	13
		69,2	0,93	12,9	2	MW 051 - 90 L 6	13
0,77	87,5	0,91	10	0,67	MW 021 - 80 C 4	16	
		87,5	0,93	10,1	1,18	MW 031 - 80 C 4	16
		87,5	0,93	10,1	1,18	MW 031 - 90 S 4	16
		87,5	0,94	10,3	1,9	MW 041 - 80 C 4	16
		87,5	0,94	10,3	1,9	MW 041 - 90 S 4	16
0,84	108	0,93	8,3	0,75	MW 021 - 80 C 4	13	
		108	0,94	8,4	1,32	MW 031 - 80 C 4	13
		108	0,94	8,4	1,32	MW 031 - 90 S 4	13
		108	0,95	8,5	2,24	MW 041 - 90 S 4	13
0,93	140	0,95	6,5	0,9	MW 021 - 80 C 4	10	
		140	0,96	6,5	1,6	MW 031 - 80 C 4	10
		140	0,96	6,5	1,6	MW 031 - 90 S 4	10
		140	0,98	6,7	2,8	MW 041 - 90 S 4	10
		175	0,95	5,2	0,95	MW 021 - 80 B 2	16
		175	0,96	5,2	1,7	MW 031 - 80 B 2	16
		175	0,97	5,3	2,8	MW 041 - 80 B 2	16
		200	0,98	4,66	1,12	MW 021 - 80 C 4	7
		200	0,98	4,69	2	MW 031 - 80 C 4	7
		200	0,98	4,69	2	MW 031 - 90 S 4	7
		215	0,96	4,25	1,12	MW 021 - 80 B 2	13
		215	0,97	4,29	2	MW 031 - 80 B 2	13
		280	0,97	3,31	1,4	MW 021 - 80 B 2	10
		280	0,98	3,34	2,36	MW 031 - 80 B 2	10
		400	0,99	2,37	1,7	MW 021 - 80 B 2	7
		400	1	2,39	3	MW 031 - 80 B 2	7
1,5	2,91	0,95	311	0,71	MW 093 - 90 L 4	12 x40	
		2,91	0,95	311	0,8	MW 103 - 90 L 4	12 x40
		3,64	1	262	0,9	MW 093 - 90 L 4	12 x32
		3,64	1	262	1,06	MW 103 - 90 L 4	12 x32
		3,7	0,94	243	0,67	MW 092 - 90 LC 6	3,86x63
		3,7	0,94	243	0,8	MW 102 - 90 LC 6	3,86x63
		3,57	0,98	261	1,25	MW 112 - 100 LA 6	4 x63
		3,57	0,98	261	1,4	MW 122 - 100 LA 6	4 x63
		4,49	1,02	216	1,06	MW 093 - 90 L 4	9,75x32
		4,49	1,02	216	1,25	MW 103 - 90 L 4	9,75x32
		4,57	0,97	202	0,8	MW 092 - 100 LA 6	3,13x63
		4,57	0,97	202	0,9	MW 102 - 100 LA 6	3,13x63
		4,67	1	204	0,9	MW 092 - 90 LC 6	3,86x50
		4,67	1	204	1,06	MW 102 - 90 LC 6	3,86x50
		4,5	1,03	218	1,6	MW 112 - 100 LA 6	4 x50
		4,5	1,03	218	1,9	MW 122 - 100 LA 6	4 x50
		5,42	1,01	178	0,75	MW 083 - 90 L 4	8,08x32
		5,52	1,01	174	1,12	MW 093 - 90 L 4	6,34x40
		5,52	1,01	174	1,32	MW 103 - 90 L 4	6,34x40
		5,47	1,03	180	1,25	MW 093 - 100 LA 6	5,15x32
		5,76	0,99	164	0,95	MW 092 - 90 L 4	3,86x63
		5,76	0,99	164	1,06	MW 102 - 90 L 4	3,86x63
		5,76	1,02	169	1,06	MW 092 - 100 LA 6	3,13x50
		5,76	1,02	169	1,18	MW 102 - 100 LA 6	3,13x50
		5,83	1,03	168	1,18	MW 092 - 90 LC 6	3,86x40
		5,83	1,03	168	1,4	MW 102 - 90 LC 6	3,86x40
		5,63	1,07	181	2,24	MW 112 - 100 LA 6	4 x40
		5,63	1,07	181	2,65	MW 122 - 100 LA 6	4 x40
		6,93	1,05	145	0,95	MW 083 - 90 L 4	8,08x25
		7,37	1,01	131	0,71	MW 082 - 90 L* 4	3,8 x50
		7,09	1,01	136	0,71	MW 082 - 90 LC 6	2,54x50
		6,9	1,06	146	1,5	MW 093 - 90 L 4	6,34x32
		6,9	1,06	146	1,7	MW 103 - 90 L 4	6,34x32
		7,26	1,04	137	1,18	MW 092 - 90 L 4	3,86x50
		7,26	1,04	137	1,4	MW 102 - 90 L 4	3,86x50
		7,2	1,05	139	1,32	MW 092 - 100 LA 6	3,13x40
		7,2	1,05	139	1,6	MW 102 - 100 LA 6	3,13x40

P_1 kW	n_2 min ⁻¹	P_2 kW	M_2 daN m	fs	Gear reducer - Motor		i
1)					2)		
1,5	7,2	1,05	139	1,32	MW 092 - 90 LC 6	3,13x40	
	7,2	1,05	139	1,6	MW 102 - 90 LC 6	3,13x40	
	7,09	1,09	146	2,65	MW 112 - 100 LA 6	3,17x40	
	8,62	1,05	116	1,06	MW 083 - 90 L 4	5,08x32	
	9,21	1,06	110	1	MW 082 - 90 L* 4	3,8 x40	
	8,75	1	110	0,75	MW 082 - 90 L 4	2,54x63	
	9	1,04	110	0,85	MW 082 - 100 LA 6	2 x50	
	8,83	1,15	125	1,8	MW 103 - 90 L 4	6,34x25	
	9,07	1,07	113	1,6	MW 092 - 90 L 4	3,86x40	
	9,07	1,07	113	1,9	MW 102 - 90 L 4	3,86x40	
	9	1,09	116	1,8	MW 092 - 90 LC 6	3,13x32	
	9	1,09	116	2,12	MW 102 - 90 LC 6	3,13x32	
1,05	11,3	1,05	89	0,71	MW 072 - 90 LC 6	2 x40	
	11	1,09	94	1,4	MW 083 - 90 L 4	5,08x25	
	11,5	1,09	90	1,32	MW 082 - 90 L* 4	3,8 x32	
	11	1,06	92	0,95	MW 082 - 90 L 4	2,54x50	
	11,3	1,08	92	1,12	MW 082 - 100 LA 6	2 x40	
	11,1	1,09	94	1,25	MW 082 - 90 LC 6	2,54x32	
	11,2	1,09	93	1,9	MW 092 - 90 L 4	3,13x40	
	11,1	1,11	96	2,12	MW 092 - 100 LA 6	2,54x32	
1,13	13,8	1,07	74	0,67	MW 062 - 90 L* 4	2,54x40	
	1,13	13,8	1,07	0,8	MW 072 - 90 L* 4	2,54x40	
	1,11	1,05	71	0,71	MW 072 - 90 L 4	2 x50	
	1,13	14,1	1,08	74	0,75	MW 062 - 90 LC 6	2 x32
	1,13	14,1	1,08	74	0,9	MW 072 - 90 LC 6	2 x32
	13,8	1,18	81	1,4	MW 083 - 90 L 4	5,08x20	
	13,8	1,11	77	1,5	MW 082 - 90 L* 4	3,18x32	
	13,8	1,1	76	1,32	MW 082 - 90 L 4	2,54x40	
	14,1	1,11	75	1,5	MW 082 - 100 LA 6	2 x32	
	14,2	1,13	76	1,6	MW 082 - 90 LC 6	2,54x25	
	14,3	1,06	71	1,06	MW 081 - 100 LA 6	63	
	14,3	1,06	71	1,06	MW 081 - 90 LC 6	63	
	14,3	1,09	73	2	MW 091 - 100 LA 6	63	
	1,22	17,2	1,1	61	0,85	MW 062 - 90 L* 4	2,54x32
	1,23	17,5	1,09	60	0,8	MW 062 - 90 L 4	2 x40
	1,22	17,2	1,1	61	1	MW 072 - 90 L* 4	2,54x32
	1,23	17,5	1,09	60	0,95	MW 072 - 90 L 4	2 x40
	1,24	18	1,12	60	0,95	MW 062 - 90 LC 6	2 x25
	1,24	18	1,12	60	1,18	MW 072 - 90 LC 6	2 x25
	1,23	18	1,07	57	0,71	MW 061 - 100 LA 6	50
	1,23	18	1,07	57	0,71	MW 061 - 90 LC 6	50
	1,23	18	1,07	57	0,85	MW 071 - 90 LC 6	50
	17,6	1,15	62	1,9	MW 082 - 90 L* 4	3,18x25	
	17,2	1,13	63	1,7	MW 082 - 90 L 4	2,54x32	
	17,2	1,15	61	1,9	MW 082 - 100 LA 6	2 x25	
	18	1,11	59	1,32	MW 081 - 100 LA 6	50	
	18	1,11	59	1,32	MW 081 - 90 LC 6	50	
	18	1,14	60	2,24	MW 091 - 100 LA 6	50	
	22,1	1,14	49,4	1,12	MW 062 - 90 L* 4	2,54x25	
	21,9	1,13	49,2	1	MW 062 - 90 L 4	2 x32	
	22,1	1,14	49,4	1,32	MW 072 - 90 L* 4	2,54x25	
	21,9	1,13	49,2	1,18	MW 072 - 90 L 4	2 x32	
	22,2	1,07	46,1	0,75	MW 061 - 90 L 4	63	
	22,2	1,07	46,1	0,85	MW 071 - 90 L 4	63	
	22,5	1,11	47,3	0,95	MW 061 - 100 LA 6	40	
	22,5	1,11	47,3	1,12	MW 071 - 100 LA 6	40	
	22,5	1,11	47,3	0,95	MW 061 - 90 LC 6	40	
	22,5	1,11	47,3	1,12	MW 071 - 90 LC 6	40	
	22,1	1,17	51	2,12	MW 082 - 90 L 4	2,54x25	
	22,2	1,11	47,8	1,4	MW 081 - 90 L 4	63	
	22,5	1,15	48,8	1,8	MW 081 - 100 LA 6	40	
	22,5	1,15	48,8	1,8	MW 081 - 90 LC 6	40	
0,96	28	1,13	38,7	0,71	MW 042 - 90 L 4	2 x25	
0,96	28	1,13	38,7	0,85	MW 052 - 90 L 4	2 x25	
0,95	28,1	1,12	38	0,75	MW 051 - 90 LC 6	32	
	28	1,16	39,6	1,32	MW 062 - 90 L 4	2 x25	
	28	1,16	39,6	1,6	MW 072 - 90 L 4	2 x25	
	28	1,12	38,3	0,95	MW 061 - 90 L 4	50	
	28	1,12	38,3	1,12	MW 071 - 90 L 4	50	

Values in red state nominal thermal power P_{th} (ambient temperature 40 °C, continuous duty, see ch. 4).


1) Powers valid for continuous duty S1; **increase** possible for S2 ... S10 (see ch. 2b) in which case P_2 , M_2 increase and fs decreases proportionately.

2) For complete designation when ordering see ch. 3.

* Mounting position B5R (see table ch. 2b).



9. Manufacturing programme (garmotors)



P_1 kW	n_2 min ⁻¹	P_2 kW	M_2 daN m	fs	Gear reducer - Motor		i
1)					2)		
1,5	28,1	1,15	39	1,18	MW	061 - 100 LA 6	32
	28,1	1,15	39	1,4	MW	071 - 100 LA 6	32
	28,1	1,15	39	1,18	MW	061 - 90 LC 6	32
	28,1	1,15	39	1,4	MW	071 - 90 LC 6	32
	27,6	1,24	43	2,36	MW	082 - 90 L 4	2,54x20
	28	1,15	39,4	1,8	MW	081 - 90 L 4	50
1,24	35	1,22	33,2	0,71	MW	042 - 90 L 4	2 x20
1,24	35	1,22	33,2	0,85	MW	052 - 90 L 4	2 x20
1,08	35	1,14	31	0,67	MW	041 - 90 L 4	40
1,08	35	1,14	31	0,8	MW	051 - 90 L 4	40
1,06	36	1,16	30,7	0,85	MW	041 - 100 LA 6	25
1,06	36	1,16	30,7	1	MW	051 - 100 LA 6	25
1,06	36	1,16	30,7	0,85	MW	041 - 90 LC 6	25
1,06	36	1,16	30,7	1	MW	051 - 90 LC 6	25
34,5	1,24	34,5	1,5	MW	062 - 90 L* 4	2,54x16	
35	1,24	33,7	1,32	MW	062 - 90 L 4	2 x20	
34,5	1,24	34,5	1,8	MW	072 - 90 L* 4	2,54x16	
35	1,24	33,7	1,6	MW	072 - 90 L 4	2 x20	
35	1,16	31,7	1,25	MW	061 - 90 L 4	40	
35	1,16	31,7	1,5	MW	071 - 90 L 4	40	
36	1,18	31,4	1,6	MW	061 - 100 LA 6	25	
36	1,18	31,4	1,9	MW	071 - 100 LA 6	25	
36	1,18	31,4	1,6	MW	061 - 90 LC 6	25	
36	1,18	31,4	1,9	MW	071 - 90 LC 6	25	
34,5	1,26	34,9	2,8	MW	082 - 90 L 4	2,54x16	
35	1,19	32,4	2,36	MW	081 - 90 L 4	40	
43,8	1,24	27	0,9	MW	042 - 90 L 4	2 x16	
43,8	1,24	27	1,12	MW	052 - 90 L 4	2 x16	
1,17	43,8	1,16	25,4	0,85	MW	041 - 90 L 4	32
1,17	43,8	1,16	25,4	1	MW	051 - 90 L 4	32
43,8	1,26	27,5	1,7	MW	062 - 90 L 4	2 x16	
43,8	1,26	27,5	2,12	MW	072 - 90 L 4	2 x16	
43,8	1,19	26	1,6	MW	061 - 90 L 4	32	
43,8	1,19	26	1,9	MW	071 - 90 L 4	32	
0,84	56	1,17	20	0,67	MW	031 - 90 L 4	25
56	1,2	20,4	1,06	MW	041 - 90 L 4	25	
56	1,2	20,4	1,25	MW	051 - 90 L 4	25	
56,3	1,25	21,3	1,12	MW	041 - 100 LA 6	16	
56	1,22	20,8	2	MW	061 - 90 L 4	25	
56	1,22	20,8	2,36	MW	071 - 90 L 4	25	
0,92	70	1,2	16,3	0,8	MW	031 - 90 L 4	20
70	1,27	17,3	1,12	MW	041 - 90 L 4	20	
70	1,27	17,3	1,32	MW	051 - 90 L 4	20	
69,2	1,27	17,6	1,5	MW	051 - 100 LA 6	13	
69,2	1,27	17,6	1,25	MW	041 - 90 LC 6	13	
69,2	1,27	17,6	1,5	MW	051 - 90 LC 6	13	
70	1,28	17,5	2,12	MW	061 - 90 L 4	20	
70	1,28	17,5	2,5	MW	071 - 90 L 4	20	
1,18	87,5	1,26	13,8	0,85	MW	031 - 90 L 4	16
87,5	1,28	14	1,4	MW	041 - 90 L 4	16	
87,5	1,28	14	1,7	MW	051 - 90 L 4	16	
87,5	1,3	14,2	2,65	MW	061 - 90 L 4	16	
87,5	1,3	14,2	3,15	MW	071 - 90 L 4	16	
108	1,29	11,4	1	MW	031 - 90 L 4	13	
108	1,3	11,5	1,6	MW	041 - 90 L 4	13	
108	1,3	11,5	1,9	MW	051 - 90 L 4	13	
0,89	140	1,23	8,4	0,67	MW	021 - 80 C 2	20
140	1,3	8,9	1,18	MW	031 - 90 L 4	10	
140	1,33	9,1	2	MW	041 - 90 L 4	10	
1,15	175	1,29	7	0,71	MW	021 - 80 C 2	16
	175	1,3	7,1	1,25	MW	031 - 80 C 2	16
	175	1,3	7,1	1,32	MW	031 - 90 S 2	16
	175	1,32	7,2	2,12	MW	041 - 80 C 2	16
	175	1,32	7,2	2,12	MW	041 - 90 S 2	16
200	1,34	6,4	1,5	MW	031 - 90 L 4	7	
200	1,36	6,5	2,5	MW	041 - 90 L 4	7	
1,25	215	1,31	5,8	0,85	MW	021 - 80 C 2	13
215	1,32	5,9	1,5	MW	031 - 80 C 2	13	
215	1,32	5,9	1,5	MW	031 - 90 S 2	13	
215	1,33	5,9	2,36	MW	041 - 80 C 2	13	
215	1,33	5,9	2,36	MW	041 - 90 S 2	13	


P_1 kW	n_2 min ⁻¹	P_2 kW	M_2 daN m	fs	Gear reducer - Motor		i
1)					2)		
1,5	280	1,32	4,52	1	MW	021 - 80 C 2	10
	280	1,33	4,55	1,7	MW	031 - 80 C 2	10
	280	1,33	4,55	1,7	MW	031 - 90 S 2	10
	400	1,36	3,24	1,25	MW	021 - 80 C 2	7
	400	1,36	3,25	2,24	MW	031 - 80 C 2	7
	400	1,36	3,25	2,24	MW	031 - 90 S 2	7
1,85	3,64	1,23	323	0,75	MW	093 - 90 LB 4	12 x32
	3,64	1,23	323	0,85	MW	103 - 90 LB 4	12 x32
	3,57	1,2	322	1	MW	112 - 100 LB 6	4 x63
	3,57	1,2	322	1,18	MW	122 - 100 LB 6	4 x63
	3,57	1,24	332	1,8	MW	132 - 100 LB 6	4 x63
	4,49	1,25	267	0,85	MW	093 - 90 LB 4	9,75x32
	4,49	1,25	267	1	MW	103 - 90 LB 4	9,75x32
	4,57	1,19	250	0,75	MW	102 - 100 LB 6	3,13x63
	4,5	1,27	269	1,32	MW	112 - 100 LB 6	4 x50
	4,5	1,27	269	1,5	MW	122 - 100 LB 6	4 x50
	5,52	1,24	215	0,9	MW	093 - 90 LB 4	6,34x40
	5,52	1,24	215	1,06	MW	103 - 90 LB 4	6,34x40
	5,47	1,27	222	1	MW	093 - 100 LB 6	5,15x32
	5,47	1,27	222	1,18	MW	103 - 100 LB 6	5,15x32
	5,76	1,22	203	0,75	MW	092 - 90 LB 4	3,86x63
	5,76	1,22	203	0,85	MW	102 - 90 LB 4	3,86x63
	5,76	1,26	209	0,85	MW	092 - 100 LB 6	3,13x50
	5,76	1,26	209	0,95	MW	102 - 100 LB 6	3,13x50
	5,63	1,31	223	1,8	MW	112 - 100 LB 6	4 x40
	5,63	1,31	223	2,12	MW	122 - 100 LB 6	4 x40
	6,93	1,3	179	0,75	MW	083 - 90 LB 4	8,08x25
	6,9	1,3	180	1,18	MW	093 - 90 LB 4	6,34x32
	6,9	1,3	180	1,4	MW	103 - 90 LB 4	6,34x32
	7,26	1,28	169	1,18	MW	092 - 90 LB 4	3,86x50
	7,26	1,28	169	1,18	MW	102 - 90 LB 4	3,86x50
	7,2	1,29	172	1,12	MW	092 - 100 LB 6	3,13x40
	7,2	1,29	172	1,32	MW	102 - 100 LB 6	3,17x40
	7,09	1,34	181	2,5	MW	122 - 100 LB 6	3,17x40
	8,62	1,29	143	0,85	MW	083 - 90 LB 4	5,08x32
	9,21	1,31	135	0,8	MW	082 - 90 LB*4	3,8 x40
	9	1,28	136	0,67	MW	082 - 100 LB 6	2 x50
	8,83	1,42	154	1,25	MW	093 - 90 LB 4	6,34x25
	8,83	1,42	154	1,5	MW	103 - 90 LB 4	6,34x25
	9,07	1,32	139	1,32	MW	092 - 90 LB 4	3,86x40
	9,07	1,32	139	1,6	MW	102 - 90 LB 4	3,86x40
	11	1,34	116	1,12	MW	083 - 90 LB 4	5,08x25
	11,5	1,34	111	1,06	MW	082 - 90 LB*4	3,8 x32
	11	1,3	113	0,8	MW	082 - 100 LB 6	2,54x50
	11,3	1,33	113	0,9	MW	082 - 100 LB 6	2 x40
	11,2	1,35	115	1,5	MW	092 - 90 LB 4	3,13x40
	11,2	1,35	115	1,8	MW	102 - 90 LB 4	3,13x40
	11,1	1,37	118	1,7	MW	092 - 100 LB 6	2,54x32
	11,1	1,37	118	2	MW	102 - 100 LB 6	2,54x32
	14,1	1,34	91	0,71	MW	072 - 100 LB 6	2 x32
	13,8	1,45	101	1,12	MW	083 - 90 LB 4	5,08x20
	13,8	1,37	95	1,18	MW	082 - 90 LB*4	3,18x32
	13,8	1,36	94	1,06	MW	082 - 90 LB 4	2,54x40
	14,1	1,37	93	1,25	MW	082 - 100 LB 6	2 x32
	14,3	1,31	87	0,85	MW	081 - 100 LB 6	63
	14	1,4	96	2	MW	092 - 90 LB 4	3,13x32
	14,3	1,35	90	1,4	MW	091 - 100 LB 6	63
	14,3	1,35	90	1,6	MW	101 - 100 LB 6	63
	17,2	1,36	75	0,71	MW	062 - 90 LB*4	2,54x32
	17,2	1,36	75	0,85	MW	072 - 90 LB*4	2,54x32
	17,3	1,35	73	0,75	MW	072 - 90 LB 4	2 x40
	17,4	1,38	73	0,8	MW	062 - 100 LB 6	2 x25
	17,4	1,38	73	0,95	MW	072 - 100 LB 6	2 x25
	17,37	1,32	70	0,71	MW	071 - 100 LB 6	50
	17,6	1,42	77	1,5	MW	082 - 90 LB*4	3,18x25
	17,2	1,39	77	1,4	MW	082 - 90 LB 4	2,54x32
	18	1,37	73	1,12	MW	081 - 100 LB 6	50
	17,9	1,51	80	2,12	MW	092 - 90 LB 4	3,13x25
	18	1,4	74	1,8	MW	091 - 100 LB 6	50

Values in red state nominal thermal power P_{tN} (ambient temperature 40 °C, continuous duty, see ch. 4).

1) Powers valid for continuous duty S1; **increase** possible for S2 ... S10 (see ch. 2b) in which case P_2 , M_2 increase and fs decreases proportionately.

2) For complete designation when ordering see ch. 3.

* Mounting position B5R (see table ch. 2b).



P₁ kW	n₂ min ⁻¹	P₂ kW	M₂ daN m	fs	Gear reducer - Motor			i
1)					2)			
1)								
1,85	18	1,4	74	2,12	MW	101 - 100 LB 6	50	
1,36	22,1	1,41	61	0,9	MW	062 - 90 LB*4	2,54x25	
1,35	21,9	1,39	61	0,8	MW	062 - 90 LB 4	2 x32	
1,36	22,1	1,41	61	1,06	MW	072 - 90 LB*4	2,54x25	
1,35	21,9	1,39	61	1	MW	072 - 90 LB 4	2 x32	
1,32	22,2	1,32	57	0,71	MW	071 - 90 LB 4	63	
1,36	22,5	1,38	58	0,75	MW	061 - 100 LB 6	40	
1,52	22,5	1,38	58	0,9	MW	071 - 100 LB 6	40	
22,1	1,44	63	1,8		MW	082 - 90 LB 4	2,54x25	
22,2	1,37	59	1,12		MW	081 - 90 LB 4	63	
22,5	1,42	60	1,5		MW	081 - 100 LB 6	40	
22,5	1,43	61	2,36		MW	091 - 100 LB 6	40	
0,96	28	1,4	47,7	0,67	MW	052 - 90 LB 4	2 x25	
1,49	28	1,43	48,9	1,06	MW	062 - 90 LB 4	2 x25	
1,49	28	1,43	48,9	1,25	MW	072 - 90 LB 4	2 x25	
1,49	28	1,39	47,2	0,8	MW	061 - 90 LB 4	50	
1,49	28	1,39	47,2	0,95	MW	071 - 90 LB 4	50	
1,49	28,1	1,42	48,1	0,95	MW	061 - 100 LB 6	32	
28,1	1,42	48,1	1,18		MW	071 - 100 LB 6	32	
27,5	1,54	53	2		MW	082 - 90 LB*4	3,18x16	
27,6	1,53	53	1,9		MW	082 - 90 LB 4	2,54x20	
28	1,42	48,6	1,5		MW	081 - 90 LB 4	50	
28,1	1,45	49,2	1,9		MW	081 - 100 LB 6	32	
1,24	35	1,5	41	0,71	MW	052 - 90 LB 4	2 x20	
1,06	36	1,43	37,8	0,67	MW	041 - 100 LB 6	25	
1,06	36	1,43	37,8	0,8	MW	051 - 100 LB 6	25	
34,5	1,53	42,5	1,18		MW	062 - 90 LB*4	2,54x16	
35	1,52	41,6	1,06		MW	062 - 90 LB 4	2 x20	
34,5	1,53	42,5	1,4		MW	072 - 90 LB*4	2,54x16	
35	1,52	41,6	1,32		MW	072 - 90 LB 4	2 x20	
35	1,43	39,1	1		MW	061 - 90 LB 4	40	
35	1,43	39,1	1,18		MW	071 - 90 LB 4	40	
36	1,46	38,7	1,25		MW	061 - 100 LB 6	25	
36	1,46	38,7	1,5		MW	071 - 100 LB 6	25	
34,5	1,55	43,1	2,36		MW	082 - 90 LB 4	2,54x16	
35	1,47	40	2		MW	081 - 90 LB 4	40	
1,34	43,8	1,53	33,3	0,75	MW	042 - 90 LB 4	2 x16	
1,34	43,8	1,53	33,3	0,9	MW	052 - 90 LB 4	2 x16	
1,17	43,8	1,43	31,3	0,67	MW	041 - 90 LB 4	32	
1,17	43,8	1,43	31,3	0,8	MW	051 - 90 LB 4	32	
43,8	1,55	33,9	1,4		MW	062 - 90 LB 4	2 x16	
43,8	1,55	33,9	1,7		MW	072 - 90 LB 4	2 x16	
43,8	1,47	32,1	1,25		MW	061 - 90 LB 4	32	
43,8	1,47	32,1	1,5		MW	071 - 90 LB 4	32	
43,8	1,49	32,6	2,5		MW	081 - 90 LB 4	32	
1,3	56	1,48	25,2	0,85	MW	041 - 90 LB 4	25	
1,3	56	1,48	25,2	1	MW	051 - 90 LB 4	25	
56	1,51	25,7	1,6		MW	061 - 90 LB 4	25	
56	1,51	25,7	1,9		MW	071 - 90 LB 4	25	
70	1,56	21,3	0,9		MW	041 - 90 LB 4	20	
70	1,56	21,3	1,12		MW	051 - 90 LB 4	20	
70	1,58	21,6	1,7		MW	061 - 90 LB 4	20	
70	1,58	21,6	2		MW	071 - 90 LB 4	20	
1,18	87,5	1,56	17	0,71	MW	031 - 90 LB 4	16	
87,5	1,58	17,3	1,18		MW	041 - 90 LB 4	16	
87,5	1,58	17,3	1,4		MW	051 - 90 LB 4	16	
87,5	1,6	17,5	2,12		MW	061 - 90 LB 4	16	
87,5	1,6	17,5	2,65		MW	071 - 90 LB 4	16	
1,29	108	1,58	14,1	0,8	MW	031 - 90 LB 4	13	
108	1,6	14,2	1,32		MW	041 - 90 LB 4	13	
108	1,6	14,2	1,6		MW	051 - 90 LB 4	13	
108	1,62	14,4	2,5		MW	061 - 90 LB 4	13	
108	1,62	14,4	3		MW	071 - 90 LB 4	13	
1,4	140	1,61	11	0,95	MW	031 - 90 LB 4	10	
140	1,64	11,2	1,6		MW	041 - 90 LB 4	10	
140	1,64	11,2	1,9		MW	051 - 90 LB 4	10	
175	1,61	8,8	1		MW	031 - 90 SB 2	16	
175	1,62	8,9	1,7		MW	041 - 90 SB 2	16	
175	1,62	8,9	2		MW	051 - 90 SB 2	16	
200	1,65	7,9	1,18		MW	031 - 90 LB 4	7	


Values in red state nominal thermal power P_{IN} (ambient temperature 40 °C, continuous duty, see ch. 4).

1) Powers valid for continuous duty S1; increase possible for S2 ... S10 (see ch. 2b) in which case P_2 , M_2 increase and fs decreases proportionately.

2) For complete designation when ordering see ch. 3.

* Mounting position B5R (see table ch. 2b).

P₁ kW	n₂ min ⁻¹	P₂ kW	M₂ daN m	fs	Gear reducer - Motor			i
1)					2)			
1)								
1,85	200	1,67	8	2	MW	041 - 90 LB 4	7	
215	1,63	7,2	1,18		MW	031 - 90 SB 2	13	
215	1,64	7,3	2		MW	041 - 90 SB 2	13	
280	1,64	5,6	1,4		MW	031 - 90 SB 2	10	
280	1,67	5,7	2,36		MW	041 - 90 SB 2	10	
400	1,68	4,01	1,8		MW	031 - 90 SB 2	7	
400	1,7	4,05	3		MW	041 - 90 SB 2	7	
2)								
2,2 1,75	3,64	1,46	384	0,71	MW	103 - 90 LC 4	12	x32
3,57	1,43	383	0,85		MW	112 - 112 M 6	4	x63
3,57	1,43	383	0,95		MW	122 - 112 M 6	4	x63
3,57	1,48	395	1,5		MW	132 - 112 M 6	4	x63
4,49	1,49	317	0,71		MW	093 - 90 LC 4	9,75x32	
4,49	1,49	317	0,85		MW	103 - 90 LC 4	9,75x32	
4,5	1,51	320	1,12		MW	112 - 112 M 6	4	x50
4,5	1,51	320	1,32		MW	122 - 112 M 6	4	x50
4,5	1,55	329	2,24		MW	132 - 112 M 6	4	x50
5,53	1,51	261	0,85		MW	093 - 100 LA 4	7,91x32	
5,53	1,51	261	1		MW	103 - 100 LA 4	7,91x32	
5,76	1,45	241	0,71		MW	102 - 90 LC 4	3,86x63	
5,76	1,5	248	0,71		MW	092 - 112 M 6	3,13x50	
5,76	1,5	248	0,8		MW	102 - 112 M 6	3,13x50	
5,56	1,5	257	1,12		MW	112 - 100 LA 4	4	x63
5,56	1,5	257	1,32		MW	122 - 100 LA 4	4	x63
5,63	1,56	265	1,5		MW	112 - 112 M 6	4	x40
5,63	1,56	265	1,8		MW	122 - 112 M 6	4	x40
6,8	1,51	212	0,9		MW	093 - 100 LA 4	5,15x40	
6,8	1,51	212	1,06		MW	103 - 100 LA 4	5,15x40	
6,9	1,55	214	1		MW	093 - 90 LC 4	6,34x32	
6,9	1,55	214	1,18		MW	103 - 90 LC 4	6,34x32	
7,11	1,49	199	0,71		MW	092 - 100 LA 4	3,13x63	
7,11	1,49	199	0,85		MW	102 - 100 LA 4	3,13x63	
7,26	1,53	201	0,8		MW	092 - 90 LC 4	3,86x50	
7,26	1,53	201	0,95		MW	102 - 90 LC 4	3,86x50	
7,2	1,54	204	0,9		MW	092 - 112 M 6	3,13x40	
7,2	1,54	204	1,12		MW	102 - 112 M 6	3,13x40	
7	1,57	214	1,5		MW	112 - 100 LA 4	4	x50
7	1,57	214	1,8		MW	122 - 100 LA 4	4	x50
7,09	1,59	215	1,8		MW	112 - 112 M 6	3,17x40	
7,09	1,59	215	2,12		MW	122 - 112 M 6	3,17x40	
8,62	1,54	170	0,71		MW	083 - 90 LC 4	5,08x32	
8,5	1,57	177	1,18		MW	093 - 100 LA 4	5,15x32	
8,5	1,57	177	1,4		MW	103 - 100 LA 4	5,15x32	
8,96	1,56	166	0,95		MW	092 - 100 LA 4 </		




P_1 kW	n_2 min ⁻¹	P_2 kW	M_2 daN m	fs	Gear reducer - Motor	i		P_1 kW	n_2 min ⁻¹	P_2 kW	M_2 daN m	fs	Gear reducer - Motor	i		
1)					2)			1)						2)		
2,2	14,3	1,6	107	1,18	MW 091 -112 M 6	63		2,2	1,67	70	1,86	25,3	0,9	MW 051 -100 LA 4	20	
	14,3	1,6	107	1,4	MW 101 -112 M 6	63			1,67	70	1,86	25,3	0,75	MW 041 - 90 LC 4	20	
	14,3	1,65	110	2,12	MW 111 -112 M 6	63			1,67	70	1,86	25,3	0,9	MW 051 - 90 LC 4	20	
	17,5	1,65	90	1,06	MW 082 - 100 LA 4	2 x40			70	1,88	25,7	1,4	MW 061 -100 LA 4	20		
	17,2	1,66	92	1,18	MW 082 - 90 LC 4	2,54x32			70	1,88	25,7	1,7	MW 071 -100 LA 4	20		
	18	1,69	89	1,32	MW 082 -112 M 6	2 x25			70	1,88	25,7	1,4	MW 061 - 90 LC 4	20		
	18	1,63	86	0,9	MW 081 -112 M 6	50			70	1,88	25,7	1,7	MW 071 - 90 LC 4	20		
	17,3	1,7	94	1,9	MW 092 - 100 LA 4	2,54x32			69,2	1,89	26,1	1,6	MW 061 -112 M 6	13		
	17,9	1,79	95	1,8	MW 092 - 90 LC 4	3,13x25			69,2	1,89	26,1	1,9	MW 071 -112 M 6	13		
	18	1,66	88	1,5	MW 091 -112 M 6	50			70	1,9	26	2,8	MW 081 -100 LA 4	20		
	18	1,66	88	1,8	MW 101 -112 M 6	50										
1,35	21,9	1,65	72	0,71	MW 062 - 90 LC 4	2 x32		1,81	87,5	1,88	20,5	0,95	MW 041 -100 LA 4	16		
1,35	21,9	1,65	72	0,85	MW 072 - 90 LC 4	2 x32		1,81	87,5	1,88	20,5	1,18	MW 051 -100 LA 4	16		
1,52	22,5	1,64	69	0,75	MW 071 -112 M 6	40		1,81	87,5	1,88	20,5	0,95	MW 041 - 90 LC 4	16		
	21,9	1,69	74	1,4	MW 082 - 100 LA 4	2 x32			87,5	1,91	20,8	1,8	MW 061 -100 LA 4	16		
	22,1	1,72	74	1,5	MW 082 - 90 LC 4	2,54x25			87,5	1,91	20,8	2,12	MW 071 -100 LA 4	16		
	22,2	1,63	70	0,95	MW 081 -100 LA 4	63			87,5	1,91	20,8	1,8	MW 061 - 90 LC 4	16		
	22,2	1,63	70	0,95	MW 081 - 90 LC 4	63			87,5	1,91	20,8	2,12	MW 071 - 90 LC 4	16		
	22,5	1,69	72	1,25	MW 081 -112 M 6	40			108	1,91	16,9	1,12	MW 041 -100 LA 4	13		
	22,1	1,82	78	2	MW 092 - 100 LA 4	2,54x25			108	1,91	16,9	1,32	MW 051 -100 LA 4	13		
	22,2	1,67	72	1,6	MW 091 -100 LA 4	63			108	1,91	16,9	1,12	MW 041 - 90 LC 4	13		
	22,2	1,67	72	1,9	MW 101 -100 LA 4	63			108	1,91	16,9	1,32	MW 051 - 90 LC 4	13		
	22,5	1,7	72	2	MW 091 -112 M 6	40			108	1,93	17,1	2,12	MW 061 -100 LA 4	13		
1,49	28	1,7	58	0,9	MW 062 - 90 LC 4	2 x25			108	1,93	17,1	2,5	MW 071 -100 LA 4	13		
1,49	28	1,7	58	1,06	MW 072 - 90 LC 4	2 x25			108	1,93	17,1	2,12	MW 061 - 90 LC 4	13		
1,49	28	1,65	56	0,67	MW 061 -100 LA 4	50			108	1,93	17,1	2,5	MW 071 - 90 LC 4	13		
1,74	28	1,65	56	0,8	MW 071 -100 LA 4	50			140	1,95	13,3	1,4	MW 041 -100 LA 4	10		
1,49	28	1,65	56	0,67	MW 061 - 90 LC 4	50			140	1,95	13,3	1,6	MW 051 -100 LA 4	10		
1,49	28	1,65	56	0,8	MW 071 - 90 LC 4	50			140	1,95	13,3	1,4	MW 041 - 90 LC 4	10		
1,49	28,1	1,69	57	0,8	MW 061 -112 M 6	32			140	1,95	13,3	1,6	MW 051 - 90 LC 4	10		
1,66	28,1	1,69	57	0,95	MW 071 -112 M 6	32			140	1,97	13,4	2,5	MW 061 -100 LA 4	10		
	28	1,75	60	1,7	MW 082 - 100 LA 4	2 x25			140	1,97	13,4	3	MW 071 - 100 LA 4	10		
	27,6	1,82	63	1,6	MW 082 - 90 LC 4	2,54x20			140	1,97	13,4	2,5	MW 061 - 90 LC 4	10		
	28	1,69	58	1,25	MW 081 -100 LA 4	50			140	1,97	13,4	3	MW 071 - 90 LC 4	10		
	28	1,69	58	1,25	MW 081 - 90 LC 4	50			175	1,91	10,4	0,85	MW 031 - 90 LA 2	16		
	28	1,72	58	1,6	MW 081 -112 M 6	32			175	1,93	10,5	1,4	MW 041 - 90 LA 2	16		
	27,6	1,84	64	2,65	MW 092 - 100 LA 4	2,54x20			175	1,93	10,5	1,7	MW 051 - 90 LA 2	16		
	28	1,73	59	2	MW 091 -100 LA 4	50			175	1,95	10,6	2,65	MW 061 - 90 LA 2	16		
	35	1,81	49,5	0,9	MW 062 - 90 LC 4	2 x20			200	1,99	9,5	1,7	MW 041 -100 LA 4	7		
	35	1,81	49,5	1,06	MW 072 - 90 LC 4	2 x20			200	1,99	9,5	2	MW 051 -100 LA 4	7		
1,66	35	1,7	46,5	0,85	MW 061 -100 LA 4	40			200	1,99	9,5	1,7	MW 041 - 90 LC 4	7		
	35	1,7	46,5	1	MW 071 -100 LA 4	40			200	1,99	9,5	2	MW 051 - 90 LC 4	7		
1,66	35	1,7	46,5	0,85	MW 061 - 90 LC 4	40			215	1,94	8,6	1	MW 031 - 90 LA 2	13		
1,66	35	1,7	46,5	1	MW 071 - 90 LC 4	40			215	1,95	8,7	1,6	MW 041 - 90 LA 2	13		
1,65	36	1,74	46,1	1,06	MW 061 -112 M 6	25			215	1,95	8,7	2	MW 051 - 90 LA 2	13		
1,84	36	1,74	46,1	1,25	MW 071 -112 M 6	25			280	1,96	6,7	1,18	MW 031 - 90 LA 2	10		
	35	1,84	50	1,9	MW 082 - 100 LA 4	2 x20			280	1,99	6,8	2	MW 041 - 90 LA 2	10		
	34,5	1,85	51	1,9	MW 082 - 90 LC 4	2,54x16			400	2	4,77	1,5	MW 031 - 90 LA 2	7		
	35	1,74	47,6	1,7	MW 081 -100 LA 4	40			400	2,02	4,82	2,5	MW 041 - 90 LA 2	7		
	35	1,74	47,6	1,7	MW 081 - 90 LC 4	40										
	36	1,78	47,1	2	MW 081 -112 M 6	25										
	35	1,76	48,1	2,65	MW 091 -100 LA 4	40										
1,34	43,8	1,82	39,6	0,75	MW 052 - 90 LC 4	2 x16			3	3,57	1,95	522	0,71	MW 122 -112 MC 6	4 x63	
1,17	43,8	1,71	37,2	0,67	MW 051 - 90 LC 4	32				3,57	2,02	539	1,12	MW 132 -112 MC 6	4 x63	
	43,8	1,85	40,3	1,18	MW 062 - 90 LC 4	2 x16				3,76	2,09	531	2,12	MW 142 -132 S 6	3,8 x63	
	43,8	1,85	40,3	1,4	MW 072 - 90 LC 4	2 x16				4,5	2,06	436	0,8	MW 112 -112 MC 6	4 x50	
1,83	43,8	1,75	38,2	1,06	MW 061 -100 LA 4	32				4,5	2,06	436	0,95	MW 122 -112 MC 6	4 x50	
	43,8	1,75	38,2	1,25	MW 071 -100 LA 4	32				4,5	2,12	449	1,6	MW 132 -112 MC 6	4 x50	
1,83	43,8	1,75	38,2	1,06	MW 061 - 90 LC 4	32				4,74	2,18	440	3	MW 142 -132 S 6	3,8 x50	
1,83	43,8	1,75	38,2	1,25	MW 071 - 90 LC 4	32				5,53	2,06	356	0,71	MW 103 -100 LB 4	7,91 x32	
	43,8	1,87	40,8	2,24	MW 082 - 100 LA 4	2 x16				5,56	2,04	351	0,85	MW 112 -100 LB 4	4 x63	
	43,8	1,78	38,8	2,12	MW 081 -100 LA 4	32				5,56	2,04	351	0,95	MW 122 -100 LB 4	4 x63	
1,3	56	1,76	29,9	0,75	MW 041 -100 LA 4	25				5,63	2,13	362	1,12	MW 112 -112 MC 6	4 x40	
1,3	56	1,76	29,9	0,85	MW 051 -100 LA 4	25				5,63	2,13	362	1,32	MW 122 -112 MC 6	4 x40	
1,3	56	1,76	29,9	0,75	MW 041 - 90 LC 4	25				5,56	2,11	362	1,6	MW 132 -100 LB 4	4 x63	
1,3	56	1,76	29,9	0,85	MW 051 - 90 LC 4	25				5,63	2,18	371	2,12	MW 132 -112 MC 6	4 x40	
	56	1,79	30,5	1,4	MW 061 -100 LA 4	25				2,49	6,8	2,06	289	0,75	MW 103 -100 LB 4	5,15 x40
	56	1,79	30,5	1,6	MW 071 -100 LA 4	25				2,49	7,2	2,1	278	0,67	MW 092 -112 MC 6	3,13 x40
	56	1,79	30,5	1,4	MW 061 - 90 LC 4	25				2,49	7,2	2,1	278	0,8	MW 102 -112 MC 6	3,13 x40
	56	1,79	30,5	1,6	MW 071 - 90 LC 4	25				7	2,14	292	1,12	MW 112 -100 LB 4	4 x50	
	56	1,83	31,1	2,65	MW 081 -100 LA 4	25				7	2,14	292	1,32	MW 122 -100 LB 4	4 x50	
1,67	70	1,86	25,3	0,75	MW 041 -100 LA 4	20				7,09	2,17	293	1,32	MW 112 -112 MC 6	3,17 x40	

Values in red state nominal thermal power P_{th} (ambient temperature 40 °C, continuous duty, see ch. 4).

1) Powers valid for continuous duty S1; **increase** possible for S2 ... S10 (see ch. 2b) in which case P_2 , M_2 increase and fs decreases proportionately.

2) For complete designation when ordering see ch. 3.



P_1 kW	n_2 min ⁻¹	P_2 kW	M_2 daNm	fs	Gear reducer - Motor	i
1)	2)					
3	7,09 7	2,17 2,2	293 300	1,6 2,24	MW 122 -112 MC 6 MW 132 -100 LB 4	3,17x40 4 x50
	8,5 8,5	2,15 2,15	241 241	0,85 1	MW 093 -100 LB 4 MW 103 -100 LB 4	5,15x32 5,15x32
	8,96 8,96	2,12 2,12	226 226	0,71 0,85	MW 092 -100 LB 4 MW 102 -100 LB 4	3,13x50 3,13x50
	8,87 8,87	2,14 2,14	231 231	0,8 0,95	MW 092 -112 MC 6 MW 102 -112 MC 6	2,54x40 2,54x40
	8,75 8,75	2,21 2,21	242 242	1,6 1,8	MW 112 -100 LB 4 MW 122 -100 LB 4	4 x40 4 x40
	8,75 8,75	2,27	247	2,8	MW 132 -100 LB 4	4 x40
	11,2 11,2	2,18 2,18	186 186	0,95 1,12	MW 092 -100 LB 4 MW 102 -100 LB 4	3,13x40 3,13x40
	11,1 11,1	2,23 2,23	192 192	1,06 1,25	MW 092 -112 MC 6 MW 102 -112 MC 6	2,54x32 2,54x32
	11 11	2,26 2,26	196 196	1,8 2,12	MW 112 -100 LB 4 MW 122 -100 LB 4	3,17x40 3,17x40
2,44 2,3	13,8 14,1	2,2 2,22	152 151	0,67 0,75	MW 082 -100 LB 4* MW 082 -112 MC 6	2,54x40 2 x32
	13,8 13,8	2,23 2,23	154 154	1,06 1,32	MW 092 -100 LB 4 MW 102 -100 LB 4	2,54x40 2,54x40
	14,3 14,3	2,18 2,18	146 146	0,85 1	MW 191 -112 MC 6 MW 101 -112 MC 6	63 63
	14,3 14,3	2,18 2,18	146 146	0,85 0,85	MW 091 -132 S 6 MW 091 -132 S 6	63 63
	14,3 14,3	2,18 2,18	146 146	1 1	MW 101 -132 S 6 MW 101 -132 S 6	63 63
	14,3 14,3	2,24 2,24	150 150	1,6 1,9	MW 111 -112 MC 6 MW 121 -112 MC 6	63 63
	14,3 14,3	2,24 2,24	150 150	1,6 1,9	MW 111 -132 S 6 MW 121 -132 S 6	63 63
	17,5 18	2,25 2,3	123 122	0,8 0,95	MW 082 -100 LB 4 MW 082 -112 MC 6	2 x40 2 x25
	18 18	2,22 2,22	118 118	0,67 0,67	MW 081 -112 MC 6 MW 091 -112 MC 6	50 50
	17,3 17,3	2,32 2,32	128 128	1,4 1,7	MW 092 -100 LB 4 MW 102 -100 LB 4	2,54x32 2,54x32
	18 18	2,27 2,27	120 120	1,12 1,32	MW 091 -112 MC 6 MW 101 -112 MC 6	50 50
	18 18	2,27 2,27	120 120	1,12 1,32	MW 091 -132 S 6 MW 101 -132 S 6	50 50
	17,6 17,6	2,48 2,48	134 134	2,36 2,8	MW 112 -100 LB 4 MW 122 -100 LB 4	3,17x25 3,17x25
	18 18	2,33 2,33	123 123	2,12 2,5	MW 111 -112 MC 6 MW 121 -112 MC 6	50 50
	18 18	2,33 2,33	123 123	2,12 2,12	MW 111 -132 S 6 MW 111 -132 S 6	50 50
	21,9 22,2	2,31 2,22	101 96	1 0,71	MW 082 -100 LB 4 MW 081 -100 LB 4	2 x32 63
	22,5 22,5	2,3 2,3	98 98	0,9 0,9	MW 081 -112 MC 6 MW 081 -112 MC 6	40 40
	22,1 22,1	2,48 2,48	107 107	1,5 1,8	MW 092 -100 LB 4 MW 102 -100 LB 4	2,54x25 2,54x25
	22,2 22,2	2,5 2,5	108 108	1,7 2	MW 092 -112 MC 6 MW 102 -112 MC 6	2,54x16 2,54x16
	22,2 22,2	2,27 2,27	98 98	1,12 1,32	MW 091 -100 LB 4 MW 101 -100 LB 4	63 63
	22,2 22,2	2,27 2,27	98 98	1,32 1,32	MW 091 -100 LB 4 MW 101 -100 LB 4	63 63
	22,5 22,5	2,32 2,32	99 99	1,5 1,8	MW 091 -112 MC 6 MW 101 -112 MC 6	40 40
	22,5 22,5	2,32 2,32	99 99	1,5 1,8	MW 091 -132 S 6 MW 101 -132 S 6	40 40
1,49 1,49 1,66	28 28 28,1	2,32 2,32 2,3	79 79 78	0,67 0,8 0,71	MW 062 -100 LB 4 MW 072 -100 LB 4 MW 071 -112 MC 6	2 x25 2 x25 32
	28 28	2,38	81	1,25	MW 082 -100 LB 4	2 x25
	28 28	2,31	79	0,9	MW 081 -100 LB 4	50
	28,1 28,1	2,35 2,35	80 80	1,18 1,18	MW 081 -112 MC 6 MW 081 -132 S 6	32 32
	27,6 28	2,51 2,35	87 80	1,9 1,5	MW 092 -100 LB 4 MW 091 -100 LB 4	2,54x20 50
	28 28	2,35 2,35	80 80	1,8 1,8	MW 091 -100 LB 4 MW 101 -100 LB 4	50 50
	28,1 28,1	2,4 2,4	82 82	1,9 1,9	MW 091 -112 MC 6 MW 091 -132 S 6	32 32
	1,91 1,91	35 35	2,47 2,47	0,67 0,8	MW 062 -100 LB 4 MW 072 -100 LB 4	2 x20 2 x20


Values in red state nominal thermal power P_{th} (ambient temperature 40 °C, continuous duty, see ch. 4).

1) Powers valid for continuous duty S1; increase possible for S2 ... S10 (see ch. 2b) in which case P_2 , M_2 increase and fs decreases proportionately.

2) For complete designation when ordering see ch. 3.

* Mounting position B5R (see table ch. 2b).

P_1 kW	n_2 min ⁻¹	P_2 kW	M_2 daNm	fs	Gear reducer - Motor	i	
1)	2)						
3	1,94 1,84	35	2,32	63	0,75 MW	071 -100 LB 4	40
	36	2,37	63	0,95	MW 071 -112 MC 6	25	
	35	2,52	69	1,32	MW 082 -100 LB 4	2 x20	
	35	2,38	65	1,18	MW 081 -100 LB 4	40	
	36	2,42	64	1,5	MW 081 -112 MC 6	25	
	36	2,42	64	1,5	MW 081 -132 S 6	25	
	34,5	2,56	71	2,36	MW 092 -100 LB 4	2,54x16	
	35	2,4	66	1,9	MW 091 -100 LB 4	40	
	2,09	43,8	2,52	55	0,85 MW	062 -100 LB 4	2 x16
	2,09	43,8	2,52	55	1 MW	072 -100 LB 4	2 x16
	1,83	43,8	2,38	52	0,8 MW	061 -100 LB 4	32
	2,13	43,8	2,38	52	0,95 MW	071 -100 LB 4	32
	43,8	2,55	56	1,7	MW 082 -100 LB 4	2 x16	
	43,8	2,42	53	1,5	MW 081 -100 LB 4	32	
	43,8	2,47	54	2,5	MW 091 -100 LB 4	32	
	2,1	56	2,44	41,6	1 MW	061 -100 LB 4	25
	2,35	56	2,44	41,6	1,18 MW	071 -100 LB 4	25
	56	2,49	42,4	2	MW	081 -100 LB 4	25
	1,67	70	2,53	34,5	0,67 MW	051 -100 LB 4	20
	70	2,56	35	1,06	MW	061 -100 LB 4	20
	70	2,56	35	1,25	MW	071 -100 LB 4	20
	69,2	2,58	35,6	1,4	MW	071 -112 MC 6	13
	70	2,6	35,4	2	MW	081 -100 LB 4	20
	1,81	87,5	2,57	28	0,71 MW	041 -100 LB 4	16
	1,81	87,5	2,57	28	0,85 MW	051 -100 LB 4	16
	87,5	2,6	28,4	1,32	MW	061 -100 LB 4	16
	87,5	2,6	28,4	1,6	MW	071 -100 LB 4	16
	87,5	2,62	28,6	2,5	MW	081 -100 LB 4	16
	1,97	108	2,6	23,1	0,8 MW	041 -100 LB 4	13
	1,97	108	2,6	23,1	0,95 MW	051 -100 LB 4	13
	108	2,63	23,3	1,5	MW	061 -100 LB 4	13
	108	2,66	23,6	3	MW	081 -100 LB 4	13
	2,34	140	2,66	18,2	1 MW	041 -100 LB 4	10
	2,34	140	2,66	18,2	1,18 MW	051 -100 LB 4	10
	140	2,69	18,3	1,8	MW	061 -100 LB 4	10
	140	2,69	18,3	2,24	MW	071 -100 LB 4	10
	175	2,63	14,4	1,06	MW	041 - 90 LB 2	16
	175	2,63	14,4	1,25	MW	051 - 90 LB 2	16
	175	2,66	14,5	1,9	MW	061 - 90 LB 2	16
	175	2,66	14,5	2,24	MW	071 - 90 LB 2	16
	200	2,71	13	1,25	MW	041 - 100 LB 4	7
	200	2,71	13	1,5	MW	051 - 100 LB 4	7
	200	2,73	13	2,24	MW	061 - 100 LB 4	7
	200	2,73	13	2,8	MW	071 - 100 LB 4	7
	215	2,66	11,8	1,18	MW	041 - 90 LB 2	13
	215	2,66	11,8	1,4	MW	051 - 90 LB 2	13
	215	2,68	11,9	2,24	MW	061 - 90 LB 2	13
	215	2,68	11,9	2,8	MW	071 - 90 LB 2	13
	280	2,71	9,3	1,5	MW	041 - 90 LB 2	10
	280	2,71	9,3	1,8	MW	051 - 90 LB 2	10
	400	2,75	6,6	1,8	MW	041 - 90 LB 2	7
	400	2,75	6,6	2,12	MW	051 - 90 LB 2	7
4	3,76	2,79	709	1,6	MW	142 -132 M 6	3,8 x63
	4,74	2,91	587	2,24	MW	142 -132 M 6	3,8 x50
	5,56	2,72	468	0,71	MW	122 -112 M 4	4 x63
	5,56	2,81	483	1,18	MW	132 -112 M 4	4 x63
	5,92	2,98	481	3	MW	142 -132 M 6	3,8 x40
	7	2,85	389	0,85	MW	112 -112 M 4	4 x50
	7	2,85	389	1	MW	122 -112 M 4	4 x50
	7	2,93	400	1,7	MW	132 -112 M 4	4 x50
	2,77	8,5	2,86	321	0,75 MW	103 -112 M 4	5,15x32
	8,75	2,95	322	1,18	MW	112 -112 M 4	4 x40
	8,75	2,95	322	1,4	MW	122 -112 M 4	4 x40
	8,75	3,02	330	2,12	MW	132 -112 M 4	4 x40
	10,9	3,11	273	0,8	MW	103 -112 M 4	5,15x25
	3,21	11,2	2,91	248	0,71 MW	092 -112 M 4	3,13x40
	3,21	11,2	2,91	248	0,85 MW	102 -112 M 4	3,13x40




P_1 kW	n_2 min ⁻¹	P_2 kW	M_2 daN m	fs	Gear reducer - Motor		i
1)					2)		
4	11	3,01	261	1,4	MW	112 -112 M 4	3,17x40
	11	3,01	261	1,6	MW	122 -112 M 4	3,17x40
	11	3,08	267	2,5	MW	132 -112 M 4	3,17x40
	13,6	3,17	223	1	MW	103 -112 M 4	5,15x20
	13,8	2,97	206	0,8	MW	092 -112 M 4	2,54x40
	13,8	2,97	206	0,95	MW	102 -112 M 4	2,54x40
	13,9	3,03	209	1,06	MW	102 -132 M 6	2,03x32
	14,3	2,91	195	0,75	MW	101 -132 M 6	63
	13,8	3,1	215	1,6	MW	112 -112 M 4	3,17x32
	13,8	3,1	215	2	MW	122 -112 M 4	3,17x32
	14,3	2,99	200	1,18	MW	111 -132 M 6	63
	14,3	2,99	200	1,4	MW	121 -132 M 6	63
	14,3	3,07	205	2,36	MW	131 -132 M 6	63
	17,3	3,09	171	1,06	MW	092 -112 M 4	2,54x32
	17,3	3,09	171	1,25	MW	102 -112 M 4	2,54x32
	18	3,03	161	0,85	MW	091 -132 M 6	50
	18	3,03	161	1	MW	101 -132 M 6	50
	17,6	3,31	179	1,8	MW	112 -112 M 4	3,17x25
	17,6	3,31	179	2,12	MW	122 -112 M 4	3,17x25
	18	3,1	165	1,6	MW	111 -132 M 6	50
	18	3,1	165	1,9	MW	121 -132 M 6	50
3,11	21,9	3,08	134	0,75	MW	082 -112 M 4	2 x32
	22,1	3,3	143	1,12	MW	092 -112 M 4	2,54x25
	22,1	3,3	143	1,32	MW	102 -112 M 4	2,54x25
	22,2	3,31	143	1,5	MW	102 -132 M 6	2,03x20
	22,2	3,03	130	0,85	MW	091 -112 M 4	63
	22,2	3,03	130	1	MW	101 -112 M 4	63
	22,5	3,1	131	1,12	MW	091 -132 M 6	40
	22,5	3,1	131	1,32	MW	101 -132 M 6	40
	22,1	3,36	146	2,24	MW	112 -112 M 4	3,17x20
	22,1	3,36	146	2,8	MW	122 -112 M 4	3,17x20
	22,2	3,11	134	1,6	MW	111 -112 M 4	63
	22,2	3,11	134	1,8	MW	121 -112 M 4	63
	22,5	3,18	135	2,12	MW	111 -132 M 6	40
	22,5	3,18	135	2,5	MW	121 -132 M 6	40
	28	3,18	108	0,95	MW	082 -112 M 4	2 x25
	28	3,08	105	0,67	MW	081 -112 M 4	50
	28,1	3,13	106	0,9	MW	081 -132 M 6	32
	27,6	3,35	116	1,4	MW	092 -112 M 4	2,54x20
	27,6	3,35	116	1,7	MW	102 -112 M 4	2,54x20
	28	3,14	107	1,12	MW	091 -112 M 4	50
	28	3,14	107	1,32	MW	101 -112 M 4	50
	28,1	3,2	109	1,4	MW	091 -132 M 6	32
	28,1	3,2	109	1,7	MW	101 -132 M 6	32
	27,6	3,42	118	2,8	MW	112 -112 M 4	3,17x16
	27,6	3,42	118	3,35	MW	122 -112 M 4	3,17x16
	28	3,2	109	2,12	MW	111 -112 M 4	50
	28	3,2	109	2,5	MW	121 -112 M 4	50
	35	3,35	92	1	MW	082 -112 M 4	2 x20
	35	3,17	86	0,9	MW	081 -112 M 4	40
	36	3,23	86	1,12	MW	081 -132 M 6	25
	34,5	3,41	94	1,7	MW	092 -112 M 4	2,54x16
	34,5	3,41	94	2,12	MW	102 -112 M 4	2,54x16
	35	3,2	87	1,4	MW	091 -112 M 4	40
	35	3,2	87	1,7	MW	101 -112 M 4	40
	36	3,38	90	1,6	MW	091 -132 M 6	25
	36	3,38	90	1,9	MW	101 -132 M 6	25
	35	3,28	89	2,65	MW	111 -112 M 4	40
	35	3,28	89	3,15	MW	121 -112 M 4	40
2,13	43,8	3,18	69	0,71	MW	071 -112 M 4	32
	43,8	3,4	74	1,25	MW	082 -112 M 4	2 x16
	43,8	3,23	71	1,18	MW	081 -112 M 4	32
	43,8	3,29	72	1,8	MW	091 -112 M 4	32
	43,8	3,29	72	2,24	MW	101 -112 M 4	32
2,1	56	3,26	56	0,75	MW	061 -112 M 4	25
2,35	56	3,26	56	0,9	MW	071 -112 M 4	25
	56	3,32	57	1,5	MW	081 -112 M 4	25
	56	3,45	59	2,12	MW	091 -112 M 4	25
2,58	70	3,42	46,6	0,8	MW	061 -112 M 4	20
3,01	70	3,42	46,6	0,95	MW	071 -112 M 4	20
	70	3,46	47,2	1,5	MW	081 -112 M 4	20

Values in red represent thermal power P_{th} (ambient temperature 40 °C, continuous duty, see ch. 4).

1) Powers valid for continuous duty S1; increase possible for S2 ... S10 (see ch. 2b) in which case P_2 , M_2 increase and fs decreases proportionately.

2) For complete designation when ordering see ch. 3.



P_1 kW	n_2 min ⁻¹	P_2 kW	M_2 daN m	fs	Gear reducer - Motor		i	
1)					2)			
4	69,2	3,49	48,1	1,7	MW	081 -132 M 6	13	
	70	3,5	47,7	2,5	MW	091 -112 M 4	20	
	2,82	87,5	3,47	37,8	1	MW	061-112 M 4	16
	3,29	87,5	3,47	37,8	1,18	MW	071-112 M 4	16
	87,5	3,5	38,2	1,9	MW	081 -112 M 4	16	
	3,04	108	3,51	31,1	1,12	MW	061-112 M 4	13
	108	3,51	31,1	1,32	MW	071-112 M 4	13	
	108	3,54	31,4	2,24	MW	081 -112 M 4	13	
	140	3,58	24,4	1,4	MW	061-112 M 4	10	
	140	3,58	24,4	1,7	MW	071-112 M 4	10	
	140	3,61	24,6	2,65	MW	081 -112 M 4	10	
	200	3,64	17,4	1,7	MW	061-112 M 4	7	
	200	3,64	17,4	2	MW	071-112 M 4	7	
5,5	3,76	3,84	974	1,18	MW	142 -132 MB 6	3,8 x63	
	4,74	4	807	1,6	MW	142 -132 MB 6	3,8 x50	
	5,56	3,86	664	0,85	MW	132 -112 MC 4	4 x63	
	5,59	3,86	660	0,85	MW	132 -132 MB 6	2,56 x63	
	5,85	4	653	1,6	MW	142 -132 S 4	3,8 x63	
	5,92	4,1	661	2,12	MW	142 -132 MB 6	3,8 x40	
	4,05	7	3,92	534	0,71	MW	122 -112 MC 4	4 x50
	4,05	7,04	3,92	531	0,71	MW	122 -132 MB 6	2,56 x50
	7	4,03	550	1,25	MW	132 -112 MC 4	4 x50	
	7,04	4,03	547	1,25	MW	132 -132 MB 6	2,56 x50	
	7,37	4,16	539	2,24	MW	142 -132 S 4	3,8 x50	
	4,44	8,75	4,06	443	0,85	MW	112 -112 MC 4	4 x40
	4,44	8,75	4,06	443	1	MW	122 -112 MC 4	4 x40
	8,7	3,93	431	0,71	MW	122 -132 S 4	2,56 x63	
	4,44	8,8	4,06	440	1	MW	122 -132 MB 6	2,56 x40
	8,75	4,15	453	1,5	MW	132 -112 MC 4	4 x40	
	8,7	4,05	445	1,18	MW	132 -132 S 4	2,56 x63	
	8,8	4,15	451	1,6	MW	132 -132 MB 6	2,56 x40	
	9,21	4,27	442	2,8	MW	142 -132 S 4	3,8 x40	
	11	4,14	359	1	MW	112 -112 MC 4	3,17 x40	
	11	4,14	359	1,18	MW	122 -112 MC 4	3,17 x40	
	11	4,1	357	0,85	MW	112 -132 S 4	2,56 x50	
	11	4,1	357	1	MW	122 -132 S 4	2,56 x50	
	11	4,19	363	1	MW	112 -132 MB 6	2,56 x32	
	11	4,17	362	1,25	MW	122 -132 MB 6	2,56 x32	
	11	4,21	367	1,7	MW	132 -132 S 4	2,56 x50	
	11	4,3	373	2	MW	132 -132 MB 6	2,56 x32	
	11	4,34	376	3,15	MW	142 -132 S 4	3,17 x40	
	3,7	13,8	4,09	283	0,71	MW	102 -112 MC 4	2,54 x40
	3,6	13,9	4,17	287	0,67	MW	092 -132 MB 6	2,03 x32
	3,6	13,9	4,17	287	0,8	MW	102 -132 MB 6	2,03 x32
	13,8	4,27	296	1,18	MW	112 -112 MC 4	3,17 x32	
	13,8	4,27	296	1,4	MW	122 -112 MC 4	3,17 x32	
	13,7	4,23	295	1,12	MW	112 -132 MC 4	3,17 x32	
	13,7	4,23	295	1,32	MW	122 -132 S 4	2,56 x40	
	14,3	4,11	275	0,85	MW	111 -132 MB 6	63	
	14,3	4,11	275	1	MW	121 -132 MB 6	63	
	13,7	4,32	301	2,12	MW	132 -132 S 4	2,56 x40	
	14,3	4,22	282	1,7	MW	131 -132 MB 6	63	
	4,17	17,3	4,25	235	0,75	MW	092 -112 MC 4	2,54 x32
	4,17	17,3	4,25	235	0,9	MW	102 -112 MC 4	2,54 x32
	4,36	17,2	4,18	232	0,67	MW	092 -132 S 4	2,03 x40
	4,36	17,2	4,18	232	0,8	MW	102 -132 S 4	2,03 x40
	18	4,16	221	0,75	MW	101 -132 MB 6	50	
	17,6	4,55	246	1,25	MW	112 -112 MC 4	3,17 x25	
	17,6	4,55	246	1,5	MW	122 -112 MC 4	3,17 x25	
	17,1	4,35	243	1,4	MW	112 -132 S 4	2,56 x32	
	17,1	4,35	243	1,6	MW	122 -132 S 4	2,56 x32	
	18	4,27	226	1,18	MW	111 -132 MB 6	50	
	18	4,27	226	1,4	MW	121 -132 MB 6	50	
	17,1	4,44	248	2,65	MW	132 -132 S 4	2,56 x32	
	18	4,36	231	2,36	MW	131 -132 MB 6	50	
	22,1	4,54	196	0,8	MW	092 -112 MC 4	2,54 x25	
	22,1	4,54	196	0,95	MW	102 -112 MC 4	2,54 x25	



P_1 kW	n_2 min ⁻¹	P_2 kW	M_2 daN m	fs	Gear reducer - Motor	i
1)					2)	
5,5	22,2	4,17	179	0,75	MW 101 -112 MC 4	63
	22,2	4,17	179	0,75	MW 101 -132 S 4	63
	22,5	4,26	181	0,8	MW 091 -132 MB 6	40
	22,5	4,26	181	0,95	MW 101 -132 MB 6	40
	22,1	4,62	200	1,7	MW 112 -112 MC 4	3,17x20
	22,1	4,62	200	2	MW 122 -112 MC 4	3,17x20
	21,9	4,61	201	1,5	MW 112 -132 S 4	2,56x25
	21,9	4,61	201	1,8	MW 122 -132 S 4	2,56x25
	22	4,65	202	1,8	MW 112 -132 MB 6	2,56x16
	22	4,65	202	2,12	MW 122 -132 MB 6	2,56x16
	22,2	4,28	184	1,12	MW 111 -112 MC 4	63
	22,2	4,28	184	1,32	MW 121 -112 MC 4	63
	22,2	4,28	184	1,12	MW 111 -132 S 4	63
	22,2	4,28	184	1,32	MW 121 -132 S 4	63
	22,5	4,38	186	1,5	MW 111 -132 MB 6	40
	22,5	4,38	186	1,8	MW 121 -132 MB 6	40
	22,2	4,36	188	2,12	MW 131 -132 S 4	63
3,5	28	4,37	149	0,71	MW 082 -112 MC 4	2 x25
	27,6	4,61	159	1,06	MW 092 -112 MC 4	2,54x20
	27,6	4,61	159	1,25	MW 102 -112 MC 4	2,54x20
	27,6	4,6	159	0,95	MW 092 -132 S 4	2,03x25
	27,6	4,6	159	1,12	MW 102 -132 S 4	2,03x25
	27,7	4,64	160	1,12	MW 092 -132 MB 6	2,03x16
	27,7	4,64	160	1,32	MW 102 -132 MB 6	2,03x16
	28	4,31	147	0,8	MW 091 -112 MC 4	50
	28	4,31	147	0,95	MW 101 -112 MC 4	50
	28	4,31	147	0,8	MW 091 -132 S 4	50
	28	4,31	147	0,95	MW 101 -132 S 4	50
	28	4,31	147	0,8	MW 112 -112 MC 4	3,17x16
	28	4,31	147	0,95	MW 112 -132 S 4	2,56x20
	28,1	4,4	149	1,06	MW 091 -132 MB 6	32
	28,1	4,4	149	1,25	MW 101 -132 MB 6	32
	27,6	4,7	163	2	MW 112 -112 MC 4	3,17x16
	27,4	4,68	163	1,9	MW 112 -132 S 4	2,56x20
	27,4	4,68	163	2,24	MW 122 -132 S 4	2,56x20
	28	4,4	150	1,5	MW 111 -112 MC 4	50
	28	4,4	150	1,8	MW 121 -112 MC 4	50
	28	4,4	150	1,5	MW 111 -132 S 4	50
	28,1	4,48	152	1,9	MW 111 -132 MB 6	32
	28,1	4,48	152	2,24	MW 121 -132 MB 6	32
4,45	35	4,61	126	0,75	MW 082 -112 MC 4	2 x20
	35	4,36	119	0,67	MW 081 -112 MC 4	40
4,12	36	4,44	118	0,8	MW 081 -132 MB 6	25
	34,5	4,69	130	1,25	MW 092 -112 MC 4	2,54x16
	34,5	4,69	130	1,5	MW 102 -112 MC 4	2,54x16
	34,5	4,67	129	1,18	MW 092 -132 S 4	2,03x20
	34,5	4,67	129	1,4	MW 102 -132 S 4	2,03x20
	35	4,4	120	1,06	MW 091 -112 MC 4	40
	35	4,4	120	1,25	MW 101 -112 MC 4	40
	35	4,4	120	1,06	MW 091 -132 S 4	40
	35	4,4	120	1,25	MW 101 -132 S 4	40
	36	4,65	123	1,12	MW 091 -132 MB 6	25
	36	4,65	123	1,32	MW 101 -132 MB 6	25
	34,2	4,75	133	2,36	MW 112 -132 S 4	2,56x16
	34,2	4,75	133	2,8	MW 122 -132 S 4	2,56x16
	35	4,51	123	2	MW 111 -132 S 4	40
	35	4,51	123	2,36	MW 121 -132 S 4	40
	43,8	4,68	102	0,9	MW 082 -112 MC 4	2 x16
	43,8	4,44	97	0,85	MW 081 -112 MC 4	32
	43,8	4,44	97	0,85	MW 081 -132 S 4	32
	43,1	4,74	105	1,4	MW 092 -132 S 4	2,03x16
	43,1	4,74	105	1,7	MW 102 -132 S 4	2,03x16
	43,8	4,52	99	1,32	MW 091 -112 MC 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -112 MC 4	32
	43,8	4,52	99	1,32	MW 091 -132 S 4	32
	43,8	4,52	99	1,6	MW 101 -132 S 4	32
	43,8	4,52	99	1,32	MW 121 -132 S 4	32
	43,8					



9. Manufacturing programme (garmotors)



P_1 kW	n_2 min^{-1}	P_2 kW	M_2 daN m	fs	Gear reducer - Motor		i
1)					2)		
1)							
7,5	22,1	6,3	273	1,18	MW	112 -132 M* 4	3,17x20
	21,9	6,3	274	1,12	MW	112 -132 M 4	2,56x25
	22,1	6,3	273	1,5	MW	122 -132 M* 4	3,17x20
	21,9	6,3	274	1,32	MW	122 -132 M 4	2,56x25
	22	6,3	275	1,32	MW	112 -132 MC 6	2,56x16
	22	6,3	275	1,5	MW	122 -132 MC 6	2,56x16
	22,2	5,8	251	0,85	MW	111 -132 M 4	63
	22,2	5,8	251	1	MW	121 -132 M 4	63
	22,5	6	253	1,12	MW	111 -132 MC 6	40
	22,5	6	253	1,32	MW	121 -132 MC 6	40
	22,5	6	253	1,12	MW	111 -160 M 6	40
	22,5	6	253	1,32	MW	121 -160 M 6	40
	21,9	6,4	278	2,24	MW	132 -132 M 4	2,56x25
	22,2	6	256	1,6	MW	131 -132 M 4	63
	22,5	6,1	258	2,12	MW	131 -132 MC 6	40
	22,5	6,1	258	2,12	MW	131 -160 M 6	40
5,8	27,6	6,3	217	0,75	MW	092 -132 M* 4	2,54x20
	27,6	6,3	217	0,71	MW	092 -132 M 4	2,03x25
5,8	27,6	6,3	217	0,9	MW	102 -132 M* 4	2,54x20
	27,6	6,3	217	0,8	MW	102 -132 M 4	2,03x25
5,55	27,7	6,3	218	0,95	MW	102 -132 MC 6	2,03x16
28	5,9	201	0,71	MW	101 -132 M 4	50	
5,8	28,1	6	204	0,75	MW	091 -132 MC 6	32
5,8	28,1	6	204	0,9	MW	101 -132 MC 6	32
	27,4	6,4	222	1,4	MW	112 -132 M 4	2,56x20
	27,4	6,4	222	1,7	MW	122 -132 M 4	2,56x20
	28	6	205	1,12	MW	111 -132 M 4	50
	28	6	205	1,32	MW	121 -132 M 4	50
	28,1	6,1	207	1,4	MW	111 -132 MC 6	32
	28,1	6,1	207	1,6	MW	121 -132 MC 6	32
	28,1	6,1	207	1,4	MW	111 -160 M 6	32
	28,1	6,1	207	1,6	MW	121 -160 M 6	32
	27,4	6,5	226	2,8	MW	132 -132 M 4	2,56x20
	28	6,1	209	2,12	MW	131 -132 M 4	50
34,5	6,4	177	0,95	MW	092 -132 M* 4	2,54x16	
34,5	6,4	176	0,9	MW	092 -132 M 4	2,03x20	
34,5	6,4	176	1,06	MW	102 -132 M 4	2,03x20	
35	6	164	0,75	MW	091 -132 M 4	40	
35	6	164	0,9	MW	101 -132 M 4	40	
36	6,3	168	0,85	MW	091 -132 MC 6	25	
36	6,3	168	1	MW	101 -132 MC 6	25	
34,2	6,5	181	1,7	MW	112 -132 M 4	2,56x16	
34,2	6,5	181	2	MW	122 -132 M 4	2,56x16	
35	6,1	168	1,4	MW	111 -132 M 4	40	
35	6,1	168	1,7	MW	121 -132 M 4	40	
35	6,2	170	2,65	MW	131 -132 M 4	40	
43,1	6,5	143	1,06	MW	092 -132 M 4	2,03x16	
43,1	6,5	143	1,25	MW	102 -132 M 4	2,03x16	
43,8	6,2	135	1	MW	091 -132 M 4	32	
43,8	6,2	135	1,18	MW	101 -132 M 4	32	
45	6,4	136	1,25	MW	101 -132 MC 6	20	
43,8	6,3	137	1,8	MW	111 -132 M 4	32	
43,8	6,3	137	2,12	MW	121 -132 M 4	32	
5,7	56	6,2	106	0,8	MW	081 -132 M 4	25
	56	6,5	110	1,12	MW	091 -132 M 4	25
	56	6,5	110	1,32	MW	091 -132 M 4	25
	56,3	6,5	111	1,25	MW	091 -132 MC 6	16
	56,3	6,5	111	1,5	MW	101 -132 MC 6	16
	56	6,5	112	2	MW	111 -132 M 4	25
	56	6,5	112	2,36	MW	121 -132 M 4	25
70	6,5	89	0,8	MW	081 -132 M 4	20	
70	6,6	89	1,32	MW	091 -132 M 4	20	
70	6,6	89	1,6	MW	101 -132 M 4	20	
69,2	6,7	92	1,5	MW	091 -132 MC 6	13	
69,2	6,7	92	1,8	MW	101 -132 MC 6	13	
70	6,6	90	2,5	MW	111 -132 M 4	20	
70	6,6	90	3	MW	121 -132 M 4	20	
87,5	6,6	72	1	MW	081 -132 M 4	16	
87,5	6,6	72	1,6	MW	091 -132 M 4	16	
87,5	6,6	72	1,9	MW	101 -132 M 4	16	
108	6,6	59	1,18	MW	081 -132 M 4	13	
108	6,7	60	1,9	MW	091 -132 M 4	13	


Values in red state nominal thermal power P_{tq} (ambient temperature 40 °C, continuous duty, see ch. 4).

1) Powers valid for continuous duty S1; increase possible for S2 ... S10 (see ch. 2b) in which case P_2 , M_2 increase and fs decreases proportionately.

2) For complete designation when ordering see ch. 3.

* Mounting position B5R (see table ch. 2b).

P_1 kW	n_2 min^{-1}	P_2 kW	M_2 daN m	fs	Gear reducer - Motor		i	
1)					2)			
1)								
7,5	140	6,8	46,1	1,4	MW	081 -132 M 4	10	
	140	6,8	46,4	2,24	MW	091 -132 M 4	10	
9,2	5,85	6,7	1093	1	MW	142 -132 MB 4	3,8 x63	
	7,37	7	901	1,4	MW	142 -132 MB 4	3,8 x50	
7,6	8,7	6,8	745	0,71	MW	132 -132 MB 4	2,56x63	
	9,21	7,1	740	1,7	MW	142 -132 MB 4	3,8 x40	
	11	7	614	1	MW	132 -132 MB 4	2,56x50	
	11	7,3	629	1,9	MW	142 -132 MB 4	3,17x40	
6	13,7	7,1	493	0,67	MW	112 -132 MB 4	2,56x40	
6	13,7	7,1	493	0,8	MW	122 -132 MB 4	2,56x40	
	13,7	7,2	503	1,25	MW	132 -132 MB 4	2,56x40	
	13,8	7,7	532	1,9	MW	142 -132 MB 4	3,17x32	
6,6	17,1	7,3	406	0,85	MW	112 -132 MB 4	2,56x32	
6,6	17,1	7,3	406	1	MW	122 -132 MB 4	2,56x32	
	17,1	7,4	415	1,6	MW	132 -132 MB 4	2,56x32	
	17,6	7,9	426	2,8	MW	142 -132 MB 4	3,17x25	
	21,9	7,7	336	0,9	MW	112 -132 MB 4	2,56x25	
	21,9	7,7	336	1,06	MW	122 -132 MB 4	2,56x25	
	22,2	7,2	308	0,67	MW	111 -132 MB 4	63	
	22,2	7,2	308	0,8	MW	121 -132 MB 4	63	
	21,9	7,8	341	1,8	MW	132 -132 MB 4	2,56x25	
	22,2	7,3	314	1,32	MW	131 -132 MB 4	63	
6,4	27,6	7,7	266	0,67	MW	102 -132 MB 4	2,03x25	
	27,4	7,8	273	1,12	MW	112 -132 MB 4	2,56x20	
	27,4	7,8	273	1,32	MW	122 -132 MB 4	2,56x20	
	28	7,4	251	0,9	MW	111 -132 MB 4	50	
	28	7,4	251	1,06	MW	121 -132 MB 4	50	
	27,4	7,9	277	2,24	MW	132 -132 MB 4	2,56x20	
	28	7,5	256	1,7	MW	131 -132 MB 4	50	
6,9	34,5	7,8	216	0,71	MW	092 -132 MB 4	2,03x20	
6,9	34,5	7,8	216	0,85	MW	102 -132 MB 4	2,03x20	
7,1	35	7,4	201	0,75	MW	101 -132 MB 4	40	
	34,2	7,9	222	1,4	MW	112 -132 MB 4	2,56x16	
	34,2	7,9	222	1,7	MW	122 -132 MB 4	2,56x16	
	35	7,5	206	1,18	MW	111 -132 MB 4	40	
	35	7,5	206	1,4	MW	121 -132 MB 4	40	
	34,2	8,1	226	2,65	MW	132 -132 MB 4	2,56x16	
	35	7,6	209	2,12	MW	131 -132 MB 4	40	
7,5	43,1	7,9	176	0,85	MW	092 -132 MB 4	2,03x16	
7,5	43,1	7,9	176	1	MW	102 -132 MB 4	2,03x16	
	43,8	7,6	165	0,8	MW	091 -132 MB 4	32	
	43,8	7,6	165	0,95	MW	101 -132 MB 4	32	
	43,8	7,7	168	1,4	MW	111 -132 MB 4	32	
	43,8	7,7	168	1,7	MW	121 -132 MB 4	32	
	43,8	7,8	170	2,8	MW	131 -132 MB 4	32	
	56	7,9	135	0,9	MW	091 -132 MB 4	25	
	56	7,9	135	1,06	MW	101 -132 MB 4	25	
	56	8	137	1,7	MW	111 -132 MB 4	25	
	56	8	137	2	MW	121 -132 MB 4	25	
7,2	70	8	109	0,67	MW	081 -132 MB 4	20	
	70	8	110	1,12	MW	091 -132 MB 4	20	
	70	8	110	1,32	MW	101 -132 MB 4	20	
	70	8,1	111	2	MW	111 -132 MB 4	20	
	70	8,1	111	2,36	MW	121 -132 MB 4	20	
7,8	87,5	8	88	0,8	MW	081 -132 MB 4	16	
	87,5	8,1	89	1,32	MW	091 -132 MB 4	16	
	87,5	8,1	89	1,6	MW	101 -132 MB 4	16	
	87,5	8,2	89	2,5	MW	111 -132 MB 4	16	
	87,5	8,2	89	3	MW	121 -132 MB 4	16	
	108	8,1	72	1	MW	081 -132 MB 4	13	
	108	8,3	73	1,6	MW	091 -132 MB 4	13	
	108	8,3	73	1,9	MW	101 -132 MB 4	13	
	140	8,3	57	1,12	MW	081 -132 MB 4	10	
	140	8,3	57	1,8	MW	091 -132 MB 4	10	
	140	8,3	57	2,12	MW	101 -132 MB 4	10	
11	8	4,5	7,8	1660	0,67	MW	142 -160 L 6	3,17x63
	9,1	5,85	8	1307	0,8	MW	142 -132 MC 4	3,8 x63
	8,9	5,67	8,1	1372	0,95	MW	142 -160 L 6</td	



P_1 kW	n_2 min ⁻¹	P_2 kW	M_2 daN m	fs	Gear reducer - Motor	i
11	7,37	8,3	1077	1,12	MW 142 -132 MC 4	3,8 x50
	7	8,2	1117	0,9	MW 142 -160 M 4	3,17x63
	7,09	8,4	1127	1,18	MW 142 -160 L 6	3,17x40
6,9	8,8	8,3	901	0,8	MW 132 -160 L 6	2,56x40
	9,21	8,5	884	1,4	MW 142 -132 MC 4	3,8 x40
	8,82	8,5	919	1,32	MW 142 -160 M 4	3,17x50
	8,8	8,5	925	1,4	MW 142 -160 L 6	2,56x40
8,5	11	8,4	734	0,85	MW 132 -132 MC 4	2,56x50
8,5	11	8,4	734	0,85	MW 132 -160 M 4	2,56x50
	11	8,7	752	1,6	MW 142 -132 MC 4	3,17x40
	11	8,7	752	1,6	MW 142 -160 M 4	3,17x40
6	13,7	8,5	590	0,67	MW 122 -132 MC 4	2,56x40
5,7	14,1	8,5	580	0,71	MW 122 -160 L 6	2 x32
9,3	13,7	8,6	602	1,06	MW 132 -132 MC 4	2,56x40
9,3	13,7	8,6	602	1,06	MW 132 -160 M 4	2,56x40
9	14,1	8,8	594	1,18	MW 132 -160 L 6	2 x32
	14,3	8,4	564	0,85	MW 131 -160 L 6	63
	13,8	9,2	636	1,6	MW 142 -132 MC 4	3,17x32
	13,7	8,8	616	1,8	MW 142 -160 M 4	2,56x40
	14,1	9,3	630	2	MW 142 -160 L 6	2,56x25
	14,3	8,7	579	1,5	MW 141 -160 L 6	63
6,6	17,1	8,7	485	0,71	MW 112 -132 MC 4	2,56x32
6,6	17,1	8,7	485	0,8	MW 122 -132 MC 4	2,56x32
7	17,5	8,6	470	0,67	MW 112 -160 M 4	2 x40
7,5	17,5	8,6	470	0,8	MW 122 -160 M 4	2 x40
	18	8,5	453	0,71	MW 121 -160 L 6	50
	17,1	8,9	496	1,32	MW 132 -132 MC 4	2,56x32
	17,5	8,8	479	1,18	MW 132 -160 M 4	2 x40
	18	8,7	462	1,18	MW 131 -160 L 6	50
	17,6	9,4	509	2,36	MW 142 -132 MC 4	3,17x25
	17,1	9,3	518	1,9	MW 142 -160 M 4	2,56x32
	18	8,9	473	2,12	MW 141 -160 L 6	50
8,5	21,9	9,2	402	0,75	MW 112 -132 MC 4	2,56x25
8,5	21,9	9,2	402	0,9	MW 122 -132 MC 4	2,56x25
7,7	21,9	8,8	386	0,8	MW 112 -160 M 4	2 x32
7,7	21,9	8,8	386	0,95	MW 122 -160 M 4	2 x32
8	22,5	9,2	392	0,85	MW 112 -160 L 6	2 x20
8	22,5	9,2	392	1	MW 122 -160 L 6	2 x20
9,3	22,2	8,6	368	0,67	MW 121 -132 MC 4	63
9,3	22,2	8,6	368	0,67	MW 121 -160 M 4	63
8,3	22,5	8,8	372	0,75	MW 111 -160 L 6	40
8,3	22,5	8,8	372	0,9	MW 121 -160 L 6	40
	21,9	9,4	408	1,5	MW 132 -132 MC 4	2,56x25
	21,9	9	393	1,6	MW 132 -160 M 4	2 x32
	22,2	8,7	375	1,06	MW 131 -132 MC 4	63
	22,2	8,7	375	1,06	MW 131 -160 M 4	63
	22,5	8,9	378	1,4	MW 131 -160 L 6	40
	21,9	9,5	414	2,65	MW 142 -160 M 4	2,56x25
	22,2	8,9	383	1,9	MW 141 -160 M 4	63
9,2	27,4	9,4	326	0,95	MW 112 -132 MC 4	2,56x20
9,2	27,4	9,4	326	1,12	MW 122 -132 MC 4	2,56x20
	28	9,3	318	0,9	MW 112 -160 M 4	2 x25
	28	9,3	318	1,06	MW 122 -160 M 4	2 x25
8,7	28,1	9,4	319	1,06	MW 112 -160 L 6	2 x16
8,7	28,1	9,4	319	1,25	MW 122 -160 L 6	2 x16
	28	8,8	300	0,75	MW 111 -132 MC 4	50
	28	8,8	300	0,9	MW 121 -132 MC 4	50
	28	8,8	300	0,75	MW 111 -160 M 4	50
	28	8,8	300	0,9	MW 121 -160 M 4	50
9,1	28,1	9	304	0,95	MW 111 -160 L 6	32
9,1	28,1	9	304	1,12	MW 121 -160 L 6	32
	27,4	9,5	331	1,9	MW 132 -132 MC 4	2,56x20
	28	9,5	323	1,8	MW 132 -160 M 4	2 x25
	28	9	306	1,5	MW 131 -132 MC 4	50
	28	9	306	1,5	MW 131 -160 M 4	50
	28,1	9,1	310	1,8	MW 131 -160 L 6	32
	27,4	9,6	334	3,35	MW 142 -160 M 4	2,56x20
	28	9,1	311	2,5	MW 141 -160 M 4	50
6,9	34,5	9,3	259	0,71	MW 102 -132 MC 4	2,03x20
	34,2	9,5	265	1,18	MW 112 -132 MC 4	2,56x16
	34,2	9,5	265	1,4	MW 122 -132 MC 4	2,56x16
	35	9,5	258	1,12	MW 112 -160 M 4	2 x20

Values in red state nominal thermal power P_{tq} (ambient temperature 40 °C, continuous duty, see ch. 4).



1) Powers valid for continuous duty S1; increase possible for S2 ... S10 (see ch. 2b) in which case P_2 , M_2 increase and fs decreases proportionately.

2) For complete designation when ordering see ch. 3.

P_1 kW	n_2 min ⁻¹	P_2 kW	M_2 daN m	fs	Gear reducer - Motor	i	
11	35	9,5	258	1,32	MW 122 -160 M 4	2 x20	
	35	9	246	1	MW 111 -132 MC 4	40	
	35	9	246	1,18	MW 121 -132 MC 4	40	
	35	9	246	1	MW 111 -160 M 4	40	
	34,2	9,7	271	2,12	MW 132 -132 MC 4	2,56x16	
	35	9,6	261	2,24	MW 132 -160 M 4	2 x20	
	35	9,1	249	1,8	MW 131 -132 MC 4	40	
	35	9,1	249	1,8	MW 131 -160 M 4	40	
7,5	43,1	9,5	210	0,85	MW 102 -132 MC 4	2,03x16	
8	43,8	9	198	0,67	MW 091 -132 MC 4	32	
8	43,8	9	198	0,8	MW 101 -132 MC 4	32	
	43,8	9,6	209	1,4	MW 112 -160 M 4	2 x16	
	43,8	9,6	209	1,6	MW 122 -160 M 4	2 x16	
	43,8	9,2	201	1,18	MW 111 -132 MC 4	32	
	43,8	9,2	201	1,5	MW 121 -132 MC 4	32	
	43,8	9,2	201	1,18	MW 111 -160 M 4	32	
	45	9,5	203	1,32	MW 111 -160 L 6	20	
	45	9,5	203	1,6	MW 121 -160 L 6	20	
	43,8	9,8	214	2,5	MW 132 -160 M 4	2 x16	
	43,8	9,3	203	2,24	MW 131 -160 M 4	32	
15	10,6	7	11,2	1523	0,67	MW 142 -160 L 4	3,17x63
10,1	7,04	11,3	1537	0,8	MW 142 -180 L 6	2,56x50	
11,8	8,82	11,6	1253	0,95	MW 142 -160 L 4	3,17x50	
	11	11,8	1025	1,18	MW 142 -160 L 4	3,17x40	
9,3	13,7	11,8	821	0,75	MW 132 -160 L 4	2,56x40	
9	14,1	11,9	811	0,85	MW 132 -180 L 6	2 x32	
	13,7	12	840	1,32	MW 142 -160 L 4	2,56x40	
	14,1	12,7	859	1,4	MW 142 -180 L 6	2,56x25	
	14,3	11,8	789	1,12	MW 141 -180 L 6	63	
10,9	17,5	12	654	0,9	MW 132 -160 L 4	2 x40	
11,7	18	11,9	630	0,85	MW 131 -180 L 6	50	
	17,1	12,7	707	1,4	MW 142 -160 L 4	2,56x32	
	17,6	12,8	695	1,9	MW 142 -180 L 6	2,56x20	
	18	12,2	645	1,5	MW 141 -180 L 6	50	
7,7	21,9	12,1	526	0,71	MW 122 -160 L 4	2 x32	
12,2	21,9	12,3	536	1,12	MW 132 -160 L 4	2 x32	
12,6	22,5	12,8	544	1,25	MW 132 -180 L 6	2 x20	
	22,2	11,9	512	0,8	MW 131 -160 L 4	63	
	22,5	12,1	515	1,06	MW 131 -180 L 6	40	
	21,9	12,9	564	2	MW 142 -160 L 4	2,56x25	




9. Manufacturing programme (garmotors)



P_1 kW	n_2 min ⁻¹	P_2 kW	M_2 daN m	fs	Gear reducer - Motor			i	
1)					2)				
15	22,2	12,2	523	1,4	MW	141 -160 L	4	63	
	22,5	12,4	525	1,8	MW	141 -180 L	6	40	
10	28	12,7	434	0,75	MW	122 -160 L	4	2 x25	
10,3	28	12	410	0,67	MW	121 -160 L	4	50	
9,1	28,1	12,2	415	0,71	MW	111 -180 L	6	32	
9,1	28,1	12,2	415	0,8	MW	121 -180 L	6	32	
	28	12,9	440	1,32	MW	132 -160 L	4	2 x25	
	28	12,2	417	1,06	MW	131 -160 L	4	50	
	28,1	12,5	423	1,32	MW	131 -180 L	6	32	
	27,4	13,1	456	2,5	MW	142 -160 L	4	2,56x20	
	28	12,4	425	1,9	MW	141 -160 L	4	50	
10,8	35	12,9	352	0,8	MW	112 -160 L	4	2 x20	
10,8	35	12,9	352	1	MW	122 -160 L	4	2 x20	
11,4	35	12,3	335	0,71	MW	111 -160 L	4	40	
11,4	35	12,3	335	0,85	MW	121 -160 L	4	40	
	35	13,1	356	1,6	MW	132 -160 L	4	2 x20	
	35	12,5	340	1,32	MW	131 -160 L	4	40	
	36	13	345	1,5	MW	131 -180 L	6	25	
	34,2	13,4	373	2,8	MW	142 -160 L	4	2,56x16	
	35	12,6	344	2,36	MW	141 -160 L	4	40	
11,8	43,8	13,1	285	1	MW	112 -160 L	4	2 x16	
11,8	43,8	13,1	285	1,18	MW	122 -160 L	4	2 x16	
12,5	43,8	12,5	274	0,9	MW	111 -160 L	4	32	
12,5	43,8	12,5	274	1,06	MW	121 -160 L	4	32	
	43,8	13,3	291	1,9	MW	132 -160 L	4	2 x16	
	43,8	12,7	277	1,7	MW	131 -160 L	4	32	
	45	13,2	279	1,9	MW	131 -180 L	6	20	
	43,8	13,1	287	2,5	MW	141 -160 L	4	32	
10,4	56	12,9	221	0,67	MW	101 -160 L	4	25	
	56	13,1	223	1	MW	111 -160 L	4	25	
	56	13,1	223	1,18	MW	121 -160 L	4	25	
	56,3	13,2	224	1,18	MW	111 -180 L	6	16	
	56,3	13,2	224	1,4	MW	121 -180 L	6	16	
	56	13,2	225	1,9	MW	131 -160 L	4	25	
	56,3	13,4	228	2,12	MW	131 -180 L	6	16	
11,2	70	13,1	179	0,67	MW	091 -160 L	4	20	
11,2	70	13,1	179	0,8	MW	101 -160 L	4	20	
	70	13,2	180	1,25	MW	111 -160 L	4	20	
	70	13,2	180	1,5	MW	121 -160 L	4	20	
	69,2	13,4	185	1,4	MW	111 -180 L	6	13	
	69,2	13,4	185	1,7	MW	121 -180 L	6	13	
	70	13,3	182	2,36	MW	131 -160 L	4	20	
12,2	87,5	13,3	145	0,8	MW	091 -160 L	4	16	
12,2	87,5	13,3	145	0,95	MW	101 -160 L	4	16	
	87,5	13,4	146	1,5	MW	111 -160 L	4	16	
	87,5	13,4	146	1,8	MW	121 -160 L	4	16	
	87,5	13,6	148	2,8	MW	131 -160 L	4	16	
	108	13,5	120	0,95	MW	091 -160 L	4	13	
	108	13,5	120	1,12	MW	101 -160 L	4	13	
	108	13,6	120	1,8	MW	111 -160 L	4	13	
	108	13,6	120	2,12	MW	121 -160 L	4	13	
	140	13,6	93	1,12	MW	091 -160 L	4	10	
	140	13,6	93	1,32	MW	101 -160 L	4	10	
	140	13,7	93	2	MW	111 -160 L	4	10	
	140	13,7	93	2,36	MW	121 -160 L	4	10	
18,5	11	8,8	14,3	1556	0,8	MW	142 -200 LR	6	2,56x40
	13,6	11	14,5	1266	0,9	MW	142 -180 M	4	2,56x50
	14,9	13,7	14,9	1036	1,06	MW	142 -180 M	4	2,56x40
	14,3	14,6	974	0,9	MW	141 -200 LR	6	63	
10,9	17,5	14,8	806	0,71	MW	132 -180 M	4	2 x40	
11,7	18	14,7	778	0,71	MW	131 -200 LR	6	50	
	17,1	15,6	871	1,12	MW	142 -180 M	4	2,56x32	
	18	15,8	839	1,4	MW	142 -200 LR	6	2 x25	
	18	15	795	1,25	MW	141 -200 LR	6	50	
12,2	21,9	15,1	661	0,9	MW	132 -180 M	4	2 x32	
12,8	22,5	15	636	0,85	MW	131 -200 LR	6	40	
	21,9	16	696	1,6	MW	142 -180 M	4	2,56x25	
	22,5	16	678	1,8	MW	142 -200 LR	6	2 x20	
	22,2	15	645	1,12	MW	141 -180 M	4	63	

P_1 kW	n_2 min ⁻¹	P_2 kW	M_2 daN m	fs	Gear reducer - Motor			i	
1)					2)				
18,5	22,5	15,2	647	1,5	MW	141 -200 LR	6	40	
	28	15,9	543	1,06	MW	132 -180 M	4	2 x25	
	28	15,1	515	0,85	MW	131 -180 M	4	50	
14,5	28,1	15,4	522	1,06	MW	131 -200 LR	6	32	
	27,4	16,1	562	2	MW	142 -180 M	4	2,56x20	
	28	15,4	524	1,5	MW	141 -180 M	4	50	
10,8	35	15,9	434	0,67	MW	112 -180 M	4	2 x20	
10,8	35	15,9	434	0,8	MW	122 -180 M	4	2 x20	
11,4	35	15,2	413	0,71	MW	121 -180 M	4	40	
11,4	35	16,1	439	1,32	MW	132 -180 M	4	2 x20	
	35	15,4	419	1,06	MW	131 -180 M	4	40	
	36	16	425	1,25	MW	131 -200 LR	6	25	
	34,2	16,5	460	2,36	MW	142 -180 M	4	2,56x16	
	35	15,5	424	1,9	MW	141 -180 M	4	40	
11,8	43,8	16,1	352	0,8	MW	112 -180 M	4	2 x16	
11,8	43,8	16,1	352	0,95	MW	122 -180 M	4	2 x16	
12,5	43,8	15,5	337	0,71	MW	111 -180 M	4	32	
12,5	43,8	15,5	337	0,85	MW	121 -180 M	4	32	
	43,8	16,5	359	1,5	MW	132 -180 M	4	2 x16	
	43,8	15,7	342	1,32	MW	131 -180 M	4	32	
	45	16,2	345	1,6	MW	131 -200 LR	6	20	
	43,8	16,2	354	2	MW	141 -180 M	4	32	
	56	16,1	275	0,85	MW	111 -180 M	4	25	
	56	16,1	275	1	MW	121 -180 M	4	25	
	56	16,3	278	1,5	MW	131 -180 M	4	25	
	56,3	16,5	281	1,8	MW	131 -200 LR	6	16	
	56	16,4	280	2,8	MW	141 -180 M	4	25	
	70	16,3	223	1	MW	111 -180 M	4	20	
	70	16,3	223	1,18	MW	121 -180 M	4	20	
	70	16,5	224	1,9	MW	131 -180 M	4	20	
	87,5	16,5	180	1,18	MW	111 -180 M	4	16	
	87,5	16,5	180	1,4	MW	121 -180 M	4	16	
	87,5	16,7	183	2,24	MW	131 -180 M	4	16	
	108	16,8	149	1,4	MW	111 -180 M	4	13	
	108	16,8	149	1,7	MW	121 -180 M	4	13	
	108	16,8	149	2,65	MW	131 -180 M	4	13	
	140	16,9	115	1,6	MW	111 -180 M	4	10	
	140	16,9	115	1,9	MW	121 -180 M	4	10	
22	11	8,8	17,1	1851	0,67	MW	142 -200 L	6	2,56x40
	13,6	11	17,3	1506	0,75	MW	142 -180 L	4	2,56x50
	14,9	13,7	17,7	1232	0,9	MW	142 -180 L	4	2,56x40
	16,8	14,3	17,3	1158	0,75	MW	141 -200 L	6	63
	17,1	18,6	1036	0,95	MW	142 -180 L	4	2,56x32	
	18,6	18	18,8	998	1,18	MW	142 -200 L	6	2 x25
	18	17,8	946	1,06	MW	141 -200 L	6	50	
	12,2	21,9	18	786	0,8	MW	132 -180 L	4	2 x32
	12,8	22,5	17,8	756	0,71	MW	131 -200 L	6	40
	22,5	19	18,8	828	1,32	MW	142 -180 L	4	2,56x25
	22,5	19	18,8	806	1,5	MW	142 -200 L	6	2 x20
	22,5	19	17,8	767	0,95	MW	141 -180 L	4	63
	22,5	18,1	17,8	770	1,25	MW	141 -200 L	6	40
	15,7	28	18,9	645	0,9	MW	132 -180 L	4	2 x25
	16,2	28	17,9	612	0,71	MW	131 -180 L	4	50
	14,5	28,1	18,3	621	0,9	MW	131 -200 L	6	32
	27,4	19,2	668	1,7	MW	142 -180 L	4	2,56x20	
	28	18,3	623	1,25	MW	141 -180 L	4	50	
	28,1	19	644	1,32	MW	141 -200 L	6	32	
	17	35	19,2	523	1,12	MW	132 -180 L	4	2 x20
	17,7	35	18,3	499	0,9	MW	131 -180 L	4	40
	18,3	36	19,1	506	1,06	MW	131 -200 L	6	25
	34,2	19,6	547	1,9	MW	142 -180 L	4	2,56x16	
	35	18,5	504	1,6	MW	141 -180 L	4	40	
	36	19,3	513	1,8	MW	141 -200 L	6	25	
12,5	43,8	18,4	401	0,71	MW				



P₁ kW	n₂ min ⁻¹	P ₂ kW	M ₂ daN m	fs	Gear reducer - Motor			i
1)					2)			
Gear reducer - Motor								
22	45	19,5	413	2,24	MW	141 -200 L	6	20
16,1	56	19,2	327	0,71	MW	111 -180 L	4	25
16,1	56	19,2	327	0,85	MW	121 -180 L	4	25
56	19,4	331	1,32	MW	131 -180 L	4	25	
56,3	19,7	334	1,5	MW	131 -200 L	6	16	
56	19,6	333	2,36	MW	141 -180 L	4	25	
17,4	70	19,4	265	0,85	MW	111 -180 L	4	20
17,4	70	19,4	265	1	MW	121 -180 L	4	20
70	19,6	267	1,6	MW	131 -180 L	4	20	
69,2	19,8	274	1,8	MW	131 -200 L	6	13	
70	19,7	268	2,8	MW	141 -180 L	4	20	
87,5	19,6	214	1	MW	111 -180 L	4	16	
87,5	19,6	214	1,18	MW	121 -180 L	4	16	
87,5	19,9	217	1,9	MW	131 -180 L	4	16	
108	19,9	177	1,18	MW	111 -180 L	4	13	
108	19,9	177	1,4	MW	121 -180 L	4	13	
108	20	177	2,12	MW	131 -180 L	4	13	
140	20,1	137	1,4	MW	111 -180 L	4	10	
140	20,1	137	1,6	MW	121 -180 L	4	10	
30	14,9	13,7	24,1	0,67	MW	142 -200 L	4	2,56x40
17,3	17,5	24,4	1332	0,8	MW	142 -200 L	4	2 x40
21,4	21,9	25,9	1129	1	MW	142 -200 L	4	2,56x25
22,2	21,9	25,6	1119	0,85	MW	142 -200 L	4	2 x32
23,2	22,2	24,3	1046	0,71	MW	141 -200 L	4	63
22,8	27,4	26,1	912	1,25	MW	142 -200 L	4	2,56x20
25	28	26,1	891	1,18	MW	142 -200 L	4	2 x25
	28	24,9	849	0,95	MW	141 -200 L	4	50
17	35	26,1	713	0,8	MW	132 -200 L	4	2 x20
17,7	35	24,9	680	0,67	MW	131 -200 L	4	40
	35	26,3	719	1,4	MW	142 -200 L	4	2 x20
	35	25,2	687	1,18	MW	141 -200 L	4	40
19,9	43,8	26,7	582	0,95	MW	132 -200 L	4	2 x16
19,4	43,8	25,4	554	0,85	MW	131 -200 L	4	32
	43,8	26,9	587	1,7	MW	142 -200 L	4	2 x16
	43,8	26,3	574	1,25	MW	141 -200 L	4	32
25,1	56	26,4	451	0,95	MW	131 -200 L	4	25

Values in red state nominal thermal power P_{th} (ambient temperature 40 °C, continuous duty, see ch. 4).

1) Powers valid for continuous duty S1; increase possible for S2 ... S10 (see ch. 2b) in which case P_{th}, M₂ increase and fs decreases proportionately.



2) For complete designation when ordering see ch. 3.

P₁ kW	n₂ min ⁻¹	P ₂ kW	M ₂ daN m	fs	Gear reducer - Motor			i
1)					2)			
Gear reducer - Motor								
30	56	26,7	455	1,7	MW	141 -200 L	4	25
	70	26,7	364	1,18	MW	131 -200 L	4	20
	70	26,8	366	2,12	MW	141 -200 L	4	20
	87,5	27,1	296	1,4	MW	131 -200 L	4	16
	87,5	27,3	298	2,5	MW	141 -200 L	4	16
	108	27,3	242	1,6	MW	131 -200 L	4	13
37	25	28	1099	0,95	MW	142 -225 S	4	2 x25
	25,7	28	1047	0,75	MW	141 -225 S	4	50
	26,4	35	886	1,12	MW	142 -225 S	4	2 x20
	27,3	35	848	0,95	MW	141 -225 S	4	40
	19,4	43,8	683	0,67	MW	131 -200 LG	4	32
	31,2	43,8	724	1,32	MW	142 -225 S	4	2 x16
	43,8	32,4	708	1	MW	141 -225 S	4	32
	25,1	56	556	0,75	MW	131 -200 LG	4	25
	56	32,9	561	1,4	MW	141 -225 S	4	25
	27	32,9	449	0,95	MW	131 -200 LG	4	20
	70	33,1	451	1,7	MW	141 -225 S	4	20
	31,3	87,5	365	1,12	MW	131 -200 LG	4	16
	87,5	33,7	367	2	MW	141 -225 S	4	16
	108	33,7	299	1,32	MW	131 -200 LG	4	13
45	25	28	1336	0,8	MW	142 -225 M	4	2 x25
	26,4	35	1078	0,95	MW	142 -225 M	4	2 x20
	27,3	35	1031	0,8	MW	141 -225 M	4	40
	31,2	43,8	881	1,12	MW	142 -225 M	4	2 x16
	35,5	43,8	861	0,85	MW	141 -225 M	4	32
	56	40	682	1,12	MW	141 -225 M	4	25
	70	40,2	549	1,4	MW	141 -225 M	4	20
	87,5	40,9	447	1,6	MW	141 -225 M	4	16
55	35,5	43,8	1052	0,71	MW	141 -250 M	4	32
	39,4	56	834	0,95	MW	141 -250 M	4	25
	41,2	70	671	1,12	MW	141 -250 M	4	20
	87,5	50	546	1,32	MW	141 -250 M	4	16



10. Designs, dimensions, mounting positions and oil quantities

W 011 ... 071



Design¹⁾

standard
worm extension

UO3A
UO3D

Size red. motor B5	a B	A	c ₁	D Ø H7	d ₁ Ø H7	F	G	H h11	H ₀ h11	H ₁ h12	K Ø	L	M Ø h6	N Ø h6	P Ø	T	Z	P ₁ Ø	X Ø ≈	Y ≈	Y ₁ ≈	W ≈	W ₁ ≈	Mass kg 3)
01 71 ⁸⁾ 71 B5R ⁸⁾	32 52	61 51	19	11 20 4)	M 5 2)	76 87	71 82	48 56	34,5 41,5	7 12 10	10 8,5 5)	75 3 66	55 105 80	90 3 46	91 106 80	39 140 160 140	122 140 211 225	185 — 335 —	229 — 349	309 — 353	353 — 112	101 112 192	171 112 182	8 11 —
02 71 ⁸⁾ 71 80 ⁸⁾ 80 B5R ⁸⁾	40 62	70 62	24	14 25	M 6 4)	87	82	56	41,5	9,5	12 10	85 5)	68 105 3	105 3 46	106 140 160 200 160	122 140 211 275 354	185 — 372 418	229 — 372 418	328 — 418	372 — 112	101 112 192	171 122 222	11 14 —	
03 71 ⁸⁾ 71 80 90 ⁸⁾ 90 B5R ⁸⁾	50 75	86 75	28	16 30	M 6 4)	98 98	100 100	67	49	9,5	13 12	100 5)	85 120 3	126 95 6)	53 120 126 120 200 200	140 160 140 200 160 160	122 211 275 376 396 472	185 211 376 307 396 472	229 275 376 307 396 472	350 440 440 307 472 122	394 440 440 307 472 187	101 112 192	187 222 222	14 18 21
04 05 71 80 90 100 ⁸⁾ 100 B5R ⁸⁾	63 90	102 83	32	19 30	M 8	118 118	125 125	80	58,5 11,5	16 14	100 80	120 3	151 114	63 151 114	160 200 200 200 180 200 250 200	140 231 307 429 505 553 468 355	211 307 429 505 553 149 149	275 307 429 505 553 149 149	409 473 473 505 553 149 149	473 112 122 243 243 249 33	112 122 122 243 243 249 33	223 27 32		
06 07 80 ⁸⁾ 90 ⁸⁾ 100 ⁸⁾ *112 ⁸⁾	80 106	132 103	38 (80) 40 (81)	24 36	M 10	138 138	150 150	100	69,5 14	20 17	130 110	160 3,5	189 135	75 189 135	200 160 180 200 207 250 250	160 231 355 508 593 657 657	231 355 508 593 657 164 164	307 355 508 593 657 164 164	469 545 545 122 280 43 48	473 112 122 243 243 249 33	122 280 43 48	37 42		

1) See ch. 3 for motor design.

2) Working length of thread 2 · F.

3) Values valid for brake motor.

4) Holes turned through 45° with respect to the drawing.

5) Tolerance t8.

6) Option of P₁ = 160, with price addition: consult us.

7) On request for 100L 4, 112M 4 excluded size 81 also available mounting position B5R (see ch. 2b).


8) Brake motor not possible.

* **IMPORTANT:** in the event of a **brake motor** and shaft mounting or mounting positions V5, V6, **consult us**. Brake motor F0 112MC not possible.

Mounting positions - direction of rotation - and oil quantities [l]

B3	B6	B7	B8	V5	V6	Size	B3	B6, B7	B8	V5, V6
						01	0,16	0,2	0,16	0,16
						02	0,26	0,35	0,26	0,26
						03	0,4	0,6	0,4	0,4
						04, 05	0,8	1,15	0,8	0,8
						06, 07	1,3	2,2	1,7	1,3

Unless otherwise stated, gearmotors are supplied in mounting position B3 (B3 and B8 for sizes ≤ 64) which, being standard, is **omitted** from the designation.





PalaDrive

Worm Gear Reducers and Gear Motors

SERIES W

10. Designs, dimensions, mounting positions and oil quantities

W 081 ... 141

Design¹⁾

standard

UO2A⁵⁾

Size red. motor B5	a B	A B	c ₁	D Ø H7	d ₁ Ø H7	F	G	G ₀	G ₁	G ₂	H	H ₀	H ₁	K Ø h11	L	M Ø h6	N Ø h6	P Ø	T	V ₀ Ø max	Z	P ₁ Ø	X Ø ≈	Y ≈	Y ₁ ≈	W ≈	W ₁ ≈	Mass kg			
08 100 100 112 *132 ⁷⁾	100	180 131	130	48	28 42	M 12	170	180	122	11	180	125	84,5	16	23	165	130	200 3,5	236 165	45	90	200 180	270	355 620	705 769	149 164	325 350	62 69	67 76		
09 10 100 112 132 132 160 ⁶⁾	125	225 155	155	60	32 58	M 12 ⁸⁾	205	221	148	15	225	150	99,5	18	28	215	180	250 4	287 194	50	106	250 207	343	419 769	845 871	164 164	400 400	103 113	110 124		
11 12 112 132 160 180 ⁸⁾	160	272 183	187	70 (160) 75 (161)	38 58	M 14 ⁸⁾	247	255	178	15	280	180	118,5	22	33	265	230	300 4	345 232	60	125	250 207	343	419 769	845 871	164 164	400 400	103 113	110 124		
13 13 132 160 180 *200	200	342 214	235	90	48 82	M 16 ⁸⁾	292	324	222	20	335	225	137,5	27	40	300	250	350 5	431 270	80	150	300 260	402	537 904	947 1039	164 196	465 490	172 203	183 219		
14 160 180 200 225 250 ⁶⁾	250	425 250	287	110	55 82	M 20 ⁸⁾ 3)	360	379	277	20	410	280	163	33	50	400	350	450 5	537 320	80	180	350 315	540	634 734	947 1149	164 235	465 515	172 236	183 260		
																					350 315	540	634 734	1130	1149 1244	257 1363	515 419	257 459			
																					400 354	615	734	1244	1363	257	625	419	459		
																					450 416	690	—	1439	—	292	755	633	—		
																					450 416	690	—	1439	—	292	755	667	—		

1) See ch. 3 for motor design.

2) Working length of thread 2 · F.

3) Holes turned through 22° 30' with respect to the drawing.

4) Values valid for brake motor.

5) Prearranged design for worm shaft extension (see ch. 2).

6) Mounting position B5R (see ch. 2b), brake motor not possible.

7) On request for 132M 4 also available mounting position B5R (see ch. 2b).

8) Brake motor F0 180L not possible.

* **IMPORTANT:** in the event of brake motor and shaft mounting or mounting positions V5, V6, consult us. Brake motor F0 132MB not possible. For motor 200LG 4, X dimension increases by 73 mm, Y and Y₁ dimensions increase by 110 mm and mass by 35 kg, brake motor not possible.

Mounting positions - direction of rotation - and oil quantities [l]



B3	B6	B7 ¹⁾	B8	V5	V6	Size	B3	B6, B7	B8	V5, V6
						08 09, 10 11, 12	1,9 3,4 5,6	5,4 10 18	4,2 8,2 15	3 5,7
						13 14	9,5 17	33 57	30 51	20 34

Unless otherwise stated, gearmotors are supplied in mounting positions B3 which, being standard, is omitted from the designation.

1) Sizes 13 and 14 in B7, mounting position with n_t > 710 min⁻¹, carry a price addition.



MW 012 ... 072

Design¹⁾standard
worm extensionUO3A
UO3D

Size red. motor B5	a a ₁	A B	c ₁	D Ø H7	d ₁ Ø	F	G	H h11	H ₀ h11	H ₁ h12	K Ø	L	M Ø	N Ø h6	P Ø	T	Z	P ₁ Ø	X Ø ≈	Y ≈	Y ₁ ≈	W ≈	W ₁ ≈	Mass kg				
01	63	32 32	61 52	51	19	11 20	M 5 4)	76	71	48	34,5	7	10 8,5	75	55 5)	90 3	91 66	39	140	122	185	229	309	353	101	172	8 10	
02	63	40 40	70 62	57,5	24	14 25	M 6 4)	87	82	56	41,5	9,5	12 10	85	68 5)	105 3	106 80	46	140	122	185	229	328 354	372 418	101 112	183 194	11 14	13 17
03	63	50 40	86 75	70,5	28	16 30	M 6 4)	98	100	67	49	9,5	13 12	100	85 5)	120 3	126 95	53	140 160 200	122 140 231	185 211 307	229 275 396	350 376 472	394 440 122	101 112 222	191 202 222	14 18 22	16 21 27
04	71	63	102	83	32	19 30	M 8	118	125	80	58,5	11,5	16 14	100	80	120 3	151 114	63	160 200 200	140 160 180	211 231 270	275 307 355	409 429 468	473 505 553	112 122 149	224 234 261	23 27 33	26 32 38
05	80	50	90	90 ⁸⁾																								
06	71	80	132	103	38	(80) 40	M 10	138	150	100	69,5	14	20 17	130	110	160 3,5	189 135	75	160 200 200	140 160 180	211 231 270	275 307 355	449 469 508	513 545 593	112 122 149	250 250 269	33 37 43	36 42 48
07	80	50	106	103	24	36													200	207	343	—	581	—	164	284	50	—
	100 ⁷⁾																											

1) See ch. 3 for motor design.

2) Working length of thread 2 · F.

3) Values valid for brake motor.

4) Holes turned through 45° with respect to the drawing.

5) Tolerance t8.

6) Option of P₁ = 160, with price addition: consult us.

7) Mounting position B5R (see ch. 2b); brake motor not possible.

8) Brake motor F0 90LB and 90LC not possible.

Mounting positions - direction of rotation - and oil quantities [l]



B3	B6	B7	B8	V5	V6	Size	B3	B6, B7	B8	V5, V6
						01	0,2	0,25	0,2	0,2
						02	0,32	0,4	0,32	0,32
						03	0,5	0,7	0,5	0,5
						04, 05	1	1,3	1	1
						06, 07	1,5	2,5	2	1,5
										UTC 696

Unless otherwise stated, gearmotors are supplied in mounting position B3 (B3 and B8 for sizes ≤ 64) which, being standard, is omitted from the designation.



10. Designs, dimensions, mounting positions and oil quantities

MW 082 ... MW 142



Design¹⁾

standard

UO2A⁵⁾

Size red. motor B5	a a ₁	A B	c ₁	D Ø H7	d ₁ Ø H7	F	G	G ₀	G ₁	G ₂	H h11	H ₀ h11	H ₁ h12	K Ø	L	M Ø h6	N Ø h6	P Ø	T	V ₀ Ø max	Z	P ₁ Ø	X Ø ≈	Y ≈	Y ₁ ≈	W ≈	W ₁ ≈	Mass kg			
08	80 90 100 112	100 63 131	180 131	130	48 42	M 12	170	180	122	11	180	125	84,5	16	23	165	130	200 3,5	236 165	45	90	200 200 250 250	160 270 343 343	231 355 419 445	581 620 693 693	657 705 769 795	122 149 164 164	305 305 307 307	57 63 70 77		
09	90	125 80	225 155	155	60	32 58	M 12 ⁸	205	221	148	15	225	150	99,5	18	28	215	180	250 4	287 194	50	106	200 250 250 300	180 343 343 402	270 355 419 537	696 781 845 828	781 149 164 963	375 375 375 196	98 103 112 145	103 112 115 161	
10	100																					207 207 207	343 343 343	445 445 445	769 871 871	149 164 164	375 375 375	105 115 115	126		
11	112	160 100	272 183	187	70 (160)	38 58	M 14 ⁸	247	255	178	15	280	180	118,5	22	33	265	230	300 4	345 232	60	125	250 250 300 350	207 207 260 315	343 343 402 540	419 845 845 634	921 947 1039 1055	164 164 196 1055	460 460 460 —	165 175 206 235	172 186 222 263
12	132																					260									
13	100 112 132	200 100	342 214	235	90	48 82	M 16 ⁸	292	324	222	20	335	225	137,5	27	40	300	250	350 5	431 270	80	150	250 250 300 350	207 207 260 315	343 343 402 540	419 845 845 634	959 959 1018 1169	1035 1061 1153 1263	164 164 196 235	560 560 560 560	272 282 326 367
14	160 180 200 225	250 250	425 250	287	110	55 82	M 20 ⁸	360	379	277	20	410	280	163	33	50	400	350	450 5	537 320	80	180	300 350 350 400 450	260 540 615 615 690	402 634 734 734 —	537 1279 1354 1354 1439	1141 1276 1473 1473 —	196 690 257 257 292	466 499 553 579	482 523 589 619	
																						370									

1) See ch. 3 for motor design.

2) Working length of thread 2 · F.

3) Holes turned through 22° 30' with respect to the drawing.

4) Values valid for brake motor.

5) Prearranged design for worm shaft extension (see ch. 2).

6) Mounting position **B5R** (see ch. 2b), brake motor not possible.

7) Brake motor not possible.

8) Brake motor **F0 132MC** not possible.

Mounting positions - direction of rotation - and oil quantities [l]


B3	B6	B7 ¹⁾	B8	V5	V6	Size	B3	B6, B7	B8	V5, V6
						08 09, 10 11, 12 13 14	2,1 3,8 6,5 10,4 18,3	6,3 11,6 20,8 38 67	4,5 8,8 16,5 31,5 53	3,3 6,3 11,2 21,2 35,7

Unless otherwise stated, gearmotors are supplied in mounting positions **B3** which, being standard, is omitted from the designation.


1) Sizes 08 ... 14 in mounting position **B6** carry a price addition.






10. Designs, dimensions, mounting positions and oil quantities

**Design**


standard
worm extension



1)

UO3A
UO3D**Design¹⁾**
standardUO2A⁴⁾**MW 023 ... 073**

UTC 697

MW 083 ... 103

UTC 698

Size red. motor B5	a	A	c ₁	D Ø H7	d ₁ Ø H7	F	G	G ₀	G ₁	G ₂	H	H ₀	H ₁	K	L	L ₁	M Ø h6	N Ø h6	P Ø	T	V ₀ Ø max	Z	P ₁ Ø	X Ø	Y ≈	Y ₁ ≈	W ≈	W ₁ ≈	Mass kg				
02	63	40	70 62	57,5	24	14 25	M 6 5)	106	—	—	82	56	41,5	9,5	12	10	85	68 6)	105 3	106 80	—	46	140	122	185	229	347	391	101	171	11	13	
03	63 71	50	86 75	70,5	28	16 30	M 6 5)	117	—	—	100	67	49	9,5	13	12	100	85 6)	120 3	126 95	—	53	140 160	122 140	185 211	229 275	369 395	413 459	101 112	187 197	14	16	
04 05	71 80	63	102 90	83	32	19 30	M 8	145	—	—	125	80	58,5	11,5	16	14	100	80	120 3	151 114	—	63	160 200	140 160	211 231	275 307	436 456	500 532	112 122	223 243	24	27	
06 07	71 80	80	132 106	103	38 36	M 10	165	—	—	150	100	69,5	14	20	17	130	110	160 3,5	189 135	—	75	160 200	140 160	211 231	275 307	476 496	540 572	112 122	260 280	34	37		
08	80 90	100	180 131	130	48	28 42	M 12	203	180	122	11	180	125	84,5	16	23	—	165	130	200 3,5	236 165	45	90	200 200	160 180	231 270	307 355	614 653	690 738	122 149	325 325	59	64
09 10 112M	90 100 112M	125	225	155	60	32 58	M 12 ⁸	249	221	148	15	225	150	99,5	18	28	—	215	180	250 4	287 194	50	106	200 250 250	180 207 207	270 343	355 419	740 813	825 889	149 164	375 400	101	106

1) See ch. 3 for motor design.

2) Working length of thread 2 - F.

3) Values valid for brake motor.

4) Prearranged design for worm shaft extension (see ch. 2).

5) Holes turned through 45° with respect to the drawing.

6) Tolerance t8.

Mounting positions - direction of rotation - and oil quantities [l]


B3	B6	B7	B8	V5	V6	Size	B3	B6, B7	B8	V5, V6
						02	0,42	0,5	0,42	0,42
						03	0,6	0,8	0,6	0,6
						04, 05	1,2	1,55	1,2	1,2
						06, 07	1,7	2,8	2,3	1,8
						08	2,4	6,8	4,8	3,6
						09, 10	4,2	12,8	9,3	6,8

Schemi di grand. 40 ... 81 validi anche per grand. 100 ... 126.

Schemes for sizes 02 ... 07 valid also for sizes 08 ... 10.

UTC 699

Unless otherwise stated, gearmotors are supplied in mounting position B3 (B3 and B8 for sizes ≤ 64) which, being standard, is omitted from the designation.



11. Combined gear reducer and gearmotor units

Table A - Nominal torques for final gear reducer

n_2 min ⁻¹	Final gear reducer size / i worm gear pair											
	03/20			04/25			06/25			07/25		
	M_{N2} daN m	η	$M_{2\max}$ daN m		M_{N2} daN m	η	$M_{2\max}$ daN m		M_{N2} daN m	η	$M_{2\max}$ daN m	
11,2	20,1	0,7	33,4	32	0,7	58	63	0,72	109	75	0,72	118
9	20,5	0,68	35	33,8	0,69	61	65	0,71	113	77	0,71	123
4,5	21,3	0,66	38,4	37,8	0,66	68	72	0,68	127	82	0,68	137
2,24	23,9	0,64	40,2	42,9	0,64	73	80	0,65	133	87	0,65	141
1,12	25	0,62	40,2	47,5	0,62	73	80	0,63	133	90	0,63	141
0,56	25*	0,6	40,2	47,5	0,6	73	80*	0,61	133	90*	0,61	141
0,28	25**	0,58	40,2	47,5*	0,58	73	80**	0,59	133	90**	0,59	141
0,14	25**	0,57	40,2	47,5*	0,57	73	80**	0,58	133	90**	0,58	141
0,071	25**	0,55	40,2	47,5*	0,55	73	80**	0,56	133	90**	0,56	141
M ₂ Size [daN m]	25			47,5			80			90		

* ** In these cases f_s required, provided that it always results ≥ 1 , can be reduced of 1,12 (*) or 1,18 (**).

Table B - Types of combined units

Type of combined unit	Final gear reducer size			
	03	04	06	07
W1 + W1	W 031/20 + W 1 o/or MW 011	W 041/25 + W 1 o/or MW 011	W 061/25 + W 1 o/or MW 021⁵⁾	W 071/25 + W 1 o/or MW 021⁵⁾
W1 + MW1				
1) $i_N \approx 250 \dots 1\,600$	$i_{final} = 20$	$i_{final} = 25$	$i_{final} = 25$	$i_{final} = 25$
MW1 + R 2, R 3	MW 031- 80B 4 ... B5A/70³⁾ + R 2 o/or MR 2, MR 3 40	MW 041-80B 4 ... B5A/56³⁾ + R 2 o/or MR 2, MR 3 40	MW 061-90L 4 ... B5/56 + R 2,R 3 o/or MR2,MR3 50⁴⁾	MW 071-90L 4 ... B5/56 + R 2,R 3 o/or MR2,MR3 50⁴⁾
MW1 + MR 2, MR 3				
2) $i_N \approx 160 \dots 4\,000$	$i_{final} = 20$	$i_{final} = 25$	$i_{final} = 25$	$i_{final} = 25$
MW 2 + R 2	MW 032-71B 4 ... B5A/27,6³⁾ + R 2 o/or MR 2, MR 3 32	MW 042-80B 4 ... B5A/22,1³⁾ + R 2 o/or MR 2, MR 3 40	MW 062 - 80B 4 ... B5A/22,1³⁾ + R 2 o/or MR 2, MR 3 40	MW 072 - 80B 4 ... B5A/22,1³⁾ + R 2 o/or MR 2, MR 3 40
MW 2 + MR 2, MR 3	design: shaft end Ø 14			
3) $i_N \approx 400 \dots 10\,000$	$i_{final} = 50,7$	$i_{final} = 63,5$	$i_{final} = 63,5$	$i_{final} = 63,5$

For initial gear reducer performance see: this catalogue ch. 7 or 9 for worm gear reducer, and catalogue E ch. 6 or 8 for coaxial gear reducer.

1) An anchor link is fitted between initial and final gear reducer.

2) The gearmotor has 140 mm motor mounting flange (dimension P_o, ch. 12).

3) The gearmotor has 160 mm motor mounting flange (dimension P_o, ch. 12).

4) Gear reducer in «oversized B5 flange» (see ch. 17 cat. E).








Table A - Nominal torques for final gear reducer

n_2 min ⁻¹	Final gear reducer size / i worm gear pair							
	08/25		09/32		11/32		M_{N2} daN m	M_{2max} daN m
	M_{N2} daN m	η	M_{N2} daN m	η	M_{N2} daN m	η		
11,2	129	0,74	215	0,74	339	0,76	636	
9	133	0,73	229	0,73	361	0,75	680	
4,5	145	0,69	257	0,69	413	0,71	784	
2,24	154	0,67	268	0,66	458	0,68	850	
1,12	160	0,65	268	0,64	468	0,65	850	
0,56	160*	0,63	268	0,61	468	0,63	850	
0,28	160**	0,61	268	0,6	468	0,61	850	
0,14	160**	0,59	268	0,58	468	0,59	850	
0,071	160**	0,57	268	0,56	468	0,57	850	
M_2 size [daN m]	160		300		500			

* , ** In these cases f_s required, provided that it always results ≥ 1 , can be reduced of 1,12 (*) or 1,18 (**).

Table B - Types of combined units

Type of combined unit	Final gear reducer size		
	08	09	11
W 1 + W 1 W 1 + W 2	W 081/25 + W 1, W 2 o/or MW 1, MW 032	W 091/32 + W 1, W 2 o/or MW 1, MW 042	W 111/32 + W 1, W 2 o/or MW 1, MW 062
 W1 + MW1 W1 + MW2  1) $i_N \approx 315 \dots 8\,000$	$i_{final} = 25$	$i_{final} = 32$	$i_{final} = 32$
MW 1 + R 2, R 3  MW 1 + MR 2, MR 3  $i_N \approx 200 \dots 5\,000$	MW 081-100LB 4 ... B5/56 + R 2,R 3o/or MR 2, MR 63⁴⁾ per $M_{N2} \leq 112$ daN m MW 081-90L 4 ... B5/56 + R 2,R 3o/or MR 2, MR 3 50⁴⁾	MW 091-112M 4 ... B5/43,8 + R 2,R 3o/or MR 2, MR 3 63⁴⁾	MW 111-132MB 4 ... B5/43,8 + R 2,R 3o/or MR 2, MR 3 80⁴⁾ per $M_{N2} \leq 400$ daN m MW 111-132MB 4 ... B5A/43,8⁵⁾ + R 2,R 3o/or MR 2, MR 3 64⁴⁾ per $M_{N2} \leq 315$ daN m MW 111-112M 4 ... B5/43,8 + R 2,R 3o/or MR 2, MR 3 63⁴⁾
MW 2 + R 2, R 3  MW 2 + MR 2, MR 3  $i_N \approx 500 \dots 12\,500$	MW 082-90L 4 ... B5/22,1 + R 2,R 3o/or MR 2, MR 3 50⁴⁾	MW 092-112M 4 ... B5/17,3 + R 2,R 3o/or MR 2, MR 3 63⁴⁾	MW 112-112M 4 ... B5/13,8 + R 2,R 3o/or MR 2, MR 3 63⁴⁾
	$i_{final} = 63,5$	$i_{final} = 81,1$	$i_{final} = 102$

For initial gear reducer performance see: this catalogue ch. 7 or 9 for worm gear reducer, and catalogue E ch. 6 or 8 for coaxial gear reducer.

1) An anchor link is fitted between initial and final gear reducer.

4) Gear reducer in «oversized B5 flange» (see ch. 17 cat. E); size 63 has a low speed shaft reduced to 28 mm: «oversized B5 flange - Ø 28».

5) The gearmotor has 250 mm motor mounting flange (dimension P_o , ch. 12).

6) The gearmotor has 300 mm motor mounting flange (dimension P_o , ch. 12).





7) The gearmotor has 350 mm motor mounting flange (dimension P_o , ch. 12).





















Table A - Nominal torques for final gear reducer

n_2 min^{-1}	Final gear reducer size / i worm gear pair								
	12/32			13/32			14/40		
	M_{N2} daN m	η	$M_{2\max}$ daN m	M_{N2} daN m	η	$M_{2\max}$ daN m	M_{N2} daN m	η	$M_{2\max}$ daN m
11,2	442	0,76	691	730	0,78	1 201	1 190	0,79	2 013
9	466	0,75	739	767	0,77	1 258	1 270	0,78	2 072
4,5	516	0,71	851	851	0,73	1 487	1 440	0,73	2 467
2,24	556	0,68	921	923	0,69	1 662	1 562	0,69	2 812
1,12	560	0,65	921	1 000	0,67	1 736	1 704	0,66	3 034
0,56	560*	0,63	921	1 000*	0,64	1 736	1 900	0,64	3 134
0,28	560**	0,61	921	1 000**	0,63	1 736	1 900*	0,61	3 134
0,14	560**	0,59	921	1 000**	0,61	1 736	1 900**	0,60	3 134
0,071	560**	0,57	921	1 000**	0,58	1 736	1 900**	0,57	3 134
M₂ Size	[daN m]		560			1 000			1 900

Table B - Types of combined units

Type of combined unit	Final gear reducer size		
	12	13	14
W 1 + W 1 W 1 + W 2 	W 121/32 + W 1,W 2 o/or MW 1,MW 062	W 131/32 + W 1,W 2 o/or MW 1,MW 082	W 141/40 + W 1,W 2 o/or MW 1,MW 092
W1 + MW 1 W1 + MW 2  1) $i_N \approx 315 \dots 10\,000$	$i_{\text{final}} = 32$	$i_{\text{final}} = 32$	$i_{\text{final}} = 40$
MW1 + R 2, R 3 	MW 121-132MB 4 ... B5/43,8 + R 2,R 3 o/or MR 2, MR 3 80⁴⁾ per $M_{N2} \leq 400$ daN m MW 121-132MB 4 ... B5A/43,8⁵⁾ + R 2,R 3 o/or MR 2, MR 3 64⁴⁾	MW 131-180L 4 ... B5/43,8 + R 2,R 3 o/or MR 2, MR 3 100⁴⁾ per $M_{N2} \leq 800$ daN m MW 131-180L 4 ... B5A/43,8⁶⁾ + R 2,R 3 o/or MR 2, MR 3 81⁴⁾ per $M_{N2} \leq 670$ daN m MW 151-132MB 4 ... B5/43,8 + R 2,R 3 o/or MR 2, MR 3 80⁴⁾	MW 141-200L 4 ... B5A/35⁷⁾ + R 2,R 3 o/or MR 2, MR 3 101⁴⁾ per $M_{N2} \leq 1\,400$ daN m MW 141-180L 4 ... B5/35 + R 2,R 3 o/or MW 2, MR 3 100⁴⁾
MW 1 + MR 2, MR 3 	$i_N \approx 200 \dots 6\,300$ $i_{\text{final}} = 32$	$i_{\text{final}} = 32$	$i_{\text{final}} = 40$
MW 2 + R 2, R 3 	MW 122-112M 4 ... B5/13,8 + R 2,R 3 o/or MR 2, MR 3 63⁴⁾	MW 132-132MB 4 ... B5/17,1 + R 2,R 3 o/or MR 2, MR 3 80⁴⁾	MW 142-180L 4 ... B5/13,7 + R 2,R 3 o/or MR 2, MR 3 100⁴⁾
MW 2 + MR 2, MR 3 	$i_N \approx 500 \dots 16\,000$ $i_{\text{final}} = 102$	$i_{\text{final}} = 81,8$	$i_{\text{final}} = 102$

12. Combined unit dimensions¹⁾ (garmotors)

1) See relevant catalogues for design, mounting position and oil quantities of single gear reducers.

2) The coupling position of the initial gear reducer with respect to the final one should be described in detail, though only in the case of 1, 2 or 3.

Important: personal safety-guards are the Buyer's responsibility (98/37/EC).



Size			a	a ₁	A	c ₁	D Ø H7	d ₁ Ø	F	G	H h11	H ₁ h12	K Ø	M Ø	N Ø h6	O 5	P Ø	P ₁ Ø	T	W ₁	Z	X Ø ≈	Y ≈	Y ₁ ≈	W ≈	Mass kg							
gear	educer	mot.	a ₀	a ₂	B			e ₁	1)		H ₀ h11	L L ₁				G ₀	Q		U		Z ₁												
final	initial	B5																															
03 W-1	MW-011	32	63	50	40	86	70,5	28	16	M 6 2)	76	100	49	9,5	100	85	116	120	—	140	126	183	53	122	185	229	253	253	101	17	19		
	MW-1	MR2, MR3	40	63	32	—	75		30		211	67	13	12	4)	—		3			140	160	204	39	122	185	229	463	507	101	22	24	
	MW-2	MR2, MR3	32	63							186									140	140	191		122	185	229	438	482	101	20	22		
04 W-1	MW-011	32	63	63	32	50	102	83	32	19	M 8	76	125	58,5	11,5	100	80	129	120	—	140	151	205	63	122	185	229	279	279	101	22	24	
	MW-1	MR2, MR3	40	63	32	—	90		30		231	80	16	14				3			160	140	230 ⁵⁾	39	122	185	229	496	540	101	27	29	
	MW-2	MR2, MR3	32	63																160	160	224 ⁵⁾		140	211	275	522	586	101	30	33		
06 W-1	MW-021	40	63	80	50	132	103	38	24	M 10	87	150	69,5	14	130	110	153	160	3,5	—	140	189	250	75	122	185	229	323	323	101	35	37	
	MW-1	MR2, MR3	50	63	40	—	106		36		282										160	140	286		122	185	229	567	611	101	43	45	
	MW-2	MR2, MR3	40	63	40						251										160	140	267		122	185	229	536	580	101	37	39	
08 W-1	MW-031	50	63	100	50	63	180	130	48	28	M 12	98	180	84,5	16	165	130	187	200	3,5	—	140	189	236	75	122	185	229	429	429	101	58	60
	MW-032	50	63	71	40	40					347										160	140	305	53	122	185	229	439	439	112	62	65	
	MW-1	MR2, MR3	63	63	71	80					314										160	140	357		140	211	275	730	794	112	74	77	
08 W-1	MW-1	MR2, MR3	63	63	71	80					314										160	140	331		122	185	229	671	715	101	63	65	
	MW-2	MR2, MR3	50	63	71	80					314										160	140	305		122	185	229	671	715	112	67	70	
	MW-3	MR2, MR3	50	63	71	80														160	140	200		122	185	229	697	761	112	67	70		
09 W-1	MW-041	63	71	125	63	80	225	155	60	32	M 12 ⁸	118	225	99,5	18	215	180	222	250	4	—	160	287	375	106	140	211	275	515	515	112	97	100
	MW-042	63	63	50	50	80					382										160	140	407 ⁵⁾	375 ⁵⁾	140	211	275	806	870	112	110	113	
	MW-1	MR2, MR3	63	63	71	80															160	140	305		140	211	275	826	902	122	114	119	
11 W-1	MW-061	80	71	160	80	100	272	187	70	38	M 14 ⁸	138	280	118,5	22	265	230	268	300	4	—	160	345	460	125	140	211	275	593	593	112	163	166
	MW-062	80	71	80	50	100					466										160	140	500		160	231	307	942	1018	122	188	193	
	MW-011	MR2, MR3	80	80	90	90					469										160	140	207		160	231	307	981	1066	149	194	199	
11 W-1	MW-011	MR2, MR3	80	80	90	90					424										160	140	472		140	211	275	880	944	112	167	170	
	MW-012	MR2, MR3	63	63	71	80					424										160	140	460		140	211	275	880	944	122	171	176	
	MW-012	MR2, MR3	63	63	71	80														160	140	207		140	211	275	939	1024	149	184	191		
13 W-1	MW-081	100	100	200	100	100	342	235	90	48	M 16 ⁸	170	335	137,5	27	300	250	328	350	5	—	200	431	560	150	160	231	307	745	745	112	163	166
	MW-082	100	100	200	100	100					574										200	200	620		160	231	307	942	1018	149	188	193	
	MW-1	MR2, MR3	100	100	90	100					511										200	200	585		160	231	307	1161	1246	149	187	192	
13 W-1	MW-081	80	80	200	100	81	342	235	90	48	M 16 ⁸	170	335	137,5	27	300	250	328	350	5	—	200	431	560	150	160	231	307	745	745	112	163	166
	MW-082	80	80	200	100	90					511										200	200	620		160	231	307	942	1018	149	188	193	
	MW-2	MR2, MR3	80	80	80	90					514										200	200	585		160	231	307	1161	1246	149	187	192	
14 W-1	MW-091	125	90	250	125	80	425	287	110	55	M 16 ⁸	205	410	163	33	400	350	401	450	5	—	200	537	690	180	180	270	355	876	876	149	480	485
	MW-092	125	100	125	125	80	250				629										200	200	620		180	270	355	895	895	164	487	494	
	MW-1	MR2, MR3	100	100	101	112					645										200	200	620		180	270	355	945	1014	164	501	512	
14 W-1	MW-1	MR2, MR3	100	100	101	112															200	200	620		180	270	355	1266	1353	149	484	489	
	MW-2	MR2, MR3	100	100	101	112															200	200	620		180	270	355	1341	1417	149	491	498	

1) Working length of thread $2 \cdot F$.

2) Holes turned through 45° with respect to the drawing.

3) Holes turned through $22^{\circ} 30'$ with respect to the drawing.
 4) Tolerance t8

- 4) Tolerar
- 5) Highes

6) Values valid for brake motor.

b) Values valid for brake motor



Initial gear reducer or garmotor mounting position

In order to make easier the individualization of the combined gear reducer and garmotor mounting position refer to following table where, according to the final gear reducer mounting position and to the initial gear reducer or garmotor coupling position, the mounting positions of the same initial gear reducer or garmotor are stated.

Initial garmotor mounting position

Coupling position	- Final gear reducer mounting position					
	B3	B6	B7	B8	V5	V6
-	B8* ≤64 B8 ≥80 					
1	B8* ≤64 B8 ≥80 					
2						
3						
	B5* ≤40 B3* ≥50 					

* This standard mounting position must **not** be stated in the designation.

1) Grease quantity is the same foreseen for B3 mounting position of cat. E.
On name plate there is a * in correspondence of mounting position.

**13. Radial loads¹⁾ F_{r1} [daN] on high speed shaft end**

13. Radial loads¹⁾ F_{r1} [daN] on high speed shaft end
14. Radial loads F_{r2} [daN] or axial loads F_{a2} [daN] on low speed shaft end

Radial loads generated on the shaft end by a drive connecting gear reducer and motor must be less than or equal to those given in the relevant table.

The radial load F_{r1} given by the following formula refers to most common drives:

$$F_{r1} = \frac{2865 \cdot P_1}{d \cdot n_1} \text{ [daN]} \quad \text{for timing belt drive}$$

$$F_{r1} = \frac{4775 \cdot P_1}{d \cdot n_1} \text{ [daN]} \quad \text{for V-belt drive}$$

where: P_1 [kW] is power required at the input side of the gear reducer, n_1 [min^{-1}] is the speed, d [m] is the pitch diameter.

Radial loads given in the table are valid for overhung loads on centre line of high speed shaft end, i.e. operating at a distance of $0,5 \cdot e$ (e = shaft end length) from the shoulder. If they operate at $0,315 \cdot e$ multiply by 1,25; if they operate at $0,8 \cdot e$ multiply by 0,8.

n_1 min^{-1}	Grandezza riduttore - Gear reducer size																			
	01		02		03		04, 05		06, 07		08		09, 10		11, 12		13		14	
	W1	W2	W1	W2	W1	W2	W1	W2	W1	W2	W1	W2	W1	W2	W1	W2	W1	W2	W1	W2
1 400	14	11,2	21,2	17	31,5	17	47,5	26,5	71	26,5	106	42,5	160	75	236	170	265	170	375	250
1 120	15	11,8	22,4	18	33,5	18	50	28	75	28	112	45	170	80	250	180	280	180	400	265
900	16	12,5	23,6	19	35,5	19	53	30	80	30	118	47,5	180	85	265	190	300	190	425	280
710	18	14	26,5	21,2	40	21,2	60	33,5	90	33,5	132	53	200	95	300	212	335	212	475	315
560	19	15	28	22,4	42,5	22,4	63	35,5	95	35,5	140	56	212	100	315	224	355	224	500	335
450	20	16	30	23,6	45	23,6	67	37,5	100	37,5	150	60	224	106	335	236	375	236	530	355
355	22,4	18	33,5	26,5	50	26,5	75	42,5	112	42,5	170	67	250	118	375	265	425	265	600	400

1) An axial load of up to 0,2 times the value in the table is permissible, simultaneously with the radial load. If exceeded consult us.

14 - Radial loads F_{r2} [daN] or axial loads F_{a2} [daN] on low speed shaft end**Axial loads F_{a2}**

Permissible F_{a2} is shown in the column where direction of rotation of low speed shaft (black or white arrow) and direction of the axial force (solid or broken arrow) correspond to those of the gear reducer in question. Direction of rotation and direction of force may be established viewing the gear reducer from any point, providing the same point adopted for both.

Wherever possible, choose the load conditions corresponding the column on the right.

Radial loads F_{r2}

Radial loads generated on the shaft end by a drive connecting gear reducer and machine must be less than or equal to those given in the relevant table.

Normally, radial loads on low speed shaft ends are considerable: in fact there is a tendency to connect the gear reducer to the machine by means of a transmission with high transmission ratio (economizing on the gear reducer) and with small diameters (economizing on the drive, and for requirements dictated by overall dimensions).

Bearing life and wear (which also affect gears unfavourably) and low speed shaft strength, clearly impose limits on permissible radial load.

The high value which radial load may take on, and the importance of not exceeding permissible values, make it necessary to take full advantage of the gear reducer's possibilities.

Permissible radial loads given in the table are therefore based on: the product of speed n_2 [min^{-1}] multiplied by bearing life L_h [h] required, the direction of rotation, the angular position φ [$^\circ$] of the load and torque M_2 [daN m] required.

Radial loads given in the table are valid for overhung loads on centre line of low speed shaft end, i.e. operating at a distance of $0,5 \cdot E$ (E = shaft end length) from the shoulder. If operating at $0,315 \cdot E$ multiply by 1,25; if operating at $0,8 \cdot E$ multiply by 0,8.



14. Radial loads F_{r2} [daN] or axial loads F_{a2} [daN] on low speed shaft end



Radial load F_{r2} for most common drives has the following value and angular position:

$$F_{r2} = \frac{1\,910 \cdot P_2}{d \cdot n_2} \text{ [daN]}$$

for chain drive (lifting in general); for timing belt drive replace 1 910 with 2 865





Rotazione
Rotation





$$F_{r2} = \frac{4\,775 \cdot P_2}{d \cdot n_2} \text{ [daN]}$$

for V-belt drive





$$F_{r2} = \frac{2\,032 \cdot P_2}{d \cdot n_2} \text{ [daN]}$$

for spur gear pair drive







$$F_{r2} = \frac{6\,781 \cdot P_2}{d \cdot n_2} \text{ [daN]}$$

for friction wheel drive (rubber-on-metal)



where: P_2 [kW] is power required at the output side of the gear reducer, n_2 [min^{-1}] is the speed, d [m] is the pitch diameter.

IMPORTANT: 0° coincides with a half line lying parallel to the worm axis, and oriented as shown above, and therefore it follows the rotation of the worm axis as shown below.





14. Radial loads F_{r2} [daN] or axial loads F_{a2} [daN] on low speed shaft end

01

$n_2 \cdot L_h$	M_2	$F_{r2}^{(1)}$												$F_{a2}^{(2)}$				
min ⁻¹ · h	daN m	0 45 90 135 180 225 270 315							0 45 90 135 180 225 270 315							80	125	
		0	45	90	135	180	225	270	315	0	45	90	135	180	225			
355 000	5,3	180	180	180	180	180	180	180	180	180	180	180	180	180	180	80	125	
710 000	3,75	140	150	170	180	180	180	180	160	180	180	150	132	140	170	180	80	125
	2,65	150	160	180	180	180	180	180	180	180	180	170	150	150	170	180	80	125
900 000	3,75	125	132	160	180	180	180	170	140	180	180	140	125	125	150	180	80	125
	2,65	140	140	160	180	180	180	170	150	180	180	150	140	140	160	180	80	125
	1,9	150	150	170	180	180	180	170	160	180	180	160	150	150	160	180	80	125
1 120 000	2,65	125	132	150	180	180	180	160	140	180	170	140	125	125	150	170	80	112
	1,9	140	140	150	170	180	180	160	140	180	160	140	132	140	150	170	80	118
	1,32	140	150	160	170	180	170	160	150	180	160	150	140	140	150	170	80	118
1 400 000	2,65	118	118	140	160	180	170	150	125	180	150	125	112	118	135	160	80	106
	1,9	125	132	140	160	170	170	150	132	170	150	132	125	125	140	160	80	106
	1,32	132	132	140	160	160	160	150	140	160	150	140	132	132	140	160	80	106
1 800 000	2,65	106	106	125	150	170	160	140	118	170	140	118	100	106	125	150	71	95
	1,9	112	118	132	150	160	150	140	125	160	140	125	112	112	125	150	80	95
	1,32	118	125	132	140	150	150	140	125	150	140	125	118	118	132	140	80	95
2 240 000	2,65	95	100	118	140	160	150	132	106	160	132	106	90	95	112	140	63	85
	1,9	106	106	118	140	150	140	132	112	150	132	112	100	106	118	140	71	85
	1,32	112	112	125	132	140	140	132	118	140	132	118	112	112	118	132	80	90
2 800 000	2,65	85	90	106	132	150	140	118	95	150	125	95	80	85	100	132	56	75
	1,9	95	100	112	132	140	140	118	106	140	125	100	95	95	106	132	63	80
	1,32	100	106	112	125	132	132	118	106	132	125	106	100	100	112	125	71	80
3 550 000	1,9	85	90	100	118	132	125	112	95	132	112	95	85	85	100	118	56	71
	1,32	95	95	106	118	125	125	112	100	125	112	100	90	95	100	118	63	71
	0,95	100	100	106	118	118	118	112	100	118	112	100	95	100	106	118	67	75

02

224 000	9	250	250	250	250	250	250	250	250	250	250	250	250	250	250	250	112	180	
450 000	6,3	200	200	236	250	250	250	250	224	250	250	212	190	200	236	250	250	112	180
	4,5	212	224	250	250	250	250	250	236	250	250	236	212	212	236	250	250	112	180
560 000	6,3	180	190	224	250	250	250	250	200	250	250	200	170	180	212	250	250	112	180
	4,5	200	200	236	250	250	250	250	212	250	250	212	190	200	224	250	250	112	180
	3,15	212	212	236	250	250	250	250	224	250	250	224	212	212	224	250	250	112	180
710 000	6,3	160	170	200	250	250	250	224	180	250	236	180	150	160	190	250	250	112	160
	4,5	180	190	212	250	250	250	224	190	250	236	190	170	180	200	250	250	112	160
	3,15	190	200	212	236	250	250	224	200	250	236	200	190	190	212	236	250	112	170
900 000	6,3	140	150	190	236	250	250	212	160	250	212	160	140	140	180	236	250	106	140
	4,5	160	170	190	224	250	236	212	180	250	212	180	160	160	190	224	250	112	150
	3,15	180	180	200	224	236	236	212	190	236	212	190	170	170	190	224	236	112	150
1 120 000	4,5	150	150	180	212	236	224	190	160	236	200	160	140	150	170	212	236	106	132
	3,15	160	160	180	212	224	212	200	170	224	200	170	160	160	180	212	224	112	140
	2,24	170	170	190	200	212	212	200	180	212	200	180	170	170	180	200	212	112	140
1 400 000	4,5	132	140	160	200	224	212	180	150	224	180	150	132	132	160	200	224	95	118
	3,15	150	150	170	190	212	200	180	160	212	180	160	140	150	160	190	212	106	125
	2,24	160	160	170	190	200	200	180	160	200	180	160	150	160	170	190	200	112	125
1 800 000	4,5	118	125	150	190	212	200	170	132	200	170	132	112	118	140	180	212	80	106
	3,15	132	140	150	180	190	190	170	140	190	170	140	132	132	150	180	200	90	112
	2,24	140	140	160	180	190	180	170	150	190	170	150	140	140	150	170	190	100	112
2 240 000	4,5	106	112	140	170	200	190	150	125	190	160	118	106	106	132	170	200	71	95
	3,15	118	125	140	170	180	180	150	132	180	160	132	118	118	140	170	190	80	100
	2,24	132	132	150	160	170	170	150	140	170	160	140	125	132	140	160	180	90	100
2 800 000	4,5	100	100	125	160	190	180	140	112	180	150	112	90	95	118	160	190	60	90
	3,15	112	112	132	160	170	170	140	118	170	150	118	106	112	125	150	170	71	90
	2,24	118	125	132	150	160	160	140	125	160	150	125	118	118	132	150	170	80	95
3 550 000	3,15	100	106	125	150	160	150	132	112	160	132	112	95	100	118	140	160	63	80
	2,24	106	112	125	140	150	150	132	118	150	132	118	106	106	125	140	150	71	85
	1,6	118	118	125	140	150	140	132	118	150	132	118	112	118	125	140	150	75	85

1) An axial load of up to 0,2 times the value in the table is permissible, simultaneously with the radial load. If exceeded consult us.

2) A radial load of up to 0,2 times the value in the table is permissible, simultaneously with the axial load. If exceeded consult us.



14. Radial loads F_{r2} [daN] or axial loads F_{a2} [daN] on low speed shaft end

size **03**

$n_2 \cdot L_h$ min ⁻¹ · h	M_2 daN m	$F_{r2}^{(1)}$												$F_{a2}^{(2)}$	
		0 45 90 135 180 225 270 315						0 45 90 135 180 225 270 315						size	
		0°	0°	0°	0°	0°	0°	0°	0°	0°	0°	0°	0°	0°	0°
140 000	25	335	355	355	355	355	355	355	355	355	355	355	355	160	250
	18	355	355	355	355	355	355	355	355	355	355	355	355	160	250
	12,5	355	355	355	355	355	355	355	355	355	355	355	355	160	250
180 000	18	300	315	355	355	355	355	355	335	355	355	280	280	355	355
	12,5	335	355	355	355	355	355	355	355	335	355	315	335	355	355
	9	355	355	355	355	355	355	355	355	355	355	355	355	160	250
224 000	18	265	280	355	355	355	355	300	355	355	300	250	250	335	355
	12,5	300	315	355	355	355	355	335	355	355	335	300	300	355	355
	9	335	355	355	355	355	355	355	355	355	355	315	335	355	355
280 000	12,5	280	280	335	355	355	355	315	355	355	300	265	265	335	355
	9	300	315	355	355	355	355	335	355	355	300	335	335	355	355
355 000	12,5	250	265	315	355	355	355	280	355	355	280	236	250	300	355
	9	280	280	335	355	355	355	300	355	355	300	265	280	315	355
	6,3	300	300	335	355	355	355	315	355	355	315	280	300	335	355
450 000	12,5	224	236	280	355	355	355	315	355	355	300	265	265	335	355
	9	250	265	300	355	355	355	315	355	355	300	335	335	355	355
	6,3	265	280	315	335	355	355	315	280	355	355	265	300	335	355
	4,5	280	280	315	335	355	355	315	300	355	355	300	280	300	355
560 000	12,5	200	212	265	335	355	355	300	224	355	300	224	190	200	250
	9	224	236	280	335	355	355	300	250	355	300	250	212	224	265
	6,3	250	250	280	315	335	355	300	265	335	300	265	236	250	315
	4,5	265	265	280	315	335	355	315	300	280	335	300	250	265	315
710 000	12,5	180	190	236	315	355	355	265	200	355	280	200	160	170	224
	9	200	212	250	315	335	355	280	224	335	280	224	200	200	236
	6,3	224	236	265	300	315	315	280	236	315	280	236	224	224	250
	4,5	236	250	265	300	315	315	300	250	315	280	250	236	236	280
900 000	12,5	160	170	224	300	355	315	250	180	335	250	180	140	150	200
	9	180	190	236	280	315	300	250	200	315	265	200	170	180	224
	6,3	200	212	236	280	300	280	250	224	300	265	224	200	200	236
	4,5	224	224	250	265	280	280	250	236	280	265	236	212	212	265
1 120 000	9	170	170	212	265	300	280	236	190	300	236	180	160	200	280
	6,3	190	190	224	265	280	280	236	200	280	236	200	190	212	265
	4,5	200	200	224	250	265	265	236	212	200	224	200	224	250	280
1 400 000	9	150	160	200	250	280	265	212	170	280	224	170	140	180	250
	6,3	170	180	200	250	265	224	190	170	265	224	180	160	200	265
	4,5	180	190	212	236	250	250	224	200	250	224	200	180	200	236
1 800 000	9	132	140	180	236	265	250	200	150	265	200	150	125	160	224
	6,3	150	160	190	224	250	236	200	170	250	212	170	150	180	224
	4,5	170	170	190	224	236	224	200	180	236	212	180	160	190	236
2 240 000	9	118	125	160	224	250	236	180	140	250	190	132	106	112	265
	6,3	140	140	170	212	236	224	190	150	236	190	150	132	160	236
	4,5	150	160	180	200	224	212	190	160	224	190	160	150	170	224
2 800 000	9	106	112	150	200	236	224	170	125	236	180	118	95	100	250
	6,3	125	132	160	200	224	212	170	140	224	180	140	118	122	224
	4,5	140	140	160	190	212	200	170	150	212	180	150	132	148	212
	3,15	150	170	190	200	190	180	160	160	200	180	160	150	170	200
3 550 000	6,3	112	118	140	180	212	200	160	125	200	160	125	106	112	212
	4,5	125	132	150	180	200	190	160	140	190	170	132	125	140	200
	3,15	132	140	150	170	180	180	160	140	180	170	140	132	150	190

max 355

max 160 max 250

1) An axial load of up to 0,2 times the value in the table is permissible, simultaneously with the radial load. If exceeded consult us.

2) A radial load of up to 0,2 times the value in the table is permissible, simultaneously with the axial load. If exceeded consult us.



14. Radial loads F_{r2} [daN] or axial loads F_{a2} [daN] on low speed shaft end

size 04, 05

$n_2 \cdot L_h$	M_2	$F_{r2}^{(1)}$												$F_{a2}^{(2)}$												
		min ⁻¹ · h						daN m	0	45	90	135	180	225	270	315	0	45	90	135	180	225	270	315	size	04, 05
90 000	47,5 33,5	400 475	425 500	530 530	530 530	530 530	530 530	475 530	530 530	530 530	450 530	355 450	375 475	530 530	530 530	530 530	236 236	375 375	236 236	375 375	236 236	375 375	236 236	375 375		
112 000	33,5 23,6	425 500	450 500	530 530	530 530	530 530	530 530	500 530	530 530	530 530	475 530	400 475	425 475	530 530	530 530	530 530	530 530	236 236	375 375	236 236	375 375	236 236	375 375	236 236	375 375	
140 000	33,5 23,6 17	375 450 475	425 475 500	530 530 530	530 530 530	530 530 530	530 530 530	450 500	530 530	530 530	425 475	355 425	375 425	475 530	530 530	530 530	530 530	236 236	375 375	236 236	375 375	236 236	375 375	236 236	375 375	
180 000	33,5 23,6 17 11,8	335 400 425 475	375 500 500 530	475 530 530 530	530 530 530 530	530 530 530 530	530 530 530 530	400 450	530 530	530 530	375 475	315 425	335 425	425 530	530 530	530 530	530 530	236 236	375 375	236 236	375 375	236 236	375 375	236 236	375 375	
224 000	33,5 23,6 17 11,8	300 355 400 425	335 375 425 450	425 450 500 530	530 530 530 530	530 530 530 530	530 530 530 530	355 400	500 500	475 500	375 425	530 530	335 425	280 400	280 400	400 530	530 530	236 236	375 375	236 236	375 375	236 236	375 375	236 236	375 375	
280 000	23,6 17 11,8	315 355 400	335 375 450	425 500	530 530	530 530	450 530	375 475	530 530	375 425	530 530	355 425	300 425	315 425	400 530	530 530	236 236	355 375	236 236	375 375	236 236	375 375	236 236	375 375		
355 000	23,6 17 11,8	280 335 355	315 335 375	375 400 475	500 500	530 530	530 530	425 475	335 375	530 500	425 475	315 375	265 375	280 375	355 425	500 530	236 236	315 335	236 236	375 375	236 236	375 375	236 236	375 375		
450 000	23,6 17 11,8 8,5	250 300 335 355	280 315 335 375	355 450 475 475	530 500 450 450	500 530 475 425	500 530 400 425	300 335	400 475	400 375	280 375	236 315	250 315	315 375	425 475	450 500	530 530	200 236	280 300	236 236	315 315	236 236	375 375	236 236	375 375	
560 000	23,6 17 11,8 8,5	236 265 300 315	250 280 315 335	315 335 400 400	425 425 425 425	500 530 425 400	475 530 425 375	265 300	355 425	375 375	265 315	212 315	224 315	300 375	425 475	530 530	530 530	170 212	265 265	212 212	280 280	236 236	375 375	236 236	375 375	
710 000	17 11,8 8,5	236 265 280	250 315 375	315 375	400 400	425 425	400 400	335 375	400 400	375 375	265 300	224 280	236 280	224 315	300 375	375 425	450 500	180 212	250 250	212 212	265 265	224 224	375 375	236 236	375 375	
900 000	17 11,8 8,5	212 250 265	224 300 300	280 355 335	355 375 375	375 375 355	375 375 315	236 265	315 236	265 236	200 236	212 236	265 236	355 375	425 400	450 475	530 530	160 180	224 224	180 180	224 224	200 200	375 375	236 236	375 375	
1 120 000	17 11,8 8,5	190 224 236	200 236 280	265 335 335	400 475 300	355 425 250	280 375 250	224 224	280 375	300 375	224 224	190 236	212 212	180 224	224 236	265 315	375 425	400 450	132 160	200 200	212 212	212 212	180 180	375 375	236 236	375 375
1 400 000	17 11,8 8,5	170 200 224	180 212 224	236 315 315	315 315 315	335 335 280	265 265 280	200 224	326 300	315 300	160 224	190 190	160 180	160 180	224 224	315 250	375 300	400 355	118 140	180 190	190 190	175 175	375 375	236 236	375 375	
1 800 000	17 11,8 8,5 6	150 180 200 212	160 190 212 224	212 280 280 265	300 315 300 280	335 375 280 265	315 375 250 224	180 180	326 300	315 300	132 190	140 180	170 190	140 180	224 224	315 250	375 300	400 355	95 125	160 170	170 170	170 170	375 375	236 236	375 375	
2 240 000	17 11,8 8,5 6	132 160 180 200	140 170 190 200	200 212 224 224	280 300 280 250	265 326 280 265	236 236 200 212	160 170	315 300	315 300	118 170	125 160	170 190	140 180	224 224	335 265	375 300	400 355	80 106	140 150	150 150	150 150	375 375	236 236	375 375	
2 800 000	17 11,8 8,5 6	118 150 170 180	125 150 170 190	180 212 236 236	265 250 236 236	236 265 200 190	200 265 236 212	140 170	280 280	224 224	100 180	106 160	150 180	140 180	224 224	300 250	375 300	400 355	67 90	132 140	140 140	140 140	375 375	236 236	375 375	
3 550 000	11,8 8,5 6	132 150 160	140 160 170	180 190 212	236 224 236	265 224 236	200 180	150	265 250 200	200 170	118 160	125 160	160 180	118 180	224 224	280 250	300 250	375 300	80 95	125 125	125 125	125 125	375 375	236 236	375 375	

max 530

max 236 max 375

1) An axial load of up to 0,2 times the value in the table is permissible, simultaneously with the radial load. If exceeded consult us.

2) A radial load of up to 0,2 times the value in the table is permissible, simultaneously with the axial load. If exceeded consult us.

**PalaDrive**

Worm Gear Reducers and Gear Motors

SERIES W14. Radial loads F_{r2} [daN] or axial loads F_{a2} [daN] on low speed shaft endsize **06, 07**

$n_2 \cdot L_h$	M_2	$F_{r2}^{1)}$												$F_{a2}^{2)}$						
		min ⁻¹ · h	daN m	0	45	90	135	180	225	270	315	0	45	90	135	180	225	270	315	
90 000	80	560	630	800	800	800	800	800	670	800	800	670	670	560	750	800	800	800	355	560
	56	710	750	800	800	800	800	800	800	800	800	800	750	670	670	800	800	800	355	560
112 000	56	630	670	800	800	800	800	800	800	710	800	800	710	600	630	750	800	800	355	560
	40	710	750	800	800	800	800	800	800	750	800	800	750	670	710	800	800	800	355	560
140 000	56	560	600	750	800	800	800	800	800	630	800	800	630	530	560	710	800	800	355	560
	40	630	670	800	800	800	800	800	800	710	800	800	710	630	630	750	800	800	355	560
	28	710	710	800	800	800	800	800	800	750	800	800	750	670	710	800	800	800	355	560
180 000	56	500	530	670	800	800	800	750	560	800	800	560	450	475	630	800	800	800	355	560
	40	560	600	710	800	800	800	750	630	800	800	630	560	560	670	800	800	800	355	560
	28	630	670	750	800	800	800	750	670	800	800	670	630	630	710	800	800	800	355	560
224 000	56	450	475	630	800	800	800	710	530	800	710	500	400	425	560	800	800	800	335	500
	40	530	560	670	800	800	800	710	560	800	750	560	500	500	630	800	800	800	355	530
	28	560	600	670	800	800	800	710	630	800	750	630	560	560	670	800	800	800	355	560
	20	630	630	710	750	800	800	710	670	800	750	670	600	600	630	750	800	800	355	560
280 000	40	475	500	600	750	800	800	670	530	800	670	530	450	450	560	800	800	800	355	475
	28	530	560	630	750	800	800	750	670	560	800	670	560	500	530	600	750	800	355	500
	20	560	600	630	710	750	750	670	600	750	670	600	560	560	630	710	750	800	355	500
355 000	40	425	450	560	710	800	750	600	475	800	630	475	400	400	530	710	800	800	315	425
	28	475	500	560	670	750	710	630	530	750	630	530	450	475	560	670	750	800	355	450
	20	530	530	600	670	710	670	630	560	710	630	560	500	500	560	670	710	800	355	450
	14	560	560	600	670	670	670	630	560	670	630	560	530	560	600	630	670	800	355	475
450 000	40	375	400	500	670	750	710	560	425	750	560	425	335	355	475	630	800	800	265	375
	28	425	450	530	630	710	670	560	475	710	600	475	400	425	500	630	710	800	315	400
	20	475	500	560	630	670	630	560	500	670	600	500	450	475	530	630	670	800	355	425
	14	500	500	560	600	630	630	560	530	630	570	530	500	500	530	600	630	800	355	425
560 000	40	335	355	475	630	710	670	530	375	710	530	375	300	315	425	600	750	800	224	355
	28	400	400	500	600	670	630	530	425	670	530	425	375	375	475	600	670	800	280	355
	20	425	450	500	560	630	600	530	475	630	530	450	425	425	500	560	630	800	315	375
	14	450	475	500	560	600	560	530	475	600	530	475	450	450	500	560	600	800	335	375
710 000	40	300	315	425	560	670	630	475	335	670	500	335	265	280	375	560	710	800	190	315
	28	355	375	450	560	630	600	475	400	630	500	375	335	335	425	560	630	800	250	335
	20	400	400	475	530	600	560	500	425	560	500	425	375	375	450	530	600	800	280	335
	14	425	425	475	530	560	530	500	450	560	500	450	400	425	475	530	560	800	300	355
900 000	40	250	280	375	530	630	600	425	300	630	450	280	224	236	335	530	670	800	160	280
	28	315	335	400	530	600	560	450	355	560	450	355	300	315	375	500	600	800	212	300
	20	355	375	425	500	560	530	450	375	530	475	375	335	355	400	500	560	800	250	300
	14	375	400	425	500	530	500	450	400	530	475	400	375	375	425	500	530	800	265	315
1 120 000	28	280	300	375	500	560	530	425	315	560	425	315	265	280	355	475	560	800	180	265
	20	315	335	400	475	530	500	425	355	500	425	355	315	315	355	475	530	800	212	280
	14	355	355	400	450	500	475	425	375	475	425	375	335	335	400	450	500	800	236	280
1 400 000	28	250	265	355	450	530	500	375	280	530	400	280	236	250	315	450	530	800	160	236
	20	300	315	355	450	475	450	400	315	475	400	315	280	280	355	425	500	800	190	250
	14	315	335	375	425	450	450	400	335	450	400	335	315	315	355	425	475	800	212	250
1 800 000	28	224	236	315	425	500	450	355	250	475	355	250	200	212	280	400	500	800	132	212
	20	265	280	335	400	450	425	355	280	450	355	280	250	250	315	400	475	800	160	224
	14	280	300	335	400	425	355	315	255	425	375	315	280	280	335	425	490	800	190	224
	10	315	315	355	375	400	400	355	335	400	375	315	300	315	335	375	400	800	200	236
2 240 000	20	236	250	300	375	425	400	335	265	425	335	265	224	236	280	375	450	800	140	200
	14	265	280	315	375	400	375	335	280	400	335	280	250	265	300	375	400	800	170	212
	10	280	300	315	355	375	335	300	265	375	335	300	280	280	315	355	375	800	180	212
2 800 000	20	212	224	280	355	400	375	300	236	400	315	236	200	212	265	355	425	800	125	180
	14	236	250	300	355	375	355	315	255	375	315	265	236	236	280	335	375	800	150	190
	10	265	265	300	335	355	315	280	265	355	315	280	250	265	280	335	355	800	160	190
3 550 000	20	190	200	250	335	375	355	280	212	375	280	212	170	180	236	335	400	800	106	160
	14	212	224	265	315	355	335	280	236	355	300	236	212	212	250	315	355	800	125	170
	10	236	250	280	300	335	315	280	250	335	300	250	236	236	265	315	335	800	140	170

max 800

max 355

max 560

1) An axial load of up to 0,2 times the value in the table is permissible, simultaneously with the radial load. If exceeded consult us.

2) A radial load of up to 0,2 times the value in the table is permissible, simultaneously with the axial load. If exceeded consult us.

**PalaDrive**

Worm Gear Reducers and Gear Motors

SERIES W14. Radial loads F_{r2} [daN] or axial loads F_{a2} [daN] on low speed shaft end**08**

$n_2 \cdot L_h$ min ⁻¹ · h	M_2 daN m	$F_{r2}^{(1)}$												$F_{a2}^{(2)}$					
		△							▲					size					
		0	45	90	135	180	225	270	315	0	45	90	135	180	225	270	315	↑	↓
90 000	160	670	750	1060	1250	1250	1250	1180	800	1250	1250	750	560	630	900	1250	1250	530	900
	112	850	900	1180	1250	1250	1250	1250	1000	1250	1250	950	800	850	1000	1250	1250	560	900
112 000	112	750	800	1060	1250	1250	1250	1180	900	1250	1180	850	710	750	950	1250	1250	560	900
	80	900	950	1120	1250	1250	1250	1180	1000	1250	1250	950	850	850	1060	1250	1250	560	900
	56	1000	1000	1120	1250	1250	1250	1180	1060	1250	1250	1060	950	950	1120	1250	1250	560	900
	40	1060	1060	1180	1250	1250	1250	1180	1120	1250	1250	1060	1000	1060	1120	1250	1250	560	900
140 000	112	670	750	950	1250	1250	1250	1060	800	1250	1120	750	630	630	900	1250	1250	530	800
	80	800	850	1000	1250	1250	1250	1120	900	1250	1120	900	750	800	950	1250	1250	560	850
	56	900	950	1060	1250	1250	1250	1120	950	1250	1120	950	850	900	1000	1250	1250	560	900
	40	950	1000	1060	1180	1250	1250	1120	1000	1250	1120	1000	950	950	1060	1180	1250	560	900
180 000	112	600	630	850	1250	1250	1250	1000	710	1250	1000	670	530	560	800	1180	1250	450	710
	80	710	750	950	1180	1250	1250	1000	800	1250	1060	800	670	710	850	1180	1250	560	750
	56	800	850	950	1120	1250	1250	1180	1000	1250	1060	850	750	800	950	1120	1250	560	800
	40	850	900	1000	1120	1180	1250	1120	900	1250	1120	1000	900	850	950	1120	1180	560	800
224 000	112	530	560	800	1120	1250	1180	900	630	1250	950	600	450	475	710	1120	1250	375	630
	80	630	670	850	1120	1250	1180	950	710	1250	950	710	600	630	800	1060	1250	500	670
	56	750	750	900	1060	1180	1120	950	800	1180	1000	800	710	710	850	1060	1180	560	710
	40	800	800	900	1060	1120	1060	950	850	1120	1000	850	750	800	900	1000	1120	560	750
280 000	80	560	630	800	1060	1180	1120	850	670	1180	900	630	530	560	710	1000	1250	425	600
	56	670	710	800	1000	1120	1060	900	750	1060	900	710	630	670	800	1000	1120	500	630
	40	710	750	850	950	1000	1000	900	750	1000	900	750	710	710	800	950	1060	560	670
335 000	80	500	560	710	950	1120	1060	800	600	1120	800	560	450	500	630	950	1180	355	560
	56	600	630	750	950	1000	950	800	670	1000	850	670	560	600	710	900	1060	450	560
	40	670	670	800	900	950	950	800	710	950	850	710	630	670	750	900	1000	500	600
450 000	80	450	475	630	900	1060	950	710	530	1060	750	500	400	425	560	850	1120	300	475
	56	530	560	710	850	950	900	750	600	950	750	600	500	530	670	850	1000	375	530
	40	600	630	710	850	900	850	750	630	900	750	630	560	600	670	850	900	425	530
	28	630	670	710	800	850	850	750	670	850	750	670	630	630	710	800	850	475	560
560 000	80	400	425	600	850	950	900	670	475	1000	670	450	355	375	530	800	1060	250	450
	56	475	530	630	800	900	850	710	560	900	710	530	450	475	600	800	950	335	475
	40	560	560	670	800	850	800	710	600	850	710	600	530	530	630	750	850	400	475
	28	600	600	670	750	800	800	710	630	800	710	630	560	600	670	750	800	425	500
710 000	56	425	450	560	750	850	800	630	500	850	670	475	400	425	530	750	900	280	425
	40	500	530	600	710	800	750	630	530	800	670	530	475	475	560	710	800	335	425
	28	530	560	630	710	750	710	630	560	750	670	560	530	530	600	710	750	375	450
900 000	56	375	400	530	710	800	750	560	450	800	600	425	355	375	475	670	850	250	375
	40	450	475	560	670	750	710	600	500	750	600	475	425	425	530	670	750	300	400
	28	500	500	560	670	710	670	600	530	710	600	530	475	475	560	630	710	335	400
1 120 000	56	335	375	475	670	750	710	530	400	750	560	375	315	315	450	630	800	212	335
	40	400	425	500	630	710	670	560	450	710	560	450	375	400	475	630	710	265	355
	28	450	475	530	600	670	630	560	475	670	560	475	425	450	500	600	670	300	375
1 400 000	56	300	335	450	630	710	670	500	355	710	500	335	265	280	400	600	750	170	300
	40	355	375	475	600	670	630	500	400	670	530	400	335	335	450	600	670	224	315
	28	400	425	500	560	630	600	530	450	630	530	450	400	400	475	560	630	265	335
1 800 000	56	265	280	400	560	630	600	450	315	670	475	300	224	236	355	560	710	140	265
	40	315	335	425	560	630	600	475	355	630	475	355	300	315	400	530	630	190	280
	28	375	375	450	530	560	560	475	400	560	500	400	355	355	425	530	600	236	300
2 240 000	40	280	315	400	530	600	560	425	335	560	450	315	265	280	355	500	600	170	265
	28	335	355	400	500	560	450	375	355	530	450	355	315	335	400	500	560	200	265
2 800 000	40	250	280	355	475	560	530	400	300	560	400	280	236	250	335	475	560	140	235
	28	300	315	375	475	500	500	400	335	500	425	335	280	300	355	450	530	180	255
3 550 000	40	224	250	315	450	530	500	355	265	530	375	250	200	212	300	450	560	118	212
	28	265	280	355	425	475	450	375	300	475	375	300	250	265	335	425	500	150	224

max 1 250

max 560

max 900

1) An axial load of up to 0,2 times the value in the table is permissible, simultaneously with the radial load. If exceeded consult us.

2) A radial load of up to 0,2 times the value in the table is permissible, simultaneously with the axial load. If exceeded consult us.

**PalaDrive**

Worm Gear Reducers and Gear Motors

SERIES W14. Radial loads F_{r2} [daN] or axial loads F_{a2} [daN] on low speed shaft endsize **08 bis**³⁾

$n_2 \cdot L_h$ min ⁻¹ · h	M_2 daN m	$F_{r2}^{(1)}$												$F_{a2}^{(2)}$				
		0	45	90	135	180	225	270	315	0	45	90	135	180	225	270	315	
280 000	160 112	1250 1250	560 560	900 900														
355 000	80 56	1250 1250	560 560	900 900														
450 000	80 56	1250 1250	560 560	900 900														
560 000	80 56	1250 1250	560 560	900 900														
710 000	56 40	1250 1250	560 560	900 900														
900 000	56 40	1250 1250	560 560	900 900														
1 120 000	56 40 28	1250 1250 1250	560 560 560	900 900 900														
1 400 000	56 40 28	1180 1250 1250	1250 1250 1250	560 560 560	850 900 900													
1 800 000	56 40 28	1120 1180 1250	1250 1250 1250	560 560 560	800 850 850													
2 240 000	40 28	1120 1180	1250 1250	560 560	750 800													
2 800 000	40 28	1060 1060	1180 1180	1250 1250	1250 1250	1180 1180	1060 1120	1250 1120	560 560	710 750								
3 550 000	40 28 20	950 1000 1000	1060 1060 1060	1180 1180 1180	1250 1250 1250	1180 1180	1120 1120	1060 1120	560 560 560	670 670 710								
max 1 250															max 560		max 900	

1) An axial load of up to 0,2 times the value in the table is permissible, simultaneously with the radial load. If exceeded consult us.

2) A radial load of up to 0,2 times the value in the table is permissible, simultaneously with the axial load. If exceeded consult us.

3) Values valid for taper roller bearings on low speed shaft (ch. 17).

**PalaDrive**

Worm Gear Reducers and Gear Motors

SERIES W14. Radial loads F_{r2} [daN] or axial loads F_{a2} [daN] on low speed shaft endsize **09 , 10**

$n_2 \cdot L_h$	M_2	$F_{r2}^{(1)}$												$F_{a2}^{(2)}$							
		min ⁻¹ · h	daN m	0	45	90	135	180	225	270	315	0	45	90	135	180	225	270	315		
90 000	300	800	850	1320	1800	1800	1600	1500	950	1800	1600	900	630	710	1060	1800	1800	630	1120	1120	
	212	1060	1120	1400	1800	1800	1800	1600	1180	1800	1700	1180	950	1000	1320	1800	1800	800	1250	1250	
112 000	212	900	1000	1320	1800	1800	1800	1500	1060	1800	1500	1060	850	900	1180	1800	1800	750	1120	1120	
	150	1120	1180	1400	1800	1800	1800	1500	1250	1800	1600	1250	1060	160	1320	1700	1800	800	1180	1180	
140 000	212	800	900	1180	1700	1800	1800	1400	950	1800	1400	900	710	750	1060	1700	1800	630	1000	1000	
	150	1000	1060	1320	1700	1800	1800	1400	1120	1800	1500	1120	950	950	1250	1600	1800	800	1060	1060	
	106	1120	1180	1320	1600	1700	1700	1400	1250	1700	1500	1180	1060	1120	1320	1600	1800	800	1120	1120	
180 000	212	710	750	1060	1600	1600	1500	1250	850	1800	1320	800	600	630	950	1500	1800	530	850	850	
	150	900	950	1180	1500	1800	1600	1320	1000	1700	1320	1000	800	850	1120	1500	1800	710	950	950	
	106	1000	1060	1250	1500	1600	1500	1320	1120	1600	1320	1120	950	1000	1180	1500	1700	800	1000	1000	
	75	1120	1120	1250	1400	1500	1500	1320	1180	1500	1320	1180	1060	1500	1120	1400	1600	800	1000	1000	
224 000	150	800	850	1060	1400	1700	1500	1180	900	1600	1250	900	710	750	1000	1400	1700	600	850	850	
	106	900	950	1120	1400	1500	1500	1250	1000	1500	1250	1000	850	900	1060	1400	1600	710	900	900	
	75	1000	1060	1180	1320	1400	1400	1250	1060	1400	1250	1060	1000	1000	1120	1320	1500	800	950	950	
280 000	150	710	750	1000	1320	1600	1500	1120	800	1500	1180	800	630	670	900	1320	1600	530	750	750	
	106	850	900	1060	1320	1400	1400	1120	900	1400	1180	900	800	800	1000	1250	1500	630	800	800	
	75	900	950	1060	1250	1320	1320	1180	1000	1320	1180	1000	900	900	1060	1250	1400	710	850	850	
	53	1000	1000	1120	1250	1320	1250	1180	1060	1320	1180	1060	1320	1180	1060	1250	1320	1250	800	850	850
350 000	150	630	670	900	1250	1500	1400	1000	710	1400	1060	710	560	560	800	1250	1500	425	670	670	
	106	750	800	950	1180	1320	1250	1060	850	1320	1060	800	710	710	900	1180	1400	560	710	710	
	75	850	850	1000	1180	1250	1250	1060	900	1250	1060	900	800	800	950	1180	1320	630	750	750	
	53	900	950	1000	1120	1180	1180	1060	950	1180	1060	950	900	900	1000	1120	1250	710	800	800	
450 000	150	530	600	800	1180	1250	1180	950	630	1320	950	600	475	500	710	1120	1500	355	600	600	
	106	670	710	900	1120	1250	1180	950	750	1250	1000	750	630	630	800	1120	1320	475	630	630	
	75	750	800	900	1120	1180	1120	1000	800	1180	1000	800	710	750	900	1060	1250	560	670	670	
	53	800	850	950	1060	1120	1120	1000	850	1120	1000	850	800	800	900	1060	1180	600	710	710	
560 000	150	475	500	750	1120	1060	1000	850	560	1180	900	530	400	425	630	1060	1320	300	530	530	
	106	600	630	800	1060	1180	1120	900	670	1180	900	670	560	560	750	1060	1250	400	600	600	
	75	670	710	850	1000	1120	1060	900	750	1120	950	750	670	670	800	1000	1180	500	600	600	
	53	750	750	850	1000	1060	1000	900	800	1060	950	800	710	750	850	1000	1060	560	630	630	
710 000	106	530	560	750	1000	1120	1060	800	600	1120	850	600	475	500	670	950	1180	355	530	530	
	75	630	630	750	950	1060	1000	850	670	1060	850	670	600	600	750	950	1060	425	560	560	
	53	670	710	800	900	1000	950	850	750	1000	850	750	670	670	750	900	1000	475	560	560	
900 000	106	450	500	670	900	1060	1000	750	530	1060	750	530	425	450	600	900	1120	300	475	475	
	75	560	600	710	900	1000	950	750	630	1000	800	600	530	530	670	850	1000	375	500	500	
	53	630	630	750	850	950	900	800	670	900	800	670	600	600	710	850	950	425	500	500	
1 120 000	106	400	450	600	850	950	900	670	475	1000	710	450	355	375	530	850	1060	250	425	425	
	75	500	530	670	850	950	900	710	560	950	750	560	475	500	630	800	950	315	450	450	
	53	560	600	670	800	850	800	710	630	850	750	600	530	560	670	800	900	375	450	450	
	37,5	600	630	710	800	850	800	710	630	800	750	600	600	670	750	850	950	425	475	475	
1 400 000	106	355	400	560	800	850	800	630	425	900	670	400	315	335	475	750	1000	200	375	375	
	75	450	475	600	750	900	850	670	500	850	670	500	425	425	560	750	900	280	400	400	
	53	500	530	630	750	800	800	670	560	800	670	560	500	500	600	750	850	335	425	425	
	37,5	560	630	710	750	750	670	600	560	750	670	600	530	560	630	710	800	375	425	425	
1 800 000	75	400	425	530	710	850	750	600	450	800	630	450	355	375	500	710	850	236	355	355	
	53	450	475	560	710	750	750	630	500	750	630	500	450	450	560	670	800	280	375	375	
	37,5	500	530	600	670	710	710	630	530	700	630	530	500	500	600	750	850	315	375	375	
2 240 000	75	355	375	500	670	800	710	560	400	750	560	400	315	335	450	670	800	200	315	315	
	53	425	450	530	670	710	670	560	450	710	600	450	400	400	500	630	750	250	335	335	
	37,5	450	475	560	630	670	670	560	500	670	600	500	450	450	530	630	710	280	355	355	
2 800 000	75	315	335	450	630	750	670	500	375	710	530	355	280	300	400	630	750	170	300	300	
	53	375	400	475	600	670	630	530	425	670	530	400	355	375	450	600	710	212	300	300	
	37,5	425	450	500	600	630	630	530	450	630	560	450	400	425	475	600	670	250	315	315	
3 550 000	75	265	300	400	600	630	600	475	315	670	475	300	236	250	355	560	750	140	265	265	
	53	335	355	450	560	630	600	475	375	630	500	375	315	315	400	560	670	190	265	265	
	37,5	375	400	450	560	600	560	500	425	600	500	400	355	375	450	530	630	224	280	280	

max 1 800

max 800 max 1250

1) An axial load of up to 0,2 times the value in the table is permissible, simultaneously with the radial load. If exceeded consult us.

2) A radial load of up to 0,2 times the value in the table is permissible, simultaneously with the axial load. If exceeded consult us.

**PalaDrive**

Worm Gear Reducers and Gear Motors

SERIES W14. Radial loads F_{r2} [daN] or axial loads F_{a2} [daN] on low speed shaft endsize **09 bis³⁾, 10 bis³⁾**

$n_2 \cdot L_h$	M_2	$F_{r2}^{(1)}$												$F_{a2}^{(2)}$						
		min ⁻¹ · h	daN m	0	45	90	135	180	225	270	315	0	45	90	135	180	225	270	315	
224 000	300	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	900	1400
	212	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	900	1400
280 000	150	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	900	1400
	106	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	900	1400
355 000	150	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	900	1400
	106	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	900	1400
450 000	150	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	900	1400
	106	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	900	1400
560 000	150	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	900	1400
	106	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	900	1400
	75	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	900	1400
710 000	150	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	900	1400
	106	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	900	1400
	75	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	900	1400
	53	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	900	1400
900 000	106	1900	1900	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	900	1400
	75	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	900	1400
	53	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	900	1400
1 120 000	106	1800	1900	2000	2000	2000	2000	2000	2000	2000	2000	1900	1900	1900	1900	1900	1900	1900	900	1320
	75	1900	1900	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	900	1400
	53	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	900	1400
	37,5	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	900	1400
1 400 000	106	1700	1700	1900	2000	2000	2000	2000	2000	1800	1800	1600	1700	1800	1800	2000	2000	2000	900	1250
	75	1700	1800	1900	2000	2000	2000	2000	2000	1800	1800	1700	1700	1900	1900	2000	2000	2000	900	1320
	53	1800	1800	1900	2000	2000	2000	2000	2000	1900	1900	1800	1800	1900	1900	2000	2000	2000	900	1320
	37,5	1800	1900	2000	2000	2000	2000	2000	2000	1900	1900	1800	1800	1900	1900	2000	2000	2000	900	1320
1 800 000	106	1500	1600	1800	2000	2000	2000	1800	1600	2000	1800	1600	1500	1500	1700	2000	2000	2000	900	1180
	75	1600	1600	1800	1900	2000	2000	1800	1700	2000	1800	1700	1600	1700	1900	2000	2000	2000	900	1180
	53	1700	1700	1800	1900	2000	2000	1900	1800	1700	2000	1800	1700	1600	1700	1800	1900	2000	900	1250
	37,5	1700	1700	1800	1900	1900	2000	1800	1700	1700	1900	1800	1700	1700	1800	1900	1900	1900	900	1250
2 240 000	75	1600	1600	1800	1900	2000	1900	1800	1600	2000	1800	1600	1500	1600	1700	1900	2000	2000	900	1120
	53	1600	1700	1800	1900	1900	2000	1900	1800	1700	2000	1800	1700	1600	1700	1900	1900	1900	900	1180
	37,5	1700	1700	1800	1800	1900	1900	1900	1800	1700	1700	1800	1800	1700	1700	1800	1800	1900	900	1180
2 800 000	75	1500	1500	1600	1800	1900	1800	1700	1500	2000	1700	1500	1400	1500	1600	1800	1900	1900	900	1060
	53	1500	1600	1700	1800	1800	1700	1600	1500	2000	1700	1500	1400	1500	1600	1800	1900	1900	900	1060
	37,5	1600	1600	1700	1700	1800	1700	1700	1600	2000	1700	1500	1400	1500	1600	1700	1800	1900	900	1120
3 550 000	75	1320	1400	1500	1700	1800	1700	1600	1400	2000	1600	1400	1320	1320	1500	1700	1800	1800	850	1000
	53	1400	1400	1500	1600	1700	1700	1600	1500	2000	1600	1500	1400	1400	1500	1600	1700	1800	900	1000
	37,5	1500	1500	1500	1600	1700	1700	1600	1500	2000	1600	1500	1400	1400	1500	1600	1700	1800	900	1000

max 2 000

max 900

max 1 400

1) An axial load of up to 0,2 times the value in the table is permissible, simultaneously with the radial load. If exceeded consult us.

2) A radial load of up to 0,2 times the value in the table is permissible, simultaneously with the axial load. If exceeded consult us.

3) Values valid for taper roller bearings on low speed shaft (ch. 17).



14. Radial loads F_{r2} [daN] or axial loads F_{a2} [daN] on low speed shaft end

size 11

$n_2 \cdot L_h$	M_2	$F_{r2}^{(1)}$												$F_{a2}^{(2)}$					
		0	45	90	135	180	225	270	315	0	45	90	135	180	225	270	315		
min ⁻¹ · h	daN m																		
180 000	500	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120
	355	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120
224 000	355	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120
	250	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120
280 000	355	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120
	250	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120
355 000	355	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120
	250	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120
450 000	355	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120
	250	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120
560 000	250	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120
	180	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120
	125	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120
710 000	250	2650	2800	3000	3000	3000	3000	3000	2800	3000	3000	2800	2500	2650	3000	3000	3000	1320	2000
	180	2800	2800	3000	3000	3000	3000	3000	3000	3000	3000	3000	2800	2800	3000	3000	3000	1320	2000
	125	2800	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120
	90	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120
900 000	250	2360	2500	2800	3000	3000	3000	3000	2500	3000	3000	2500	2360	2360	2800	3000	3000	1320	1800
	180	2500	2650	2800	3000	3000	3000	3000	2650	3000	3000	2650	2500	2500	2800	3000	3000	1320	1900
	125	2650	2800	3000	3000	3000	3000	3000	2800	3000	3000	2800	2650	2650	2800	3000	3000	1320	1900
	90	2800	2800	3000	3000	3000	3000	3000	2800	3000	3000	2800	2800	2800	2800	3000	3000	1320	1900
1 120 000	180	2360	2500	2650	3000	3000	2800	2500	2500	3000	2500	2360	2360	2650	3000	3000	3000	1320	1700
	125	2500	2500	2800	3000	3000	2800	2650	2650	3000	2800	2650	2500	2500	2650	3000	3000	1320	1800
	90	2500	2650	2800	2800	3000	3000	2800	2650	3000	2800	2650	2500	2500	2650	2800	3000	1320	1800
	63	2650	2650	2800	2800	3000	3000	2800	2650	3000	2800	2650	2650	2650	2800	2800	3000	1320	1800
1 400 000	180	2240	2240	2500	2800	3000	2800	2650	2360	3000	2650	2360	2240	2240	2500	2800	3000	1320	1600
	125	2360	2360	2500	2800	2800	2800	2650	2360	3000	2650	2360	2240	2240	2500	2800	3000	1320	1700
	90	2360	2500	2500	2650	2800	2800	2650	2360	3000	2650	2360	2240	2240	2500	2800	3000	1320	1700
	63	2500	2500	2500	2650	2650	2650	2650	2360	3000	2650	2360	2240	2240	2650	2800	3000	1320	1700
1 800 000	125	2240	2360	2500	2650	2800	2800	2500	2360	3000	2650	2240	2240	2500	2650	2800	1320	1500	
	90	2360	2360	2500	2650	2800	2800	2650	2360	3000	2650	2360	2240	2240	2500	2650	2800	1320	1600
	63	2360	2500	2500	2650	2650	2650	2650	2360	3000	2650	2360	2240	2240	2650	2800	3000	1320	1600
2 240 000	125	2120	2120	2360	2500	2650	2650	2360	2240	3000	2650	2120	2120	2240	2500	2650	2650	1250	1400
	90	2120	2240	2360	2500	2650	2650	2360	2240	3000	2650	2120	2120	2240	2500	2650	2650	1250	1500
	63	2240	2240	2360	2500	2650	2650	2360	2240	3000	2650	2120	2120	2240	2500	2650	2650	1320	1500
2 800 000	125	1900	2000	2120	2240	2360	2500	2650	2240	2000	2500	1900	1900	2120	2360	2500	1180	1320	
	90	2000	2120	2240	2360	2500	2650	2240	2120	2000	2500	2000	2000	2120	2360	2500	1250	1400	
	63	2120	2120	2240	2360	2500	2650	2240	2120	2000	2500	2120	2120	2240	2360	2500	1320	1400	
3 550 000	125	1800	1800	2000	2240	2360	2240	2120	1900	1700	1800	2000	2240	2360	1060	1250			
	90	1900	1900	2000	2240	2240	2120	2000	1900	1800	1900	2000	2240	2360	1180	1250			
	63	1900	2000	2000	2120	2240	2240	2120	2000	1900	1900	2000	2120	2240	1180	1320			

max 3 000

max 1 320

max 2 120

**PalaDrive**

Worm Gear Reducers and Gear Motors

SERIES W14. Radial loads F_{r2} [daN] or axial loads F_{a2} [daN] on low speed shaft end

size 12


$n_2 \cdot L_h$ min ⁻¹ · h	M_2 daN m	$F_{r2}^{(1)}$												$F_{a2}^{(2)}$					
		0	45	90	135	180	225	270	315	0	45	90	135	180	225	270	315		
180 000	500	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120	
	355	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120	
224 000	355	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120	
	250	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120	
280 000	355	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120	
	250	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120	
355 000	355	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120	
	250	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120	
450 000	355	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120	
	250	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120	
560 000	250	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120	
	180	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120	
	125	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120	
710 000	250	2650	2800	3000	3000	3000	3000	3000	2800	3000	3000	2800	2500	2650	3000	3000	3000	1320	2000
	180	2800	2800	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	2800	3000	3000	1320	2000	
	125	2800	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120	
	90	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	3000	1320	2120	
900 000	250	2360	2500	2800	3000	3000	3000	3000	2500	3000	3000	2500	2360	2800	3000	3000	3000	1320	1800
	180	2500	2650	2800	3000	3000	3000	3000	2650	3000	3000	2650	2500	2800	3000	3000	3000	1320	1900
	125	2650	2800	3000	3000	3000	3000	3000	2800	3000	3000	2800	2650	2800	3000	3000	3000	1320	1900
	90	2800	2800	3000	3000	3000	3000	3000	2800	3000	3000	2800	2800	2800	3000	3000	3000	1320	1900
1 120 000	180	2360	2500	2650	3000	3000	3000	2800	2500	3000	2800	2360	2650	3000	3000	3000	1320	1700	
	125	2500	2500	2800	3000	3000	3000	2800	2650	3000	2800	2650	2500	2650	3000	3000	3000	1320	1800
	90	2500	2650	2800	2800	3000	3000	2800	2650	3000	2800	2650	2500	2650	2800	3000	3000	1320	1800
	63	2650	2650	2800	2800	3000	3000	2800	2650	3000	2800	2650	2650	2650	2800	2800	3000	1320	1800
1 400 000	180	2240	2240	2500	2800	3000	2800	2650	2360	3000	2800	2500	2360	2650	3000	3000	3000	1320	1600
	125	2360	2360	2500	2800	2800	2800	2800	2650	2360	2800	2650	2360	2240	2500	2800	3000	1320	1700
	90	2360	2500	2500	2650	2800	2800	2650	2500	2360	2800	2650	2360	2240	2500	2800	2800	1320	1700
	63	2500	2500	2500	2650	2650	2650	2650	2500	2360	2800	2650	2360	2240	2500	2650	2800	1320	1700
1 800 000	125	2240	2360	2500	2650	2800	2800	2500	2360	2800	2650	2360	2240	2240	2500	2650	2800	1320	1500
	90	2360	2360	2500	2650	2800	2800	2650	2500	2360	2800	2650	2360	2240	2500	2650	2800	1320	1600
	63	2360	2500	2500	2650	2650	2650	2650	2500	2360	2800	2650	2360	2240	2500	2650	2800	1320	1600
2 240 000	125	2120	2120	2360	2500	2650	2650	2360	2240	2800	2120	2000	2120	2240	2500	2650	2800	1250	1400
	90	2240	2240	2360	2500	2650	2650	2360	2240	2800	2120	2000	2120	2240	2500	2650	2800	1250	1400
	63	2240	2240	2360	2500	2650	2650	2360	2240	2800	2120	2000	2120	2240	2500	2650	2800	1250	1400
2 800 000	125	1900	2000	2120	2360	2500	2500	2240	2000	2500	2240	2000	1900	1900	2120	2360	2500	1180	1320
	90	2000	2120	2240	2360	2500	2500	2240	2000	2500	2240	2000	1900	1900	2120	2360	2500	1250	1400
	63	2120	2120	2240	2360	2500	2500	2240	2000	2500	2240	2000	1900	1900	2120	2360	2500	1250	1400
3 550 000	125	1800	1800	2000	2240	2360	2240	2120	1900	2360	2120	1900	1700	1800	2000	2240	2360	1060	1250
	90	1900	1900	2000	2240	2240	2120	2000	1900	2240	2120	1900	1800	1900	2000	2240	2360	1180	1250
	63	1900	2000	2000	2120	2240	2240	2120	2000	2240	2120	2000	1900	1900	2000	2120	2240	1180	1320

max 3 000

max 1320 max 2120

1) An axial load of up to 0,2 times the value in the table is permissible, simultaneously with the radial load. If exceeded consult us.

2) A radial load of up to 0,2 times the value in the table is permissible, simultaneously with the axial load. If exceeded consult us.



14. Radial loads F_{r2} [daN] or axial loads F_{a2} [daN] on low speed shaft end

size 13

$n_2 \cdot L_h$	M_2	$F_{r2}^{(1)}$												$F_{a2}^{(2)}$					
		0	45	90	135	180	225	270	315	0	45	90	135	180	225	270	315		
min ⁻¹ · h	daN m	0	45	90	135	180	225	270	315	0	45	90	135	180	225	270	315		
140 000	1000	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
	710	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
180 000	1000	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
	710	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
	500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
224 000	710	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
	500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
	355	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
280 000	710	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
	500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
	355	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
	250	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
	180	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
355 000	500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
	355	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
	250	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
	180	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
450 000	500	4000	4250	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
	355	4250	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
	250	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
	180	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
560 000	500	3750	4000	4500	4500	4500	4500	4500	4000	4500	4500	4500	4500	4500	4500	4500	4500	2000	3000
	355	4000	4250	4500	4500	4500	4500	4500	4250	4500	4500	4500	4500	4500	4500	4500	4500	2000	3000
	250	4250	4250	4500	4500	4500	4500	4500	4250	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
	180	4250	4250	4500	4500	4500	4500	4500	4250	4500	4500	4500	4500	4500	4500	4500	4500	2000	3150
710 000	500	3350	3550	4250	4500	4500	4500	4500	3750	4500	4500	4500	4500	4500	4500	4500	4500	2000	2650
	355	4000	3750	4250	4500	4500	4500	4500	3750	4500	4500	4500	4500	4500	4500	4500	4500	2000	2800
	250	4000	4000	4250	4500	4500	4500	4500	4000	4500	4500	4500	4500	4500	4500	4500	4500	2000	3000
	180	4000	4000	4250	4500	4500	4500	4500	4000	4500	4500	4500	4500	4500	4500	4500	4500	2000	3000
900 000	355	3350	3550	4000	4250	4500	4500	4000	3550	4500	4500	3350	3350	3750	4250	4500	4500	2000	2650
	250	3550	3750	4000	4250	4500	4500	4000	3750	4500	4500	3550	3550	3750	4250	4500	4500	2000	2650
	180	3750	3750	4000	4250	4500	4500	4000	3750	4500	4500	3550	3550	3750	4250	4500	4500	2000	2800
	125	3750	3750	4000	4250	4500	4500	4000	3750	4500	4500	3550	3550	3750	4250	4500	4500	2000	2800
1 120 000	355	3150	3350	3750	4000	4250	4500	3750	3350	4500	3000	3150	3550	4000	4500	4500	4500	2000	2500
	250	3350	3350	3750	4000	4250	4500	3750	3350	4500	3150	3350	3550	4000	4250	4500	4500	2000	2500
	180	3350	3550	3750	4000	4000	4000	3750	3550	4000	3150	3350	3550	4000	4000	4000	4000	2000	2500
	125	3550	3550	3750	4000	4000	4000	3750	3550	4000	3150	3350	3550	3550	3550	3750	4000	2000	2650
1 400 000	355	3000	3000	3350	4000	4000	4000	3550	3000	2800	2800	3350	3750	4250	4250	4250	4250	1900	2240
	250	3000	3150	3550	3750	4000	3750	3550	3150	3000	3000	3350	3750	4000	4000	4000	4000	2000	2360
	180	3150	3350	3550	3750	3750	3550	3350	3750	3550	3150	3350	3750	3750	3750	3750	3750	2000	2360
	125	3350	3350	3550	3750	3750	3550	3350	3750	3550	3150	3350	3750	3750	3750	3750	3750	2000	2360
1 800 000	355	2650	2800	3150	3550	3750	3550	3150	2800	3750	3350	2500	2650	3000	3550	4000	4000	1700	2120
	250	2800	3000	3150	3550	3550	3150	3000	3000	2800	3550	3350	3000	3150	3550	3750	3750	1900	2120
	180	3000	3000	3150	3350	3550	3350	3150	3000	3000	3000	3550	3350	3000	3150	3550	3750	2000	2240
	125	3000	3000	3150	3350	3350	3150	3150	3000	3000	3000	3150	3350	3000	3150	3350	3750	2000	2240
2 240 000	250	2650	2650	3000	3350	3350	3000	2800	3350	3000	2650	2500	2650	3000	3350	3550	3550	1800	2000
	180	2800	2800	3000	3150	3350	3150	3000	2800	3350	3000	2650	2650	3000	3150	3350	3550	1900	2000
	125	2800	2800	3000	3150	3150	3000	2800	3150	3000	2800	2800	3000	3150	3350	3550	3550	2000	2120
2 800 000	250	2360	2500	2800	3150	3350	3150	2800	2500	3150	2800	2500	2650	2650	2650	2650	2650	1600	1900
	180	2500	2650	2800	3000	3150	3000	2800	2650	3150	2800	2650	2500	2500	2800	3000	3150	1700	1900
	125	2650	2650	2800	3000	3000	3000	2800	2650	3000	2800	2650	2650	2650	2650	2650	2650	1800	1900
3 550 000	250	2240	2360	2650	3000	3000	3000	2650	2360	3000	2650	2120	2240	2360	2360	2360	2360	1500	1700
	180	2360	2360	2650	2800	3000	2800	2650	2360	3000	2650	2120	2240	2360	2360	2360	2360	1600	1800
	125	2360	2500	2650	2800	2800	2800	2650	2360	3000	2650	2120	2240	2360	2360	2360	2360	1700	1800

max 4 500

max 2 000

max 3 150

1) An axial load of up to 0,2 times the value in the table is permissible, simultaneously with the radial load. If exceeded consult us.

2) A radial load of up to 0,2 times the value in the table is permissible, simultaneously with the axial load. If exceeded consult us.



14. Radial loads F_{r2} [daN] or axial loads F_{a2} [daN] on low speed shaft end

size 14

$n_2 \cdot L_h$	M_2	$F_{r2}^{(1)}$												$F_{a2}^{(2)}$					
		min ⁻¹ · h	daN m	0	45	90	135	180	225	270	315	0	45	90	135	180	225	270	315
180 000	1900	5000	5600	6300	6300	6300	6300	6300	6000	6300	6300	5600	4500	4750	6300	6300	6300	1400	3000
	1320	6000	6300	6300	6300	6300	6300	6300	6300	6300	6300	6300	6000	6000	6300	6300	6300	2000	3000
224 000	1320	5300	6000	6300	6300	6300	6300	6300	6000	6300	6300	6000	5000	5300	6300	6300	6300	1800	2800
	950	6000	6300	6300	6300	6300	6300	6300	6300	6300	6300	6300	6000	6000	6300	6300	6300	2240	3000
280 000	1320	5000	5300	6300	6300	6300	6300	6300	5600	6300	6300	5300	4500	4750	6000	6300	6300	1600	2650
	950	5600	6000	6300	6300	6300	6300	6300	6000	6300	6300	5300	5600	6300	6300	6300	2000	2800	
	670	6000	6300	6300	6300	6300	6300	6300	6300	6300	6300	6300	6000	6000	6300	6300	6300	2320	2800
355 000	950	5000	5300	6300	6300	6300	6300	6300	5600	6300	6300	5300	4750	5000	6000	6300	6300	1800	2500
	670	5600	6300	6300	6300	6300	6300	6300	6000	6300	6300	6000	5300	6000	6300	6300	6300	2120	2650
	475	6000	6300	6300	6300	6300	6300	6300	6000	6300	6300	6000	5600	6000	6300	6300	6300	2360	2650
450 000	950	4500	4750	5600	6300	6300	6300	6300	5000	6300	6300	5000	4250	4500	5600	6300	6300	1600	2360
	670	5000	5300	6000	6300	6300	6300	6300	5300	6300	6300	5300	4750	5000	6000	6300	6300	1900	2500
	475	5300	5600	6000	6300	6300	6300	6300	5600	6300	6300	5300	5300	6000	6300	6300	2120	2500	
560 000	950	4250	4500	5300	6300	6300	6300	5600	4750	6300	6000	4500	4000	4250	5000	6300	6300	1500	2240
	670	4750	4750	5600	6300	6300	6300	5600	5000	6300	6000	5000	4500	4500	5300	6300	6300	1700	2240
	475	5000	5000	5600	6000	6300	6300	5600	5300	6300	6000	5300	4750	5000	5600	6000	6300	1900	2360
	335	5300	5300	5600	6000	6300	6300	6000	5300	6300	6000	5300	5000	5300	5600	6000	6300	2120	2360
710 000	950	3750	4000	5000	6000	6300	6300	5300	4250	6300	5300	4250	3550	3750	4750	6000	6300	1250	2000
	670	4250	4500	5000	6000	6300	6000	5300	4500	6300	5600	4500	4000	4250	5000	6000	6300	1600	2120
	475	4500	4750	5300	6000	6300	6000	5300	4750	6000	5300	4750	4500	4500	5000	6000	6300	1800	2120
	335	5000	5300	5600	6000	6300	6000	5300	5000	6000	5300	5000	4750	4750	5300	5600	6000	1900	2240
900 000	670	4000	4000	4750	5600	6000	6000	6000	4250	6000	5000	4250	3750	3750	4500	5600	6300	1400	1900
	4250	4250	4750	5300	5600	5600	5600	5000	4500	5600	5000	4500	4000	4250	4750	5300	6000	1600	2000
1 120 000	670	3550	3750	4500	5300	5600	5300	4750	4000	5600	4750	3750	3350	3550	4250	5300	6000	1250	1800
	475	4000	4000	4500	5000	5300	5300	4750	4250	5300	4750	4000	3750	4000	4250	5000	5600	1500	1900
	335	4000	4250	4500	5000	5300	5000	4750	4250	5300	4750	4000	4000	4500	5000	5300	1600	1900	
1 400 000	670	3350	3550	4000	5000	5300	5000	4250	3550	5300	4500	3550	3150	3150	4000	4750	5600	1180	1700
	475	3550	3750	4250	4750	5000	5000	4250	3750	5000	5000	4500	3750	3550	4000	4750	5300	1400	1700
	335	3750	4000	4250	4750	4750	4250	4000	4750	4750	4000	4000	3750	3750	4250	4750	5000	1500	1800
1 800 000	670	3000	3150	3750	4500	5000	4750	4000	3350	5000	4000	3150	2800	3000	3550	4500	5300	1000	1500
	475	3350	3350	4000	4500	4750	4500	4000	3550	4750	4250	3550	3150	3350	3750	4500	5000	1250	1600
	335	3550	3550	4000	4250	4500	4500	4000	3750	4500	4250	3750	3350	3550	3750	4250	4750	1400	1600
2 240 000	475	3000	3150	3550	4250	4500	4250	3750	3350	4500	4000	3150	4500	4000	4250	4750	5000	1120	1500
	335	3150	3350	3750	4000	4250	4250	3750	3350	4250	3750	3350	3150	3150	3550	4000	4500	1250	1500
max 6 300																		max 2 800	max 4 500

Values valid for solid low speed shaft (see ch. 17).

size 14 bis

180 000	1900	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	3150	5000
224 000	1320	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	3150	5000
280 000	1320	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	3150	5000
355 000	950	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	3150	5000
450 000	950	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	3150	5000
560 000	950	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	3150	4500
710 000	950	6700	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	6700	7100	7100	7100	7100	3150	4250
	670	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	3150	4500
900 000	950	6700	6700	7100	7100	7100	7100	7100	6700	7100	7100	6700	6300	6700	7100	7100	7100	3150	4000
	670	6700	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	7100	3150	4250
1 120 000	670	6000	6300	7100	7100	7100	7100	7100	6300	7100	7100	6300	6000	6000	6700	7100	7100	3000	3750
	475	6300	6700	7100	7100	7100	7100	7100	6700	7100	7100	6700	6300	6300	6700	7100	7100	3150	4000
	335	6700	7100	7100	7100	7100	7100	7100	6700	7100	7100	6700	6700	6700	7100	7100	7100	3150	4000
1 400 000	670	5600	6000	6300	7100	7100	7100	6700	6000	5300	7100	6700	5300	6000	6000	7100	7100	2800	3550
	475	6000	6000	6700	7100	7100	7100	6700	6000	5300	7100	6700	6000	6000	6300	7100	7100	3150	3550
	335	6000	6300	6700	7100	7100	7100	6700	6000	6300	7100	6700	6000	6000	6300	7100	7100	3150	3750
1 800 000	670	5000	5300	6000	6700	7100	6700	6000	5300	7100	6700	5000	5000	6000	6700	7100	7100	2650	3150
	475	5300	5600	6000	6700	6700	6700	6000	5600	7100	6700	5300	5300	6000	6700	7100	7100	3000	3350
	335	5600	6000	6300	6700	6700	6700	6000	6000	5300	7100	6700	5300	5600	6000	6700	7100		



15. Structural and operational details

Worm gear pair

Number of teeth – wormwheel z_2 and worm z_1 , axial module m_x , reference lead angle y_m , static efficiency η_s and worm gear pair moment of inertia J_1 for gear reducers and gearmotors **W 1, W 2, MW 1, MW 2, MW 3**.

In the case of **W 2, MW 2** and **MW 3** gear reducers and gearmotors, the moment of inertia on the high speed shaft (disregarding motor) is that of the worm divided by the cylindrical gear pair total ratio squared.

i		Gear reducer size										
		01	02	03	04, 05	06, 07	08	09, 10	11, 12	13	14	
7	z_2/z_1 m_x m s	21/3 2,2 0,71	21/3 2,8 0,71	21/3 3,4 0,71	28/4 3,5 0,74	28/4 4,5 0,74	—	—	—	—	—	
10	z_2/z_1 m_x m s	20/2 2,3 0,65	20/2 2,8 0,65	20/2 3,5 0,65	30/3 3,3 0,69	30/3 4,2 0,7	30/3 5,3 0,7	30/3 6,6 0,72	30/3 8,6 0,72	—	—	
13	z_2/z_1 m_x m s	26/2 1,8 0,62	26/2 2,3 0,62	26/2 2,9 0,63	26/2 3,7 0,64	26/2 4,7 0,64	26/2 5,9 0,65	39/3 5,2 0,68	39/3 6,8 0,69	39/3 8,5 0,7	—	
16	z_2/z_1 m_x m s	32/2 1,5 0,6	32/2 1,9 0,6	32/2 2,4 0,6	32/2 3,1 0,61	32/2 3,9 0,62	32/2 4,9 0,63	32/2 6,2 0,63	32/2 8 0,64	48/3 7,1 0,68	48/3 9 0,69	
20	z_2/z_1 m_x m s	20/1 2,3 0,5	20/1 2,8 0,5	20/1 3,5 0,5	40/2 2,5 0,6	40/2 3,2 0,6	40/2 4,1 0,61	40/2 5,1 0,61	40/2 6,6 0,62	40/2 8,3 0,63	40/2 10,4 0,63	
25	z_2/z_1 m_x m s	25/1 1,9 0,48	25/1 2,4 0,48	25/1 3 0,48	25/1 3,8 0,5	25/1 4,8 0,5	25/1 6,1 0,51	50/2 4,2 0,59	50/2 5,4 0,59	50/2 6,8 0,61	50/2 8,6 0,62	
32	z_2/z_1 m_x m s	32/1 1,5 0,45	32/1 1,9 0,45	32/1 2,4 0,45	32/1 3,1 0,46	32/1 3,9 0,47	32/1 6° 38' 0,48	32/1 6° 55' 0,49	32/1 7° 5' 0,49	32/1 8 0,51	32/1 10,1 0,51	64/2 6,8 0,59
40	z_2/z_1 m_x m s	40/1 1,3 0,42	40/1 1,6 0,42	40/1 2 0,42	40/1 2,5 0,44	40/1 3,2 0,45	40/1 4,1 0,46	40/1 5,1 0,46	40/1 6,6 0,47	40/1 8,3 0,48	40/1 10,4 0,49	
50	z_2/z_1 m_x m s	50/1 1 0,38	50/1 1,3 0,38	50/1 1,6 0,38	50/1 2,1 0,41	50/1 2,7 0,42	50/1 3,3 0,43	50/1 4,2 0,44	50/1 5,4 0,45	50/1 6,8 0,46	50/1 8,6 0,47	
63	z_2/z_1 m_x m s	—	63/1 1 0,34	63/1 1,3 0,35	63/1 1,7 0,38	63/1 2,1 0,38	63/1 3,4 0,39	63/1 4,4 0,4	63/1 5,5 0,41	63/1 6,9 0,42	63/1 7 0,44	
Momento di inerzia (di massa) J_1 [kg m ²] sulla vite ≈ Moment of inertia (of mass) J_1 [kg m ²] on the worm ≈		—	—	—	—	—	0,0014	0,0037	0,0078	0,0192	0,0376	


Low speed shaft angular backlash

A rough guide for low speed shaft angular backlash is given in the table (the worm being held stationary). Values vary according to design and temperature.

Gear reducers with **controlled** or **reduced backlash** can be supplied on request (see ch. 17), subject to longer delivery times and price addition; choose a **higher** service factor.

Gear reducer size	Angular backlash [rad] ¹⁾	
	min	max
01	0,0030	0,0118
02	0,0025	0,0100
03	0,0020	0,0080
04, 05	0,0018	0,0071
06, 07	0,0016	0,0063
08	0,0013	0,0050
09, 10	0,0011	0,0045
11, 12	0,0010	0,0040
13	0,0008	0,0032
14	0,0007	0,0028

1) At a distance of 1 m from the low speed shaft centre, angular backlash in mm is obtained multiplying the table value by 1 000 (1 rad = 3438').



Efficiency η

Efficiency η is derived from the P_{N2} / P_{N1} ratio in the case of gear reducers (ch. 7) and P_2 / P_1 in the case of gearmotors (ch. 9). The values obtained will be valid assuming normal working conditions, worm operating as driving member, proper lubrication, adequate running-in (ch. 16), and a load near to the nominal value.

During the **initial working period** (about 50 hours) and generally at every cold start, efficiency will be lower (by about 12% for worms with $z_1 = 1$; 6% for worms with $z_1 = 2$ and 3% for worms with $z_1 = 3$).

«Static» efficiency η_s on starting (see table in the preceding section) is much lower than η («starting friction») must be overcome at speed 0); as speed picks up gradually, efficiency will rise correspondingly until the catalogue value is reached.

Inverse efficiency η_{inv} – produced by the wormwheel as driver – is always less than η . It can be calculated approximately as follows:

$$\eta_{inv} \approx 2 - 1 / \eta; \quad \text{likewise: } \eta_{s\,inv} \approx 2 - 1 / \eta_s$$

Irreversibility

A worm gear reducer or gearmotor is **dynamically irreversible** (that is, it ceases to turn the instant the wormshaft receives no further stimulus that would keep the worm itself in rotation e.g. motor torque, inertia from the worm and related fan, motor flywheels, couplings, etc.) when $\eta < 0,5$ as η_{inv} then drops below 0.

This state becomes necessary wherever there is a **need for stopping and holding** the load, even without the aid of a brake. Where continuous vibration occurs, dynamic irreversibility may not be obtainable.

A gear reducer or gearmotor is **statically irreversible** (that is, rotation cannot be imparted by way of the low speed shaft) when $\eta_s < 0,5$.

This is a state **necessary to keep the load at standstill**; taking into account, however, that efficiency can increase with time spent in operation, it would be advisable to assume $\eta_s \leq 0,4$ ($\gamma_m < 5^\circ$).

Where continuous vibration occurs, static irreversibility may not be obtainable.

A gear reducer or gearmotor has **low static reversibility** (i.e. rotation may be imparted by way of the low speed shaft with high torque and/or vibration) when $0,5 < \eta_s \leq 0,6$ ($7^\circ 30' < \gamma_m \leq 12^\circ$).

A gear reducer or gearmotor has **complete static reversibility** (i.e. rotation may be imparted by way of the low speed shaft) when $\eta_s > 0,6$ ($\gamma_m > 12^\circ$).

This state is advisable where there is a **need for easy start-up of the gear reducer by way of the low speed shaft**.

Overloads

Since worm gear pairs are often subject to high static and dynamic overloads by dint of the fact that they are especially suited to bear them, the need arises – more so than with other gear pairs – for verifying that such overloads will always remain lower than $M_{2\,max}$ (ch. 7).

Overloads are normally generated when one has:

- starting on full load (especially for high inertias and low transmission ratios), braking, shocks;
- irreversible gear reducers, or gear reducers with low reversibility in which the wormwheel becomes driver due to driven machine inertia;
- applied power higher than that required; other static or dynamic causes.

The following general observations on overloads are accompanied by some formulae for carrying out evaluations in certain typical instances.

Where no evaluation is possible, install safety devices which will keep values within $2 \cdot M_{N2}$.

Starting torque

When starting on full load (especially for high inertias and low transmission ratios) verify that $M_{2\,max}$ is equal to or greater than starting torque, by using the following formula:

$$M_{2\,\text{start}} = \frac{M_{\text{start}}}{M_N} \cdot M_2 \text{ available} - M_2 \text{ required} \cdot \frac{J}{J + J_0 \cdot \eta} + M_2 \text{ required}$$

where:

M_2 required is torque absorbed by the machine through work and friction;
 M_2 available is output torque derived from the motor's nominal power rating;
 J_0 is the moment of inertia (of mass) of the motor;
 J is the external moment of inertia (of mass) in kg m² (gear reducers, couplings, driven machine) referred to the motor shaft;
for other symbols see ch. 2b.

NOTE: When seeking to verify that starting torque is sufficiently high for starting, take into account efficiency η_s when evaluating M_2 available, and starting friction, if any, in evaluating M_2 required.

Stopping machines with high kinetic energy (high moments of inertia combined with high speeds) with or without braking (braking applied to wormshaft, or use of brake motor)

Select a gear reducer with static reversibility ($\eta_s > 0,5$); if using a brake motor, verify braking stress with the following formula:

$$\left(\frac{M_f}{\eta_{s\,inv}} \cdot i + M_2 \text{ required} \right) \frac{J}{J + J_0 / \eta_{s\,inv}} - M_2 \text{ required} \leq M_{2\,max}$$

where:

M_f is the braking torque setting (see table in ch. 2b).
 $\eta_{s\,inv}$ is static inverse efficiency (see previous heading);
for other symbols see above and ch.1.

Where selection of a statically reversible gear reducer is not possible (i.e. $\eta_s \leq 0,5$) slowing-down should be sufficiently gradual (avoiding application of excessive stress to the unit itself) as to ensure that:

$$\frac{J_2 \cdot \alpha_2}{10} - M_2 \leq M_{2\,max}$$

where:
 J_2 [kg m²] is the moment of inertia (of mass) of the driven machine referred to the gear reducer's low speed shaft;

M_2 [daN m] is torque absorbed by the machine through work and friction;
 α_2 [rad/s²] is the low speed shaft's angular deceleration; this may be reduced by fly-wheel fitted to the wormshaft, electric deceleration ramps, lowering of braking torque when braking systems are in use, etc.

, may be arrived at theoretically (within broadly safe limits) or experimentally (by testing against stopping time and distance etc.).
If a brake motor is in use, the following formula may be used for a safe evaluation of α_2 :

$$\alpha_2 = \frac{10 \cdot M_f}{J_0 \cdot i}$$

in which the motor is presumed without load and subject to its braking torque setting M_f [daN m] (see table in ch. 2b).

Operation with brake motor

Stating time t_a and revolutions of motor a_1

$$t_a = \frac{(J_0 + J/\eta) \cdot n_1}{95,5 \cdot M_{\text{start}} - \frac{M_2 \text{ required}}{i \cdot \eta}} \quad [\text{s}]; \quad \varphi a_1 = \frac{t_a \cdot n_1 \text{ rad}}{19,1}$$

Braking time t_f and revolutions of motor f_1

$$t_f = \frac{(J_0 + J/\eta_{inv}) \cdot n_1}{95,5 \left(\frac{M_f}{M_{\text{start}}} + \frac{M_2 \text{ required} \cdot \eta_{inv}}{i} \right)} \quad [\text{s}]; \quad \varphi f_1 = \frac{t_f \cdot n_1 \text{ rad}}{19,1}$$

where:

M_{start} [daN m] is motor starting torque $\frac{955 \cdot P_1}{n_1} \cdot \frac{M_{\text{start}}}{M_N}$ (see ch. 2b);
 M_f [daN m] is the braking torque setting of the motor (see ch. 2b);
for other symbols see above and ch. 1.

With the gear reducer run in and operating at normal running temperature – assuming a regular air-gap and ambient humidity and utilizing suitable electrical equipment – repetition of the braking action, as affected by variation in temperature of the brake and by the state of wear of friction surface, is approx $\pm 0,1 \cdot \varphi f_1$.
During warm-up (1 ÷ 3 h, small through to large sizes), braking times and distances tend to increase to the point of stabilizing at or around values corresponding to rated catalogue efficiency.

Duration of friction surface

As a rough guide, the number of applications permissible between successive adjustments of the air-gap is given by the following formula:

$$\frac{W \cdot 10^5}{M_f \cdot \varphi f_1}$$

where:
 W [MJ] is the work of friction between successive adjustments of the air-gap as indicated in the table. For other symbols see above.


The air-gap should measure between 0,25 minimum and 0,7 maximum; as a rough guide, 5 adjustments can be made.

Motor size	W MJ
63	10,6
71	14
80	18
90	24
100	24
112	45
132	67
160, 180M	90
180L, 200	125



Gear reducers input face

The **W 1** gear reducer input face has a machined surface with tapped holes for fitting motor mounting etc.



Gear reducer size	a	A	B	F	K Ø H8	L	M	T Ø	U
				1)	2)				
01	16	72	54	M 5	5	—	—	103	66
02, 03	20	81,5	66,5	M 5	5	—	—	119	80
04 ... 07	25	106	80	M 6	6	—	—	149	96
08	31,3	125	108	M 8	8	—	—	187	129
09, 10	40	166	136	M 8	8	78	216	252	157
11 ... 13	50	214	168	M 10	10	98	268	312	194
14	62,5	274	210	M 12	12	128	332	387	241


1) Lunghezza utile del filetto 2 · F.

2) Lunghezza utile del foro 1,6 · K.

1) Working length of thread 2 · F.

2) Working length of hole 1,6 · K.

The **W 2** gear reducer input face has a machined flange with holes for fitting motor mountings etc.




Gear reducer size	F	K Ø	M ₁ Ø	N ₁ Ø	P ₁ Ø H7	V ₁	Q ₁	S
	1)							
01	—	9,5	115	95	140	105	4	10
02, 03	M 8	9,5	115	95	140	105	4	11
04 ... 07	M 8	9,5	130	110	160	120	4,5	12
08	M 10	11,5	165	130	200	—	4,5	14
09, 10	M 10	—	165	130	200	—	4,5	16
11 ... 13	M 12	—	215	180	250	—	5	18
14	M 12	—	265	230	300	—	5	20

1) Lunghezza utile del filetto 1,25 · F.

1) Working length of thread 1,25 · F.


Fixing bolt dimensions for gear reducer feet




1) When tightening bolts at the fan side (sizes 08 ... 14) the fan cowl (which must enclose the fan assembly in order to enhance air-flow) needs to be removed for the purpose. When installing, ensure the cowl clears any surrounding walls by at least half the gear reducer's centre distance.

Gear reducer size	Bolt UNI 5737-88 (l max)
01	M 6 x 25
02	M 8 x 35
03	M 8 x 40
04, 05	M 10 x 50
06, 07	M 12 x 60
08	M 14 x 55
09, 10	M 16 x 65
11, 12	M 20 x 80
13	M 24 x 90
14	M 30 x 120


Plug position



Mounting position B7



Mounting position B6 1)






UTC 722

W 1, W 2, W 3(08 ... 14)

W 2 (08 ... 14)

W 3 (02 ... 10)


(08 ... 10)



1) For continuous duty and high input speed an expansion tank is envisaged: consult us.



Shaft end




Estremità d'albero - Shaft end

D ¹⁾ Ø	E ²⁾ Ø	d	Linguetta Parallel key			Cava Keyway		
			b	h	l ³⁾	b	t	t ₁
11	j 6	23 (20)	M 5	4 x 4 x 18 (12)		4	2,5	12,7
14	j 6	30 (25)	M 6	5 x 5 x 25 (16)		5	3	16,2
16	j 6	30	M 6	5 x 5 x 25		5	3	18,2
19	j 6	40 (30)	M 6	6 x 6 x 36 (25)		6	3,5	21,7
24	j 6	50 (36)	M 8	8 x 7 x 45 (25)		8	4	27,2
28	j 6	60 (42)	M 8	8 x 7 x 45 (36)		8	4	31,2
32	k 6	80 (58)	M 10	10 x 8 x 70 (50)		10	5	35,3
38	k 6	80 (58)	M 10	10 x 8 x 70 (50)		10	5	41,3
40	h 7	58	M 10	12 x 8 x 50		12	5	43,3
48	k 6	110 (82)	M 12	14 x 9 x 90 (70)		14	5,5	51,8
55	m 6	110 (82)	M 12	16 x 10 x 90 (70)		16	6	59,3
60	m 6	105	M 16	18 x 11 x 90		18	7	64,4
70	j 6	105	M 16	20 x 12 x 90		20	7,5	74,9
75	j 6	105	M 16	20 x 12 x 90		20	7,5	79,9
90	j 6	130	M 20	25 x 14 x 110		25	9	95,4
110	j 6	165	M 24	28 x 16 x 140		28	10	116,4

1) Tolerance valid only for high speed shaft end. Diameter D tolerance for low speed shaft end (ch. 17) is **h7** for D ≤ 60, **j6** for D ≥ 70.

2) Values in brackets are for short shaft end.



UTC 723

Hollow low speed shaft

Foro Hole Ø H7	Linguetta Parallel key	Cava Keyway					
		b	h	l*	b	t	t ₁
19	6 x 6 x 36	6	3,5	21,7			
24	8 x 7 x 45	8	4	27,2			
28	8 x 7 x 63	8	4	31,2			
32	10 x 8 x 70	10	5	35,3			
38	10 x 8 x 90	10	5	41,3			
40	12 x 8 x 90	12	5,5 ¹⁾	43,3			
48	14 x 9 x 110	14	5,5	51,8			
60	18 x 11 x 140	18	7	64,4			
70	20 x 12 x 180	20	7,5	74,9			
75	20 x 12 x 180	20	7,5	79,9			
90	25 x 14 x 200	25	9	95,4			
110	28 x 16 x 250	28	10	116,4			

* Recommended length.

Shaft end of driven machine

Dimensions of shaft end to which the gear reducer's hollow shaft is to be keyed are those recommended in the table on following page and shown in the figures below.


Sizes 01 ... 03: fitting with key (fig. a) or fitting with key and locking rings (fig. b).

Sizes 04 ... 14 : fitting with key (fig. c) or fitting with key and locking bush (fig. d); see also ch.16 and 17.


In the case of cylindrical shaft end with only diameter D (fig. a, c), for the seat D on input side, we recommend tolerance h6 or j6 instead of j6 or k6 to facilitate mounting.

Important: the shoulder diameter of the shaft end of the driven machine abutting with the gear reducer must be at least $(1,18 \div 1,25) \cdot D$.

01 ... 03



04 ... 14



Gear reducer size	D Ø H7/j6, k6	D ₃ Ø H7/h6	E	E ₀	E ₁	E ₂	E ₃	I	m	m ₀	n	r
01	19	15	62,5	67	0	59	8	36	21	19,5	—	1,5
02	24	19	76,5	81	13	54	14	45	23,5	18,5	—	1,5
03	28	24	87	91,5	16,5	61	14	63	21,5	11	—	1,5
04, 05	32	27	110	—	57	34	10	70	28	—	6	1,5
06	38	32	134	—	71	39,5	12	90	30	—	6	1,5
07	40	34	134	—	71	39,5	12	90	30	—	6	1,5
08	48	41	162	—	87	46,5	14	110	35	—	7	2
09, 10	60	52	193	—	102	55	16	140	32	—	7	2
11	70	62	228	—	124	63	16	180	35	—	8	2
12	75	66	228	—	124	63	18	180	35	—	8	2
13	90	80	274	—	150	75	21	200	50	—	9	3
14	110	98	331	—	180	90	25	250	55	—	10	3



16. Installation and maintenance

General

Be sure that the structure on which gear reducer or gearmotor is fitted is plane, levelled and sufficiently dimensioned in order to assure fitting stability and vibration absence, keeping in mind all transmitted forces due to the masses, to the torque, to the radial and axial loads.

Position the gear reducer or gearmotor so as to allow a free passage of air for cooling both gear reducer and motor (especially at gear reducer and motor fan sides).

Avoid: any obstruction to the air-flow; heat sources near the gear reducer that might affect the temperature of cooling-air and of gear reducer for radiation; insufficient air recycle or any other factor hindering the steady dissipation of heat.

Mount the gear reducer so as not to receive vibrations.

When external loads are present use pins or locking blocks, if necessary.

When fitting gear reducer and machine and/or gear reducer and eventual flange **B5** it is recommended to use **locking adhesives** such as LOCTITE on the fastening screws (also on flange mating surfaces).

For outdoor installation or in a hostile environment protect the gear reducer or gearmotor with anticorrosion paint. Added protection may be afforded by water-repellent grease (especially around the rotary seating of seal rings and the accessible zones of shaft end).

Gear reducers and gearmotors should be protected wherever possible, and by whatever appropriate means, from solar radiation and extremes of weather; weather protection **becomes essential** when high or low speed shafts are vertically disposed, or where the motor is installed vertical with fan uppermost.

For ambient temperatures greater than 40 °C or less than 0 °C, consult us.

Before wiring-up the gearmotor, make sure that motor voltage corresponds to input voltage. If the direction of rotation is not as desired, invert two phases at the terminals.

Star-delta starting should be adopted for starting on no load (or with a very small load) and/or when the necessity is for smooth starts, low starting current and limited stresses.

If overloads are imposed for long periods of time, or if shocks or danger of jamming are envisaged, then motor-protections, electronic torque limiters, fluid couplings, safety couplings, control units or other suitable devices should be fitted.

Where duty cycles involve a high number of starts on-load, it is advisable to utilize **thermal probes** (fitted on the wiring) for motor protection; a thermal overload relay is unsuitable since its threshold must be set higher than the motor's nominal current rating.

Use varistors to limit voltage peaks due to contactors.

Caution! Bearing life, good shaft and coupling running depend on alignment precision between the shafts. Carefully align the gear reducer with the motor and the driven machine (with the aid of shims if need be), interposing flexible couplings whenever possible.

Whenever a leakage of lubricant could cause heavy damages, increase the frequency of inspections and/or envisage appropriate control devices (e.g.: remote oil level gauge, lubricant for food industry, etc.).

In polluting surroundings, take suitable precautions against lubricant contamination through seal rings or other.

Gear reducer or gearmotor should not be put into service before it has been incorporated on a machine which is conform to 98/37/EC directive.

For brake or special motors, consult us for specific information.

Fitting of components to shaft ends

It is recommended that the bore of parts keyed to shaft ends is machined to H7 tolerance; G7 is permissible for high speed shaft ends $D \geq 55$ mm, provided that load is uniform and light; for low speed shaft ends, tolerance must be K7 when load is not uniform and light. Other details are given in the «Shaft end» table (ch. 15).

Before mounting, clean mating surfaces thoroughly and lubricate against seizure and fretting corrosion.

Installing and removal operations should be carried out with **pullers** and **jacking screws** using the tapped hole at the shaft butt-end; for H7/m6 and K7/j6 fits it is advisable that the part to be keyed is pre-heated to a temperature of 80 \div 100 °C.

Hollow low speed shaft

For the shaft end of machines where the hollow shaft of the gear reducer is to be keyed, j6 or k6 tolerances are recommended (according to requirements). Other details are given under «Shaft end» and «Shaft end of driven machine» (ch. 15).


In order to have an easier installing and removing of gear reducer sizes 04 ... 14 (with circlip groove) proceed as per the drawings a, b, respectively.

The system illustrated in the fig. c, d is good for axial fastening. For sizes 04 ... 14, when shaft end of driven machine has no shoulder a spacer may be located between the circlip and the shaft end itself (as in the lower half of the fig. d).

The use of **locking rings** (sizes 01 ... 03, fig. e), or of **locking bush** (sizes 04 ... 14 , fig. f) will permit easier and more accurate installing and removing and to eliminate backlash between key and keyway.

The locking rings or the locking bush are fitted after mounting, the shaft end of the driven machine must be as prescribed at ch. 15. Do not use molybdenum bisulphide or equivalent lubricant for the lubrication of the parts in contact. We recommend the use of a **locking adhesive** such as LOCTITE 601. For vertical ceiling-type mounting, contact us.

A **washer** for installing, removing (excluding sizes 01 ... 03) and axial fastening of gear reducer (ch. 17) with or without **locking rings** or **locking bush** (dimensions shown in the table) and a **protection cap** for the hollow low speed shaft can be supplied on request. Parts in contact with the circlip must have sharp edges.



Gear reducer size	A	D Ø	D ₁ Ø	D ₃ Ø	E ₃ ≈	F	F ₁	h	h ₁	L	n	Bolt for axial fastening	UNI 5737-88	M [daN m] ³⁾
01	—	19	22,5	15	—	—	—	14,8	2,8	6,3	1,1	M 8 x 25 ¹⁾		2,9
02	—	24	27,5	19	—	—	—	14,8	2,8	12,6	1,2	M 8 x 25 ¹⁾		3,2
03	—	28	32	24	—	—	—	18,5	3,2	12,6	1,2	M 10 x 30 ¹⁾		4,3
04, 05	18	32	23	27	9	M 10	M 6	10	—	19	6	M 10 x 35		4,3
06	18	38	27	32	11	M 10	M 6	12	—	23	6	M 10 x 35		5,3
07	18	40	28	34	11	M 10	M 6	12	—	23	6	M 10 x 35		5,3
08	23	48	35	41	13	M 12	M 8	14	—	28	7	M 12 x 45		9,2
09, 10	30	60	45	52	15	M 14	M 10	16	—	35	7	M 14 x 45		17
11	36	70	54	62	15	M 16	M 12	19	—	40	8	M 16 x 50		21
12	36	75	59	66	17	M 16	M 12	19	—	40	8	M 16 x 50 ³⁾		21
13	49	90	72	80	20	M 20	M 16	23	—	49	9	M 20 x 60 ²⁾		43
14	64	110	89	98	24	M 24	M 16	24	—	60	10	M 24 x 70 ²⁾		83

1) UNI 5931-84.

2) For locking bush: M 20 x 65 and M 24 x 80 UNI 5737-88 class 10.9.

3) Tightening torque for locking rings or bush.

Lubrication


Gear pairs and bearings on worm are oil-bath lubricated; sizes 13 and 14 mounting position B7 with worm speed $> 710 \text{ min}^{-1}$ have upper bearings on worm lubricated by a pump inside the casing. Other bearings are likewise lubricated by oil-bath, or splashed, with the exception of upper-bearings on wormwheel in mounting position V5 and V6, where life-grease lubrication is employed (NILOS ring in sizes 12 ... 14).

All sizes are envisaged with **synthetic oil** lubrication.

Synthetic oil can withstand temperature up to **95 ÷ 110 °C**.

Sizes 01 ... 07: gear reducers are supplied **filled with synthetic oil** (AGIP Blasia S 320, KLÜBER Klübersynth GH 6-320, MOBIL Glygoyle HE 320, SHELL Tivela WB/SD; when worm speed $\leq 280 \text{ min}^{-1}$ KLÜBER Klübersynth GH 6-680), providing «**long life**» lubrication, assuming pollution-free surroundings; quantities as indicated in ch. 8 and 10, and on the lubrication plate. Ambient temperature $0 \div 40^\circ \text{C}$ with peaks of -20°C and $+50^\circ \text{C}$.

Sizes 08 ... 14 : gear reducers are supplied **without oil**; before putting into service, fill to the specified level with **synthetic oil** (AGIP Blasia S, ARAL Degol GS, BP-Energol SG-XP, MOBIL Glygoyle HE, SHELL Tivela Oil, KLÜBER Klübersynth GH ...) having the ISO viscosity-grade given in the table. Under normal conditions, the first speed range is for train of gears **W1**, the second **W2** and **W1**, (low speed), and the third **combined units** and **W1, W2, W3** (low speed). Once the running-in period has been completed (see below) an oil change accompanied by a thorough clean-out is advisable for worm speed $> 180 \text{ min}^{-1}$.



ISO viscosity grade

Mean kinematic viscosity [cSt] at 40 °C.

Worm speed min ⁻¹	Ambient temperature 0 ÷ 40 °C ²⁾ – Synthetic oil				
	08		09 ... 12		13, 14
	B3 ³⁾ , V5, V6	B6, B7, B8	B3 ³⁾ , V5, V6	B6, B7, B8	
2 800 ÷ 1 400 ³⁾	320	320	220		220
1 400 ÷ 710 ³⁾	320	320			220
710 ÷ 355 ³⁾	460	460			320
355 ÷ 180 ³⁾ < 180	680	680	460		460
	680	680			680

1) Not stated in name plate.

2) Peaks of 10 °C above and 10 °C (20 °C for ≤ 460 cSt) below the ambient temperature range are acceptable.

3) For these speeds we advise to replace oil after running-in.

Combined gear reducer and gearmotor units: lubrication remains independent, thus data relative to each single gear reducer hold good.

An overall guide to **oil-change interval**, is given in the table, and assumes pollution-free surroundings. Where heavy overloads are present, halve the value.

Oil temperature [°C]	Oil-change interval [h] - Synthetic oil
≤ 65	18 000
65 ÷ 80	12 500
80 ÷ 95	9 000
95 ÷ 110	6 300

Never mix different makes of synthetic oil; if oil-change involves switching to a type different from that used hitherto, then give the gear reducer a thorough clean-out.


Motor replacement

As all gearmotors are fitted with **standard** motors, motor replacement in case of breakdown is extremely easy. Simply observe the following instructions:

- be sure than the mating surfaces are machined under accuracy rating (UNEL 13501-69; DIN 42955);
- clean surfaces to be fitted, thoroughly;
- check and, if necessary, lower the parallel key so as to leave a clearance of 0,1 ÷ 0,2 mm between its tip and the bottom of the keyway; if shaft keyway is without end, lock the key with a pin;

for MW 1:

- check that the fit-tolerance (push-fit) between holes hole-shaft end is G7/j6 for D ≤ 28 mm, F7/k6 for D ≥ 38 mm;
- lubricate surfaces to be fitted against fretting corrosion;




Shaft-mounting arrangements

The strength and shape of the casing offer: **advantageous** possibilities for shaft mounting even – for instance – in the case of gearmotor with belt drive.

A few shaft mounting arrangements are shown here with the relative details as to selection, and installation.

In ch. 17 are shown the shaft-mounting arrangements which **can be supplied**.



Running-in: a period of about 400 ÷ 1 600 h is advisable, by which time the gear pair will have reached maximum efficiency (ch. 15); oil temperature during this period is likely to reach higher levels than would normally be the case.

Seal rings: duration depends on several factors such as dragging speed, temperature, ambient conditions, etc.; as a rough guide; it can vary from 3 150 to 25 000 h.



Warning: for gear reducers sizes 08 ... 14 , before unscrewing the filler plug with valve (symbol) wait until the unit has cooled and then open with caution.

for MW 2, MW 3:



- check that the fit-tolerance (standard locking) between holes and shaft end is K6/j6 for D ≤ 28 mm, and J6/k6 for D ≥ 38 mm; key length should be at least 0,9 pinion width;
- ensure that motor bearings and overhangs (dimension S) are as shown in the table;
- mount the spacer (with rubber cement check that between keyway and motor shaft shoulder there is a grounded cylindrical part of at least 1,5 mm) and the pinion (the latter to be preheated to a temperature of 80 ÷ 100 °C) on the motor, locking the assembly with either a bolt to the shaft butt-end, or a stop collar;
- lubricate the pinion tooth, and the seal ring and its rotary seating with grease, assembling with extreme care.

Motor size	Min. dynamic load capacity [daN]		Max dimension 'S' mm
	Front	Rear	
63	450	335	16
71	630	475	18
80	900	670	20
90	1 320	1 000	22,5
100	2 000	1 500	25
112	2 500	1 900	28
132	3 550	2 650	33,5
160	4 750	3 350	37,5
180	6 300	4 500	40
200	8 000	5 600	45
225	10 000	7 100	47,5



IMPORTANT. When shaft mounted, the gearmotor must be supported both axially and radially by the shaft end of the driven machine, as well as anchored against rotation only, by means of a reaction having **freedom of axial movement** and sufficient **clearance in its couplings** to permit minor oscillations – always in evidence – without provoking dangerous overloads on the actual gearmotor. Pivots and components subject to sliding have to be properly lubricated; we recommend the use of a locking adhesive such as LOCTITE 601 when fitting the bolts.





For sizes 01 ... 10 can be supplied (ch. 17) a semi-flexible and economical reaction arrangement, with bolt using disc springs.



Semi-flexible reaction arrangement for sizes 04 ... 14 (ch. 17) using disc springs and bracket







Rigid reaction arrangement for variable-distance anchorage for sizes 04 ... 14 (ch. 17) using a torque arm.
Where direction of rotation is opposite to the one shown in the drawing, turn the torque arm through 180°.



Similar to the previous arrangement for sizes 08 ... 14 (ch. 17), but using a flexible torque arm; safety devices may be installed to prevent accidental overloads. The flexible torque arm may be turned through 180° regardless of direction of rotation.

UTC 748

For the majority of normal cases, where weight force G is orthogonal or parallel to reaction R_R as illustrated in the drawings, reactions are calculated thus:



- G [daN]: weight force almost equal numerically to gearmotor mass (ch. 10);
- M_2 [daN m]: output torque expressed by + or - according to the direction of rotation in the drawing;
- x [m]: dimension to $x = G + 0,2 \cdot Y$ (ch. 10);
- y [m]: dimension $y = 0,5 \cdot B +$ (ch. 10);
- x_R [m]: dimension $x_R = 0,5 \cdot A$ (drawing on the left) or $x_R = H + S$ (drawing on the right) (ch. 10 and 17);
- l, s [m]: dimension s must be the shortest possible;

1) reaction R_R produced by support R:

$$R_R = (1 / x_R) \cdot [G \cdot x + (\pm M_2)] \quad [\text{daN}]$$

2) bending moment M_{fA} through the cross-section of bearing A:


$$B \quad M_{fA} = \sqrt{[G \cdot (y + s)]^2 + [R_R \cdot s]^2} \quad [\text{daN m}]$$

3) radial reaction R_A produced by bearing A:

$$B \quad R_A = \frac{1}{l} \sqrt{[G \cdot (y + s + l)]^2 + [R_R \cdot (s + l)]^2} \quad [\text{daN}]$$

4) radial reaction R_B produced by bearing B:


$$R_B = \frac{M_{fA}}{l} \quad [\text{daN}]$$



17. Accessories and non-standard designs


Low speed shafts

Supplementary description when ordering by designation: standard or double extension low speed shaft.



Gear reducer size	D Ø	E	D ₁ Ø	h	L ₁	L ₂	I	2	Z	Vite Bolt	Mass [kg]	
											UNI 5737-88	Standard
01	19 h7	30	28	4	108	138	36	78	M 6	20	0,3	0,4
02	24 h7	36	35	5	128	164	45	92	M 8	25	0,6	0,7
03	28 h7	42	35	5	148	190	63	106	M 8	25	0,8	1
04, 05	32 h7	58	47	5	184	242	70	126	M 10	30	1,2	1,5
06	38 h7	58	47	5	208	266	90	150	M 10	30	1,9	2,4
07	40 h7	58	47	5	208	266	90	150	M 10	30	2,1	2,7
08	48 h7	82	57	6	262	344	110	180	M 12	40	3,7	4,9
09, 10	60 h7	105	82	8	317	422	140	212	M 16	45	7	9,4
11	70 j6	105	82	8	355	460	180	250	M 16	45	11	14
12	75 j6	105	82	8	355	460	180	250	M 16	45	12,6	16
13	90 j6	130	102	10	430	560	200	300	M 20	60	21	28
14	110 j6	165	135	12	525	690	250	360	M 24	60	39	51

The shoulder outer diameter of the part, or of spacer abutting with the gear reducer must be $(1,25 \dots 1,4) \cdot D$.



Solid low speed shaft (size 14)


In order to permit the high radial loads given in the catalogue (14th bis), the gear reducer size 14 can be supplied with solid low speed shaft and strengthened bearings. Dimensions remain unchanged (missing the washer on shaft end).

Supplementary description when ordering by designation: solid low speed shaft pos. 1 or 2 or double extension.

Oversized hollow low speed shaft

The gear reducers and gearmotors sizes 01 ... 05 and 100 can be supplied with oversized hollow low speed shaft; dimensions are according to table on the left.

Gear reducer size	D Ø H7	Linguetta Parallel key b x h x l*	b	Cava Keyway t	t ₁
01	20	6 6 36	6	4 ¹⁾	22,2 ¹⁾
02	25	8 7 45	8	4,5 ¹⁾	27,7 ¹⁾
03	30	8 7 63	8	5 ¹⁾	32,2 ¹⁾
04 ²⁾ , 05 ²⁾	35	10 8 90	10	6 ¹⁾	37,3 ¹⁾
08	50	14 9 110	14	5,5 ¹⁾	53,8




Supplementary description when ordering by designation: oversized hollow low speed shaft.

Flange

All gear reducers and gearmotors can be supplied with B5 flange having clearance holes and spigot «recess».

Locking adhesives such as LOCTITE are recommended both around threads and on mating surfaces.

Supplementary description when ordering by designation: flange B5.



Gear reducer size	F Ø	G Ø	H ₁	H ₂ Ø	M Ø	N Ø	P	Q	S	V	Z	Mass kg
01	7	55	34,5	71	100	80	120	4	10	95	39	0,5
02	9,5	68	41,5	80	115	95	140	4	11	110	46	0,8
03	9,5	85	49	80	130	110	160	4,5	12	125	53	1
04, 05	11,5	80	58,5	100	165	130	200	4,5	14	152	63	2
06, 07	14	110	69,5	112	215	180	250	5	16	196	75	3,2
08	14	130	84,5	132	265	230	300	5	18	248	90	5,5
09, 10	18	180	99,5	150	300	250	350	6	20	290	106	8,5
11, 12	18	230	118,5	180	350	300	400	6	22	350	125	13
13	18 ⁸⁾	250	137,5	200	400	350	450	6	22	—	150	20
14	22 ⁸⁾	350	163	236	500	450	550	6	25	—	180	31

Strengthened low speed shaft bearings

Gear reducers and gearmotors sizes 04 ... 10 can be supplied with taper roller bearings supporting the low speed shaft, allowing increased radial and/or axial loads. Values for sizes 08... 10 are given in ch. 14, other values, consult us.

Supplementary description when ordering by designation: strengthened low speed shaft bearings.

Strengthened high speed shaft bearings

Gear reducers W 2 sizes 06 ... 10 with $i_N \leq 160$ can be supplied with cylindrical roller bearings supporting the high speed shaft allowing increased radial loads, values $\times 1,6$ for sizes 06 ... 08, $\times 1,4$ for sizes 09 and 10 (ch. 13); this design is standard for sizes 11 ... 14.

Supplementary description when ordering by designation: strengthened high speed shaft bearing.



Controlled or reduced backlash

Gear reducers and gearmotors with worm gear pair **controlled or reduced backlash**.

Values are 1/2 (controlled backlash) or 1/4 (reduced backlash) those stated on ch. 15; reduced backlash designed not possible for W 1 and MW 1 with input speed $n > 1\,400 \text{ min}^{-1}$.

Supplementary description when ordering by designation: **controlled backlash** or **reduced backlash**.

Square flange for servomotors

MW 1 and MW 012...072 gearmotors can be supplied with motor mounting flange when coupling with servomotors and, only for MW1, with hub clamp for fitting with key between gear reducer worm shaft and motor shaft; for MW 2 first reduction pinion keyed directly onto motor shaft end permits to avoid backlash and consequently shock on the same keying.

Considering that servomotors do not have any standardised dimensions, when selecting verify all coupling dimensions stated in the table; **d** dimension determines IEC standardised motor size in catalogue gearmotor designation (see ch. 3 and 9).

For other gearmotor dimensions see ch. 10.


In case of motor removing, first loosen the hub clamp.

For the **verifications** of keying, motor mounting flange and motor bearing resistance according to motor performances, speed, mass and length, **consult us**.

Controlled or reduced backlash design can be supplied (see ch.15 and pag. 88).

Servogearmotors complete with synchronous «brushless» and asynchronous «vector» motors designed for automation: see cat. SR.

Supplementary description when ordering by **designation: square flange ... — ...** (state $V_1 - d$ dimension; e.g.: 145-24).



Gear reducer size	V_1 □ 1)	F	K \emptyset	M₁ \emptyset	N₁ \emptyset H7	P₁ \emptyset	Q₁	S	d \emptyset	e
01	90	M 6	7	100	80	120	4	9,5	11	23
02, 03	90	M 6 ⁴	—	100	80	120	4	9	11	23
	105	M 8	9,5	115	95	140	4	11	14	30
	120	—	9,5 ⁴	130	110	160	4,5	11	19	40
04 ... 07	105	M 8 ⁴	—	115	95	140	4	10	14	30
	120	M 8	9,5	130	110	160	4,5	12	19	40
	145	—	11,5 ⁴	165	130	195	4,5	12	19	50

1) Working length of thread 1,5 · F.

2) For size 40, d = 11 and 14 only.


3) For size 63 and 64 with $V_1 = 145$ d = 24 only.

Gearmotor with interposed coupling


Gearmotors **MW 111 ... 141** can be supplied with a coupling ready fitted between gear reducer and motor. This may be a steel/plastic serrated coupling or a flexible coupling.

This kind of gearmotor utilizes **UO2B** gear reducer design (with reduced wormshaft end) to which a flange, a spacer and then the coupling are added, in addition to the motor itself.

Supplementary description when ordering by **designation** (the same as for gearmotors in ch. 9): **gearmotor with coupling** or **with flexible coupling**.




Grandezza - Size gear reducer	motor	G
11, 12	180	330
13	180, 200	375
14	180, 200 225, 250 B5R	440 470



Shaft-mounting arrangements


See technical explanations at ch. 16.

For dimensions **A**, **B** see ch. 8 and 10.




It is **better** if this arrangement is applied on sides 1.

Supplementary description when ordering by **designation: reaction bolt using disc springs**.



Supplementary description when ordering by **designation: reaction bolt using disc springs and bracket**.



Supplementary description when ordering by **designation: rigid** (for torque arm positioning, see ch. 16) or **flexible torque arm using bracket**.

Hollow low speed shaft washer

All gear reducers and gearmotors can be supplied with washer, circlip (excluding sizes 01 ... 03), bolt for axial fastening and protection cap (ch. 16).

Supplementary description when ordering by **designation: hollow low speed shaft washer**.

Gear reducer size	Bolt UNI 5737-88	Disc spring DIN 2093	T	F Ø	R 1)	M ₂ ≤ 2)
01	M 6 x 40	A 18 n. 2	8 ÷ 10	8	4,9	—
02	M 8 x 55	A 25 n. 2	10 ÷ 14	11	6,5	—
03	M 8 x 55	A 25 n. 2	10 ÷ 14	11	6,5	20
04, 05	M 12 x 70*	A 35,5 n. 2	14 ÷ 17	20	8,8	31,5
06, 07	M 12 x 90	A 35,5 n. 3	18 ÷ 25	16	10,8	56
08	M 16 x 110	A 50 n. 2	23 ÷ 32	20	13,1	100
09, 10	M 16 x 110	A 50 n. 2	23 ÷ 32	20	13,1	160

1) Theoretical value; tolerance 0 ÷ -1.

2) For higher M₂ values, utilize 2 reaction bolts or the arrangement with bracket (see below).

* Modified bolt.

Gear reducer size	Bolt UNI 5737-88	Disc spring DIN 2093	T	F Ø	S	U	R 1)
04, 05	M 12 x 70*	A 35,5 n. 1	14 ÷ 17	20	38	23	6,8
06, 07	M 12 x 90	A 35,5 n. 2	18 ÷ 25	20	38	23	8,8
08	M 16 x 110	A 50 n. 2	25 ÷ 32	20	50	30	13,1
09	M 16 x 110	A 50 n. 2	25 ÷ 32	20	50	30	13,1
11, 12	M 20 x 130	A 63 n. 3	23 ÷ 38	24	65	40	17,9
13	M 24 x 160	A 80 n. 2	29 ÷ 48	30	80	48	20,7
14	M 30 x 200	A 100 n. 2	37 ÷ 60	36	100	40	26,2

1) Theoretical value; tolerance 0 ÷ -1.

* Modified bolt.

Gear reducer size	f Ø	O	S	L	X Ø	Y	Z ≈	I
04, 05	12	280 ÷ 350	38	14	—	—	—	50
06, 07	12	280 ÷ 350	38	14	—	—	—	56
08	16	410 ÷ 510	50	17	52	242	84	74
09	16	410 ÷ 510	50	17	52	242	84	74
11, 12	22	580 ÷ 680	65	24	64	285	147	92
13	28	580 ÷ 680	80	30	88	305	137	113
14	28	580 ÷ 680	100	30	88	305	137	141



Hollow low speed shaft washer with locking rings or bush

All gear reducers and gearmotors can be supplied with washer, circlip (excluding sizes 01 ... 03), locking rings (sizes 01 ... 03) or locking bush (sizes 04 ... 14), bolt for axial fastening and protection cap (ch. 16).

Supplementary description when ordering by **designation: hollow low speed shaft washer with locking rings or bush.**

Gear reducer design ATEX II 2 G/D and 3 G/D

Worm gear reducers may be supplied according to European Community Directive ATEX 94/9/EC in order to be used in potentially explosive atmospheres of category **2 G/D** (for operation in zones 1 (G = gas), 21 (D = dust): presence of **probable** explosive atmosphere) and **3 G/D** (for operation in zones 2 (G = gas) 22 (D = dust): presence of **improbable** explosive atmosphere) with surface temperature 135 °C (T4).

These are the main variations of the product:

- Viton® seal rings;
- metal plugs;
- absence of plastic parts;
- special name plate with ATEX mark and indication of application limits;
- For category 2 G/D also:
 - double seal rings on low speed shaft;
 - thermal probes for monitoring temperature of oil and/or bearings, if any (see end of paragraph) or thermostats for the control of maximum oil temperature.

The **Atex installation and maintenance handbook** (with the additional documentation, if any) is **integral part of the supply** of each gear reducer; every indication stated in it must be carefully applied. In case of necessity consult us.

Selection of products of category 2 G/D and 3 G/D

Determine the size of gear reducer as indicated in ch. 6 considering following additional indications:

- a) maximum input speed $n_1 \leq 1\,500 \text{ min}^{-1}$.
- b) **service factor requested** determined according to ch. 5 increased with the factors stated in table 1 - **never lower than 0,85**.

Hollow low speed shaft protection

Gear reducers and gearmotors, sizes 01 ... 12 , can be supplied with only the protection cap for the area not utilized by the hollow low speed shaft (ch. 16).

Supplementary description when ordering by **designation: hollow low speed shaft protection.**

Table 1. Corrective factor fs

	2 G/D	3 G/D
Corrective factor of fs required	1,25	1,12

Verify **thermal power P_t** basing on: P_t (see tab. pag. 92), corrective factor (see table 2) and corrective factors of catalogue (see ch. 4).

Table 2. ft corrective factor for P_t

	2 G/D	3 G/D
Corrective factor of ft (thermal power)	0,8	0,9

Additional description when ordering by **designation:**


Design ATEX II 3 G/D T4 or ATEX II 2 G/D T4

Optional sensors (thermal probes or thermostats) may be available in order to reduce the interval of controls: this solution is advisable when the gear reducer or gearmotor has difficult access.

Minimum control intervals:

- 1 month **without** optional sensors;
- 3 month **with** optional sensors.

For more information see the installation and maintenance handbook U.T.D 123 and/or consult us.



Pt_N for gear reducers and gearmotors

grand. 01

n _{vite worm} min ⁻¹ 2)	u _{vite worm}									
	7	10	13	16	20	25	32	40	50	63
1 400	0,82	0,67	—	—	0,44	—	—	—	—	—
1 120	—	0,61	—	—	0,4	—	—	—	—	—
900	—	—	—	—	—	—	—	—	—	—
710	—	—	—	—	—	—	—	—	—	—
560	—	—	—	—	—	—	—	—	—	—
450	—	—	—	—	—	—	—	—	—	—

grand. 02

n _{vite worm} min ⁻¹ 2)	u _{vite worm}									
	7	10	13	16	20	25	32	40	50	63
1 400	1,14	0,93	0,84	0,77	0,6	0,55	0,49	—	—	—
1 120	1,04	0,84	0,76	0,69	0,55	0,49	0,45	—	—	—
900	0,94	0,76	0,7	0,64	0,5	0,46	—	—	—	—
710	0,87	0,7	0,63	0,58	0,45	0,41	—	—	—	—
560	0,8	0,64	—	—	0,41	—	—	—	—	—
450	—	—	—	—	0,38	—	—	—	—	—

grand. 03

n _{vite worm} min ⁻¹ 2)	u _{vite worm}									
	7	10	13	16	20	25	32	40	50	63
1 400	1,72	1,4	1,29	1,18	0,92	0,84	0,76	0,68	—	—
1 120	1,58	1,28	1,16	1,06	0,83	0,76	0,68	0,62	—	—
900	1,43	1,16	1,05	0,96	0,75	0,69	0,63	—	—	—
710	1,31	1,05	0,96	0,88	0,69	0,63	0,57	—	—	—
560	1,2	0,96	0,88	0,81	0,63	0,58	—	—	—	—
450	1,1	0,89	0,82	0,75	0,58	0,54	—	—	—	—
355	1,01	0,81	—	—	0,53	—	—	—	—	—
280	—	—	—	—	0,5	—	—	—	—	—

grand. 04, 05

n _{vite worm} min ⁻¹ 2)	u _{vite worm}									
	7	10	13	16	20	25	32	40	50	63
1 400	2,73	2,34	1,97	1,81	1,67	1,3	1,17	1,08	0,96	—
1 120	2,49	2,13	1,79	1,64	1,5	1,17	1,06	0,97	—	—
900	2,28	1,93	1,62	1,48	1,37	1,06	0,95	0,88	—	—
710	2,07	1,75	1,46	1,34	1,24	0,96	0,87	—	—	—
560	1,9	1,61	1,34	1,23	—	0,88	0,8	—	—	—
450	1,76	1,48	1,24	1,14	—	0,82	—	—	—	—
355	1,62	1,37	1,13	1,04	—	0,74	—	—	—	—
280	1,51	1,27	1,06	—	—	—	—	—	—	—

grand. 06, 07

n _{vite worm} min ⁻¹ 2)	u _{vite worm}									
	7	10	13	16	20	25	32	40	50	63
1 400	4,15	3,59	3,04	2,82	2,58	2,1	1,83	1,66	1,49	1,32
1 120	3,82	3,28	2,76	2,54	2,34	1,82	1,65	1,5	1,35	—
900	3,51	2,99	2,51	2,31	2,11	1,65	1,49	1,36	1,23	—
710	3,17	2,7	2,27	2,09	1,91	1,49	1,35	1,23	1,11	—
560	2,89	2,46	2,06	1,89	1,75	1,36	1,22	1,13	—	—
450	2,67	2,28	1,9	1,75	1,61	1,24	1,13	—	—	—
355	2,47	2,09	1,73	1,6	1,49	1,14	1,04	—	—	—
280	2,31	1,94	1,61	1,49	—	1,06	0,96	—	—	—
224	2,11	1,8	1,5	—	—	0,99	—	—	—	—
180	1,98	1,69	1,4	—	—	—	—	—	—	—
140	1,8	—	—	—	—	—	—	—	—	—
112	—	—	—	—	—	—	—	—	—	—

grand. 08

n _{vite worm} min ⁻¹ 2)	u _{vite worm}									
	7	10	13	16	20	25	32	40	50	63
1 400	—	9,8	8,5	7,8	7,2	5,7	5,1	—	—	—
1 120	—	8,5	7,3	6,6	6,2	4,84	4,32	—	—	—
900	—	7,2	6,2	5,6	5,3	4,12	3,67	3,4	—	—
710	—	6,2	5,3	4,8	4,45	3,5	3,11	2,87	—	—
560	—	5,3	4,49	4,08	3,79	2,97	2,64	2,44	—	—
450	—	4,59	3,9	3,54	3,3	2,56	2,3	—	—	—
355	—	4,02	3,41	3,09	2,89	2,24	2,01	—	—	—
280	—	3,55	3,01	2,76	2,57	1,99	1,79	—	—	—
224	—	3,18	2,69	2,44	—	1,78	1,59	—	—	—
180	—	2,88	2,42	2,21	—	1,6	—	—	—	—
140	—	2,52	2,12	—	—	1,4	—	—	—	—
112	—	2,25	1,9	—	—	—	—	—	—	—
90 ¹⁾	—	4,81	4,42	3,74	3,43	—	2,46	2,25	—	—

grand. 09, 10

n _{vite worm} min ⁻¹ 2)	u _{vite worm}									
	7	10	13	16	20	25	32	40	50	63
1 400	—	15,2	14	12,2	11,2	10,4	8	7,1	6,6	5,9
1 120	—	13,1	11,9	10,3	9,5	8,8	6,7	6	5,6	—
900	—	11,3	10,2	8,9	8,1	7,5	5,8	5,1	4,76	—
710	—	9,6	8,7	7,5	6,9	6,4	4,89	4,36	4,03	—
560	—	8,3	7,4	6,4	5,8	5,4	4,17	3,7	3,44	—
450	—	7,2	6,4	5,6	5,1	4,7	3,6	3,21	2,99	—
355	—	6,2	5,6	4,81	4,4	4,11	3,12	2,81	—	—
280	—	5,5	4,99	4,27	3,92	3,64	2,77	2,49	—	—
224	—	4,91	4,46	3,81	3,49	3,24	2,48	2,23	—	—
180	—	4,42	3,98	3,4	3,11	—	2,21	2,01	—	—
140	—	3,9	3,51	3,01	2,75	—	1,97	—	—	—
112	—	3,48	3,14	2,68	—	—	1,75	—	—	—
90 ¹⁾	—	3,14	2,85	—	—	—	—	—	—	—

grand. 11, 12

n _{vite worm} min ⁻¹ 2)	u _{vite worm}									
	7	10	13	16	20	25	32	40	50	63
1 400	—	23,4	21,8	18,9	17,4	16,1	12,5	11,4	10,3	9,3
1 120	—	20,2	18,9	16,3	14,9	13,8	10,8	9,7	8,7	7,8
900	—	17,4	16,1	13,9	12,7	11,8	9,1	8,3	7,5	6,7
710	—	15	13,8	11,8	10,8	10	7,7	7	6,3	5,7
560	—	12,8	11,8	10,1	9,2	8,5	6,6	6	5,4	4,82
450	—	11,1	10,2	8,7</td						



Motors: the following table contains the minimum requirements necessary for motors to be installed with gear reducers in areas with potentially explosive atmospheres and motors which can be supplied by Rossi Motoriduttori.

Zone	Required category of equipment ¹⁾		Motor supplied by Rossi Motoriduttori	
	Gear reducer	Motor	Standard	With brake
1	2 G/D ³⁾	2 G EExe 2 G EExd 2 G EExde with thermistors or Pt100	2 G/D EExd IIB T4 (135°C)	2 G/D EExd ⁴⁾ IIB T4 (135°C)
21		2 D IP65		
2	3 G/D	3 G EExn	3 D 135°C IP55 ⁵⁾	
22		3 D IP54 ²⁾		consult us

1) The devices suitable for zone 1 are also suitable for zone 2; similarly the devices suitable for zone 21 are also suitable for zone 22.

2) For conductive dusts motor must be 2 D IP65.



3) Whenever the level switch is present, the category will be 2G therefore the gear reducer is not suitable for zone 21.



4) Also EExde available.

5) It cannot be supplied with independent cooling fan.


Miscellaneous

- Expansion tank for continuous duty and high speed running of gear reducers and gearmotors **W 2 08 ... 14** and **W 3 08 ... 10** mounting position **B6**.
- Gear reducers and gearmotors sizes **08 ... 14** supplied **filled with synthetic oil**.
- Gearmotors with:
 - **HFV** (also single-phase) **brake motor** with d.c. **safety and/or parking brake** (sizes 63 ... 132) having overall dimensions nearly the same of a standard motor and braking torque $M_f = M_N$, maximum economy;
 - **two-speed motor**, **HF** standard motor, **F0** and **HFV** brake motors: 2.4, 2.6, 2.8, 2.12, 4.6, 4.8, 6.8 poles;
 - **FV0 brake motor for traverse movements**: 2, 2.4, 2.6, 2.8, 2.12 poles (always with low noise d.c. brake, see picture);
 - motor featuring: d.c. supply; single-phase; explosion-proof; with second shaft end; with non-standard protection, voltage and frequency; provided with devices against overloads and overheating;
 - **motor without fan cooled by natural convection** (size 63 ... 112); design for textile industry.
- Gear reducers and gearmotors with **mechanical torque limiter** on **output** shaft, gear reducer sizes **01 ... 11** (excluding size 81). Gear reducer design with mechanical **friction** type torque limiter (friction surfaces without asbestos), compact and with high transmissible torque – up to **300** daN m – and top quality standards. It protects the drive from accidental overloads by excluding the effect of inertia loads transmitted from up-line masses and, also if the gear reducer is irreversible (the torque limiter being mounted on the output shaft), inertia loads transmitted from down-line masses. When the transmitted torque tends to exceed the setting value the drive «slips» although it **remains** engaged with torque equal to the limiter setting value; slipping stops as soon as the load returns to normal; in the case of very brief overloads the driven machine will continue normal operation (after decelerating or stopping) without requiring reset procedures.






External limiter mounting



Intermediate limiter mounting



Limiter mounting onto combined units

The system, as the unit is mounted externally to the gear pair, will not suffer if the direction of rotation changes and it does not affect the rigidity and meshing precision between worm and worm wheel (this is important to ensure the correct transmission of torque and the limitation of undue backlash between teeth through time). The system also permits **shaft mounting** with the limiter mounted **externally** (easily accessible) or in the **intermediate** position (better safety protection). It can be interposed, in the **combined units**, between initial worm gear reducer and final worm gear reducer, sizes **08 ... 14**.

On request slide detector. For more details see **specific literature**.

- **MLA and MLS unit, mechanical torque limiter on input shaft**, motor sizes **80 ... 200** (180 for MLS).

Mechanical torque limiter unit to be interposed between gear reducer and B5 mounting position motor standardized to IEC or (wide belt or planetary motor-variator) or, in **combined units**, between the initial gear reducer and the final worm gear reducer, sizes **03 ... 14**.




Axially ultra-compact design: excellent load bearing with life lubricated double row angular contact ball bearings (motor size ≤ 112) or «O» disposed taper roller bearings.

The unit protects the drive from accidental overloads by excluding inertia loads transmitted from up-line masses and if the gear reducer is reversible (the torque limiter being on the input shaft), inertia loads transmitted from down-line masses.

LA unit is friction type (friction surfaces without asbestos). When the transmitted torque tends to exceed the setting, the drive «slips» although **it remains** engaged and transmits torque equal to the limiter setting value; slipping stops as soon as the load returns to normal; in the case of very brief overloads the driven machine will continue normal operation (after decelerating or stopping) without requiring reset procedures.

LS unit is ball type. When the transmitted torque tends to exceed the setting, the drive is «disengaged» so **it does not remain connected**. The driven machine will therefore stop.

LA and LS units are mechanically interchangeable. On request slide detector. For more details see **specific literature**.


MLA
frictionMLS
ballsMLS / MLA
mounted between gear reducer
and motor or motor-variatorMLS / MLA
mounted onto combined units

* on request

- Hollow low speed shaft with acme-type thread.
- Gearmotors with interposed compact clutch-brake or fluid coupling/brake unit.
- Semi-flexible and hydrodynamic couplings.
- Special paint options:
 - **external, single-compound**: antirust zinc primer plus blue RAL 5010 DIN 1843 synthetic paint (excluding sizes 01 ... 07);
 - **external, dual-compound**: dual-compound epoxy-polyamidic antirust primer plus dual-compound blue RAL 5010 DIN 1843 polyurethane enamel (excluding sizes 01 ... 07).
- Special seal rings; **double seal** (excluding sizes 01 ... 03).
- For high transmission ratios combined units can be also obtained with initial gearmotor **MW 012** with final gear reducer size ≤ 81 and with initial gearmotor **MW 013** for final gear reducer size ≥ 100 .







PALAWATR

**Head Office : 76 Moo 11 Buddhamonthon V Rd.,
Raiking, Sampran, Nakornpathom 73210
Tel : 0-2811-9022 Fax : 0-2811-9519**

**Hadyai : 37 Chotivittayakul 3 Rd., Khohong,
Hadyai, Songkhla 90110
Tel : 0-7446-5506 Fax : 0-7446-5507**

www.palawatr.co.th E-mail : marketing@palawatr.co.th