circaid® Power Added Compression Band (PAC Band)

Measure Circumference	Standard	Large	Extra Large
В	19 - 27	25 - 50	45 - 56
A1	19 - 36	22 - 41	22 - 41

Measure in cm on the skin standing using a tape measure

c = Measure the circumference around the area

B = Ankle

A1 = Arch

