



## FLO X TOP MOUNT CLAMP


FLX/018/C07



### POSITION CLAMP PLATE ONTO WORK SURFACE




## CONFIGURE FOR WORKSURFACE THICKNESS








# FIT C-BRACKET




## ⚠ IMPORTANT NOTE

Ensure inside of bracket is flush against back of work surface

# FIT CLAMP SCREWS




#### **FULLY TIGHTEN SCREWS**



## CONFIGURE 180° STOP (if required)

A 180° STOP ENGAGED





## A WARNING

- · Do not use this product for any purpose other than that for which it was designed
- Ensure desk/worksurface is suitable to take the weight of the arm/s and monitors
- Supported weight must not exceed the maxium load
- Take care when installing as fingers could become trapped

## A MAINTENANCE AND INSPECTION

- Ensure all screws are tightened and occasionally adjust
- Ensure arm is pushed fully down onto the clamp before installing the monitor(s)
- Clean with a damp cloth, NO solvents

## A DISCLAIMERS

- The use of power tools, lever bars or excessive force during the installation, or re-configuration of the product will invalidate your guarantee
- · Failure to observe the recommendations in the use, and configuration of these products may affect your guarantee
- As a part of Colebrook Bosson Saunders ongoing product improvement programme the design of products may change without prior notice and details may vary from those illustrated

## PATENTS

Colebrook Bosson Saunders hold a number of patents and other intellectual property rights covering our products and processes. You can find patent information on our website at: www.colebrookbossonsaunders.com/patents

Please consider leaving these instructions with the product if further installation may be required by others

FLX-018-C07-INST-A-SEPT-2022



Print size - A4 297mm x 210mm FOLD FOLD FOLD