

1. If your battery door is bowing in the middle its possible that the bolts 3 door bolts are adding a compression load causing it to bow.



To remove the bolt compression, increase the upper bolt hole from 6 to 8mm, this will remove the load and make door removal and fitting much easier as the upper bolt lines up better.



2. We are also working on an alternative holding system that will hold the midpoint of the door in position, this will guarantee correct fitment. We will update customer on this in due course.