

Part No.

QTHA-HSTE

Male Quick-test run x male Quick-test run x male Quick-test branch tee, brass

Connect three hoses or a combination of 3 hoses, adapters and hand pumps or manifolds



QTHA-HSTE

Specs/Attributes

Country of origin	USA
Has Check Valve	No
Materials	Brass
Max Operating Temperature	225 °F / 105 °C
Max Pressure	5000 PSI / 350 bar / 35 MPa
Max Vacuum	0.00 InHg / 0.0 kPa
Min Operating Temperature	0 °F / -18 °C
Seal Materials	Buna-N
Dimensions	H: 1.96 in (4.98 cm) x W: 1.25 in (3.18 cm)