



# *Sky Guide 10*

## “Basket of Roses”

BRONZE METAL CLAY PENDANT  
STEP GUIDE TUTORIAL


*By Rodi Frunze*



Available @ [www.metalclayadventures.com](http://www.metalclayadventures.com)



## Required Tool Checklist



- ✓ Inspiration
- ✓ 20g Bronze Clay (or any 15% shrinkage metal clay)
- ✓ Basic metal clay tool kit
- ✓ Circle template
- ✓ Document protector

### Soldering Option:

- ✓ 5mm round cabochon (optional)
- ✓ [5mm round bezel cup](#) (optional)

- ✓ [Stainless steel mesh](#) or firing blanket
- ✓ Stainless steel container with vented lid
- ✓ [Activated coconut carbon](#)
- ✓ A kiln with 1500 F/ 815.5C capacity.

### Soldering Option:

- ✓ Torch with heat capacity 1400F
- ✓ [Phosphorus-copper paste solder](#)

