




Doréma

frametekening / diagram: S22 E02 1



staal / steel

pos.	artikel nr. part no.	aantal quantity	frame deel frame part	maat mm. size mm.	∅ mm.	pos.	artikel nr. part no.	aantal quantity	frame deel frame part	maat mm. size mm.	∅ mm.
1	38339	1		A 1000 B 1000 C 600	22x1 19x1 22x1	6	38337	1		430+60	22x1
2	38340	1		A 1000 B 1000	22x1 19x1	7	38336	2		300	22x1
3	37698	2		1100	19x1	8	38338	1		1000	22x1
4	38284	3		940+60	22x1	9	38335	2		190	19x1
5	38334	1		140	19x1	10	34990	1		600	19x1

Access.	Aantal / Qty.
B = buisklem / adjusting clamp 22 mm.	9

BEWAAR DEZE FRAMETEKENING
KEEP THIS FRAME DIAGRAM IN A SAFE PLACE
 Voor nalevering van losse framedelen altijd het framenummer en het artikelnummer opgeven.
 When ordering separate frame parts always mention the diagram number and part number.