

DIGITAL TIRE PRESSURE GAUGE INSTRUCTIONS

V2 QUICK REFERENCE CHART:

KEY	FUNCTION	DESCRIPTION
UNIT	ON	Short press (1 second) to power on
	OFF	Long Press (3 Seconds) to power off
	CHANGE UNIT	Press to change unit of measurement
LIGHT	BACK LIGHT	Press to turn backlight on for 20 seconds
		Long Press (3 Seconds) to turn backlight on until turned off
	ZERO	Long Press (5 Seconds) to calibrate back to zero



