

Wonder Slick Stick

Instructions for use:

The key to using Wonder Slick Stick is to use as little as possible. For CBN wheels, apply Slick Stick to the tooling, not the wheel. For bandsaw blades, apply Slick Stick to the side of the spinning blade. For lathe beds, apply directly to the bed with the applicator. When at all possible, apply Slick Stick to the tooling only.

The caution against using too much Slick Stick, especially on a CBN wheel, is that particles from grinding will accumulate in the excess Slick Stick and reduce the cutting efficiency. If this happens, clean the CBN wheel with a penetrating fluid like PB Blaster. and a wire brush. Dry the wheel thoroughly and apply only a small amount of Slick Stick.